

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

10-Jul-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 1036 A

1 pc	Front bumper	\$	696.00
1 pc	Front bumper emblem	\$	44.00
1 pc	Front bumper o/s fog lamp cover	\$	66.00
1 pc	Front bumper n/s & o/s side retainer @ \$16.00	\$	32.00
1 pc	Front o/s fender inner shield @ \$120.00	\$	120.00
1 pc	Front bumper o/s protector	\$	51.00
1 pc	Front o/s wheel cover @ \$116.00	\$	116.00
1 pc	Front o/s head lamp	\$	1,028.00
		\$	2,153.00
	Less 10%	\$	215.30
		\$	1,937.70

S/NETT

1 pc	Front bumper clips	\$	48.00
1 pc	Front o/s fender sticker	\$	30.00
1 set	Front o/s fender inner shield clips	\$	28.00
	Towing Fee	\$	50.00
	Sundry	\$	50.00
	To check front o/s wheel alignment	\$	80.00
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs	\$	180.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the support panel, etc.	\$	200
		\$	650.00
	To putty and spray painting on front bumper, front o/s fender	\$	180
		\$	400.00
	To apply rustproofing on the repaired and replaced panels.	\$	120.00
		\$	3,573.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahin 16/07/19
11/7/19 1000h
2 hrs
45
Alvin Poon photo