

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: AXA	DATE	: 11-Jul-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SLP1287G
ADDRESS	:	MODEL	: SUBARU FORESTER
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:	JF1SJ6K85H6089248	
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Dented</i>	1	\$ 1,487.50	\$ 1,487.50
2	TAIL GATE LOGO <i>new</i>	1	\$ 112.00	\$ 112.00
3	TAIL GATE INNER TRIM BOARD <i>new</i>	1	\$ 612.00	\$ 612.00
4	TAIL GATE EMBLEM "SUBARU" <i>new</i>	1	\$ 75.00	\$ 75.00
5	TAIL GATE EMBLEM "AWD" <i>new</i>	1	\$ 57.00	\$ 57.00
6	TAIL GATE EMBLEM "FORESTER" <i>new</i>	1	\$ 72.00	\$ 72.00
7	TAIL GATE EMBLEM "XT" <i>new</i>	1	\$ 68.00	\$ 68.00
8	TAIL GATE WEATHER STRIP <i>new</i>	1	\$ 364.80	\$ 364.80
9	TAIL GATE OUTER MOULDING <i>cracked</i>	1	\$ 498.00	\$ 498.00
10	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 214.00	\$ 214.00
11	REAR BUMPER <i>new</i>	1	\$ 689.00	\$ 689.00
13	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 79.00	\$ 158.00
14	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 71.00	\$ 142.00
15	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 52.00	\$ 52.00
16	REAR BUMPER REINFORCEMENT <i>Bent</i>	1	\$ 400.00	\$ 400.00
17	REAR FENDER INNER COWLING <i>new</i>	2	\$ 257.00	\$ 514.00
18	REAR FENDER INNER TRIM <i>new</i>	2	\$ 812.00	\$ 1,624.00
19	TAIL LAMP <i>new</i>	2	\$ 598.00	\$ 1,196.00

1225

175

268

812 408

20	TAIL LAMP LOWER BRACKET <i>new</i>	2	\$ 54.00	\$ 108.00	+
21	REAR END PANEL <i>Dented</i>	1	\$ 684.00	\$ 684.00	✓
22	REAR END PANEL TOP GARNISH <i>old</i>	1	\$ 369.00	\$ 369.00	135
23	REAR FLOOR PANEL <i>Reps</i>	1	\$ 684.00	\$ 684.00	x
24	REAR FLOOR PANEL TOP SIDE BOARD <i>new</i>	2	\$ 128.00	\$ 256.00	+
25	REAR FLOOR PANEL TOP BOARD <i>old</i>	1	\$ 598.00	\$ 598.00	✓
26	REAR TOOLS SIDE SPONGE <i>new</i>	2	\$ 359.00	\$ 718.00	+
27	REAR SPARE TYRE LOWER SPONGE <i>new</i>	1	\$ 512.00	\$ 512.00	+
28	REAR TOOLS CENTRE SPONGE <i>form</i>	1	\$ 298.00	\$ 298.00	✓
29	REAR EXHAUST SILENCER <i>3pr</i>	2	\$ 785.00	\$ 1,570.00	+
30	REAR EXHAUST CENTER PIPE <i>5m</i>	1	\$ 986.00	\$ 986.00	x

6816
5452.80

TOTAL PRICE \$ 15,118.30
LESS 20% \$ 3,023.66
SUB TOTAL PRICE \$ 12,094.64

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	TAIL GATE INNER TRIM CLIP <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS <i>new</i>	1	\$ 60.00	\$ 60.00
3	REAR FENDER INNER TRIM CLIPS <i>new</i>	1	\$ 60.00	\$ 60.00
4	REAR FENDER INNER COWLING CLIPS <i>new</i>	1	\$ 30.00	\$ 30.00
5	REAR TAIL LAMP CLIPS SET <i>new</i>	1	\$ 30.00	\$ 30.00
6	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1	\$ 30.00	\$ 30.00
7	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00
8	RAER WINDSCREEN SEALANT <i>3pr</i>	1	\$ 60.00	\$ 60.00
9	REAR WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00
10	REVERSE SENSOR <i>2pr</i>	1	\$ 350.00	\$ 350.00

40

TOTAL \$ 880.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION			
1	WELD, KNOCK, OUT DENTS AND STRAIGHTEN ACCIDENT DAMAGED PARTS	\$1,600.00	900	
2	TO PUTTY, SPRAY PAINT, POLISH AND WAX ADJACENT PANELS	\$1,400.00	900	
3	WIRING, BULB CHECKING	\$120.00	30	
4	REMOVE AND REFIX CUSHION/SEAT/UPHOLSTERY TO FACILITATE REPAIR	\$250.00	80	
5	REMOVE AND REFIX EXHAUST SYSTEM	\$200.00	x	
9	TRANSFER TAILGATE MECHANISM	\$ 120.00	80	

6	REMOVE AND REFIX REAR WINDSCREEN	\$120.00	✓	
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$120.00 50		

TOTAL

\$ 3,930.00

2160

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,974.64
TOTAL LABOUR COST : \$ 3,930.00
TOTAL REPAIR COST : \$ 16,904.64

APPROVED DETAILS

EXCESS :
NO. OF WORKINGDAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adrian L
L/S 12/07/19.

06 hrs.

total: 8022.80.

L/S : 6.4K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: