



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLG 6755 L

Finalised

Parts (a) Cost / List Price Items	\$ 3343.00	5,587.66
Plus/Less 25%	\$ 835.75	1,396.92
Total of Cost / List	\$ 2507.25	4,190.75
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items		
Total Parts Cost	\$	4,190.75
Labour	\$ 1360.00	2,100.00
Total	\$ 3867.25	6,290.75

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 11/7/19 at

Remarks By Surveyor

- (a) The repair of this vehicle is authorized / Is not authorized until further notice.
- (b) Recommended Days of Repair : 04 day(s)
- (c) Resurvey : Required / Not Required
- (d) Excess : \$
- (e) Signature of surveyor : L Date: 11/7/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :	<u>SLG 6755 L</u>	Submit By :	<u>SERENGE</u>
Make & Model :	<u>TOYOTA PRIUS</u>	Year Manufacture :	<u>2016</u>
Chassis No. :	<u>JTDKB3FU003536072</u>	Engine No. :	
		Cost / List	

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front door	1	\$1,211.40		✓
2	LH front door hinge top	1	\$78.34		X
3	LH front door hinge bottom	1	\$78.34		X
4	LH front door weatherstrip	1	\$198.70		X
5	LHF door glass outer moulding	1	\$107.80		X
6	LHF power window motor	1	\$187.90		X
7	LHF power window regulator	1	\$570.60		X
8	LH rear door	1	\$1,211.40		✓
9	LH rear door hinge top	1	\$78.34		X
10	LH rear door hinge bottom	1	\$78.34		X
11	LH rear door weatherstrip	1	\$198.70		✓
12	LHR door glass outer moulding	1	\$107.80		X
13	LHR power window motor	1	\$187.90		X
14	LHR power window regulator	1	\$570.60		X
15	LH side skirt	1	\$721.50		✓
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

3343

