



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Repair Estimates

SLG 6755 L

Parts	(a) Cost / List Price Items	\$	5,587.66
	Plus/Less 25%	\$	1,396.92
	<b>Total of Cost / List</b>	<b>\$</b>	<b>4,190.75</b>
	(b) Nett Price Items		
	Less		
	<b>Total of Nett Item</b>		
	(c) Special Nett Items		
<b>Total Parts Cost</b>		<b>\$</b>	<b>4,190.75</b>
<b>Labour</b>		<b>\$</b>	<b>2,100.00</b>
<b>Total</b>		<b>\$</b>	<b>6,290.75</b>

Not Authorized  
Resurvey Before Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth  
Company : LKK  
Survey conducted on : 11/7/19 at \_\_\_\_\_

### Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : L Date: 11/7/19



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SLG 6755 L**  
Make & Model : **TOYOTA PRIUS**  
Chassis No : **JTDKB3FU003536072**

Submit By : **SERENGE**  
Year Manufacture : **2016**  
Engine No. :

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front door	1	\$1,211.40		✓
2	LH front door hinge top	1	\$78.34		X
3	LH front door hinge bottom	1	\$78.34		X
4	LH front door weatherstrip	1	\$198.70		?
5	LHF door glass outer moulding	1	\$107.80		X
6	LHF power window motor	1	\$187.90		?
7	LHF power window regulator	1	\$570.60		?
8	LH rear door	1	\$1,211.40		✓
9	LH rear door hinge top	1	\$78.34		X
10	LH rear door hinge bottom	1	\$78.34		X
11	LH rear door weatherstrip	1	\$198.70		✓
12	LHR door glass outer moulding	1	\$107.80		X
13	LHR power window motor	1	\$187.90		?
14	LHR power window regulator	1	\$570.60		?
15	LH side skirt	1	\$721.50		✓
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

