Not Authorized 1/2 94 11940.42 11/7/19 72.

## FASTECT AUTO PTE LTD BLK1 KAKI BUKIT AVE 6 #01-46,48,50 AUTOBAY SINGAPORE 417883

VEHICLE NO:SL	Z 7290D	
QTY	PARTICULAR	11.00
1 PCS	BOOTLID 1295-95	\$1,485.90
1 PCS	BOOTLID REAR LOGO 76.50	Nec \$86.60
1 PCS	BOOTLID CAMRY EMBLEM 78.50	W \$82.50
1 PCS	BOOTLID OUTER HANDLE	17 \$366.20
1 PCS	BOOTLID LOCK STRIKER	1 1 \$121.00 ×
1 PCS	BOOTLID 'HYBRID' EMBLEM P.S. H	sec \$102.00
1 PCS	BOOTLID WEATHERSTRIP	1v1 \$288.50
1 PCS	BOOTLID INNER LOCK 48.60	1~1 \$652.30
2 PCS	BOOTLID REFLECTORS@\$850.10 691.93 x 2 > 1383.80	C/L \$1,700.20
1 PCS	BOOTLID INNER TRIM 368. 20	De/70-2 \$499.20
1 SET	BOOTLID INNER TRIM CLIPS	\$60.00 X
2 PCS	BOOTLID HINGES @\$155.00	م م \$310.00 ×
2 PCS	BOOTLID LICENCE PLATE LAMPS @\$60.00	17 \$120.00 X
1 PCS	BOOTLID LICENCE PLATE TOP GARNISH	CM \$122.50
1 PCS	REAR BUMPER / 09 9. 6 3	ار \$1,299.10
2 PCS	REAR BUMPER SIDE RETAINERS @\$105.00	1/1 \$210.00 ×
1 SET	REAR BUMPER CLIPS	\$60.00
1 PCS	REAR BUMPER BEAM	クリ \$510.90 /
1 PCS	REAR BUMPER LOWER SKIRTING $620.90$	m/Qe \$645.10
1 PCS	REAR BUMPER LOWER TRAY	79-1 \$545.50
1 SET	REAR BUMPER LOWER TRAY CLIPS	11 \$50.00 <b>⋈</b>
1 PCS	REAR END PANEL \$79.60	Bonk 10 \$688.20
1 PCS	REAR END PANEL TOP GARNISH 38/9	T~1 \$485.50
1 PCS	REAR FLOOR PANEL	\$1,145.20
1 PCS	REAR FLOOR PANEL TOP BOARD 486.20	my \$620.30
1 PCS	REAR FLOOR PANEL TOOLS SPONGE 596-87	70 cm \$811.20
2 PCS	REAR TAILLAMPS @\$950.00 896.9572 = 1793.50	CM \$1,900.00
2 PCS	TAILLAMP HOUSING PANELS @\$355.00	\$710.00 X
2 PCS	REAR FENDERS @\$1480.00	<b>1,960.00 X 1,960.00 X</b>
2 PCS	REAR FENDER INNER TRIMS @\$622.10 \$95-10x2-1/90.20	De 73.1 \$1,244.20
1 SET	REAR FENDER INNER TRIM CLIPS	√ √ \$50.00 ×
2 PCS	TAILLAMP LOWER BRACKETS @\$25.00	1 ↑ \$50.00 ×
1 PCS	REAR EXHAUST	\$1,020.50
2 PCS	REAR EXHAUST MOUNTINS @\$65.00	17 \$130.00
1 PCS	REAR EXHAUST HEAT SHIELD	11 \$166.50 ×
1 PCS	REAR WINDSCREEN MOULDING	<b>4</b> ↑ \$98.10 ×
1 PCS	REAR BOOTLID LOCK SENSOR	SVC \$228.10 X
	S.NETT REAR BUMPER REVERSE SENSOR PEAR FIND PANIL SEALANT	\$20,625.30 \$100 \$380.00 \$20 AC \$50.00 \$20 \$50.00 \$20 \$50.00 \$20 \$11 \$280.00 \$20
4.000	S.NETT	shill
1 SET	REAR BUMPER REVERSE SENSOR	\$380.002.00
1 PCS	REAR END FAIL SEALANT	Nec \$50.00
1 PCS	REAR WINDSCREEN SEALANT	17 \$50.00 ℃
1 PCS	REAR LICENCE PLATE WHOLDER	Bet \$50.00 40
1 SET	REAR FLOOR PANEL INSULATOR	
1 SET	REAR REVERSE CAMERA	5WN \$500.00300
1 SET	REAR EXHAUST CHROME	\$0,00.088\$

LABOUR CHARGES:		
TO CHECK WIRING		<b>\$</b> 80.00 ⋛ <i>O</i>
TO DISMANTLE & REPLACING REVERSE SENSOR		\$80.00 (W
TO TRANSFER BOOTLID MECHANISM		\$120.00 60
TO DISMANTLE & REFIX REAR EXHAUST	1	<b>↑</b> \$100.00 ×
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY		\$120.00
TO DISMANTLE & REFIX REAR WINDSCREEN	4.	√ \$150.00 X
TO SPRAY RUST PROOFING	•	\$120.00 60
TO MOUNT VEHICLE ON CAR O-LINER	*	1 \$380.00 💢
LABOUR FOR PANEL BEATING & REPLACING PARTS		\$1,800.00 <i>XO</i> J
TO PUTTY & SPRAY PAINTING		\$1,800.00 // 0,7
	TOTAL	\$27,065.30

2870

## <u>LKK Auto Consultants</u> hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- $\bullet$  No  $\oplus_{\mathbb{R}^{d+1}}$  modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

## Acknowledged by Repairer

Signature:

Date: