

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5545B**AAD1907-109***Not Authored
L/Sing &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

*11 JUL 2019***SHC 5545B**

VF1ABL15AUC278905

RENAULT

LATITUDE

10.7.19

AXA

15/8/2014

		PART	LIST
1	1	BUMPER COVER REAR	\$ <i>Bu</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$ <i>Dir/No</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$ <i>Sn</i> 113.47 X
4	1	BUMPER BRACKET SIDE RH REAR	\$ <i>Sn</i> 135.97 X
5	1	BUMPER RETAINER RH REAR	\$ <i>Sn</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$ <i>Sn</i> 43.61 X
7	1	BUMPER BRACKET SIDE LH REAR	\$ <i>Sn</i> 135.97 X
8	1	BUMPER RETAINER LH REAR	\$ <i>Sn</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$ <i>CM</i> 43.61 ✓
10	1	BUMPER BEAM REAR	\$ <i>Ry</i> 777.52 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$ <i>H</i> 225.95 X
12	1	BUMPER BEAM BRACKET RH REAR	\$ <i>H</i> 225.95 X
13	1	BOOT REAR	\$ <i>Ry</i> 2,872.68 ✓
14	1	BOOT FINISHER	\$ <i>Sn</i> 470.06 X
15	1	BOOT WHEATERSTRIP	\$ <i>Sn</i> 323.05 X
16	1	BOOT REFLECTOR LAMP LH	\$ <i>Sn</i> 493.35 X
17	1	BOOT REFLECTOR LAMP RH	\$ <i>Sn</i> 493.35 ✓
18	1	BOOT BADGE 'RENAULT'	\$ <i>re</i> 225.36 ✓
19	1	BOOT BADGE	\$ <i>re</i> 225.36 ✓
20	1	BOOT STRUT LH	\$ <i>Sn</i> 276.08
21	1	BOOT STRUT RH	\$ <i>Sn</i> 276.08
22	1	BOOT HINGE LH	\$ <i>H</i> 367.84
23	1	BOOT HINGE RH	\$ <i>H</i> 367.84
24	1	BOOT INNER TRIM	\$ <i>Sn</i> 586.45
25	1	BOOT SWITCH	\$ <i>Sn</i> 168.13
26	1	BOOT LOCK	\$ <i>H</i> 202.67
27	1	BOOT LOCK CATCH	\$ <i>H</i> 74.40
28	2	LICENCE PLATE LAMP	\$ <i>Sn</i> 50.52
29	2	BOOT RUBBER PLUG	\$ <i>Sn</i> 221.81

Trans-cab Auto Services Pte Ltd**AAD1907-109**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5545B

30	1	FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	
31	1	FENDER PANEL REAR RH	\$	R	3,299.13	
32	1	WHEELARCH REAR RH	\$	Sn	543.47	
33	1	FENDER PANEL REAR LH	\$	R	3,299.13	
34	1	FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	
35	1	WHEELARCH REAR LH	\$	Sn	543.47	
36	1	TAILLAMP RH	\$	Sn	552.55	
37	1	TAILLAMP PANEL RH	\$	R	986.70	
38	1	TAILLAMP LH	\$	Sn	552.55	
39	1	TAILLAMP PANEL LH	\$	R	986.70	
40	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	can	404.56	
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
43	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
44	1	EXHAUST REAR	\$	R	7,489.05	X
45	1	EXHAUST CAP REAR	\$	R	230.49	X
46	1	FUEL FLAP	\$	Sn	343.57	X
TOTAL			\$		36,212.51	
10%			\$		3,621.25	
			\$		32,591.26	

Special Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	na	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	—
10	1	EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	na	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	na	30.00	—
13	1	BOOT STICKER "6555-3333"	\$	na	30.00	—
14	1	BOOT INNER TRIM CLIP	\$	na	45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	X

Trans-cab Auto Services Pte Ltd**AAD1907-109**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5545B

17	1	SPARE TYRE	\$	Sh	330.00	}
18	1	FENDER INNER TRIM CLIP RH	\$	na	28.00	
19	1	TAILLAMP CLIP RH	\$	na	5.00	
20	2	REAR WINDSCREEN SEALANT	\$	na	80.00	
21	1	WINDSCREEN MOULDING	\$	na	100.00	
22	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
23	1	TAILLAMP CLIP LH	\$	na	5.00	
24	1	FENDER INNER TRIM CLIP LH	\$	na	28.00	
25	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
26	1	Rear left tyre	\$	Sh	330.00	
27	1	Rear left tyre rim	\$	Sh	380.00	}
28	1	Rear right tyre	\$	Sh	330.00	
29	1	Rear right tyre rim	\$	Sh	380.00	
TOTAL			\$		3,645.02	

TOTAL PARTS	\$	36,236.28
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	600
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	500
To supply and re-do rear luggage floor panel insulation padding.	\$	na	380.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	80
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1907-109**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5545B

To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To Rust-Proofing Of The Affected Areas.	\$	170.00 301
To repair and realign rear exhaust pipe.	\$	nn 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 601
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00 X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00 X

TOTAL \$ 19,200.00**Over-All Total \$ 55,436.28**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be employed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

(LUMP SUM) Repair Days**25 DAYS****3 days**