

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0856/2019/GW
Date : 16-Jul-19

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : ALAN KOH TRADING CO
Driver's name : Mr. Koh Joo Ling
Address : 33A Jalan Malu Malu
: Singapore 769694
Telephone : HP +65 81261398
Type of Claim : Third Party Claims
Policy No. : 1700078024
Vehicle No : **SFE 18 C**
Model Code : Audi A3 SB 1.0 TF
Model / Year : 14/11/2017
Engine No : CHZ 571093
Chassis No : WAUZZZ8V9JA041060
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-Jul-19
Place of Accident : Hougang Ave 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFE 18 C

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To remove and transfer rhs front door's multi-lock system and power window devices.	S/N \$ 280.00 X.	
3	To dismantle and renew front bumper , rhs front fender and rhs front door. Reinstall all parts removed.	\$ 2,800.00 500 .	
4	To respray front bumper, rhs front fender, rhs front door and rear doors. ✓ ✓ <i>Rear Fenders</i>	\$ 3,300.00 2750.	
5	To renew rhs front rim and carry out wheel alignment. ✓	S/N \$ 280.00 ✓	
6	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>7,212.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFE 18 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Regis</i>	\$ 1,698.00	+
2	FRONT BUMPER GUIDE SECTION-RH <i>new</i>	\$ 35.00	+
3	FRONT FENDER-RH <i>Regis</i>	\$ 778.00	+
4	FRONT FENDER BRACKET-RH <i>3 new</i>	\$ 43.00	+
5	FRONT FENDER BRACE-RH	\$ 88.00	+
6	FRONT DOOR-RH <i>Regis</i>	\$ 2,073.00	+
7	FRONT DOOR OUTER SEAL-RH <i>new</i>	\$ 146.00	+
8	BONDING AGENT <i>new</i>	\$ 45.00	T
9	FRONT DOOR CATCH-RH <i>2 new</i>	\$ 96.00	+
10	DATE PLATE FOR TYRE PRESSURE	\$ 26.00	+
11	FRONT RIM-RH <i>let</i>	\$ 651.00	✓
12	RUBBER VALVE <i>new</i>	2 \$ 7.00	+
13	SUNDRIES <i>?</i>	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		: \$ 5,986.00	
TOTAL LABOUR CHARGES		: \$ 7,212.00	
GRAND TOTAL		: \$ 13,198.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lij*
Surveyed Date : *17/07/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *not authorised, 05 days.*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant