



**SINGAPORE
POLICE FORCE**



T/20190710/2205

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

4 of 4

Report No. T/20190710/2205

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: L / Staff Sgt GHAZALI BIN IBRAHIM	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 10/07/2019 22:19
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP168	SN 085
Signature: Singapore Police Force	

Budget Direct insurance

Certificate of Insurance

Comprehensive Car Policy
Policy Number: P10044028R01

Motor Vehicles (Third-Party Risks And Compensation) Act (Chapter 189) (Republic of Singapore), Motor Vehicles (Third-Party Risks And Compensation) Rules, 1996 Edition (Republic of Singapore), Road Transport Act, 1987 (Malaysia), Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Certificate Number P10044028R01 (Comprehensive / Authorised Driver Plan)

1) Vehicle Registration Number	:	SGR7794T
Chassis Number	:	JN1BAAC11Z0004192
2) Effective Date / Time of Commencement of Insurance for the Purpose of the Act	:	16/02/2019 (00:00)
3) Date / Time of Expiry of Insurance	:	15/02/2020 (23:59)
4) Excess (i) Policy	:	S\$ 600.00
(ii) Windscreen	:	S\$ 100.00
5) Policyholder	:	RAMLAN BIN ABD RAHMAN
6) Persons or Classes of Persons Entitled to Drive*		
<p>Drivers named as a Main / Named Driver in this Certificate of Insurance and any other person provided he is driving on the Policyholder's order or with the Policyholder's permission. Household members of the Main Driver not named in this Certificate of Insurance will not be covered.</p> <p>Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by any reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of accident or loss. Please refer to the Product Disclosure Document for full terms and conditions.</p> <p>Main Driver / Date of Birth : RAMLAN BIN ABD RAHMAN (21/03/1966)</p> <p>Named Driver(s) / Date of Birth : No driver is named.</p>		
7) Limitation as to use*		
<p>Use only for social, domestic and pleasure purposes and for the business purposes of the drivers listed above. The Policy does not cover use for hire or reward, tuition or driving tests, racing, pace-making, reliability trials, speed-testing or the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.</p> <p>* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.</p>		
8) Finance Company	:	Speed Credit Pte Ltd

I / We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Issued in Singapore on
31/01/2019


Auto & General Insurance (Singapore) Pte. Limited
Trading as Budget Direct Insurance



Simon Birch

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G), trading as **Budget Direct Insurance**
190 Clemenceau Avenue, #03-01, Singapore Shopping Centre, Singapore 239924 Tel: 6221 2111 budgetdirect.com.sg

Police Report Pg. 2



Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



MOTOR CAR (Frt)

Front Portion

Vehicle No: SGR 7724T

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	✓		30.00
1002	991887	Frt Number Plate Base	✓		30.00
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	DD		706.00
1005	992341	Frt Bumper Clips	✓		30.00
1006	991325	Frt Bumper Bracket	✓		
1007	991462	Frt Bumper Side Retainer	✓		65.00
1008	991433	Frt Bumper Reinforcement	✓		565.70
1009	991318	Frt Bumper Beam	✓		
1010	991468	Frt Bumper Sponge	✓		207.00
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	✓		314.00
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	✓		492.70
1022	991328	Frt Grille Emblem	✓		45.00
1023	991799	Frt Grille Chrome Moulding	✓		250.00
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	✓		953.60
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			595.20
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	✓		760.83
1034	991328	Bonnet Emblem	✓		
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator	✓		147.00
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber	✓		69.40
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991923	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Labour			800.00
		Paint Work			800.00

No of Items: 16

ACTUALLY: TOTAL

16/7/19

16/7/19

Veron Chen (LKKAUTO)

From: TeamAutoPro North <teamautopl@gmail.com>
Sent: Monday, 15 July 2019 11:19 AM
To: assignments; SUR
Subject: Our Ref: SGR 7794 T / 3rd PARTY QX 246 E DATED 10TH JULY 2019
Attachments: 7794-BUDGET DIRECT.PDF

Dear Shiau Chan,

Good day.

As spoken earlier, Mr Lim will be coming today for the 1st survey.

Enclosed is the GIA report.

Thank you.

--

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,

Peach

Team AutoPro Pte Ltd

Tel: 6258 1955

Fax: 6258 1956

385 Sin Ming Drive

#01-02 Vicom Inspection Centre

Singapore 575718



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION
ACCIDENT CLAIM SECTION (SPORE POLICE
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMY SINGAPORE 298333

Ref: CS3/SPF19012425/Bvf3s2

Date: 29-07-2019



ATTN: HAFIZUL FARHAN

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 246E	Veh. Inspected	SGR 7794T
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/076	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	15/07/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN LATIO 1.5L	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JN1BAAC11Z0004192	Colour	SILVER
Odometer	260710 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65R15	CONTINENTAL	6 mm
L/H Front Tyre	185/65R15	CONTINENTAL	6 mm
R/H Rear Tyre	195/60R15	SILVERSTONE	6 mm
L/H Rear Tyre	195/60R15	SILVERSTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/07/2019	Inspect Date / Time	15/07/2019 (02:10 PM)
Survey held at	160 SIN MING DRIVE #01-14 SINGAPORE 575722		
Repairer	TEAM AUTOPRO PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

OPINION ON REPAIR COST FOR VEHICLE NO. SGR 7794T

Qty	Description of Parts	Condition	Recommended (\$)
<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	DENTED	706.00
1	FRT BUMPER CLIPS	NECESSARY	30.00
1	FRT BUMPER SIDE RETAINER	NECESSARY	65.00
1	FRT BUMPER REINFORCEMENT	* CHECK	-
1	FRT BUMPER SPONGE	* CHECK	-
1	FRT BUMPER GRILLE	DISLODGE	314.00
1	FRT GRILLE	* CHECK	-
1	FRT GRILLE EMBLEM	NECESSARY	45.00
1	FRT GRILLE CHROME MOULDING	* CHECK	-
1	FRT SUPPORT PANEL	* CHECK	-
1	FRT RH HEADLAMP ASSY	BROKEN	595.20
1	BONNET	BENT	768.83
1	BONNET INSULATOR	NECESSARY	147.00
1	BONNET RUBBER	NECESSARY	69.40
1	FRT RH FENDER (NPA)	TO REPAIR SEE LABOUR	-
	LESS 30% DISCOUNT		-822.13
			1,918.30
<u>SPECIAL NETT ITEMS</u>			
1	FRT NUMBER PLATE (SN)	BENT	30.00
1	FRT NUMBER PLATE BASE (SN)	BENT	30.00
			60.00
<u>LABOUR</u>			
	LABOUR. INCLUSIVE OF THE REPAIR OF FRT RH FENDER.		800.00
	PAINT WORK.		800.00
			-
			-
			-
			1,600.00
GRAND TOTAL			3,578.30



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (EXCLUDE CHECK ITEMS S\$1,656.90 NETT)	2,850.00
--	-----------------

Report Ref No. CS3/SPF19012425/Bvf3s2

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

RECOMMENDED REPAIR DAYS : 6

WEEKENDS : 2

TOTAL DAYS : 8

LIM TEOW GUAN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.