

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBG6188S190708

Estimate

Customer

Page 01 - 02

Name: AXA Insurance Singapore Pte Ltd

Date: 12-07-19

Address: Motor Claims Department

Vehicle No: GBG6188S

8 Shenton Way #27-01

Model/Make: Fiat Doblo Cargo

AXA Tower

Singapore 068811

Maxi 1.6 MTJ AMT Glaxe

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bonnet <i>BUC</i>	\$ 1,170.00	
2	Bonnet Hinges 02 Pcs (@S\$135.00) <i>Bent</i>	\$ 270.00	
3	Bonnet Insulator <i>de</i>	\$ 97.30	
4	Bonnet Insulator Clips (1 set) <i>net</i>	\$ 50.00	
5	Bonnet Rubber Beading 02 pcs (@ \$S\$98.40) <i>NF</i>	\$ 196.80	
6	Bonnet Inner Lock <i>twi</i>	\$ 145.00	
7	Bonnet Sponge	\$ 241.80	
8	Bonnet Sponge Clips 1 set <i>70cm net</i>	\$ 80.00	
9	Fender 02 pcs (@ \$S\$780.00) <i>Bent/Buc</i>	\$ 1,560.00	
10	Fender Cowling 02 pcs (@ \$S\$466.00) <i>MM</i>	\$ 932.00	
11	Fender Cowling Clips Lh & Rh 2 sets (@ \$S\$60.00 SN) <i>MM</i>	\$ 120.00	
12	Fender Cover "Black" 02 pcs (@ \$S\$640.00) <i>01/scene 89.50</i>	\$ 1,280.00	
13	Head Lamp 02 pcs (@ \$S\$862.40) <i>holder cre</i>	\$ 1,724.80	
14	Head Lamp Panel 02 pcs (@ \$S\$988.70) <i>R</i>	\$ 1,977.40	
15	Support Panel Centre <i>Bent</i>	\$ 790.00	
16	Bumper <i>D.S. 850</i>	\$ 1,245.50	
17	Bumper Clips 1 set <i>net</i>	\$ 58.00	
18	Bumper Reinforcement <i>D.S.</i>	\$ 752.00	
19	Bumper Lower Grille <i>70cm 488.00</i>	\$ 685.00	
20	Bumper Lower Grille Clips 1 set <i>11</i>	\$ 65.00	
21	Bumper Bracket 02 pcs (@ \$S\$171.80) <i>Bent</i>	\$ 343.60	
22	Bumper Fog Lamp Cover 02 pcs (@ \$S\$197.60) <i>11</i>	\$ 395.20	
23	Bumper Sponge <i>70cm</i>	\$ 117.60	
24	Bumper Towing Cover <i>11</i>	\$ 105.00	
25	Grille <i>3/4</i>	\$ 484.70	
26	Grille "Fiat Logo" Motif <i>mo.s</i>	\$ 142.10	
27	Diesel Pump <i>11</i>	\$ 1,370.00	
28	"Corporate" Advertisement & Artwork <i>NT</i>	\$ 300.00	
29	Wiper Tank <i>11</i>	\$ 280.00	
30	Inter Cooler <i>Bent/pur 1050</i>	\$ 3,640.00	
31	Inter Cooler Cowling <i>11</i>	\$ 435.00	
32	Inter Cooler Clips 1 set <i>11</i>	\$ 35.00	
33	Aircon Condenser <i>Bent/pur</i>	\$ 1,278.00	
34	Air Con Condensor Cowling <i>MS</i>	\$ 285.00	
C/F Balance ---->		\$ 22,651.80	

Not Attached
2/18

15/7/18

2/3 @ 12.000/7
10 day

Whistle After up



M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBG6188S190708

Estimate

Customer

Page 02 - 02

Name: AXA Insurance Singapore Pte Ltd

Date: 12-07-19

Address: Motor Claims Department

Vehicle No: GBG6188S

8 Shenton Way #27-01

Model/Make: Fiat Doblo Cargo

AXA Tower

Singapore 068811

Maxi 1.6 MTJ AMT Glaxe

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance ---->	\$ 22,651.80	
35	Front Radiator <i>Butler</i>	\$ 854.30	
36	Radiator Fan Motor Completed <i>one/for 850</i>	\$ 385.00	
37	Radiator Fan Cowling Completed	\$ 1,175.60	
38	Radiator Top Hose 11	\$ 2,017.80	X
39	Radiator Spare Tank 11	\$ 773.50	X
40	Radiator Hose Top 11	\$ 142.80	X
41	Radiator Hose Lower 11	\$ 195.70	X
42	Radiator Coolant 1 bottle 11	\$ 45.00	SN X
43	ABS Master Pump 11	\$ 4,270.00	X
44	TURBO <i>CNE 4150</i>	\$ 4,856.30	
45	Engine Lower Cover 11	\$ 975.00	X
46	Engine Mounting 1 set <i>70-11 650</i>	\$ 1,790.00	
47	Engine Top Cover 11	\$ 890.00	X
48	Number Plate Garnish <i>Dis 95</i>	\$ 387.00	
49	Number Plate and Base <i>Dis</i>	\$ 48.00	SN 405-W
50	Exhaust Sensor 11	\$ 610.00	
51	Exhaust Heat Shield 11	\$ 365.80	
52	Exhaust Heater 11	\$ 317.20	
53	Battery 11	\$ 280.00	
54	Battery Base 11	\$ 385.00	
55	Air Cleaner Completed 11	\$ 955.90	
56	Air Cleaner Hose 11	\$ 361.80	
57	Horn Unit 11	\$ 182.10	
	To check all wiring & electrical component for proper function	\$ 100.00	30
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 180.00	100
	To remove & replace radiator and conduct pressure test & bleed system	\$ 180.00	110 X
	Remove and refix Fender, Panel & Etc's ...	\$ 100.00	110 X
	To remove and refix Engine Labor Charge	\$ 350.00	250
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc's	\$ 2,800.00	1200
	To putty & spray painting & including touch up paint on accident affected	\$ 1,600.00	1100
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 100.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 50,318.60

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



M/s Liu's Brother Auto Engrg Wks

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 1196N

Vehicle Details

Vehicle No.: GBG61885

Vehicle to be Exported: No

Intended Deregistration Date: 11 Jul 2019

Vehicle Make: FIAT

Vehicle Model: DOBLO CARGO MAXI 1.6 MTJ AMT
GLAZE

Primary Colour: White

Manufacturing Year: 2017

Engine No.: 263A50008152788

Chassis No.: ZFA26300006H19083

Maximum Power Output:

Open Market Value: \$19,929.00

Original Registration Date: 20 Sep 2017

First Registration Date: 20 Sep 2017

Transfer Count: 1

Actual ARF Paid: \$997.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date:

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 19 Sep 2027

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$42,809.00

COE Rebate Amount: \$35,055.00

Total Rebate Amount: \$35,055.00

The information contained herein is correct as at 11 Jul 2019

OK