

not allowed  
2hr  
1/5 @ 5900  
15/7/19  
7 day.  
Eduphth Attorngp.



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLM5256K  
Date of Accident : 12 July 2019

Mr Abubakar Bin Abdul Wahab

Date : 15 July 2019

Estimate To Repair SJA6958Z - Mitsubishi Lancer 1.5 Mivec GLS 4A/T  
Chassis No : JMYSRCY2A8U004337

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	rear bumper <i>no/De</i>	\$ 797.00
02	1 pc	rear bumper tow cover <i>nr</i>	\$ 20.00 X
03	8 pc	rear bumper clips @ \$4.50 <i>nr</i>	\$ 36.00
04	1 pc	rear licence plate garnish <i>nr</i>	\$ 323.00 X
05	1 pc	rear bumper reflector <i>nr</i>	\$ 25.00 X
06	1 pc	front bumper <i>nr</i>	\$ 737.00
07	2 pc	front bumper side retainer @ \$44.00 <i>nr</i>	\$ 88.00 X
08	10 pc	front bumper clips @ \$3.50 <i>nr</i>	\$ 35.00
09	1 pc	front bumper reinforcement <i>best</i>	\$ 320.00
10	1 pc	front bumper spot lamp <i>nr</i>	\$ 430.00 X
11	1 pc	front bumper spot lamp garnish <i>nr</i>	\$ 30.00 X
12	1 pc	front bumper lower centre air grille <i>nr</i>	\$ 71.00 X
13	2 pc	front bumper lower spoiler @ \$221.00 <i>nr</i>	\$ 442.00 X
14	1 pc	front bumper top beam <i>best</i>	\$ 69.00
15	1 pc	radiator grille <i>nr</i>	\$ 251.00
16	1 pc	radiator grille - inner <i>best</i>	\$ 150.00
17	1 pc	radiator grille - chrome <i>nr</i>	\$ 180.00 X
18	1 pc	radiator grille emblem badge <i>nr</i>	\$ 38.00
19	1 pc	radiator grille outer garnish <i>nr</i>	\$ 160.00 X
20	4 pc	radiator grille outer garnish clips @ \$3.50 <i>nr</i>	\$ 14.00 X
21	2 pc	headlamp @ \$671.00 <i>nr</i>	\$ 1,342.00
22	2 pc	headlamp lower bracket @ \$13.00 <i>nr</i>	\$ 26.00 X
23	1 pc	bonnet <i>best/buc</i>	\$ 622.00
24	1 pc	bonnet underseal weatherstrip <i>nr</i>	\$ 28.00
25	2 pc	bonnet hinge @ \$54.00 <i>nr</i>	\$ 108.00 X
26	1 pc	bonnet lock <i>nr</i>	\$ 49.00
27	1 pc	bonnet lock cover <i>De</i>	\$ 51.00
28	1 pc	bonnet weatherstrip <i>Repair</i>	\$ 15.00 X
29	2 pc	front fender @ \$366.00 <i>nr</i>	\$ 732.00 X
Less 10 %			\$ 7,189.00
			\$ 718.90
			\$ 6,470.10
<u>SPECIAL NETT ITEMS</u>			
30	2 pc	rear parking sensor @ \$350.00 <i>short</i>	\$ 700.00 200
31	1 pc	rear licence plate <i>best</i>	\$ 50.00 40
32	1 pc	rear bumper lower spoiler (accessory) <i>nr</i>	\$ 650.00 600
33	1 pc	front bumper lower spoiler <i>nr</i>	\$ 700.00 X

4825  
4072.50



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLM5256K  
Date of Accident : 12 July 2019

Mr Abubakar Bin Abdul Wahab

Date : 15 July 2019

Estimate To Repair SJA6958Z - Mitsubishi Lancer 1.5 Mivec GLS 4A/T  
Chassis No : JMYSRCY2A8U004337

S/No	Quantity	Description	Amount
34	1 pc	<u>SPECIAL NETT ITEMS</u> front licence plate <i>rent</i>	\$ 80.00 <i>20</i>
			\$ 2,180.00
		<u>LABOUR &amp; MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 150.00 <i>30</i>
02		To reinstall of rear bumper parking sensor.	\$ 80.00 <i>50</i>
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,800.00 <i>1000</i>
04		Putty and spray painting of the affected portion.	\$ 1,500.00 <i>1400</i>
			\$ 3,530.00
		Total	\$ 12,180.10 <i>7412.5</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: