

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5256K**AAD1907-121***Not Authorised*
11 Sep 8

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

12 JUL 2019

SHC 5256K

VF1ABL15AUC276875

RENAULT

LATITUDE

10.7.19

AXA

19/2/2014

PART		LIST	
1	BUMPER COVER FRT	\$	<i>N</i> 1,259.42
1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68
1	BUMPER RETAINER FRT LH	\$	<i>SL</i> 151.41
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80
1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21
1	BUMPER BEAM FRT	\$	<i>N</i> 914.08
1	HEADLAMP LH	\$	<i>SL</i> 1,184.43
1	HEADLAMP PANEL FRT LH	\$	<i>N</i> 152.15
1	FENDER PANEL FRT LH	\$	<i>B</i> 783.83
1	WHEELARCH FRT LH	\$	<i>SL</i> 278.84
1	FENDER BRACKET LOWER LH	\$	<i>SL</i> 15.79
1	FENDER INSULATOR LH	\$	<i>SL</i> 130.84
1	FRONT BRACE PANEL	\$	<i>N</i> 177.22
1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>N</i> 89.79
1	BONNET	\$	<i>N</i> 1,941.63
1	BONNET INSULATOR	\$	<i>SL</i> 405.73
1	BONNET STRUT LH	\$	<i>SL</i> 88.61
1	BONNET STRUT RH	\$	<i>SL</i> 88.61
1	BONNET HINGE LH	\$	<i>N</i> 348.31
1	BONNET HINGE RH	\$	<i>N</i> 348.31
1	BONNET LOCK	\$	<i>N</i> 305.48
1	BONNET CABLE	\$	<i>N</i> 119.19

Trans-cab Auto Services Pte Ltd**AAD1907-121**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5256K

1	BONNET CABLE COVER	\$	<i>Sh</i> 161.03	}	<i>X</i>
1	BONNET SEAL OUTER	\$	<i>Sh</i> 92.36		
1	BONNET SEAL INNER	\$	<i>Sh</i> 157.28		
1	AIR CLEANER BOX	\$	<i>Sh</i> 464.20		
1	AIR CLEANER HOSE	\$	<i>Sh</i> 175.85		
1	AIR CLEANER LOWER	\$	<i>Sh</i> 271.26		
1	DOOR PANEL FRT LH	\$	<i>N</i> 2,844.66	}	
1	DOOR MIRROR ASSY LH	\$	<i>CM</i> 1,483.40		
1	DOOR HARNESS WIRE LH	\$	<i>Sh</i> 2,670.00	<i>X</i>	
1	ROCKER PANEL INNER GARNISH LH	\$	<i>Sh</i> 466.51	<i>X</i>	
1	ROCKER PANEL INNER LH	\$	<i>N</i> 1,024.79	<i>X</i>	
1	ROCKER PANEL OUTER LH	\$	<i>N</i> 1,184.99	<i>X</i>	
1	ROCKER PANEL CENTER LH	\$	<i>N</i> 990.25	<i>X</i>	
TOTAL		\$	26,320.18		
10%		\$	2,632.02		
		\$	23,688.16		

Special Nett

1	BUMPER CLIP FRT	\$	<i>N</i> 66.00	}	<i>X</i>
1	BUMPER BRACKET CLIP FRT LH	\$	<i>N</i> 12.00		
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>N</i> 10.50		
1	BUMPER GRILLE LOWER CLIP	\$	<i>N</i> 69.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>N</i> 70.00		
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>N</i> 20.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>N</i> 30.00		
1	WHEELARCH CLIP FRT LH	\$	<i>N</i> 30.50		
1	FRONT LEFT TYRE	\$	<i>Sh</i> 300.00		
1	FRONT LEFT TYRE RIM	\$	<i>Sh</i> 380.00		
1SET	Front licence plate with holder	\$	<i>Sh</i> 80.00		
1	WINDSCREEN SEALANT	\$	<i>N</i> 253.80		
1	FRONT WINDSCREEN MOULDING	\$	<i>N</i> 120.00		
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	<i>N</i> 100.00		
6	BONNET INSULATOR CLIP L70Y	\$	<i>N</i> 7.30		
2	BONNET STRUT L70Y	\$	<i>Sh</i> 88.61		
2	BONNET CABLE CLIP L70Y	\$	<i>N</i> 6.31		
2	BONNET CABLE COVER SCREW L70Y	\$	<i>N</i> 10.85		
1SET	RADIATOR GRILLE FRAME CLIP	\$	<i>N</i> 52.00		
1SET	RADIATOR GRILLE SCREW	\$	<i>N</i> 16.00		

Trans-cab Auto Services Pte Ltd

AAD1907-121

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5256K

- | | |
|---|--------------------------------|
| 1 | FRONT DOOR STICKER 'Trans-Cab' |
| 1 | FRONT DOOR STICKER 'Classic' |

\$
\$

80.00
80.00

TOTAL	\$	1,882.88
--------------	-----------	-----------------

TOTAL PARTS	\$	25,571.04
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$

6,000.00

To transfer of front bumper fittings, attachment and perform water seepage test.

\$

nn 380.00 X

To transfer of front fender fittings, attachment and perform water seepage test.

\$

nn 380.00 X

To transfer of front windscreen fittings and conduct water seepage test.

\$

nn 170.00 X

To check steering geometry and computer wheel alignment

\$

nn 220.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$

nn 380.00 X

To transfer of tire, rim and on wheel balancing.

\$

nn 170.00 X

Putty and spray painting of the affected portion.

\$

6,000.00 7000

To transfer of bonnet fittings, attachment and perform water seepage test.

\$

nn 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$

nn 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1907-121**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5256KTo transfer of front door fittings, attachment and
perform water seepage test.\$ *na* 380.00 *X*To apply paint protection system (PPS) maintain
and enhancement\$ *na* 380.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *15/*

To rust-proofing of the affected areas.

\$ 170.00 *30/***TOTAL** \$ **15,560.00****Over All Total** \$ **41,131.04****LUMP SUM (REPAIR DAY)***20 days**3 days*LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: