

ASS. REC. BY:

REF:

CS/A1619012456/Uqf3

Special Instruction

02

Survey: Marius

ASSIGNMENT (Office)

From (Person): Hor Yinnal

of

MG

Date/Time:

15/7/19

Neinun

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLZ 4272B

Insured:

SKV 8480Z

at Workshop m/s

EURO SUCCESS

Tel:

9828 9222 / 6742 6231

of 1 KAKI BUKIT AVE 6 #02-03 Autobay

Policy No:

0999994157

Claim No:

816937578956

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

12/7/19

CA / REV / REP. / REV 24 HRS

WPI

survey. 16/7/19

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimated ()
	<u>SLZ 4272B X</u>	
	<u>SKV 8480Z X</u>	

REP: **harcos**

REP: **AG**

ASSIGNMENT

From: **46/07/19**
 Date: **46/07/19**
 Estimated Cost: **0**
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SLZ 4272B**
 at Workshop n/s: **EURO SUCCESS**
 of: **1 Kaki Bukit Ave 6 #0-03**
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:
 (Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**
 Bal. or Market Value:
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: **5** days Res.: Yes or No
 Lum Sum: **20** % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS **WPI**
 Date: Person Contacted: Vehicle: IN / OUT

N/S	O/S

Veh No: **SLZ 4272B** Yr Regn: **4/18**
 Type: **Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or **(A)**
 Make: **mazda 3** G.C: **1496**
 Colour: **blue** A/C: Insured / Std / NI / NA
 Sp. Reading: **33280** T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: **JM6BN22A8H0165645**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brake: **In order** / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **225/60R16**
 R:
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO/YOKO or
 Front Rear
 R/Bal. **S** mm R/Bal. **A** mm
 L/Bal. **S** mm L/Bal. **S** mm
 D.O.A. **27/7/19** D.O.I. **16/7/19**
 Survey held at
 Des. of Damages: **Front** / Rear / O/S / N/S / UIC / Rooftop or
Rear
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
22/7/19 **LTA 43065**
L/S # 4000 confirmed with AH huf.
cred @ 8768.76, 69.6)

RECEIVED 23 JUL 2019

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to?

Days Of Repair: **5**
 Resurvey No. of Trip: **1**

Report Format: **OVER-TP**
 Lump Sum / I.B.A. (\$) **4000**

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee:	250 11
Transportation:	
S + RS, \$	
Photos	
Others	
TOTAL	261

PRE-REPAIR INSPECTION REQUEST – SLZ4272B vs SKV8480Z (OI) on D.O.A.: 12/07/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Tong, Wahxin
Sent: 7/15/2019 2:22:40 PM

Hi,

Please refer to the enclosed request from **Hin Tat Augustine & Partners**.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Yinrul.Hor@aig.com | www.aig.sg

From: Ruby Ong [mailto:ruby@htapartners.com.sg]
Sent: Monday, July 15, 2019 2:14 PM
To: Hor, Yinrul
Subject: [EXTERNAL] RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLZ 4272B [OUR REF. TCL.GCN.RO.50439.19.ESS]
Importance: High

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir

We refer to your email of even date.

Our client is agreeable to appoint **Marcus Chua, LKK Auto Consultants** from your list to conduct the joint pre-repair survey as a single joint expert for our client's vehicle no. **SLZ 4272B**.

Please make the necessary arrangements with the contact person. The details are as follows :

Venue : **EURO SUCCESS SERVICES PTE LTD**
1 Kaki Bukit Avenue 6
#02-03 Autobay
Singapore 417883

Contact Person : Ah Huat (Tel. 9828 9277 / 6742 6231)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313
www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Ruby Ong
Sent: Monday, 15 July 2019 11:04 AM
To: Hor, Yinrul <Yinrul.Hor@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>
Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLZ 4272B [OUR REF. TCL.GCN.RO.50439.19.ESS]
Importance: High

Your ref: SKV 8480Z
Our ref: TCL.GCN.ro.50439.19.ess

WITHOUT PREJUDICE

12 July 2019

AIG Asia Pacific Insurance Pte Ltd
Motor Claims Department
78 Shenton Way
#08-16 AIG Building
Singapore 079120

By Email Only

VERY URGENT

Dear Sirs,

CLAIMANT: GO-RENT PTE LTD

ACCIDENT INVOLVING SLZ 4272B & SKV 8480Z ALONG 188 PANDAN LOOP ON 12 JULY 2019 @ 1720HRS

We are instructed by Go-Rent Pte Ltd to notify you of a road traffic accident on 12 July 2019 at about 1720hrs along 188 Pandan Loop involving our client's vehicle registration number SLZ 4272B and vehicle registration number SKV 8480Z driven by your insured/insured's driver at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext 278

Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinrul.Hor@aig.com

To: ruby@htapartners.com.sg

Cc: Andy-SY.Fong@aig.com , Winnie-LW.Fan@aig.com , NoorMariesa.AbuKassim@aig.com , Syazairdina.Azlan@aig.com , yokeshi.chan@aig.com , ShengYang.Lim@aig.com

, Aashweenjeetkaur.Mihoosingh@aig.com , Divyashni.Subramaniam@aig.com , Wahxin.Tong@aig.com

Subject: aigencryt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKV8480Z AND SLZ4272B ON 12/07/2019

Date: Mon, 15 Jul 2019 03:18:18 +0000

Without Prejudice

Your Reference : TCL.GCN.RO.50439.19.ESS

Our Reference : SKV8480Z

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Vivlane)

AIG

FNOL Adjuster I

Singapore FNOL | Claims Operations – Auto

Yinrul.Hor@aig.com | www.aig.sg

From: Ruby Ong [mailto:ruby@htapartners.com.sg]

Sent: Monday, July 15, 2019 11:04 AM

To: Hor, Yinrul; Abu Kassim, Noor Mariesa

Subject: [EXTERNAL] REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLZ 4272B [OUR REF. TCL.GCN.RO.50439.19.ESS]

Importance: High

This message is from an external sender; be cautious with links and attachments.

Your ref: SKV 8480Z
Our ref: TCL.GCN.ro.50439.19.ess

WITHOUT PREJUDICE

12 July 2019

AIG Asia Pacific Insurance Pte Ltd
Motor Claims Department
78 Shenton Way
#08-16 AIG Building
Singapore 079120

By Email Only

VERY URGENT

Dear Sirs,

**CLAIMANT: GO-RENT PTE LTD
ACCIDENT INVOLVING SLZ 4272B & SKV 8480Z ALONG 188 PANDAN LOOP ON 12 JULY 2019 @ 1720HRS**

We are instructed by Go-Rent Pte Ltd to notify you of a road traffic accident on 12 July 2019 at about 17200hrs along 188 Pandan Loop involving our client's vehicle registration number SLZ 4272B and vehicle registration number SKV 8480Z driven by your insured/insured's driver at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313
www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	4747D

Vehicle Details

Vehicle No.:	SLZ4272B
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Jul 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	P520457346
Chassis No.:	JM6BN22A8H0165645
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,299.00
Original Registration Date:	30 Apr 2018
First Registration Date:	30 Apr 2018
Transfer Count:	2
Actual ARF Paid:	\$14,299.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2028
PARF Rebate Amount:	\$10,724.00

Intended COE Rebate Details

COE Expiry Date:	29 Apr 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,810.00
COE Rebate Amount:	\$32,341.00
Total Rebate Amount:	\$43,065.00

The information contained herein is correct as at 16 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/07/2019 11:18
Date Of Accident	12/07/2019 17:20
Exact Location Of Accident	PANDAN LOOP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ4272B
Insured/Policyholder	
Name Of Registered Owner	GO-RENT PTE LTD
Co Reg No	201824747D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-92223331

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA3 SEDAN 1.5 AT EU6

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107849833-000014 CLASSIC
Cover Note Number	

Driver

Name of Driver	RONAN TAN TENG NGE (CHEN ZHENYI)
NRIC No	S7429232A
Date Of Birth	29/08/1974
Occupation	OUTDOOR
Date Of Driving Pass	27/02/2017
Driving Experience	2 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83883433
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 12 MERPATI ROAD #10-117
Postcode	370012
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV8480Z
Vehicle Make/Model/Colour	MERCEDES BENZ / CLA180
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	AZRIN BIN MOHAMED BEJARAMIN
NRIC/Passport Number	S7240566H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	RONAN TAN TENG NGEE (CHEN ZHENYI)
Approximate Age	44
Injuries Sustain	
Injured person in which vehicle?	SLZ42728
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reportings may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - (i) understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data/personal information (as set out in this Form) and any other personal information provided by me or possessed by my insurer collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in the accident (all insurers) who have insured vehicles involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyer/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the handling of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to my enquiries to me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages) and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurers who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service provider or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above Purpose;
 - (d) my Personal Information will also be collected and used to compile my insurance for the purpose of Risk Services, investigation and management in present and all future claims;
 - (e) the information so collected (herein referred to as "Data") may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing their regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vack@idacnet.com.sg
Reporting Centre
Name: _____
NRIC/IN No: _____

15 JUL 2019

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I was about to exit, my vehicle was stationary when suddenly the vehicle B was collided on to my rear vehicle, the rear portion of my vehicle.

DECLARATION

I/We declare that the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Ram S
Driver's Signature
(If driver is not the policyholder)
Date & Time:

15 JUL 2019

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

EURO SUCCESS SERV PTE. LTD
Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231 FAX: 67411019 H/P: 98289277 (AH HUAT)

Vehicle No: **SLZ4272B** Model: **MAZDA 3**

*Not Authorized
 16/7/19
 2/s 4000/
 Takahashi
 Sdy.*

QTY	List Items	Price \$
1	REAR BUMPER <i>1075</i>	1160.00
2	REAR BUMPER L/R TOW HOOK COVERS @42.5	85.00 X
2	REAR L/R BUMPER REFLECTOR @89.5	179.00 X
1	REAR BUMPER REINFORCEMENT	541.70
2	REAR BUMPER L/R SIDE RETAINERS @42.6	85.20 X
2	REAR BUMPER TOP CLIPS @12.6	25.20
2	REAR BUMPER TOP CLIPS HOLDERS @14.2	28.40
1	REAR END PANEL	447.60
1	REAR END PANEL INNER TRIM	241.20
2	REAR L/R FLOOR SPONGE TRAYS @110.2	220.40 1PC
2	REAR L/R FENDER INNER SHIELD @68.6	137.20 X
2	REAR L/R TAILLAMPS @1078.6 <i>APP.50</i>	2157.20 1PC
2	REAR L/R TAILLAMPS PANELS @155.6	311.20 X
1	REAR SMART KEYLESS ANTENNA	241.20 X
1	REAR BOOTLID	1078.60 X
1	REAR BOOTLID LOGO	65.80
1	REAR BOOT EMBLEM 'MAZDA'	58.20
1	REAR BOOT EMBLEM '3'	34.40
1	REAR BOOT EMBLEM 'SKYACTIV'	68.60
2	REAR BOOT LID LAMP L/R @341.2	682.40 X
2	REAR L/R BOOT LID LICENCE LAMP @48.6	97.20 X
1	REAR BOOT LID INNER LOCK	250.30 X
1	REAR BOOT LID LOCK STICKER	65.50 X
1	REAR BOOT LID INNER STICKER	244.10 X
2	REAR BOOT LID L/R HINGES @115	230.00 X
1	REAR floor panel top board	124.60

TOTAL	\$11,005.20	<i>8260.20</i>
LESS 20%	\$2,201.04	
TOTAL	\$8,804.16	<i>3670.40</i>
		<i>20%</i>
		<i>2936.32</i>

Special Nett Items

	1	REAR REVERSE CAMERA	17	500.00	X
1 set		REAR BUMPER PDC SENSOR	stubs	320.00	200
1 set		REAR NUMBER PLATE WITH CASING	17	120.00	X
	4	REAR TAILLAMP SIDE CLIPS @10.6	17	42.40	X
	2	REAR EXHAUST MOUNTINGS @42.6	17	85.20	X
10		REAR FENDER INNER TRIM CLIPS @5.5	17	55.00	X
6		REAR BUMPER CLIPS @4.5	req'd	27.00	X
10		REAR BOOT INNER TRIM CLIPS @4.5	17	45.00	X

\$1,194.60

Labour Charges

TO REMOVE AND REFIX REAR REVERSE SENSOR	120.00	50
TO RESPRAY UNDERCOATING	220.00	50
TO REMOVE AND REFIX INTERIOR TRIMS TO ASSIST REPAIR	150.00	80
TO CHECK ELECTRICAL WIRING	80.00	20
TO RESPRAY PAINTING AND ETC	1100.00	800
PANEL BEATING, CUT, WELD PANEL, REMOVE AND REPLACING ABOVE PARTS	1100.00	800

\$2,770.00

501632
20
4013

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$12,768.76

11092.76

I, the undersigned hereby notify you that I am of the following:

- I am not under any suspension
- I am not under any license restriction
- I am not under any court order
- I am not under any "noisy nuisance" basis
- I am not under any other order
- I am not under any other order

Approved by Rep/itor:
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19012456/UQF3N2

Date: 25/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994157
 Claimant Vehicle No : SLZ4272B Insured Vehicle No : SKV8480Z
 Date of Loss: 12/07/2019 Nature of Claim: TP Claim No: 8169375789SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLZ4272B Engine No: P520457346
 Make & Model: MAZDA 3, 1.5 (A) Chassis No: JM6BN22A8H0165645
 Reg. Date: 30/04/2018 (Man. Year: 2017) Odometer: 33280 km
 Colour: Blue
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Toyo 8 mm Rear Left Side: Toyo 8 mm
 Front Right Side: Toyo 8 mm Rear Right Side: Toyo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,282.76	3,136.32	5,146.44	62.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,770.00	1,880.00	890.00	32.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,052.76	5,016.32	6,036.44	54.61
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	11,052.76	4,000.00	7,052.76	63.81

INSPECTION

Date of Assignment: 15/07/2019
 Date Inspected: 16/07/2019 Inspected At: Euro Success Services Pte Ltd (HQ)
 1 KAKI BUKIT AVENUE 6 #02-03
 AUTOBAY
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,160.00 FL	*1,075.00 FL
2	2		*REAR BUMPER L/R TOW HOOK COVERS	Not Necessary	85.00 FL	*- FL
3	2		*REAR L/R BUMPER REFLECTOR	Not Necessary	179.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Dented	541.70 FL	*541.70 FL
5	2		*REAR BUMPER L/R SIDE RETAINERS	Not Necessary	85.20 FL	*- FL
6	2		*REAR BUMPER TOP CLIPS	Necessary	25.20 FL	*25.20 FL
7	2		*REAR BUMPER TOP CLIPS HOLDERS	Necessary	28.40 FL	*28.40 FL
8	1		*REAR END PANEL	Dented / Bent	447.60 FL	*447.60 FL
9	1		*REAR END PANEL INNER TRIM	Twisted	241.20 FL	*241.20 FL
10	1		*REAR L/R FLOOR SPONGE TRAYS	N/s Torn	220.40 FL	*110.20 FL
11	2		*REAR L/R FENDER INNER SHIELD	Not Necessary	137.20 FL	*- FL
12	1		*REAR L/R TAILLAMPS	N/s Cracked	2,157.20 FL	*849.50 FL
13	2		*REAR L/R TAILLAMPS PANELS	Repair	311.20 FL	*- FL
14	1		*REAR SMART KEYLESS ANTENNA	Not Necessary	241.20 FL	*- FL
15	1		*REAR BOOTLID	Repair	1,078.60 FL	*- FL
16	1		*REAR BOOTLID LOGO	Necessary	65.80 FL	*65.80 FL
17	1		*REAR BOOT EMBLEM MAZDA	Necessary	58.20 FL	*58.20 FL
18	1		*REAR BOOT EMBLEM 3	Necessary	34.40 FL	*34.40 FL
19	1		*REAR BOOT EMBLEM SKYACTIV	Necessary	68.60 FL	*68.60 FL
20	2		*REAR BOOT LID LAMP L/R	Not Necessary	682.40 FL	*- FL
21	2		*REAR L/R BOOT LID LICENCE LAMP	Not Necessary	97.20 FL	*- FL
22	1		*REAR BOOT LID INNER LOCK	Not Necessary	250.30 FL	*- FL
23	1		*REAR BOOT LID LOCK STICKER	Not Necessary	65.50 FL	*- FL
24	1		*REAR BOOT LID INNER STICKER	Not Necessary	244.10 FL	*- FL
25	2		*REAR BOOT LID L/R HINGES	Not Necessary	230.00 FL	*- FL
26	1		*REAR FLOOR PANEL TOP BOARD	Torn	124.60 FL	*124.60 FL
27	1		*REAR REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
28	1		*REAR BUMPER PDC SENSOR	Shorted	320.00 FS	*200.00 FS
			(SET)			
29	1		*REAR NUMBER PLATE WITH CASING	Not Necessary	120.00 FS	*- FS
			(SET)			
30	4		*REAR TAILLAMP SIDE CLIPS	Not Necessary	42.40 FS	*- FS
31	2		*REAR EXHAUST MOUNTINGS	Not Necessary	85.20 FS	*- FS
32	10		*REAR FENDER INNER TRIM CLIPS	Not Necessary	55.00 FS	*- FS
33	6		*REAR BUMPER CLIPS	Repeated	27.00 FS	*- FS
34	10		*REAR BOOT INNER TRIM CLIPS	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,054.80	3,870.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,772.04	734.08
Total Parts (\$\$)	8,282.76	3,136.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX REAR REVERSE SENSOR.	New	120.00	50.00
2	TO RESPRAY UNDERCOATING.	New	220.00	50.00
3	TO REMOVE AND REFIX INTERIOR TRIMS TO ASSIST REPAIR.	New	150.00	80.00
4	TO CHECK ELECTRICAL WIRING.	New	80.00	20.00
5	TO RESPRAY PAINTING AND ETC.	New	1,100.00	880.00
6	PANEL BEATING, CUT, WELD PANEL, REMOVE AND REPLACING ABOVE PARTS.	New	1,100.00	800.00
Gross Labour Cost (\$\$)			2,770.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >