



ESTIMATE TO REPAIR

VEHICLE NO. : SJV 4248 S
 MAKE : HONDA
 MODEL : FIT 1.3G A
 YEAR : 2010
 CHASSIS NO : GE61226885

SURVEYOR NAME :
DATE OF SURVEY :
TIME OF SURVEY :

DATE : 15-Jul-19
 DATE OF ACCIDENT : 12-Jul-19
 THIRD PARTY REF : FBG 3816 H / AXA

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 497.50
2 pcs	Rear Bumper Retainer		\$ 16.50		\$ 33.00
1 pc	Rear End Panel				\$ 276.50
1 pc	Tailgate				\$ 771.50
1 pc	Tailgate FIT Emblem				\$ 35.20
2 pcs	Rear Windscreen Moulding		\$ 36.50		\$ 73.00
					\$ 1,686.70
	Less 20%				\$ 337.34
					\$ 1,349.36
1 pc	Rear Number Plate	S.Nett			\$ 40.00
1set	Rear Bumper Sensor	S.Nett			\$ 200.00
1 tube	Rear Winscreen Sealant	S.Nett			\$ 40.00
	To putty and spray painting				\$ 650.00
	To remove and refix rear windscreen glass				\$ 120.00
	To transfer tailgate fittings				\$ 80.00
	To anti-rust				\$ 50.00
	To send vehicle for rear number plate seal				\$ 60.00
	Labour Charges				\$ 600.00
TG/RA-	Total				\$ 3,189.36

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg

Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd