



# HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332  
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

## Estimate Repair List

25 July 2019

QUOT201907-000035  
HHTPCLAIMS19-123

INDIA INTERNATIONAL INSURANCE PTE LTD  
64 CECIL STREET, #04-00 / #05-00  
IOB BUILDING  
SINGAPORE 049711  
Attn: Motor Claims Department

### ACCIDENT INVOLVING SLX3925T & SH9484K ON 10/07/2019 ALONG RANGE ROAD BESIDE SCAPE TRAFFIC JUNCTION AT ABOUT 1015 HOURS

Insured : HUA HONG PTE LTD  
Vehicle Registration No. : SLX3925T  
Vehicle Make : HONDA  
Vehicle Model : SHUTTLE HYBRID 1.5 AUTO  
Vehicle Chassis No. : GP71109398  
Policy No. : 5087272209-02  
Date of Accident : 10/07/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Bumper / CRV		\$ 1,050.20
2	10	Front Bumper Clip / APC	\$ 3.90	\$ 39.00
3	2	Front Bumper Retainer (LH/RH) RH / DR	\$ 15.60	\$ 31.20
4	1	Front Griller Chrome (Lower) X		\$ 220.70
5	1	Front Reinforcement ?		\$ 297.00
				\$ 1,638.10
				Less 20% \$ 327.62
				\$ 1,310.48
6	1	Front No. plate	NETT	\$ 35.00 X
To dismantle & change Front bumper, Front Reinforcement, Knocking & pull straight Front chassis Frame and all area affected by accident				\$ 600.00 200
To perform wire checking				\$ 20.00 /
To spray Front bumper, Front Reinforcement, Front Reinforcement and Front chassis frame				\$ 600.00 200
				\$ 2,565.48
				7% GST \$ 179.58
				<b>Total \$ 2,745.06</b>

Store (LKK) 30/7/19, 11.00 am  
3 days  
L/S  
Reg AF Spg

myg



Authorised by Claims Dept

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: