CITY CAB PTE LTD REPAIR ESTIMATE*

KE	:			
DEL	: MERCEDES BENZ VIANO (REAR)			
Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper /			\$ 1,372.00
	Tail Gate Assy /			\$ 3,951.98
	Tail Gate Weathership X			\$ 166.63
	Tail Gate Mercedes Star Logo			\$ 45.46
	Tail Gate "2.2" Logo			\$ 78.00
	Tail Gate "CDI " Logo			\$ 78.00
	Tail Gate Via No Logo			\$ 78.00
	Tail Lamp Assy Lower, RH 7 old Parage			\$ 622.44
	SUB TOTAL	. "		\$ 6,392.51
	LESS 20%			\$ 1,278.50
	DISCOUNTED TOTAL			\$ 5,114.01
	DISCOUNTED TOTAL	- 1		5 5,114.01
	Reverse Sensor			\$ 288.00
	Tail Gate "MAXICAB" Logo			\$ 30.00
	F 7 5 5 125-5-516			
				\$ 318.00
	Labour Charge			40
	Panel Beating Spray Painting Charge			\$ 850.00
	Spray Painting Charge		,	\$ 600.00
	Wiring Charge // 12/7/	9 143	sh.	\$ 50.00
	Tuff Kote	9 1430		\$ 50.00
	Remove/Refix Reverse Sensor	///		\$ 120.00
	Remove/Refix Tailgate Glass	45	nouty,	\$ 150.00
	TOTAL LABOUR	Alle	Rosir pla	\$ 1,820.00
	1 22	50,000	a ung resurvey	
149	ESTIMATE TOTAL	5 371 31 1 1 1 1 2	ajudice" basis	\$ 7,252.01
ary N9	- Third pa	y survey is on a	streetsure and and	
	• No illega	entary itemits in the time to final approve	tom insu- to company	\
	• Suppler is subje	to final a provi		
	- January	adged by Repair	1	
	Signatu	e:	-	+
	This is an initial estimate based on a visual inspection of the al		701 6 1 :	***