

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 949C

MAKE :

MODEL : MERCEDES BENZ VIANO (REAR)

DATE 12/7/2019 10:01

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 1,372.00
	Tail Gate Assy ✓			\$ 3,951.98
	Tail Gate Weathership X			\$ 166.63
	Tail Gate Mercedes Star Logo ✓			\$ 45.46
	Tail Gate "2.2" Logo ✓			\$ 78.00
	Tail Gate "CDI" Logo ✓			\$ 78.00
	Tail Gate Via No Logo ✓			\$ 78.00
	Tail Lamp Assy Lower, RH x <i>old Damage</i>			\$ 622.44
	SUB TOTAL			\$ 6,392.51
	LESS 20%			\$ 1,278.50
	DISCOUNTED TOTAL			\$ 5,114.01
	Reverse Sensor ✓			\$ 288.00
	Tail Gate "MAXICAB" Logo ✓			\$ 30.00
				\$ 318.00
	Labour Charge			\$ 850.00 <i>400 20</i>
	Panel Beating			\$ 600.00 <i>400 20</i>
	Spray Painting Charge			\$ 50.00 <i>x</i>
	Wiring Charge			\$ 50.00 <i>20 X</i>
	Tuff Kote			\$ 120.00 <i>20 X</i>
	Remove/Refix Reverse Sensor			\$ 150.00 <i>100 X</i>
	Remove/Refix Tailgate Glass			
	TOTAL LABOUR			\$ 1,820.00
	ESTIMATE TOTAL			\$ 7,252.01
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Larry Ng

Kalvin Klay
12/7/19 1430h.
3 Pys
45
Atk Repair p LH

• Parts
 • Time
 • No
 • Supplemental
 is subject to final
 Acknowledged by Repair
 Signature