

AXA

DATE 12/7/2019 10:01

MODEL : MERCEDES BENZ VIANO (REAR)

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper / Returned			\$ 1,372.00
	Tail Gate Assy / Buckle nn			\$ 3,951.98
	Tail Gate Weathership X nn			\$ 166.63
	Tail Gate Mercedes Star Logo - X nn			\$ 45.46
	Tail Gate "2.2" Logo X nn			\$ 78.00
	Tail Gate "CDI" Logo X nn			\$ 78.00
	Tail Gate Via No Logo X nn			\$ 78.00
	Tail Lamp Assy Lower, RH X nn			\$ 622.44
	SUB TOTAL			\$ 6,392.51
	LESS 20%			\$ 1,278.50
	DISCOUNTED TOTAL			\$ 5,114.01
	Reverse Sensor X nn			\$ 288.00
	Tail Gate "MAXICAB" Logo X nn			\$ 30.00
				\$ 318.00
	Labour Charge			
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Remove/Refix Tailgate Glass			\$ 150.00
	TOTAL LABOUR			\$ 1,820.00
	ESTIMATE TOTAL			\$ 7,252.01

Kalvin Chan

12/7/19 1430h.

I [Signature] 45

Repair p LH

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.