



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2005995
INV Date 02/09/2020
Reference CC6/CTI19012476/Aba3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SLD 1209X
Insured Veh. SJS 8069G
Claim No. SNM19D203244
Policy No. DMPCSN3046851802
Accident Date 10/07/2019
Inspection Date 17/07/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI19012476/Aba3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 02-09-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJS 8069G	Veh. Inspected	SLD 1209X	
Policy No.	DMPCSN3046851802	Coverage (\$)	0.00	
Claim No.	SNM19D203244	Excess (\$)	0.00	
Assign From		Assign Date	17/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO FORTE K3	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KNAFX411MG5596058	Colour	GREY	
Odometer	65474	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MICHELIN	6 mm	
L/H Front Tyre	205/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/07/2019	Inspection Date	17/07/2019	
Survey held at	96 MOTORSPORTS PTE LTD 62/64 KAKI BUKIT AVENUE 6 SINGAPORE 417893 ARK @ KB			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 1209X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT LH DOOR	DENTED	1,325.00	1,325.00
1	FRONT LH DOOR MIRROR	TO REPAIR SEE LABOUR	668.00	-
1	FRONT LH DOOR MIRROR SIGNAL LAMP	NOT NECESSARY	105.00	-
1	ROCKER PANEL LH	TO REPAIR SEE LABOUR	695.00	-
1	REAR LH DOOR	TO REPAIR SEE LABOUR	1,395.00	-
	LESS 10% DISCOUNT		-	-132.50
			4,188.00	1,192.50
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT LH DOOR BLACK TAPE (SN)	NECESSARY	60.00	60.00
1	REAR LH DOOR BLACK TAPE (SN)	NOT NECESSARY	60.00	-
			120.00	60.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT LH DOOR MIRROR, ROCKER PANEL LH AND REAR LH DOOR.		800.00	250.00
	SPRAY PAINTING.		800.00	550.00
	WIRING.		50.00	30.00
	TO TRANSFER DOOR FITTINGS.	NOT NECESSARY	300.00	-
			1,950.00	830.00
	GRAND TOTAL		6,258.00	2,082.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00

Report Ref No. CC6/CT119012476/Aba3n2

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLD 1209X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

