

ASL

Survey ~~Report~~
31.07 @ 10am
Waiting



BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197101518W GST Reg. No. M2 0020081 X
Toll-Free Number (1800-2255269)

101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Yompong Aiang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

15 JUL 2019

ESTIMATE

Estimate No. : b1 51970
Date Estimated : 15/07/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Goh Teu Ai
16 Dunearn Road
#15-02

Singapore 309420

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBK8300A	ED05618	27/12/2018	216i GT	0

DESCRIPTION

To repair front bumper and replace finisher left.

Painting front bumper

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

Sundries.

VALUE

- 850 1275.00

- 934 1038.00

- 150 177.00

- 150 177.00

- 40.00

Total Labour 1: 2,707.00

DESCRIPTION

LH FINISHER

? x 50

QTY	PRIC	VALUE
1	49.70	49.70

Total Parts : 49.70

31/07/19 @ 10am
Rahul
9000066

Labour 1	:	2,707.00
Parts	:	49.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	192.97
Grand Total	:	2,949.67

3 days

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 51970**
Date Estimated : **15/07/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -

Goh Teu Ai
16 Dunearn Road
#15-02

Singapore 309420

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBK8300A	WBA6V12080ED05618	27/12/2018	216i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To make good the front bumper including removing attachments to facilitate repairs.	850.00		850.00 ✓
To respray front bumper.	934.00		934.00 ✓
To check electrical wiring systems at the front section for proper function.	150.00		150.00 ✓
To remove old PDC assembly and reconnect to new bumper including conduct checks for proper function.	150.00		150.00 ✓
Sundries.	40.00		40.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

Total Labour :	2,124.00
Total Parts :	0.00
Total Labour & Parts :	2,124.00
Deduction for Excess :	0.00
Total Repair Costs less Excess:	2,124.00
GST @7%:	148.68
Grand Total :	2,272.68