

INS. CASE OWNER:

KARIM

CC 31 AIG 190 12502, Rha3

LKK:
IDAC

Surveyor:

KARIM

DOI:

ASSIGNMENT

16/07/19

Date / Time:

16/7/19

Registered in Merimen:

16/7/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLT 3757 H

Claim No.:

25619233939G

Name of Insured:

Shazib Pervaiz

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

14/07/2019

Place of Accident:

Is driver the owner?

(YES) (NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Insured Liability:

%

Final ? Yes / No

SLD 5822 Z



INSRS:

WSP:

Tel:

Liability:

RMKS:

pmv



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

16/07/19

FILE REVIEWED. OLD REPORTED SHE WAS MAKING A RIGHT TURN @ JUNCTION WHEN HIT BY A VEHICLE. THE IMPACT CAUSED OI VEHICLE TO HIT ANOTHER VEHICLE (TP) STATIONARY AT THE TRAFFIC JUNCTION. SEND LETTER TO OI TO NOTIFY TP CLAIM IN NCD ISSUING.

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

18/07/19 - VIC

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

24/07/19

EMAIL TO TP TO REQUEST EVIDENCE.

EMAIL LIABILITY CLERK

MINUTEBOOK.

ORIGINAL TP LOD IN

TYPE REPORT FOR WARRANT APPROVAL

REPORT DONE

11/09/19

10/10/19

SEND WARRANT TO AIG BY EMAIL/METIMEN

AIG APPROVED WARRANT LOD @ 11/10/19.

SEND 1st OFFER TO TP.

TP ACCEPTED OFFER.

07/11/19

ALL DOCS IN ORDER TO CLOSE.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: P/P

SS 20,021.95 (7 days) Reduction: 13 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

CAROLINE

Email ☒ Call ☐

Final Liability:

% 100 (Assessed) BOLA S/N No.: 35(2)(i)

If NO or B 28, Ass. Lia:

Repair Cost: (w/acc)

SS 21,423.49

COPY TURNING @ JUNCTION

Loss of Rental (LOR):

SS - (days)

B VEH. INVOLVED

Loss of Use (LOU):

SS 1,100.00 x 10 days

Loss of Income (LOI):

SS - (\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS -

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost

SS -

3) Survey fee:

\$320.00

Total:

SS 21,525.49

Global Sum SS: -

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS 21,525.49

Name 1:

PERFORMANCE MOTORS LIMITED

Payee 2 (Strike if N.A.)

SS -

Name 2:

Payee 3 (Strike if N.A.)

SS -

Name 3:

REG. BY: RASUL

REL

12502 / P116

0362E

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / P / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SLO 58222
at Workshop n/s PERFORMANCE
of _____
Insured: Alh
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 7 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

N/S	O/S

Veh No: SLO 58222 Yr Regn: 2016 / Jun
Type: C / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: B.M.W 330I 402 c.c. 1998
Colour: Blue A/C: Insured / Std / NI / NA
Sp.Rending: 43585 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WBA8A 76020N4 06331
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Order / Jammed / Leaked / Burnt or
Brake: Order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/45R18
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or CONTINENTAL

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 14/07/19 D.O.I. 16/07/19
Survey held at PERFORMANCE
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>P/B \$20,021.95</u> <u>CHEV: \$3,023.20 / 15%.</u>

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

1) Date/Time, File Return to?

2)

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:	
Transportation:	
3 + REG. ST	
Photos	
Others	
TOTAL	

Report Format :
Lump Sum / L.B.I. (\$))

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197411119W GST Reg. No. M2-0020081-X
Toll-Free Number (1800-3255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kembangan Road
East Coast Centre
Singapore 438188
Fax: 43449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

16 JUL 2019

ESTIMATE

Estimate No. : b1 51959
Date Estimated : 15/07/2019
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Shang Jing
7 Lorong 42 Geylang
#05-02

Singapore 398028

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD5822Z	NU06331	23/06/2016	330iA/4Dr	0

DESCRIPTION

VALUE

To tow accident vehicle to PML workshop.

195.00

To replace front bumper & attachments, front right fender, bonnet, right headlight inner support bracket, front center air duct including to knock out dented area caused by the accident

3400 4,250.00

To respray front bumper, front right fender and bonnet

2899 3,221.00

To carry out body cavity preservation (2X)

200 236.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x)

451 531.00

To replace right headlight.

408 481.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 171.00

Sundries.

? 150.00

40000

Total Labour 1: 9,241.00

DESCRIPTION

QTY PRIC

VALUE

BONNET	1	1,274.80	1,274.80
FRT RH SIDE PANEL	1	702.65	702.65
FRT RH 2 SIDE PANEL BRACKET	1	34.25	34.25
EXPANDING RIVET	10	0.50	5.00
FRT RH TOP SUPPORT SIDE PANEL	1	19.20	19.20
FRT BUMPER TOP MOUNT	1	378.10	378.10
FRT LH DEFORMATION ELEMENT	1	101.80	101.80
FRT RH DEFORMATION ELEMENT	1	101.80	101.80
# FRT LH LOWER DEFORMATION ELE	1	86.40	86.40
FRT RH LOWER DEFORMATION ELEMENT	1	86.40	86.40
FRT RH BOTTOM MOUNTING SIDE PANEL	1	19.20	19.20

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401553M GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255369)

337, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64767770

280, Kampong Arang Road
East Coast Centre
Singapore 438100
Fax: 63449773

319, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796001
64796004



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Auto Consultants hence notify
(After Survey)
Receiver of the following:
- Survey before/after spray painting
- Damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from insurance Company

Page No. : 2 of 5

Acknowledged by Repairer

Signature:

Estimate No. : b1 51959
Date Estimated : 15/07/2019
Prepared By : Han Kwan Yong

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD5822Z	NU06331	23/06/2016	330iA/4Dr	0

DESCRIPTION

QTY	PRIC	VALUE
1	120.60	120.60
1	41.85	41.85
1	56.00	56.00
1	43.25	43.25
1	53.20	53.20
1	91.75	91.75
1	54.50	54.50
1	84.10	84.10
1	1,027.25	1,027.25
1	128.60	128.60
1	46.30	46.30
2	0.75	1.50
4	0.45	1.80
1	87.95	87.95
1	25.75	25.75
1	131.50	131.50
1	133.80	133.80
1	10.10	10.10
10	1.30	13.00
1	116.55	116.55
1	55.95	55.95
1	61.50	61.50
1	55.95	55.95
1	55.95	55.95
1	6.30	6.30
1	38.85	38.85
1	71.25	71.25
1	789.75	789.75
1	3,068.40	3,068.40
1	441.95	441.95
2	5.05	10.10
12	368.80	4,425.60
1	53.05	53.05

Total Parts : 10,525.55

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Reign No. _____ Claim No. _____

Date/Time 16/07/19 0435 Excess \$0

Surveyor's Name RASUL Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 6-7 days

Labour 1	:	9,241.00
Parts	:	10,525.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,383.66
Grand Total	:	21,150.21

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

23,045.25

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401555W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

260, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 51959**
Date Estimated : **15/07/2019**
Prepared By : **Han Kwan Yong**

Page No. : **3 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD5822Z	NU06331	23/06/2016	330iA/4Dr	0

Terms & Conditions of Service

- All requests for servicing, repairs, replacements or installations to the Vehicle (collectively, "Repairs") are subject to acceptance by Performance Motors Limited ("PML") and PML shall have the absolute discretion to reject or deny any request for the Repairs.
- The list of the Repairs or quantum of charges for the Repairs printed overleaf are estimates only and PML shall be entitled to carry out additional repairs or replacements ("Additional Works") if, in its absolute discretion, Additional Works are necessary provided that, where the cost of additional Works exceed S\$250, PML shall obtain the customer's prior consent (whether given orally or otherwise) before carrying out the additional Works.
- Subject to clause 2 above and save in the case of manifest error or gross negligence, in the event where PML's estimation of the Repairs recommended for the Vehicle differs from the Customer's own estimation of repairs needed, PML's estimate shall prevail.
- The Vehicle accepted by PML for the Repairs shall remain, at all times, at the Customer's own risk while the Vehicle undergoes the Repairs at PML's premises. PML's visual inspection and record of the physical condition of the Vehicle made prior to the commencement of the Repairs shall be binding and conclusive as between PML and the Customer. The Customer shall ensure that all valuables are removed from the Vehicle prior to delivering it to PML for the Repairs. PML shall not be liable, in any way, for theft, fire, accident, loss of or damage to the Vehicle, its contents or accessories whatsoever.
- The Vehicle may be driven on the road if and when PML, in its absolute discretion, decides that it is necessary for the purposes of carrying out tests in connection with the Repairs. Should any damage occur to the Vehicle in such an instance, PML's liability will be limited to the rectification of damage, free of charge.
- PML's entire liability whether, in respect of faulty workmanship or otherwise, shall be limited to the rectification of any faulty workmanship or other faults, free of charge, such faults being reasonably determined by PML to have been caused by PML in the course of the Repairs. The Customer shall, nevertheless, be responsible for all costs for the disassembly, diagnosis, inspection of the Vehicle etc., at PML's current labour charge-out rate, necessarily incurred for the purpose of determining the cause of the fault(s) if it is found that the fault(s) is or are not caused by PML.
- Except as provided in clause 6 above, PML makes no warranty (whether expressed or implied) in respect of the Repairs and shall not, to the fullest extent permitted by law, be liable under any circumstances for special, consequential or incidental damages including but not limited to the loss of use of or depreciation in value of the Vehicle.
- Unless otherwise agreed by PML in writing, the Customer shall pay the costs of the Repairs owing to PML, in cash, upon the completion of the Repairs and before the Customer collects the Vehicle. In the event any credit is granted by PML at its absolute discretion, and the Customer fails to make payment of the costs of the Repairs (or any part thereof) by the agreed payment date, interest shall be imposed on the sum remaining unpaid at the rate of 1% per month (or part thereof) from the due date of payment until the date all payments are actually received by PML. PML reserves the right, at any time, to suspend or withdraw any credit facility granted to the Customer without assigning any reason whatsoever.
- The Customer shall collect the Vehicle within 48 hours from the date PML notifies the Customer, (whether orally or otherwise), that the Vehicle is ready for collection. In the event that the Customer fails to collect the Vehicle within 48 hours, the Customer shall, in addition to the costs of the Repairs owing to PML, pay all storage charges, at a rate to be determined by PML provided always that the Customer shall not, under any circumstances, hold PML liable for any loss of or damage to the Vehicle, its contents or accessories or for any deterioration in the quality of or damage to the Vehicle arising from such storage. In the event that the Customer fails to collect the Vehicle for more than 14 days, PML shall be entitled, at its absolute discretion, to dispose of the Vehicle & deduct, from the proceeds of disposal, PML's costs in connection with the disposal as well as all other monies owing to PML.
- If PML does not receive any notification of faulty workmanship from the Customer within 7 days from the date the Customer collects the Vehicle from PML, the Customer shall be deemed to have accepted the Repairs as satisfactory.
- If the Vehicle is sent to PML for the Repairs by any person other than the Customer, PML shall be entitled, without need to make any inquiry, to treat such third party as acting for and on the Customer's behalf. PML shall be entitled to rely on this ostensible authority to carry out the repairs in compliance with such third party's instructions and the Customer shall not hold PML liable for any loss or damage suffered by the Customer as a result and shall pay for the costs of the Repairs owing to PML and further indemnify PML against all claims, losses, expenses, damages suffered or incurred by PML arising from PML's reliance on such authority and/or compliance with such instructions.
- PML may, in its absolute discretion and upon the Customer's request, provide a driver to deliver the Vehicle from the Customer to PML's premises or vice versa provided always that the driver shall, during the time of such conveyance of the Vehicle, be deemed to be the servant of the Customer and not that of PML's and the Customer shall not hold PML liable for any accident, loss of or damage to the Vehicle or its contents or accessories while the same is under the custody of the driver.
- These Terms & Conditions of Service including all annexes and attachments hereto contains the entire agreement between PML and the Customer with respect to the Services described in the Repair Order and supersedes all previous agreements and understandings between PML and the Customer relating to the subject matter herein. No amendments or changes to these Terms & Conditions of Service shall be effective unless made in writing and signed by authorized representatives of both PML and the Customer.
- If any term or provision of these Terms & Conditions of Service shall be held to be invalid, illegal or unenforceable, the remaining terms and provisions of these Terms & Conditions of Service not affected by such invalidity, illegality or unenforceability shall remain in force and effect.

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. NO. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438190
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 51959**
Date Estimated : **15/07/2019**
Prepared By : **Han Kwan Yong**

Page No. : **4 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD5822Z	NU06331	23/06/2016	330iA/4Dr	0

15. A person not party to these Terms & Conditions of Service shall have no right under any legislation for the enforcement of contractual terms by a third party (whether in force now or to be enacted in the future and as the same may be modified, adapted or supplemented from time to time) to enforce any term in these Terms & Conditions of Service.
16. The laws of the Republic of Singapore shall govern the validity and interpretation of these Terms & Conditions of Service and the Parties submit to the exclusive jurisdiction of the Courts of the Republic of Singapore.
17. The Sime Darby Motors Group companies in Singapore are committed to ensuring that your personal data is protected. The purpose of this document is to explain how we collect information about you, the procedures that we have in place to safeguard your privacy and how you can instruct us if you prefer to limit the use of that information.
- 17.1 The Vendor shall collect and use the Customer's personal data for any of the following purposes, including but not limited to:
- (a) the registration of the Vehicle with the relevant transportation authorities, including but not limited to Land Transport Authority;
 - (b) sharing of the Customer's personal data with the Vendor's principal, its related corporations and contractors, whether within Singapore or overseas, and/or insurance companies, so as to provide the necessary warranties and/or extended warranties for the Vehicle to the Customer;
 - (c) sharing of the Customer's personal data with financial institutions and motor vehicle insurers, on the Customer's behalf, in order for the Customer to obtain financing for the purchase of the Vehicle and the motor insurance on the Vehicle and when necessary, to obtain the loan amounts outstanding from financial institutions, on the Customer's behalf so as to assist the Customer in effecting the Vehicle loan redemptions;
 - (d) servicing of Vehicle and to update the Vendor's after-sales service records. The relevant personal data shall be used by the Vendor, its appointed after-sales service dealers, agents and sub-contractors and/or the Vendor's principal and/or its related corporations whether within or outside Singapore to provide the relevant after-sales service and/or to repair the Vehicle and to communicate with the Customer on any matter relating to the provision of the services in general including to notify the Customer by any means, including by short message services ("SMS") of the next/ subsequent date/mileage for routine service for the Vehicle;
 - (e) administrative, research and analysis purposes to enable it to monitor and improve the services it provides; and
 - (f) organizing events for the Customer, to inform the Customer of such events by any means (including through SMS, multi-media services ("MMS"), phone call, fax, magazines, or brochures) any new products, promotions or services provided by the Vendor in Singapore.
- 17.2 The Vendor shall also disclose the Customer's personal data:
- (a) to its service providers, for example, providers of web hosting or maintenance services, for the purpose of supplying itself with the inter connected servers and/or web site links with the relevant authorities;
 - (b) to its customer service agencies whether within or outside Singapore for administrative, research and analysis purposes to enable it to monitor and improve the services it provides;
 - (c) to the Vendor's service providers and/or the Vendor's principal, its related corporations and contractors whether within or outside Singapore for the purpose of organizing events for the Customer, to inform the Customer of and send to the Customer by any means (including through SMS, MMS, phone call, fax, magazine or brochures) any new products or promotions or services that are provided by the Vendor and/or the Vendor's principal whether within or outside Singapore;
 - (d) to the Vendor's business partners for the purpose of carrying out product promotions;
 - (e) to the Vendor's stakeholders and the Vendor's principal and its/their related corporations and contractors for the purpose of carrying out audits;
 - (f) to the Vendor's principal and/or the Vendor's stakeholders and their respective related corporations and contractors whether within or outside Singapore for the purposes of carrying out audits; and
 - (g) to the Vendor's principal and its related corporations whether located within or outside Singapore for the purpose of responding to any of the Customer's enquiries.
- 17.3 The Vendor shall retain the Customer's personal data either for the period of the business relationship or, for the requisite retention periods as stipulated in any contractual arrangements or under any applicable law, whichever is later.
- 17.4 If the Vendor amends any provision in this clause 17, it will notify the Customer via e-mail and may place notices on the Vendor's web site. The Vendor's email to the Customer shall require the Customer's consent to its change of use of the Customer's personal data. Continued use of the Vendor's services shall signify the Customer's agreement to any such changes.
- 17.5 The personal data the Customer provides may be transferred to the Vendor's principal within or outside Singapore for surveys and research purposes conducted with the objective of enhancing the Customer's satisfaction.
- 17.6 The Customer shall have a right to request a copy of the personal data the Vendor holds about the Customer and information about the ways in which the Customer's personal data has been or may have been used or disclosed within a year before the date the Customer's request. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing and indicate whether he would like to have a copy of his personal data or he wishes to have information about the ways in which his personal data is used or disclosed during the past year or both;
 - (b) include proof of his identity and address (e.g. a copy of the Customer's driving licence and a recent credit card bill); and
 - (c) specify the personal data he wants access to, including any account or reference numbers where applicable

The Vendor shall reply to the Customer as soon as reasonably possible upon its receipt of the Customer's request.



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64787770

180, Kampong Arang Road
East Coast Centre
Singapore 438188
Fax: 63449773

311, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64786601 (AfterSales)
64786634 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 51959**
Date Estimated : **15/07/2019**
Prepared By : **Han Kwan Yong**

Page No. : **5 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD5822Z	NU06331	23/06/2016	330iA/4Dr	0

- 17.7 The Customer shall pay an amount to access his personal data in the manner stated in Clause 17.6(a) above.
- 17.8 The Customer shall have the right to correct any inaccuracies in his personal data free of charge. If the Customer wishes to exercise this right, the Customer shall:
- (a) put his request in writing;
 - (b) provide the Vendor with enough information to identify himself (e.g. the Customer's account number, username, registration details); and
 - (c) specify the information that is incorrect and what it should be replaced with.
- The Vendor shall reply to the Customer as soon as practicable upon its receipt of the Customer's request.
- 17.9 The Customer's access or correction request will not be granted as of right; the Vendor's ability to accede to the Customer's access or correction request is subjected to the prohibitions and exceptions set out or which may be set out in the Singapore Personal Data Protection Act ("PDPA") and its accompanying regulations.
- 17.10 The Customer shall have the right to ask the Vendor to stop collecting, using or disclosing his personal data for any of the abovementioned purposes set out in Clauses 17.1 and 17.2. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing by way of an email sent to the Vendor;
 - (b) provide the Vendor with his name, NRIC number, mobile number, email and Vehicle registration number to identify the Customer; and
 - (c) if the Customer's objection is not to direct marketing in general, but to direct marketing by a particular channel (e.g. voice call, SMS, MMS, fax, mailers or email), the Customer has to specify the channel he is withdrawing his consent to.
- 17.11 In the event that the Customer withdraws consent to the collection, use or disclosure of his personal data such that it materially affects this Agreement and it renders the Vendor unable to, or such that it becomes difficult for the Vendor to perform or properly perform or discharge its obligations under this Agreement, at law, under the warranty undertakings, or its role as a responsible dealer of BMW vehicles, the Vendor may at its discretion, be entitled to terminate this Agreement with the Customer.
- 17.12 The obtaining the Customer's consent for the collection, use or disclosure of his personal data under this clause 17 is subject to the exceptions set out or which may be set out in the PDPA.
- 17.13 The Customer shall address all communications pertaining to this Clause 17 to:

The Data Protection Officer
Performance Motors Limited

Address:
Sime Darby Performance Centre
303 Alexandra Road
Singapore 159941

Email address:
dataprotection@pml.com.sg

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0030081-X



SUPPLEMENTARY

Estimate No. : b1 51959
Date Estimated : 15/07/2019
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Shang Jing
7 Lorong 42 Geylang
#05-02

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 398028

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD5822Z	NU06331	23/06/2016	330iA/4Dr	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To diagnose and replace front RH wire harness include resetting and checking connections for proper function	451.00		451.00 ✓
# To diagnose and replace REM control unit, set LED module, RH LED module direction indicator include programming and conducting checks for proper function	451.00		451.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET * ne /	1.55	2.00		3.10 ✓
# BLIND RIVET * ne /	1.25	1.00		1.25 ✓
# UNFILTERED AIR SNORKEL * ca /	55.20	1.00		55.20 ✓
# INTAKE DUCT * ca /	69.25	1.00		69.25 ✓
# FRT RH REPAIR WIRING SET * ca /	596.85	1.00		596.85 ✓
# FANFARE HORN HIGH TONE ELECTRONIC * ca /	94.70	1.00		94.70 ✓
# CONTROL UNIT REM * ne /	501.00	1.00		501.00 ✓
# SET LED MODULE * ne /	162.05	1.00		162.05 ✓
# CONTROL UNIT FRT LIGHT ELECTRONICS * ne /	893.90	1.00		893.90 ✓

Total Labour :	902.00
Total Parts :	2,377.30
Total Labour & Parts :	3,279.30



FINAL REPORT

Estimate No. : **b1 51959**
Date Estimated : **15/07/2019**
Prepared By : **Han Kwan Yong**

Page No. :

REPAIR FOR -
Shang Jing
7 Lorong 42 Geylang
#05-02

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 398028

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE	
SLD5822Z	NU06331	23/06/2016	330iA/4Dr	0	
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT		
To tow accident vehicle to PML workshop.	195.00		195.00	✓	
To replace front bumper and attachments, front RH fender and attachments, bonnet, front top mount, front RH deformation element, RH fog lamp support, RH support, RH bottom cover, air duct radiator, horn include knocking out dents caused by the accident	3400.00		3,400.00	✓	
To respray front bumper, front RH fender and bonnet	2899.00		2,899.00	✓	
To carry out body cavity preservation (2x) (Per panel)	200.00		200.00	✓	
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00	✓	
To replace RH LED technology headlight include programming and conducting tests for proper function	408.00		408.00	✓	
To check electrical wiring systems at the front section for proper function	150.00		150.00	✓	
# To diagnose and replace front RH wire harness include resetting and checking connections for proper function	451.00		451.00	(S)	
# To diagnose and replace REM control unit, set LED module, RH LED module direction indicator include programming and conducting checks for proper function	451.00		451.00	(S)	
Sundries	150.00		150.00	✓	
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT	
# BLIND RIVET *	1.55	2.00		3.10	
# BLIND RIVET *	1.25	1.00		1.25	
# UNFILTERED AIR SNORKEL *	55.20	1.00		55.20	
# INTAKE DUCT *	69.25	1.00		69.25	

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

BONNET	1,274.80	1.00	1,274.80 ✓
FRT RH SIDE PANEL	702.65	1.00	702.65 ✓
FRT RH 2 SIDE PANEL BRACKET	34.25	1.00	34.25 ✓
EXPANDING RIVET	0.50	10.00	5.00 ✓
FRT BUMPER TOP MOUNT	378.10	1.00	378.10 ✓
FRT RH DEFORMATION ELEMENT	101.80	1.00	101.80 ✓
INSERT AIR INLET MIDDLE	120.60	1.00	120.60 ✓
RH FOG LAMP SUPPORT	41.85	1.00	41.85 ✓
RH FINISHER ROD (SPORT)	56.00	1.00	56.00 ✓
FRT BUMPER TOWING LUG COVER PRIMED	43.25	1.00	43.25 ✓
RH AIR INLET FINISHER (SPORT)	53.20	1.00	53.20 ✓
RH PARTIALLY OPEN GRID (SPORT)	91.75	1.00	91.75 ✓
FRT SHOCK ABSORBER ECE	54.50	1.00	54.50 ✓
SET MOUNTING PDC/PMA SENSOR FRT	84.10	1.00	84.10 ✓
FRT BUMPER PANEL PRIMED (SPORT LINE	1,027.25	1.00	1,027.25 ✓
FRT RH GRILLE (SPORT)	128.60	1.00	128.60 ✓
MODEL LETTERING SIDE (SPORT LINE)	46.30	1.00	46.30 ✓
RIVET	0.45	4.00	1.80 ✓
RH SUPPORT	131.50	1.00	131.50 ✓
RH HEADLIGHT BRACKET	10.10	1.00	10.10 ✓
RH COVER BOTTOM	116.55	1.00	116.55 ✓
AIR DUCT RADIATOR	61.50	1.00	61.50 ✓
RH AIR DUCT BRAKE	55.95	1.00	55.95 ✓
FRONT ENGINE HOOD SEALING	38.85	1.00	38.85 ✓
PLAQUE 82MM	71.25	1.00	71.25 ✓
# FRT RH REPAIR WIRING SET *	596.85	1.00	596.85 (1)
# FANFARE HORN HIGH TONE ELECTRONIC *	94.70	1.00	94.70 (1)
# CONTROL UNIT REM *	501.00	1.00	501.00 (1)
# SET LED MODULE *	162.05	1.00	162.05 (1)
RH LED MODULE DIRECTION INDICATOR	789.75	1.00	789.75 ✓
RH HEADLIGHT LED TECHNOLOGY	3,068.40	1.00	3,068.40 ✓
# CONTROL UNIT FRT LIGHT ELECTRONICS *	893.90	1.00	893.90 (1)
ULTRASONIC SENSOR BLACK	236.85	1.00	236.85 ✓
DECOUPING RING PDC TORQUE CONVERTER	5.05	2.00	10.10 ✓
(DG/SL) ADHESIVE SET K6	53.05	1.00	53.05 ✓

SUPPLEMENTARY ITEMS

Total Labour :	8,755.00
Total Parts :	11,266.95
Total Labour & Parts :	20,021.95
Deduction for Excess :	
Total Repair Costs less Excess:	20,021.95
GST @7%:	1,401.54
Grand Total :	21,423.49

Print Received Message

This mail is associated with :

***SLD5822Z (2561623393SG)**
[SLT3757H]
TP
SHANG JING
Jul 14 2019 6:00PM
[SHAZIB PERVAIZ]
Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 10/10/2019 11:36 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$22525.49) - SLD5822Z - Claim Handler: Ler, Bernard-JQ

Approved:22525.49:pls offer up to \$110/day for LOU. This approval is subject to final repair bill & ATA

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SLO58222	Model:	BMW 330I
Date of Accident:	14.7.19		

Global Sum Settlement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	\$	24,658.42	
Final Repair Cost	\$	21,423.49	
Loss of Use	\$	1,680.00	14 days at \$ 120 per day
Rental (if any)	\$	-	days
LTA / GIA Search Fee	\$	2.00	
Others:	\$	/	
	\$		
Final Settlement Sum	\$	23,105.49	

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	

Payment Instruction: Payee's Breakdown		
1)	Performance Motors Ltd	\$ 21,423.49
2)	Performance Motors Ltd	\$ 2.00
3)	Shang Jing	\$ 1,680.00


 Signed by appointed surveyor

Date 7/8/19

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report/ Bill (if any))



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

18 JULY 2019

**SHAZIB PERVAIZ
27 WEST COAST CRESCENT
#21-24 BLUE HORIZON
SINGAPORE 128048**

Dear Sir/Madam,

**OUR REF : CC3/AIG19012502/ha3
YOUR REF : SLT 3757H
ACCIDENT INVOLVING SLT 3757H / SLD 5822Z / OTHERS ALONG NORTH BOUNA
VISTA ROAD ON 14.07.2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SLD 5822Z against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SLD 5822Z. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2096 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,



Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)


AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Mrs Shang Jing (the third party claimant) of 19 Shelford Rd #03-27, Spore 288408 (address), owner of SLD5822Z (vehicle no.) hereby authorize PERFORMANCE MOTORS LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SLD5822Z that was damaged pursuant to the accident which occurred on 14/07/19 (date) along Kent Ridge Road (location) involving vehicle no/s SLT3757H ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.


I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this _____ (day) of _____ (month) 20____ (year)

x 

Signed by "the third party claimant"
(with chop if applicable)

HAN KWAN YONG
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941


Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$21423.49 (Repair Cost), S\$1,100.00 (Loss of ~~rental~~ use), S\$2.00 (Disbursement), for vehicle no. SLO 58227 that was damaged pursuant to the accident which occurred on 14/7/19 (date) along Kent Ridge Road (location) involving vehicle no/s SLT37571. This is pursuant to the inspection conducted on 16/7/19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Sheng Jing ("the third party claimant") of vehicle no. SLO 58227 make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLO 58227 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 07 (day) of 11 (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449773

119, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/330 (Motorrad)
63190533 (AfterSales)
64796601 (Motorrad)
64796624 (Motorrad)

SERVICE TAX INVOICERepair Order No. : **B1 1379153**Date IN : **16/07/2019**Motor Claim Advisor: **Han Kwan Yong**Page No. : **1 of 3**Invoice Number : **2134142 / WSB**Invoice Date : **07/08/2019**Payment Terms : **30 Days From Invoice**Invoice By : **Toh Jing Xuan****- CUSTOMER INFORMATION -**

Mdm Shang Jing
7 Lorong 42 Geylang
#05-02

Singapore 398028

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.
SLD5822Z

CHASSIS NO.
NU06331

REGN. DATE
23/06/2016

MODEL
330IA/4DR

MILEAGE
43585

- - - - LABOUR 1 - - - -

	NETT
To tow accident vehicle to PML workshop.	195.00
To replace front bumper and attachments, front right fender and attachments, bonnet, front top mount, front right deformation element, right fog lamp support, right support, right bottom cover, air duct radiator, horn including knock out dented area caused by the accident.	3,400.00
To respray front bumper, front right fender and bonnet.	2,899.00
To carry out body cavity preservation. (2x). (Per panel).	200.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications.	451.00
To replace right LED technology headlight including program and conduct tests for proper function.	408.00
To check electrical wiring systems at the front section for proper function.	150.00
To diagnose and replace front right wire harness including reset and checks connections for proper function.	451.00
To diagnose and replace REM control unit, set LED module, right LED module direction indicator including program and conduct checks for proper function.	451.00
Sundries.	150.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 14.07.2019. 3RD PARTY CAR : SLT3757H.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO ON 16.07.2019 AT 2:35PM. AUTHORISED REPAIR BY MS VIC ALPEH FROM LKK AUTO ON 24.07.2019 VIA EMAIL.	
PROPOSE LOSS OF USE = \$120x14. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00
GIA SEARCH FEE = \$2.00.	0.00
VEHICLE WAS ALSO SURVEYED BY OD SURVEYOR MR SAM CHAN FROM AXA INSURANCE ON 16.07.2019 AT 12:35PM.	0.00

Total Labour 1: **8,755.00**

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190886 (AfterSales)
Fax: 63449773115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)**SERVICE TAX INVOICE**Repair Order No. : **B1 1379153**Date IN : **16/07/2019**Motor Claim Advisor: **Han Kwan Yong**Page No. : **2 of 3**Invoice Number : **2134142 / WSB**Invoice Date : **07/08/2019**Payment Terms : **30 Days From Invoice**Invoice By : **Toh Jing Xuan**

----- P A R T S -----	Qty	Retail Price	NETT
FRT RH 2 SIDE PANEL BRACKET	1	34.25	34.25
DECOUPING RING PDC TORQUE CONVERTER	2	5.05	10.10
BONNET	1	1,274.80	1,274.80
FRT RH SIDE PANEL	1	702.65	702.65
EXPANDING RIVET	10	0.50	5.00
FRT BUMPER PANEL PRIMED (SPORT LINE	1	1,027.25	1,027.25
(DG/SL) ADHESIVE SET K6	1	53.05	53.05
SET MOUNTING PDC/PMA SENSOR FRT	1	84.10	84.10
FRT RH GRILLE (SPORT)	1	128.60	128.60
MODEL LETTERING SIDE (SPORT LINE)	1	46.30	46.30
RIVET	4	0.45	1.80
PLAQUE 82MM	1	71.25	71.25
RH HEADLIGHT LED TECHNOLOGY	1	3,068.40	3,068.40
FRONT ENGINE HOOD SEALING	1	38.85	38.85
FRT BUMPER TOWING LUG COVER PRIMED	1	43.25	43.25
RH FINISHER ROD (SPORT)	1	56.00	56.00
RH PARTIALLY OPEN GRID (SPORT)	1	91.75	91.75
FRT BUMPER TOP MOUNT	1	378.10	378.10
FRT RH DEFORMATION ELEMENT	1	101.80	101.80
FRT SHOCK ABSORBER ECE	1	54.50	54.50
AIR DUCT RADIATOR	1	61.50	61.50
RH SUPPORT	1	131.50	131.50
RH HEADLIGHT BRACKET	1	10.10	10.10
BLIND RIVET	2	1.55	3.10
BLIND RIVET	1	1.25	1.25
RH AIR INLET FINISHER (SPORT)	1	53.20	53.20
RH AIR DUCT BRAKE	1	55.95	55.95
INSERT AIR INLET MIDDLE	1	120.60	120.60
FANFARE HORN HIGH TONE ELECTRONIC	1	94.70	94.70
CONTROL UNIT FRT LIGHT ELECTRONICS	1	893.90	893.90
RH LED MODULE DIRECTION INDICATOR	1	789.75	789.75
RH COVER BOTTOM	1	116.55	116.55
RH FOG LAMP SUPPORT	1	41.85	41.85
INTAKE DUCT	1	69.25	69.25
UNFILTERED AIR SNORKEL	1	55.20	55.20
SET LED MODULE	1	162.05	162.05
ULTRASONIC SENSOR BLACK	1	236.85	236.85
FRT RH REPAIR WIRING SET	1	596.85	596.85
CONTROL UNIT REM	1	501.00	501.00

Total Parts : **11,266.95**

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401553W GST Reg. No M2-0628881-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

300, Kampong Arang Road
East Coast Centre
Singapore 438160
Tel. 63190888 (AfterSales)
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190539/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1379153	Page No. : 3 of 3
Date IN : 16/07/2019	Invoice Number : 2134142 / WSB
Motor Claim Advisor: Han Kwan Yong	Invoice Date : 07/08/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Toh Jing Xuan

- - - - L A B O U R 2 - - - -

NETT

0.00

Total Labour 2: 0.00

Labour Charges : 8,605.00	Total Labour & Parts Charges : S\$ 20,021.95
Parts Charges : 11,266.95	Less Insurance Excess : S\$ 0.00
Lubricant/Misc : 150.00	Invoice Total Amount Exclude GST : S\$ 20,021.95
	GST @ 7% : S\$ 1,401.54
	Invoice Total Amount Include GST : S\$ 21,423.49

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 21,423.49**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-113401

Date of Request: 15/07/2019

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date: 15/07/2019
Enquiry By: Han Kwan Yong
TP Vehicle No.: SLT3757H
Accident Date: 14/07/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLT3757H	AIG Asia Pacific Insurance Pte. Ltd.	21/10/2018-20/10/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-113401

Date of Request: 15/07/2019

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 15/07/2019
Enquiry By Han Kwan Yong
TP Vehicle No. SLT3757H
Accident Date 14/07/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)










































Express























































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jul 2019 Edit Reg		16 Jul 2019 00:00 Edit Adj Rpt	\$520,021.95 Edit Estimates	\$520,021.95 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: SHAZIB PERVAIZ , ID: F2458057K									
Main Claimant: SHANG JING , ID: S2730362E									
Vehicle Reg. No.: SLD5822Z		Date of Loss: 14/07/2019 18:00 - :59 [36 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 2561623393SG		Policy/Cover Note No.: 1800114370 (Comprehensive)							
Vehicle Reg. No. (Insured): SLT3757H		Policy No. (Claimant): -							
Excess:									
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 25/07/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (10/10/2019): Alert - Adj Mandate Approved (\$522525.49) - SLD5822Z - Claim Handler: Ler, Berna... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLD5822Z (2561623393SG)
[SLT3757H]
TP
SHANG JING
Jul 14 2019 6:00PM
[SHAZIB PERVAIZ]
Performance Motors Limited

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser <input type="button" value="v"/>	
Letters/Correspondences						1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown					Edit
Photos/Images						3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	06/08/19 15:10	Odometer Reading				 Load JPG	<input checked="" type="checkbox"/>
2	06/08/19 15:10	Chassis Number				 Load JPG	<input checked="" type="checkbox"/>
3	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
4	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
5	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
6	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
7	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
8	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
9	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
10	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
11	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
12	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
13	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
14	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
15	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
16	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
17	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
18	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
19	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
20	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
21	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
22	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
23	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
24	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
25	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
26	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
27	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
28	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
29	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
30	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
31	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
32	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
33	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
34	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
35	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
36	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
37	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
38	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
39	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>
40	06/08/19 15:10	General View				 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	06/08/19 15:10	General View	 Load JPG	<input checked="" type="checkbox"/>
42	06/08/19 15:10	General View	 Load JPG	<input checked="" type="checkbox"/>
43	06/08/19 15:10	General View	 Load JPG	<input checked="" type="checkbox"/>
44	06/08/19 15:10	General View	 Load JPG	<input checked="" type="checkbox"/>
45	06/08/19 15:10	General View	 Load JPG	<input checked="" type="checkbox"/>
46	06/08/19 15:10	General View	 Load JPG	<input checked="" type="checkbox"/>
47	06/08/19 15:10	General View	 Load JPG	<input checked="" type="checkbox"/>
48	06/08/19 15:10	General View	 Load JPG	<input checked="" type="checkbox"/>
49	06/08/19 15:10	General View	 Load JPG	<input checked="" type="checkbox"/>
50	06/08/19 15:10	General View	 Load JPG	<input checked="" type="checkbox"/>
51	06/08/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	06/08/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	06/08/19 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	06/08/19 15:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
96	06/08/19 15:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
97	06/08/19 15:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
98	07/08/19 14:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
99	07/08/19 14:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
100	07/08/19 14:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
101	07/08/19 14:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/07/19 10:49	TP ESTIMATE + DOCS		Load PDF	
2	16/07/19 10:49	TP GIA REPORT		Load PDF	
3	18/07/19 10:12	TP ESTIMATE-MARKED		Load PDF	
4	18/07/19 16:16	LETTER TO OI		Load PDF	
5	06/09/19 13:12	GIA SEARCH		Load PDF	
6	11/11/19 12:12	WORKSHOP INVOICE		Load PDF	
7	11/11/19 12:12	AUTHORISATION TO ACT FORM		Load PDF	
8	11/11/19 12:12	Release Voucher		Load PDF	
9	11/11/19 12:12	LOD		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	17/07/19 10:04	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLT3757H (Insd veh)	Model:	BMW 330i 2.0 (A)
	SLD5822Z (TP veh)		
Date of Accident:	14/07/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	24,658.42
Final Repair Cost	:	\$	21,423.49
Loss of Use	:	\$	1,100.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	22,525.49

10.00 days at \$110.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/~~No~~—BOLA Scenario No: _____
 _35(c)____
 BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 22,525.49
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

11 Nov
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19012502/R1HA3Q2

Date: 11/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800114370

Claimant SLD5822Z

Insured Vehicle No : SLT3757H

Date of Loss: 14/07/2019

Nature of Claim: TP

Claim No: 2561623393SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLD5822Z

Make & Model: BMW 330i, 2.0 (A)

Engine No: 21259525B48B20B

Reg. Date: 23/06/2016 (Man. Year: 2016)

Chassis No: WBA8A76020NU06331

Colour: Blue

Odometer: 43585 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size: 225/45 R18

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,052.25	11,416.95	1,635.30	12.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,993.00	8,605.00	1,388.00	13.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,045.25	20,021.95	3,023.30	13.12
+ GST 7.00/7.00% (S\$)	1,613.17	1,401.54	211.63	13.12
Nett Amount (S\$)	24,658.42	21,423.49	3,234.93	13.12
+ Loss of Use (10.0 x S\$110.00/day) (S\$)		1,100.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		22,525.49		

INSPECTION

Date of Assignment: 16/07/2019

Date Inspected: 16/07/2019 Inspected At:

 Performance Motors Limited
 (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*BONNET	Bent	1,274.80 FS	*1,274.80 FS
3	1		*FRT RH SIDE PANEL	Bent	702.65 FS	*702.65 FS
4	1		*FRT RH 2 SIDE PANEL BRACKET	Necessary	34.25 FS	*34.25 FS
5	10		*EXPANDING RIVET	Necessary	5.00 FS	*5.00 FS
6	1		*FRT RH TOP SUPPORT SIDE PANEL	Serviceable	19.20 FS	*- FS
7	1		*FRT BUMPER TOP MOUNT	Cracked	378.10 FS	*378.10 FS
8	1		*FRT LH DEFORMATION ELEMENT	Not Necessary	101.80 FS	*- FS
9	1		*FRT RH DEFORMATION ELEMENT	Bent	101.80 FS	*101.80 FS
10	1		*FRT LH LOWER DEFORMATION ELE	Serviceable	86.40 FS	*- FS
11	1		*FRT RH LOWER DEFORMATION ELE	Serviceable	86.40 FS	*- FS
12	1		*FRT RH BOTTOM MOUNTING SIDE PANEL	Serviceable	19.20 FS	*- FS
13	1		*INSERT AIR INLET MIDDLE	Cracked	120.60 FS	*120.60 FS
14	1		*RH FOG LAMP SUPPORT	Cracked	41.85 FS	*41.85 FS
15	1		*RH FINISHER ROD (SPORT)	Cracked	56.00 FS	*56.00 FS
16	1		*FRT BUMPER TOWING LUG COVER PRIMED	Scratched	43.25 FS	*43.25 FS
17	1		*RH AIR INLET FINISHER (SPORT)	Cracked	53.20 FS	*53.20 FS
18	1		*RH PARTIALLY OPEN GRID (SPORT)	Cracked	91.75 FS	*91.75 FS
19	1		*FRT SHOCK ABSORBER ECE	Cracked	54.50 FS	*54.50 FS
20	1		*SET MOUNTING PDC /PMA SENSOR FRT	Cracked	84.10 FS	*84.10 FS
21	1		*FRT BUMPER PANEL PRIMED (SPO)	Deformed	1,027.25 FS	*1,027.25 FS
22	1		*FRT RH GRILLE (SPORT)	Cracked	128.60 FS	*128.60 FS
23	1		*MODEL LETTERING SIDE (SPORT LINE)	Necessary	46.30 FS	*46.30 FS
24	2		*GROMMET	Not Necessary	1.50 FS	*- FS
25	4		*RIVET	Necessary	1.80 FS	*1.80 FS
26	1		*RH LOWER PART OF HOOK LOCK	Serviceable	87.95 FS	*- FS
27	1		*BONNET CATCH BRACKET	Serviceable	25.75 FS	*- FS
28	1		*RH SUPPORT	Bent	131.50 FS	*131.50 FS
29	1		*FRT BUMPER LOWER MOUNT	Serviceable	133.80 FS	*- FS
30	1		*RH HEADLIGHT BRACKET	Cracked	10.10 FS	*10.10 FS
31	10		*C CLIP NUT	Not Necessary	13.00 FS	*- FS
32	1		*RH COVER BOTTOM	Cracked	116.55 FS	*116.55 FS
33	1		*DEFLECTOR LIP RH	Serviceable	55.95 FS	*- FS
34	1		*AIR DUCT RADIATOR	Cracked	61.50 FS	*61.50 FS
35	1		*RH AIR DUCT BRAKE	Cracked	55.95 FS	*55.95 FS
36	1		*AIR DUCT FRT BOTTOM	Not Necessary	55.95 FS	*- FS
37	1		*ADJUSTER	Not Necessary	6.30 FS	*- FS
38	1		*FRONT ENGINE HOOD SEALING	Necessary	38.85 FS	*38.85 FS
39	1		*PLAQUE 82MM	Necessary	71.25 FS	*71.25 FS
40	1		*RH LED MODULE DIRECTION INDICATOR	Not Working	789.75 FS	*789.75 FS
41	1		*RH HEADLIGHT LED TECHNOLOGY	Broken	3,068.40 FS	*3,068.40 FS
42	1		*RH FOG LIGHT LED	Serviceable	441.95 FS	*- FS
43	2		*DECOUPING RING PDC TORQUE CONVERTER	Necessary	10.10 FS	*10.10 FS
44	1		*ULTRASONIC SENSOR (2 PCS)	Necessary (1 PCS ONLY)	737.00 FS	*236.85 FS
45	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
46	2		*BLIND RIVET	Necessary	3.10 FS	*3.10 FS
47	1		*BLIND RIVET	Necessary	1.25 FS	*1.25 FS
48	1		*UNFILTERED AIR SNORKEL	Cracked	55.20 FS	*55.20 FS
49	1		*INTAKE DUCT	Cracked	69.25 FS	*69.25 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*SET FRT RH REPAIR WIRING	Cut	596.85 FS	*596.85 FS
51	1		*FANFARE HORN HIGH TONE ELECTRONIC	Cracked	94.70 FS	*94.70 FS
52	1		*CONTROL UNIT REM	Necessary	501.00 FS	*501.00 FS
53	1		*SET LED MODULE	Necessary	162.05 FS	*162.05 FS
54	1		*CONTROL UNIT FRT LIGHT ELECTRONICS	Necessary	893.90 FS	*893.90 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 13,052.25 11,416.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DIAGNOSE AND REPLACE FRONT RH WIRE HARNESS INCLUDE RESETTING AND CHECKING CONNECTIONS FOR PROPER FUNCTION	New	451.00	451.00
2	TO DIAGNOSE AND REPLACE REM CONTROL UNIT ,SET LED MODULE ,RH LED MODULE DIRECTION INDICATOR INCLUDE PROGRAMMING AND CONDUCTING CHECKS FOR PROPER FUNCTION	New	451.00	451.00
3	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP	New	195.00	195.00
4	TO REPLACE FRONT BUMPER & ATTACHMENTS ,FRONT RIGHT FENDER ,BONNET ,RIGHT HEADLIGHT INNER SUPPORT BRACKET ,FRONT CENTER AIR DUCT INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	4,250.00	3,400.00
5	TO RESPRAY FRONT BUMPER,FRONT RIGHT FENDER AND BONNET	New	3,221.00	2,899.00
6	TO CARRY OUT BODY CAVITY PRESERVATION	New	236.00	200.00
7	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS	New	531.00	451.00
8	TO REPLACE RIGHT HEADLIGHT	New	481.00	408.00
9	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (\$\$)			9,993.00	8,605.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >