

INS. CASE OWNER:

CC 3, ALB 190 12503, T1 da39/ LKK: IDAC:

Surveyor:

WMA

DOI:

ASSIGNMENT

29/7/2019

Date / Time:

16/7/19

Registered in Merimen:

16/7/19

Pre-assign / CCU / FTE



Insured Vehicle No. : SGF 5333 S

Claim No. : _____

Name of Insured : Kao Ka Yun, Alison

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II : S\$

D.O.A : 13/07/2019

Place of Accident : _____

Is driver the owner? (YES / NO) (NO)

Nature of Accident : _____

If NO, Driver Name / Age : _____

OI GIA REPORT (YES) NO ; TP GIA REPORT: (YES) / NO

Driver Tel No. : _____

(V/L: YES NO)

Insured Liability : % Final ? Yes / No

SGF 5678 A



INSRS:

WSP:

Tel:

Liability:

RMKS:

pmc



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SGF 5678 A X ; SGF 5333 S - X

STAGE

DATE / PIC

25/10/19 - FILE PASS TO TYPE MANDATE

18/11/19 - FILE PASS TO HMK TO CLOSIS

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 18/11/19

Confirm with: Caroline

Email

Call

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No. : 10

If NO or B 28, Ass. Lia :

Repair Cost: (w/431)

S\$ 10310.89

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

800.00 (\$ 100 x 8 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only ☐ LOU only ☒

LOR + LOU ☐

LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$320

Total:

S\$ 11110.89

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 11110.89

Name 1:

Performance Motors Limited

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT



Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 19740159M GST No. MC MC-000081-X
 Toll-Free Number (1800-2255269)

101, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax: 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 436180
 Fax: 63449773

117, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax: 64796601 (AfterSales)
 64796624 (Motors&S)

GST REG. NO : M2 - 0020081 - X

16 JUL 2019

ESTIMATE

Estimate No. : b1 51977
 Date Estimated : 15/07/2019
 Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lim Hong Liang
 67 Jalan Tambur

Singapore 576826

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
 78 Shenton Way
 #08-16 Chartis Building
 Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE5628A	C958487	13/03/2012	535iA	0

DESCRIPTION

VALUE

Replacing left rear door, reworking left rear side panel and rear bumper

✓ 2550 3,400.00

Spray left rear door, rear side panel and rear bumper

✓ 2527 2,808.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

✓ 257 271.00

To check electrical wiring systems and lightings at the rear section for proper function.

✓ 150 177.00

To conduct checks on all doors and bootlid central locking system for proper function.

✓ 150 177.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x)

✓ 451 531.00

To replace tyre and wheel rim including balancing. (1x). left rear tyre rim

✓ 80 94.00

To carry out body cavity preservation. (Per panel).

✓ 100 118.00

Sundries

80 ? 150.00

Total Labour 1: 7,726.00

DESCRIPTION

QTY PRIC

VALUE

ALLOY RIM 9JX19 V SPOKE 331

1 1,341.30

Int 1,341.30

RR LH DOOR

1 1,774.50

add 1,774.50

REAR DOOR SEAL

1 168.85

all 168.85

Total Parts : 3,284.65



Final Report

Estimate No. : **b1 51977**
Date Estimated : **15/07/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -

Lim Hong Liang
67 Jalan Tambur

Singapore 576826

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE5628A	C958487	13/03/2012	535iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear left door and attachments including make good the rear bumper, rear left fender and knock out dented area caused by the accident.	2,550.00		2,550.00
To respray rear left door, rear left fender and rear bumper.	2,527.00		2,527.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	257.00		257.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
To conduct checks on all doors and bootlid central locking system for proper function.	150.00		150.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x)	451.00		451.00
To replace rear left wheel rim including balancing. (1x).	80.00		80.00
To carry out body cavity preservation. (Per panel).	100.00		100.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLIP WITH WASHER NATUR	1.90	2.00		3.80
# EXPANDING NUT	1.45	2.00		2.90
ALLOY RIM 9JX19 V SPOKE 331	1,341.30	1.00		1,341.30
RR LH DOOR	1,774.50	1.00		1,774.50
REAR DOOR SEAL	168.85	1.00		168.85

SUPPLEMENTARY ITEMS

Total Labour :	6,345.00
Total Parts :	3,291.35



Supplementary

Estimate No. : **b1 51977**
Date Estimated : **15/07/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -

Lim Hong Liang
67 Jalan Tambur

Singapore 576826

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE5628A	C958487	13/03/2012	535iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# CLIP WITH WASHER NATUR	1.90	2.00		3.80 <i>ndh</i>
# EXPANDING NUT	1.45	2.00		2.90 <i>ndh</i>

Total Labour :	
Total Parts :	6.70
Total Labour & Parts :	6.70

Performance Motors Limited

A Sine Darby Motors Company
Co. Reg. No. 197401133W GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sine Darby Performance Centre
Singapore 159941
Fax: 64747770

296, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

115, Alexandra Road
Sine Darby Business Centre
Singapore 159944
Fax: 64796801 (AfterSales)
64796824 (Motocorad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

16 JUL 2019

Estimate No. : b1 51977
Date Estimated : 15/07/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lim Hong Liang
67 Jalan Tambur

Singapore 576826

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE5628A	C958487	13/03/2012	535iA	0

DESCRIPTION

VALUE

Replacing left rear door, reworking left rear side panel and rear bumper

2550 3,400.00

Spray left rear door, rear side panel and rear bumper

2527 2,808.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

257 271.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To conduct checks on all doors and bootlid central locking system for proper function.

150 177.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x)

451 531.00

To replace tyre and wheel rim including balancing. (1x). left rear tyre rim.

80 94.00

To carry out body cavity preservation. (Per panel).

100 118.00

Sundries

? 150.00

Total Labour 1: 7,726.00

DESCRIPTION

QTY

PRIC

VALUE

ALLOY RIM 9JX19 V SPOKE 331

1 1,341.30

1,341.30

RR LH DOOR

1 1,774.50

1,774.50

REAR DOOR SEAL

1 168.85

168.85

Total Parts : 3,284.65

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159943
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449775

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796501 (AfterSales)
64796524 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 51977
Date Estimated : 15/07/2019
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE5628A	C958487	13/03/2012	5351A	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 29/7/19 11:30 Excess S\$ _____

Surveyor's Name Tanjun Sign Inflic

Surveyor's Tel 97498724 Authorised Yes / No _____

Submitted Date WP Time _____

SELECT PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail tanjun@lkkautoconsultants.com

No. of Working Days Recommended 6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____



Labour 1	:	7,726.00
Parts	:	3,284.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	770.75
Grand Total	:	11,781.40

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

View Received Message

This mail is associated with :

***SKE5628A (2836509571SG)**
[SGF5333S]

TP
LIM HONG LIANG
Jul 13 2019 3:00PM
[KAO KO YUN, ALISON]
Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 15/11/2019 15:40 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11110.89) - SKE5628A - Claim Handler: Foo, Chit Yan

Approved:11110.89.

DOCUMENTS SUMMARY

There are no documents.

MOTOR INSURANCE COVER NOTE

Cover Note No. 10121042

The Insured named in the Schedule below having proposed for insurance in respect of the Motor Vehicle described in the Schedule below the risk is hereby HELD COVERED in the terms of the Company's usual form of Policy applicable thereto for the period as stated below unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

SCHEDULE

Agent No. : 212165
Name of Insured : LIM HONG LIANG
Make and Description of Vehicle : BMW 535i 3.0L AT D/AB 2WD 4DR GAS/D SR HUD
Vehicle Registration No. : SKE5628A
Year of Manufacture : 2012
Engine No. : 09628067N55B30A
Chassis No. : WBAFR72070C958487
Capacity : 2,979 Cubic Capacity
Cover Type : Comprehensive
Sum Insured (SGD) : Market Value
Period of Insurance : 13/03/2019 to 12/03/2020
Excess (SGD) : 1,000

I/We hereby certify that this Cover Note is issued in accordance with the Provisions of the Motor Vehicles (Third Party Risks & Compensation) Act (Cap. 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Not valid unless countersigned by the
Company's Authorised Representative



Sime Darby Insurance Brokers (Singapore) Pte. Ltd.

MSIG Insurance (Singapore) Pte. Ltd.
Authorised Insurers



Katherine Yeo
Senior Vice President, Brokers

Date of Issue : 08/02/2019

This Cover Note is valid for 30 days from the date of issue.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jul 2019 Edit Reg		29 Jul 2019 00:00 Edit Adj Rpt	\$9,636.35 Edit Estimates	\$9,636.35 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	KAO KO YUN, ALISON , ID: S7298025E								
Main Claimant:	LIM HONG LIANG , ID: S1555817B								
Vehicle Reg. No.:	SKE5628A	Date of Loss:	13/07/2019 15:00 - :59 [88 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2836509571SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 05/08/2018 - 04/08/2019						
Vehicle Reg. No. (Insured):	SGF5333S	Policy No. (Claimant):	10121042						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 25/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (15/11/2019): Alert - Adj Mandate Approved (\$11110.89) - SKE5628A - Claim Handler: Foo, Chit ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKE5628A (2836509571SG)
[SGF5333S]
TP
LIM HONG LIANG
Jul 13 2019 3:00PM
[KAO KO YUN, ALISON]
Performance Motors Limited

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View in Browser

Letters/Correspondences

1 per page ☐

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit

Photos/Images

3 per page ☐

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/10/19 14:05	Odometer Reading		Load JPG
2	25/10/19 14:05	Chassis Number		Load JPG
3	25/10/19 14:05	General View		Load JPG
4	25/10/19 14:05	General View		Load JPG
5	25/10/19 14:05	General View		Load JPG
6	25/10/19 14:05	General View		Load JPG
7	25/10/19 14:05	General View		Load JPG
8	25/10/19 14:05	General View		Load JPG
9	25/10/19 14:05	General View		Load JPG
10	25/10/19 14:05	General View		Load JPG
11	25/10/19 14:05	General View		Load JPG
12	25/10/19 14:05	General View		Load JPG
13	25/10/19 14:05	General View		Load JPG
14	25/10/19 14:05	General View		Load JPG
15	25/10/19 14:05	General View		Load JPG
16	25/10/19 14:05	General View		Load JPG
17	25/10/19 14:05	General View		Load JPG
18	25/10/19 14:05	General View		Load JPG
19	25/10/19 14:05	General View		Load JPG
20	25/10/19 14:05	General View		Load JPG
21	25/10/19 14:05	General View		Load JPG
22	25/10/19 14:05	General View		Load JPG
23	25/10/19 14:05	General View		Load JPG
24	25/10/19 14:05	General View		Load JPG
25	25/10/19 14:06	Reinspection Photo		Load JPG
26	25/10/19 14:06	Reinspection Photo		Load JPG
27	25/10/19 14:06	Reinspection Photo		Load JPG

Documentation

1 per page ☐

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/07/19 10:55	TP ESTIMATE + docs		Load PDF
2	16/07/19 10:55	TP GIA REPORT		Load PDF
3	30/07/19 22:02	TP ESTIMATE - MARKED		Load PDF
4	25/10/19 14:16	LOD		Load PDF
5	25/10/19 14:16	TP ESTIMATE - MARKED (FINAL)		Load PDF
6	20/11/19 08:00	WORKSHOP INVOICE		Load PDF
7	20/11/19 08:00	AUTHORISATION TO ACT FORM		Load PDF
8	20/11/19 08:00	LOD		Load PDF
9	20/11/19 08:00	Release Voucher		Load PDF
10	20/11/19 08:00	LETTER TO OI		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/07/19 09:46	OI GIA REPORT		Load PDF

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
2	14/11/19 18:08	Clear Report		 Load XLSX	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer	
Note: Remarks are private unless you show it to other parties.	

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SGF5333S (Insd veh)	Model:	BMW 535i 3.0 (A)
	SKE5628A (TP veh)		
Date of Accident:	13/07/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	11,788.56
Final Repair Cost	:	\$	10,310.89
Loss of Use	:	\$	800.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	11,110.89

8.00 days at \$100.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____
10

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 11,110.89
2)		:	\$

JOANNE LEE KHANG MIN

20 Nov
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19012503/T1DA3Q2

Date: 20/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SKE5628A

Insured Vehicle No : SGF5333S

Date of Loss: 13/07/2019

Nature of Claim: TP

Claim No: 2836509571SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKE5628A

Make & Model: BMW 535i, 3.0 (A)

Engine No: 09628067N55B30A

Reg. Date: 13/03/2012 (Man. Year: 2012)

Chassis No: WBAFR72070C958487

Colour: Black

Odometer: 68044 km

Engine Capacity: 2979 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/35 R19

Rear Tyre Size: 275/35 R19

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,441.35	3,371.35	70.00	2.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,576.00	6,265.00	1,311.00	17.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,017.35	9,636.35	1,381.00	12.53
+ GST 7.00/7.00% (S\$)	771.21	674.54	96.67	12.53
Nett Amount (S\$)	11,788.56	10,310.89	1,477.67	12.53
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
Nett Liability (S\$)		11,110.89		

INSPECTION

Date of Assignment: 29/07/2019

Date Inspected: 29/07/2019 Inspected At:

Performance Motors Limited

(Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre

Singapore 159941

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*ALLOY RIM 9J19 V SPOKE 331	Cut	1,341.30 FS	*1,341.30 FS
3	1		*RR LH DOOR	Dented	1,774.50 FS	*1,774.50 FS
4	1		*REAR DOOR SEAL	Necessary	168.85 FS	*168.85 FS
5	2		*CLIP WITH WASHER NATUR	Necessary	3.80 FS	*3.80 FS
6	2		*EXPANDING NUT	Necessary	2.90 FS	*2.90 FS

F=Franchise part, S=SpcNett.

Total Parts (\$\$)	3,441.35	3,371.35
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACING LEFT REAR DOOR ,REWORKING LEFT REAR SIDE PANEL AND REAR BUMPER	New	3,400.00	2,550.00
2	SPRAY LEFT REAR DOOR, REAR SIDE PANEL AND REAR BUMPER	New	2,808.00	2,527.00
3	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	257.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
5	TO CONDUCT CHECKS ON ALL DOORS AND BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	177.00	150.00
6	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS	New	531.00	451.00
7	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING LEFT REAR TYRE RIM	New	94.00	80.00
8	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (\$\$)			7,576.00	6,265.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >