

MS Dealer

# Performance Motors Limited

A Sime Darby Motors Company  
Cr. Reg. No. 197402119W GST Reg. No. M2 0020081-X  
Toll-Free Number (1800-2255269)



103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

16 JUL 2019

## ESTIMATE

Estimate No. : <b>b1 51966</b>	Page No. : <b>1 of 4</b>
Date Estimated : <b>15/07/2019</b>	
Prepared By : <b>Joseph Yaguel</b>	

<b>- ESTIMATE REPAIR FOR -</b> Lee Nai Bin 22A Yarwood Avenue  Singapore 588008	<b>- ACCOUNT - 121</b> AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLW1822A	EE63139	11/01/2018	X1 sDrive18i	0

DESCRIPTION	VALUE
Replacing rear bumper panel attachment	<del>425</del> 860.00
To check electrical wiring systems and lightings at the rear section for proper function.	<del>150</del> 177.00
Sundries.	40.00
<b>Total Labour 1:</b>	<b>1,067.00</b>

DESCRIPTION	QTY	PRIC	VALUE
REAR TRIM UNDERRIDE PROTECTION (XL <i>see</i> )	1	105.40	105.40
<b>Total Parts :</b>			<b>105.40</b>

Claims - (O / T / I Party / Uninsured / Driver / Driver Restatement)  
 Policy No. \_\_\_\_\_ Claim No. \_\_\_\_\_  
 Date of Claim 21/10/19 @ 1420 Excess S\$ \_\_\_\_\_  
 Surveyor's Name RPM Sign \_\_\_\_\_  
 License No. 9006068  
 Date of Report \_\_\_\_\_  
 POLICY PARTS PHOTO BY SURVEYOR \_\_\_\_\_  
 E-mail \_\_\_\_\_  
 No. of Working Days Recommended 1 days

**LINK into Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Structural modification(s) is allowed
- Costly ancillary item(s) must be resurveyed and subject to final approval from Insurance Company

Approved by Repairer \_\_\_\_\_



Labour 1	1,067.00
Parts	105.40
Labour 2	0.00
Excess	0.00
Total GST @ 7%	82.07
<b>Grand Total</b>	<b>1,254.47</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*  
 \*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 51966**  
Date Estimated : **15/07/2019**  
Prepared By : **Joseph Yaguel**

**- ESTIMATE REPAIR FOR -**  
**Lee Nai Bin**  
**22A Yarwood Avenue**

**- ACCOUNT - 121**  
**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

**Singapore 588008**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLW1822A</b>	<b>WBAJG12010EE63139</b>	<b>11/01/2018</b>	<b>X1 sDrive18i</b>	<b>0</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear underride protection trim including remove attachments to facilitate repairs.	425.00		425.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00 ✓
Sundries.	40.00		40.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR TRIM UNDERRIDE PROTECTION (X L	109.15	1.00		109.15 ✓

### # SUPPLEMENTARY ITEMS

Total Labour :	615.00
Total Parts :	109.15
Total Labour & Parts :	724.15
Deduction for Excess :	0.00
Total Repair Costs less Excess:	<b>724.15</b>
GST @7%:	50.69
Grand Total :	<b>774.84</b>