



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI19012508/T1vf3e2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 24-07-2019



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 7591U	Veh. Inspected	GBF 6658H
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000003693	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	15/07/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KDH2015022458	Colour	RED
Odometer	92889	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185 R15	YOKOHAMA	6 mm
L/H Front Tyre	185 R15	YOKOHAMA	6 mm
R/H Rear Tyre	185 R15	YOKOHAMA	6 mm
L/H Rear Tyre	185 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/07/2019	Inspection Date	17/07/2019
Survey held at	NO 8 TUAS AVE 18		
Repairer	SIN SHENG ENGINEERING SERVICES		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**