

# e

## FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883  
 TEL: 6886 9097 FAX: 6841 9095 Email: focus.autoptd@yahoo.com.sg  
 GST:200712509E RCB NO:201004495R

*not Avlonus*  
*Mak*  
*1/3 3900*  
*16/7/19*  
*to be p/h*  
*1 up*  
*5 dy.*

**M/S :** AIG ASIA PACIFIC INSURANCE PTE LTD  
 78 SHENTON WAY  
 #07-16 AIG BUILDING  
 SINGAPORE 079120  
 TEL: 6419 3000 FAX: 6835 7416  
 ATTN: Motor Claim Department  
 Your Ref No: SJV6533E  
 Claim Type: Third Party  
 Accident Date: 13/07/2019  
 TP Veh Reg No: SMA549A

**Estimate No:** EST0000962  
**Date:** 17 Jul 2019  
**Policy No:** 5098297507-01  
**Veh Reg No:** SJV6533E  
**Make/Model:** TOYOTA WISH 1.8X  
**Chassis No:** ZGE200036230  
**Engine No:** 2ZR0504684  
**Reg. Date:** 02/04/2010

### Estimate Repair Cost for Vehicle No :SJV6533E

PAGE:1/2

Description	U/Price	Quantity	Price SS	Amount SS
<b>List Price</b>				
1 Rear Boot <i>Body ID</i>	1,295.00	1 PC	1,295.00	✓
2 Rear Boot Lock <i>W/shaft</i>	491.60	1 PC	491.60	✓
3 Rear Boot Lock Catch <i>11</i>	35.20	1 PC	35.20	X
4 Rear Boot Rubber <i>To in</i>	381.60	1 PC	381.60	✓
5 Rear Boot Shock Absorber <i>11</i>	198.20	2 PC	396.40	X
6 Rear Boot Emblem <i>neu</i>	60.20	1 PC	60.20	✓
7 Rear Boot Inner Board <i>11</i>	365.00	1 PC	365.00	X
8 Rear Boot Logo <i>neu 68.10</i>	80.00	1 PC	80.00	✓
9 Rear Boot Centre Moulding <i>11</i>	295.70	1 PC	295.70	X
10 Rear End Panel <i>Best</i>	485.20	1 PC	485.20	✓
11 Rear End Panel Top Garnish <i>1 up</i>	305.00	1 PC	305.00	✓
12 Rear Fender Inner Side Garnish <i>neu</i>	566.90	1 PC	566.90	X
13 Rear Bumper <i>W/OE 586.10</i>	655.90	1 PC	655.90	✓
14 Rear Bumper Side Retainer <i>11</i>	85.90	2 PCS	171.80	X
15 Rear Bumper Bracket <i>11</i>	93.60	2 PCS	187.20	X
16 Rear Bumper Lower Clip <i>neu</i>	5.50	4 PCS	22.00	✓
17 Rear Windscreen Seal <i>neu</i>	56.20	1 PC	56.20	✓
			5,850.90	
	Less 25%		1,462.73	4,388.19
<b>Special Net</b>				
18 Rear Bumper Sensor <i>shuttl</i>	300.00	1 SET	300.00	200
19 Rear Windscreen Gum <i>neu</i>	80.00	1 PC	80.00	40
			380.00	380.00

*P-3731.20*  
*2798.25*

LKK Auto Consultants hence notify the Repairer of the following:

- To ensure two-water spray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal proceedings are allowed
- Supplementary works must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

# FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883  
TEL: 6886 9097 FAX: 6841 9095 Email: focus.autoptehd@yahoo.com.sg  
GST:200712509E RCB NO:201004495R

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
TEL: 6419 3000 FAX: 6835 7416  
ATTN: Motor Claim Department  
Your Ref No: SJV6533E  
Claim Type: Third Party  
Accident Date: 13/07/2019  
TP Veh Reg No: SMA549A

Estimate No: EST0000962  
Date: 17 Jul 2019  
Policy No: 5098297507-01  
Veh Reg No: SJV6533E  
Make/Model: TOYOTA WISH 1.8X  
Chassis No: ZGE200036230  
Engine No: 2ZR0504684  
Reg. Date: 02/04/2010

## Estimate Repair Cost for Vehicle No :SJV6533E

PAGE:2/2

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
<b>Labour</b>				
20 Panel Beating	1,200.00	1	1,200.00	800
21 Check Wiring	60.00	1	60.00	20
22 Rust Proofing	60.00	1	60.00	60
23 To Remove & Refit Rear Windscreen	160.00	1	160.00	120
24 To Remove & Replace Bumper Sensor	80.00	1	80.00	50
25 Spray Painting	900.00	1	900.00	800
			2,460.00	2,460.00
			Total	SS 7,228.19

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND TWO HUNDRED TWENTY EIGHT AND CENTS NINETEEN ONLY

Focus Auto Pte Ltd  
For FOCUS AUTO PTE LTD  
#02-50 Singapore 417883  
Tel: 66349635

48425

AUTHORISED SIGNATURE

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/07/2019 13:10
Date Of Accident	13/07/2019 12:15
Exact Location Of Accident	JURONG WEST AVE 1 (AROUND BUS STOP 490)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV6533E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TW PREMIUM AUTOMOBILE PTE LTD
Co Reg No	201320430G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91119581

### Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5098297507-01
Cover Note Number	

### Driver

Name of Driver	HERYADI BIN MOHAMAD NOH
NRIC No	S1413218Z
Date Of Birth	27/12/1960
Occupation	OUTDOOR
Date Of Driving Pass	29/08/1983
Driving Experience	35 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92981319
Fax Number	
Contact Number	
EMail Address	HERYADI_@HOTMAIL.COM

Address	BLK 433 JURONG WEST ST 42 #02-516
Postcode	640433
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE SEE ATTACHED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMA549A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHAN HANG LAM SALLY
NRIC/Passport Number	S7889999I
Contact Number	96553146
Address	NA
	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	HERYADI BIN MOHAMAD NOH
------	-------------------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJV6533E

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?


Address

BLK 433 JURONG WEST ST 42 #02-516

Postcode

Individual Statement

SKETCH PLAN



VEH A: SJV 6533E

VEH B: SMA 549A

← Jurong West Ave 1

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/07/2019 around 1215, I was stopping my vehicle, SJV 6533E at Jurong West Ave 1 (Around bus stop 490) for traffic light clearance (at the front). Suddenly, I felt an impact from the back rear. I got off my vehicle and found SMA 549A front portion hit my vehicle back rear. ~~caused~~ The hit caused my back rear badly damaged.

Reporting Only  
 Own Damage Claim  
 Third Party Claim

Reporting Only  
 Own Damage Claim  
 Third Party Claim

Focus Auto

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

*Zhang Li* 1305  
 15/07/2019

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/ID No.:

