



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29  
Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

TPALG

Vic.

Page No. 1

GK81201889

Vehicle No. SLZ9401M HONDA SHUTTLE

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (\$)	SURVEYOR ADJUSTMENT
<b>PARTS (LIST ITEMS)</b>				
1	FRONT BUMPER <i>Distorted</i>		1050.50	✓
2	FRONT BUMPER SIDE RETAINER RH & LH @ \$45.00 <i>RH bent</i>		90.00	45
2	FRONT BUMPER FOGLAMP COVER RH & LH @ \$101.00 <i>RH crumpled</i>		202.00	101
1	FRONT BUMPER REINFORCEMENT <i>Bent</i>		<del>510.00</del>	374
1	FRONT BUMPER TOW COVER <i>Missing</i>		51.00	✓
1	FRONT BUMPER LOWER GRILLE <i>detached</i>		216.00	✓
1	FRONT GRILLE <i>crumpled</i>		456.80	✓
1	FRONT GRILLE CHROME <i>cut</i>		361.00	✓
1	FRONT GRILLE LOGO <i>nee</i>		70.00	✓
1	FRONT BONNET <i>Repair</i>		1134.00	X
2	FRONT BONNET HINGE RH & LH @ \$71.00 <i>nee</i>		142.00	X
2	FRONT HEADLAMP RH & LH @ \$2250.00 <i>RH cut</i>		4500.00	2250
2	FRONT HEADLAMP LOWER BRACKET RH & LH @ \$45.60 <i>RH crumpled</i>		91.20	45.60
1	FRONT FENDER RH <i>Repair</i>		456.80	X
1	FRONT FENDER INNER SHEILD RH <i>nee</i>		116.50	X
1	FRONT WASHER TANK <i>detached</i>		318.00	✓
1	FRONT WASHER TANK MOTOR <i>nee</i>		352.00	X
1	FRONT SUPPORT PANEL <i>Repair Buckled</i>		510.00	✓
1	FRONT RADIATOR ASSY <i>nee</i>		551.00	X
1	FRONT RADIATOR TOP HOSE		81.00	X
1	FRONT RADIATOR FAN COWLING		95.00	X
1	FRONT RADIATOR FAN BLADE		95.00	X
1	FRONT RADIATOR FAN MOTOR		152.50	X
1	FRONT A/C CONDENSER <i>Bent</i>	6592.90	611.00	✓
1	FRONT A/C SIDE GARNISH LH <i>nee</i>		61.00	X
1	FRONT A/C SIDE GARNISH RH <i>crumpled</i>	5274.32	61.00	✓
1	FRONT A/C LIQUID PIPE		151.00	X
1	FRONT A/C SUCTION PIPE		151.00	X
1	FRONT A/C DISCHARGE PIPE		175.00	X
1	FRONT A/C FAN COWLING <i>crumpled</i>		72.00	✓
1	FRONT A/C FAN BLADE		61.00	X
1	FRONT A/C FAN MOTOR		165.00	X
1	FRONT SPARE TANK <i>nee</i>		256.00	X
1	FRONT SPARE TANK BREATHING HOSE <i>not nee</i>		98.00	X
			13464.30	
		less	20%	20%
			2692.86	
			10771.44	
<b>SPECIAL NETT ITEMS</b>				
1 SET	FRONT BUMPER CLIPS <i>nee</i>		<del>100.00</del>	30
1	FRONT SUPPORT PANEL CLIPS <i>nee</i>		100.00	X
1 SET	FRONT BONNET INSULATOR CLIPS <i>nee</i>		80.00	X
1	FRONT FENDER INNER SHEILD CLIPS <i>nee</i>		80.00	X
1	COOLANT <i>nee</i>		<del>100.00</del>	50
1	FRONT TYRE " FIRENZA " RH <i>nee</i>		350.00	X
1 SET	FRONT CAR PLATE WITH HOLDER <i>nee</i>		70.00	X
	<b>Total Parts</b>		11651.44	



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SLZ9401M HONDA SHUTTLE

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	<del>1400.00</del> 900	1880
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	<del>1200.00</del> 800.	
3	To remove and refix wiring at damaged areas	<del>180.00</del> 30.	
4	To perform anti rust treatment on affected areas	150.00 x	
5	To top up coolant, remove radiator and condensers	120.00 ✓	
6	To check headlamp beam	<del>120.00</del> 30	
7	To conduct water sepage test	100.00 x.	
	Labour Total :	3270.00	
TOTAL (PARTS & LABOUR) :		14921.44	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

total 7734.32  
H/S: 5.8K.  
05Days.