

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6886 9097 FAX: 6841 9095 Email: focusautoptehd@yahoo.com.sg
GST:200712509E RCB NO:201004495R

not Allowed
d/s #3200
take job H. H. H.
17/7/19
H. H. H.

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET
#04-#05 IOB BUILDING
SINGAPORE 049711

TEL: 6347 6100 FAX: 6224 4174

ATTN: Motor Claim Department

Estimate No: EST0000960

Date: 17 Jul 2019

Policy No: 5101550266

Veh Reg No: SLF7211M

Make/Model: TOYOTA COROLLA ALTIS

Your Ref No: SLF7211M

Claim Type: Third Party

Accident Date: 13/07/2019

TP Veh Reg No: SHA7865A

Chassis No: MR053REH104557696

Engine No: 1ZRX592355

Reg. Date: 09/07/2016

Estimate Repair Cost for Vehicle No :SLF7211M

PAGE:1/2

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 Rear Door - Right <i>o/s Body</i>	1,004.90	1 PC	1,004.90	✓
2 Rear Door Lock - Right <i>11</i>	348.20	1 PC	348.20	X
3 Rear Door Rubber - Right <i>ru</i>	189.00	1 PC	189.00	✓
4 Rear Door Glass Regulator - Right <i>o/s set</i>	246.20	1 PC	246.20	✓
5 Rear Door Glass Regulator Motor - Right <i>o/s set</i>	329.40	1 PC	329.40	✓
6 Rear Door Inner Board - Right <i>o/s cre</i>	456.40	1 PC	456.40	✓
7 Rear Fender - Right <i>o/s n</i>	829.20	1 PC	829.20	X
8 Rear Bumper <i>Depcur/70in</i>	527.20	1 PC	527.20	✓
9 Rear Bumper Side Retainer - Right <i>o/s 11</i>	48.20	1 PC	48.20	X
10 Rear Bumper Protection Garnish - Right <i>o/s 11</i>	52.40	1 PC	52.40	✓
11 Rear Shock Absorber - Right <i>11</i>	346.20	1 PC	346.20	X
12 Rear Hub Bearing - Right <i>o/s n</i>	298.20	1 PC	298.20	✓
			4,675.50	
	Less 25%		1,168.88	3,506.63
Special Net				
13 Rear Sport Rim - Right <i>o/s cur/set</i>	750.00	1 PC	750.00	4805.~
			750.00	750.00

3103.70
252
2327.77
4011.77

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focusautoptehd@yahoo.com.sg

GST:200712509E RCB NO:201004495R

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET

#04-#05 IOB BUILDING

SINGAPORE 049711

TEL: 6347 6100

FAX: 6224 4174

ATTN: Motor Claim Department

Estimate No: EST0000960

Date: 17 Jul 2019

Policy No: 5101550266

Veh Reg No: SLF7211M

Make/Model: TOYOTA COROLLA ALTIS

Your Ref No: SLF7211M

Claim Type: Third Party

Accident Date: 13/07/2019

TP Veh Reg No: SHA7865A

Chassis No: MR053REH104557696

Engine No: 1ZRX592355

Reg. Date: 09/07/2016

Estimate Repair Cost for Vehicle No :SLF7211M

PAGE:2/2

Description	U/Price	Quantity	Price S\$	Amount S\$
Labour				
14 Panel Beating	950.00	1	950.00	500
15 Check Wiring	60.00	1	60.00	20
16 Rust Proofing	60.00	1	60.00	40
17 To Remove & Refit Door Accessories	80.00	1	80.00	50
18 Spray Painting	820.00	1	820.00	600
			1,970.00	1,970.00
			Total	S\$ 6,226.63

TOTAL: SINGAPORE DOLLAR SIX THOUSAND TWO HUNDRED TWENTY SIX AND CENTS SIXTY THREE ONLY

Focus Auto Pte Ltd
For FOCUS AUTO PTE LTD
#02-50 Singapore 417883
Tel: 68349695

AUTHORISED SIGNATURE

LKK Auto Consultants hereby notify the Repairer of the following:

- To reserve (separate) spray painting
- To remove damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No single visit/assessment is allowed
- Supplementary work must be surveyed and is subject to prior approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

