

# FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883  
 TEL: 6886 9097 FAX: 6841 9095 Email: [focus.autopteltd@yahoo.com.sg](mailto:focus.autopteltd@yahoo.com.sg)  
 GST:200712509E RCB NO:201004495R

*not Authorized  
 d/s  
 17/7/19  
 Hdy.*

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD  
 64 CECIL STREET  
 #04-#05 IOB BUILDING  
 SINGAPORE 049711  
 TEL: 6347 6100 FAX: 6224 4174  
 ATTN: Motor Claim Department

Estimate No: EST0000960  
 Date: 17 Jul 2019  
 Policy No: 5101550266  
 Veh Reg No: SLF7211M  
 Make/Model: TOYOTA COROLLA ALTIS

Your Ref No: SLF7211M  
 Claim Type: Third Party  
 Accident Date: 13/07/2019  
 TP Veh Reg No: SHA7865A

Chassis No: MR053REH104557696  
 Engine No: 1ZR592355  
 Reg. Date: 09/07/2016

## Estimate Repair Cost for Vehicle No :SLF7211M

PAGE:1/2

| Description                                           | U/Price  | Quantity | Price<br>S\$ | Amount<br>S\$ |
|-------------------------------------------------------|----------|----------|--------------|---------------|
| <b>List Price</b>                                     |          |          |              |               |
| 1 Rear Door - Right <i>Body</i>                       | 1,004.90 | 1 PC     | 1,004.90     | ✓             |
| 2 Rear Door Lock - Right <i>11</i>                    | 348.20   | 1 PC     | 348.20       | X             |
| 3 Rear Door Rubber - Right <i>ru</i>                  | 189.00   | 1 PC     | 189.00       | ✓             |
| 4 Rear Door Glass Regulator - Right                   | 246.20   | 1 PC     | 246.20       | ?             |
| 5 Rear Door Glass Regulator Motor - Right             | 329.40   | 1 PC     | 329.40       | ?             |
| 6 Rear Door Inner Board - Right                       | 456.40   | 1 PC     | 456.40       | ?             |
| 7 Rear Fender - Right <i>~</i>                        | 829.20   | 1 PC     | 829.20       | X             |
| 8 Rear Bumper <i>Depcur/7011</i>                      | 527.20   | 1 PC     | 527.20       | ✓             |
| 9 Rear Bumper Side Retainer - Right <i>11</i>         | 48.20    | 1 PC     | 48.20        | X             |
| 10 Rear Bumper Protection Garnish - Right <i>gand</i> | 52.40    | 1 PC     | 52.40        | ✓             |
| 11 Rear Shock Absorber - Right <i>11</i>              | 346.20   | 1 PC     | 346.20       | X             |
| 12 Rear Hub Bearing - Right                           | 298.20   | 1 PC     | 298.20       | ?             |
|                                                       |          |          | 4,675.50     |               |
|                                                       | Less 25% |          | 1,168.88     | 3,506.63      |
| <b>Special Net</b>                                    |          |          |              |               |
| 13 Rear Sport Rim - Right <i>cur/2011</i>             | 750.00   | 1 PC     | 750.00       | 4805.~        |
|                                                       |          |          | 750.00       | 750.00        |

# FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883  
 TEL: 6886 9097 FAX: 6841 9095 Email: [focus.autopteltd@yahoo.com.sg](mailto:focus.autopteltd@yahoo.com.sg)  
 GST:200712509E RCB NO:201004495R

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET  
 #04-#05 IOB BUILDING  
 SINGAPORE 049711

TEL: 6347 6100 FAX: 6224 4174  
 ATTN: Motor Claim Department

Estimate No: **EST0000960**  
 Date: 17 Jul 2019  
 Policy No: 5101550266  
 Veh Reg No: **SLF7211M**  
 Make/Model: TOYOTA COROLLA ALTIS

Your Ref No: SLF7211M  
 Claim Type: Third Party  
 Accident Date: 13/07/2019  
 TP Veh Reg No: SHA7865A

Chassis No: MR053REH104557696  
 Engine No: 1ZR592355  
 Reg. Date: 09/07/2016

## Estimate Repair Cost for Vehicle No :SLF7211M

PAGE:2/2

| Description                           | U/Price | Quantity | Price<br>S\$ | Amount<br>S\$ |
|---------------------------------------|---------|----------|--------------|---------------|
| <b>Labour</b>                         |         |          |              |               |
| 14 Panel Beating                      | 950.00  | 1        | 950.00       | 500           |
| 15 Check Wiring                       | 60.00   | 1        | 60.00        | 20            |
| 16 Rust Proofing                      | 60.00   | 1        | 60.00        | 40            |
| 17 To Remove & Refit Door Accessories | 80.00   | 1        | 80.00        | 50            |
| 18 Spray Painting                     | 820.00  | 1        | 820.00       | 600           |
|                                       |         |          | 1,970.00     | 1,970.00      |
|                                       |         |          | Total        | S\$ 6,226.63  |

TOTAL: SINGAPORE DOLLAR SIX THOUSAND TWO HUNDRED TWENTY SIX AND CENTS SIXTY THREE ONLY

Focus Auto Pte Ltd  
 For **FOCUS AUTO PTE LTD**  
 #02-50 Singapore 417883  
 Tel: 68349695

AUTHORISED SIGNATURE

Liability of repairer is limited to the cost of the repair only.

- The repairer is not responsible for any damage to the vehicle or its contents.
- The repairer is not responsible for any damage to the vehicle or its contents.
- The repairer is not responsible for any damage to the vehicle or its contents.
- The repairer is not responsible for any damage to the vehicle or its contents.
- The repairer is not responsible for any damage to the vehicle or its contents.
- The repairer is not responsible for any damage to the vehicle or its contents.
- The repairer is not responsible for any damage to the vehicle or its contents.

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_