

DING AUTO PTE LTD

Blk 10, #01-20

Sin Ming Industrial Est. Sec C

Singapore 575645

Tel: 6452 1208

Fax: 6452 0614

Vehicle:	GBG5275E
Model:	TOYOTA DYNA
Chassis:	

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYORS MARKING
1	REAR TAIL LAMP RH	1	\$ 350.00	25%	\$ CM 262.50	✓
2	REAR TAIL LAMP PANEL RH	1	\$ 320.00	25%	\$ N 240.00	X
3	TAIL GATE	1	\$ 1,575.00	25%	\$ N 1,181.25	X
4	TAIL GATE HINGE RH	1	\$ 120.00	25%	\$ DT 90.00	✓
5	REAR REFLECTOR RH	1	\$ 150.00	25%	\$ CM 112.50	✓
6	REAR LOCK RH	1	\$ 175.00	25%	\$ N 131.25	X
TOTAL:					\$ 2,017.50	

	SPECIAL NETT	QTY	PRICE	SURVEYOR MARKING
1	REVERSE SENSOR	1	\$ JL 250.00	X
2	REAR CAR PLATE	1	\$ B 45.00	2012
3	REAR CAR PLATE HOLDER	1	\$ N 150.00	X
4	70 SPEED LIMIT STICKER	1	\$ M 25.00	1512
5	6 PAX STICKER	1	\$ N 25.00	1512
TOTAL:			\$ 495.00	

	LABOUR	PRICE	SURVEYOR MARKING
1	PANEL BEAT ACCIDENT AREAS	\$ 600.00	301
2	CHECK WIRING	\$ 100.00	201
3	RESPRAY REAR TAIL GATE AND TAIL BED REAR CROSSMEMBER	\$ 600.00	401
TOTAL:		\$ 1,300.00	

PARTS (SGD)	\$ 2,017.50
LABOUR (SGD)	\$ 1,300.00
SPECIAL NETT (SGD)	\$ 495.00
TOTAL (SGD)	\$ 3,812.50
GST 7% (SGD)	\$ 266.88
FINAL TOTAL (SGD)	\$ 4,079.38

Not Authorised
3 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1-B-1

Kennerth
96910663