

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: AXA INSURANCE

Address: NO 8, SHENTON WAY, #24-01
AXA TOWER, S(068811)

Telephone: 68804888

Fax: 68804740

Email motor.survey@axa.com.sg

Make/ Model : HYUNDAI ELANTRA

Vivian

Date: 15.07.2019

Chassis No : KMHDH41CMGU653731

Vehicle No: SKV8315T

Date/Time of Accide 12.07.2019/ 1845

Date of Reg : 03.10.2015

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	BOOTLID <i>Revised</i>	1	\$ 1,023.90		\$ 1,023.90
2	BOOTLID SMART KEY ANTENNA <i>new</i>	1	\$ 236.70		\$ 236.70
3	BOOTLID BOOT RELEASE ANTENNA <i>new</i>	1	\$ 236.70		\$ 236.70
4	BOOTLID INNER TRIM <i>new</i>	1	\$ 326.70		\$ + 326.70
5	BOOTLID REFLECTORS <i>but new Repeated</i>	2	\$ 788.60		\$ 1,577.20
6	BOOTLID EMBLEM "ELANTRA" <i>new</i>	1	\$ 90.30		\$ 90.30
7	BOOTLID LOGO <i>new</i>	1	\$ 75.80		\$ 75.80
8	BOOTLID OUTER HANDLE <i>new</i>	1	\$ 189.80		\$ + 189.80
9	BOOTLID "GLS" EMBLEM <i>new</i>	1	\$ 75.60		\$ 75.60
10	BOOTLID TOP LOCK <i>new</i>	1	\$ 283.10		\$ 283.10
11	BOOTLID LOWER LATCH <i>new</i>	1	\$ 45.20		\$ + 45.20
12	BOOTLID WEATHERSTRIP <i>new</i>	1	\$ 301.20		\$ + 301.20
13	BOOTLID REFLECTORS <i>new</i>	2	\$ 402.60	476.80	\$ 805.20
14	BOOTLID WEATHERSTRIP <i>new cut</i>	1	\$ 187.90		\$ + 187.90
15	BOOTLID HINGES <i>new</i>	2	\$ 86.70		\$ + 173.40
16	REAR BUMPER <i>Revised</i>	1	\$ 605.70	454.80	\$ 605.70
17	REAR BUMPER REFLECTORS <i>new</i>	2	\$ 97.60		\$ + 195.20
18	REAR BUMPER RETAINERS <i>new</i>	2	\$ 68.90		\$ 137.80
19	REAR BUMPER BOTTOM <i>Revised</i>	1	\$ 365.70		\$ 365.70
20	REAR BUMPER REINFORCEMENT <i>Revised</i>	1	\$ 488.90	328	\$ 488.90
21	REAR REINFORCEMENT BRACKETS <i>Revised</i>	2	\$ 69.70		\$ 139.40
22	REAR MUDGUARDS <i>new</i>	2	\$ 89.80		\$ + 179.60
23	REAR BUMPER COVERS <i>new</i>	2	\$ 145.80		\$ + 291.60
24	TAILAMPS <i>new</i>	2	\$ 497.60		\$ + 995.20
25	TAILAMPS PANELS <i>new</i>	2	\$ 498.50		\$ + 997.00
26	REAR FENDER INNER COWLING <i>new</i>	2	\$ 139.80		\$ + 279.60
27	REAR END PANEL <i>Revised</i>	1	\$ 523.40		\$ 523.40
28	REAR END PANEL TOP GARNISH <i>Revised</i>	1	\$ 145.80		\$ 145.80
29	REAR SILENCER BOX <i>new</i>	1	\$ 862.20		\$ + 862.20
30	REAR SILENCER BOX MOUNTING <i>new</i>	2	\$ 85.30		\$ + 170.60
31	REAR FLOOR PANEL <i>Repair</i>	1	\$ 1,055.30		\$ 1,055.30

32	REAR FLOOR PANEL TOP BOARD <i>New</i>	1	\$ 356.10	\$ x 356.10
Total List Price Cost				\$ 13,417.80
				PARTS DISCOUNT 20% \$ 10,734.24

430830
344664

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR NUMBER PLATE WITH CASING <i>New</i>	1 SET	\$ 50.00	\$ + 50.00
2	REAR BUMPER CLIPS <i>Mc</i>	1 SET	\$ 30.00	\$ — 30.00
3	REAR END PANEL TOP GARNISH CLIPS <i>Mc</i>	1 SET	\$ 30.00	\$ 10 30.00
4	REVERSE SENSOR <i>Parag</i>	1 SET	\$ 250.00	\$ 200 250.00
5	REAR FENDER INNER COWLING SET <i>Mc</i>	2 SET	\$ 60.00	\$ + 60.00
6	EMERGENCY SIGN KIT <i>Mc New</i>	1 SET	\$ 200.00	\$ + 200.00
7	END PANEL INSULATOR SEAL <i>New</i>	2	\$ 80.00	\$ 60 80.00
Total Special Nett Items				\$ 700.00

300

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 2,000.00 <i>825</i>
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,800.00 <i>820</i>
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 60 200.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ 60 150.00
TO APPLY SEALANT AND UNDERCOATING TO THE AFFECTED AREAS	\$ 60 350.00
TO REMOVE/ REFIT WIRING CHECKS ON TAILAMPS AND REFLECTORS	\$ 30 120.00
TO CONDUCT WATER LEAKAGE TEST	\$ x 150.00
TO REMOVE/ REPLACE REAR SILENCER BOX	\$ x 120.00
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING	\$ 50 150.00
TO REMOVE AND REPLACE BOOTLID MECHANISM	\$ 60 120.00
Total Others Cost	\$ 1,360.00
GRAND TOTAL	\$ 16,594.24 <i>1920</i>

Adrian Lim
L/S 16/07/15
06 Days.

total: 5666.64

W/S: 4.51C ✓

CAS GARAGE PTE LTD

Person Incharge: Allan

Direct Contact: +65 8782 7541

Email: allangoh.cas@gmail.com

Fax: +65 6509 9501

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: