

INS: CASE OWNER:

CC 4/111 190 12562, U pa3

LKK:  
IDAC:

Surveyor:

Mappus

DOI:

ASSIGNMENT

16/7/19

Date / Time:

16/7/19

Registered in Merimen:

16/7/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

YP9107L

Claim No.:

Name of Insured:

Aroma Chemical Private Limited

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

11/07/19

Place of Accident:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

GBE 7748 E



INSRS:

WSP:

Tel:

Liability:

RMKS:

Linbu



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

GBE 7748 E - X ;  
YP9107L - NA (16/19/07/4406/24 : 009-7/7/19)

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS 8,100.00

( 8

days)

Reduction: 68

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

21/6/2019

Confirm with

Susan

Email ☒

Call ☐

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No. : 27

front to rear

If NO or B 28, Ass. Lia :

Repair Cost:

SS 8,100.00

Loss of Rental (LOR):

SS

-

(

days)

Loss of Use (LOU):

SS

800.00

(580.00 x 10 days)

Loss of Income (LOI):

SS

-

(5

x days)

LOR only ☐ LOU only ☒

LOR + LOU ☐

LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS

7.45

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

8,907.45

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐

Call ☐

Payee 1:

SS

8,907.45

Name 1:

Liu's Brother Auto Engineering Workshop

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 4500.00

COPY SENT  
16/7/19



**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53397931 Tel: 6744-1730 / 731 Fax: 6744-5746 Email: liubro@gmail.com

Invoice/Ref No: GBE7748E190711

**Estimate**

Customer

Page 01 - 02

Name: India International Insurance Pte Ltd

Date: 15-07-19

Address: Motor Claims Department

Vehicle No: GBE7748E

64 Cecil Street #04-00 &amp; #05-00

Model/Make: Toyota Hiace

IOB Building Singapore 049711

Van Turbo 5 DR Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>Body od 1925.10</i>	\$ 2,051.60	
2	Tailgate Lock <i>20/5m</i>	\$ 304.00	
3	Tailgate Rubber <i>twi 395.10</i>	\$ 426.70	
4	Tailgate Inner Trim Board <i>70.1</i>	\$ 165.30	
5	Tailgate Inner Trim Board Clips 1 set <i>all</i>	\$ 50.00	
6	Tailgate Inner Lock <i>shokid</i>	\$ 359.00	
7	Tailgate Suspension 02 pcs (@ \$5335.20) <i>1.1</i>	\$ 670.40	
8	Tailgate "Toyota" Motif <i>all</i>	\$ 70.50	
8	Tailgate "8 PAX" Sticker <i>all</i>	\$ 15.00	SN 105.2
9	Tailgate "70 KM/H" Sticker <i>all</i>	\$ 15.00	SN 105.2
10	Tailgate Windscreen Glass <i>shokid 1205.10</i>	\$ 1,311.30	
11	Tailgate Windscreen Glass Moulding <i>NS</i>	\$ 219.00	
12	Tailgate Windscreen Glass Sealant <i>all</i>	\$ 50.00	SN 405.2
13	Tailgate Wiper Motor <i>1.1</i>	\$ 604.40	
14	Tailgate Wiper Arm <i>1.1</i>	\$ 98.00	
15	Tailgate Wiper Blade <i>1.1</i>	\$ 60.20	
13	Number Plate Lamp 02 pcs (@ \$578.60) <i>1.1</i>	\$ 157.20	
14	Number Plate Outer Garnish <i>Bent/scn</i>	\$ 397.00	
15	Number Plate "Metal" <i>Bent</i>	\$ 35.00	SN 155.2
16	Bumper <i>2.1</i>	\$ 465.00	
17	Bumper Bracket 04 pcs (@ \$34.55 x 4) <i>Bent</i>	\$ 138.20	
18	Bumper Clips 1 set <i>all</i>	\$ 48.00	
19	<i>1 set</i> Bumper Reverse Sensor <i>shokid</i>	\$ 220.00	SN 2005.2
20	<i>1 set</i> Bumper Reverse Camera <i>shokid</i>	\$ 690.00	SN 3005.2
21	Air Garnish <i>1.1</i>	\$ 170.00	
22	Tail Lamp 02 pcs (@ \$5365.10) <i>w/scne 015320</i>	\$ 730.20	
23	Tail Lamp Lower Garnish 02 pcs (@ \$565.10) <i>015320</i>	\$ 130.20	
24	3rd Brake Lamp <i>1.1</i>	\$ 234.20	
25	Floor Panel <i>2</i>	\$ 3,020.00	
26	Floor Panel Beam <i>Bent</i>	\$ 260.00	
27	Floor Panel Top Wooden Board <i>NT</i>	\$ 650.00	SN X
28	End Panel Outer <i>Body od</i>	\$ 566.10	
29	End Panel Inner <i>Body od</i>	\$ 936.20	
30	End Panel Top Plate <i>request</i>	\$ 299.50	
31	End Panel Sealant <i>1.1</i>	\$ 50.00	SN X
32	Spare Tyre Carrier <i>Bent</i>	\$ 289.00	
C/F Balance ---->		\$16,047.10	

Not Authorized  
LKH

16/7/19

4/5 #8100

Take ph. After ng -

Shy.



M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931, Tel: 6741-1730 / 731, Fax: 6744-5746, Email: liusbro@gmail.com

Invoice/Ref No: GBE7748E190711

**Estimate**

Customer

Page 02 - 02

Name: India International Insurance Pte Ltd

Date: 15-07-19

Address: Motor Claims Department

Vehicle No: GBE7748E

64 Cecil Street #04-00 &amp; #05-00

Model/Make: Toyota Hiace

IOB Building Singapore 049711

Van Turbo 5 DR Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance ---->	\$16,047.10	
32	Rear Rh Fender (Body Panel) <i>2R</i>	\$ 1,308.10	<i>X</i>
33	Fender Inner Panel <i>2R</i>	\$ 1,069.10	<i>X</i>
34	Tail Lamp Panel <i>Body 2R</i> <i>408.10</i> <i>(252)</i>	\$ 936.20	<i>X</i>
35	Corner Panel Garnish <i>11</i>	\$ 376.50	<i>X</i>
36	Corner Panel Bracket <i>11</i>	\$ 166.50	<i>X</i>
	"Corporate" Advertisement & Artwork <i>rel</i>	\$ 300.00	<i>SN 180 S.W</i>
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	<i>60</i>
	To check all wiring & electrical component for proper function	\$ 80.00	<i>30</i>
	Remove and refix rear bumper <b>reverse sensor</b>	\$ 80.00	<i>50</i>
	Remove and refix rear bumper <b>Reverse Camera</b>	\$ 120.00	<i>✓</i>
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 120.00	<i>111 X</i>
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 300.00	<i>1400</i>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$2,500.00	<i>1000</i>
	To putty & spray painting & including touch up paint on accident affected	\$ 1,800.00	<i>✓</i>
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	<i>✓</i>

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 25,363.50

Total amount in Lump Sum Basis for repaired vehicle

SDLS: Four Thousand Five Hundred Only



M/s Liu's Brother Auto Engrg Wks

8867.9  
 252  
 8615.92  
 S.W - 750.00  
 10hr - 2740.00  
 10145.92  
 207  
 8116.73

< > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company  
Owner ID: 1196N

Vehicle Details

Vehicle No.: GBE7748E  
Vehicle to be Exported: No  
Intended Deregistration Date: 15 Jul 2019  
Vehicle Make: TOYOTA  
Vehicle Model: TOYOTA HIACE VAN TURBO 3 DR  
MANUAL

Primary Colour: Silver  
Manufacturing Year: 2016  
Engine No.: 1KD2596281  
Chassis No.: JTFHT02PX00191566  
Maximum Power Output: -  
Open Market Value: \$27,741.00  
Original Registration Date: 21 Mar 2016  
First Registration Date: 21 Mar 2016  
Transfer Count: 1  
Actual ARF Paid: \$1,388.00

Intended PARF Rebate Details

PARF Eligibility: No  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 20 Mar 2026  
COE Category: C - Goods Vehicle & Bus  
COE Period(Years): 10  
QP Paid: \$46,502.00  
COE Rebate Amount: \$31,063.00  
Total Rebate Amount: \$31,063.00

The information contained herein is correct as at 15 Jul 2019

OK

 > **Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 1196N

**Vehicle Details**

Vehicle No.: GBE7748E

Vehicle to be Exported: No

Intended Dereistration Date: 16 Jul 2019

Vehicle Make: TOYOTA

Vehicle Model: TOYOTA HIACE VAN TURBO 5 DR  
MANUAL

Primary Colour: Silver

Manufacturing Year: 2016

Engine No.: 1KD2596281

Chassis No.: JTFHT02PX00191566

Maximum Power Output: -

Open Market Value: \$27,741.00

Original Registration Date: 21 Mar 2016

First Registration Date: 21 Mar 2016

Transfer Count: 1

Actual ARF Paid: \$1,388.00

**Intended PARF Rebate Details**

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 20 Mar 2026

COE Category: C - Goods Vehicle &amp; Bus

COE Period(Years): 10

QP Paid: \$46,502.00

COE Rebate Amount: \$31,051.00

**Total Rebate Amount: \$31,051.00**

The information contained herein is correct as at 16 Jul 2019

OK

SAVE \$\$ ON UR CAR

INSURANCE RENEWAL

Compare  
10+ Insurers

CLICK HERE &gt;

Post an Advertisement  
Sell it yourself Advertise it at just  
**\$58 until it's SOLD!**

Classic Offer! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan, Trade In Are  
Welcome, 100% Deposit Refund  
For Unapproved Loan,  
Classic Credit StarAd



Post an Ad

Advertiser Login

Ways of Selling

Browse by Category 








&lt; Back ( 1 2 ) Next &gt;

Sort by Date Posted  20 results/page 

31 vehicles

hiace

Advanced Search  Submit 

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	hiace		Any	Any	2016	Any	Any	Any	Available
	Toyota	Hiace 3.0M	\$60,000	\$8,330 /yr	28-Sep-2016	2,982 cc	-	Van	Available
<b>Fuel Type:</b> Diesel Toyota Hiace High Roof Cargo Van With Low Mileage, Well Maintained Interior And Exterior, Front And Reverse Camera Included. Loan... I-Deal Auto Trading Pte Ltd Posted: 15-Jul-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota	Hiace 3.0M	\$55,800	\$7,820 /yr	01-Sep-2016	2,982 cc	-	Van	Available
<b>Fuel Type:</b> Diesel \$3500 Drive Away! 100% Loan No Gemmick With Low Interest. High Trade In Private /commercial Vehicle. Monthly At \$852 Only. Come... Car (S) Pte Ltd Posted: 15-Jul-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota	Hiace 3.0M DX	\$53,800	\$7,680 /yr	18-Jul-2016	2,982 cc	72,235 km	Van	Available
<b>Fuel Type:</b> Diesel Toyota Hiace Manual Rear Aircon, 3 Days Delivery, Super Low Miles, No Need Repairs, \$0 Drive Away, Cash Rebate, High Loan With Lo... ABWIN Bus Pte Ltd Posted: 15-Jul-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota	Hiace 3.0M	\$52,800	\$7,330 /yr	28-Sep-2016	2,982 cc	51,000 km	Van	Available
<b>Fuel Type:</b> Diesel 100% Loan At \$832 Monthly! Cheapest In Market! Guaranteed One Of The Best Condition! Original Tip Top Condition With No Repairs N... Car (S) Pte Ltd Posted: 15-Jul-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	<b>Toyota Camry takes on Volkswagen's Passat</b> The Toyota Camry offers more legroom for rear passengers, is sportier around corners and has more safety systems but the Volkswagen Passat is more affordable and feels more premium overall. Find out more!								
	Toyota	Hiace 3.0A DX	\$55,800	\$8,250 /yr	21-Apr-2016	2,982 cc	70,500 km	Van	Available
<b>Fuel Type:</b> Diesel 1 Owner, Rare 5 Door, Toyota Hiace 3.0 Auto Transmission With Rear Aircon. Up To Full Loan Avail, Monthly At Only \$875. Powerful An... Car (S) Pte Ltd Posted: 15-Jul-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota	Hiace 3.0M DX	\$51,800	\$7,340 /yr	04-Aug-2016	2,982 cc	-	Van	Available
<b>Fuel Type:</b> Diesel Look Here! Best Selling Van On Sale! Comes With Rear Aircon System. Very Good Condition. Wear And Tear Parts Been Replaced With... ABWIN (1994) Pte Ltd Posted: 15-Jul-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									

Compare

**Shiau Chan (LKKAUTO)**

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Tuesday, 16 July 2019 9:22 AM  
**To:** Liu's Brother; SUR; Admin-D (LKKAUTO)  
**Cc:** Lalitha Krishnan - III  
**Subject:** RE: Request for 3rd party claims survey GBE7748E Claims against YP9107L  
**Attachments:** GBE7748E190711.pdf; GBE7748E Search.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle GBE7748E and let us have your report urgently.

This claim will be handled by Ms Lalitha.

\*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

P: Susan

T: 9.35a.m

V: 1h

E: ✓

---

**From:** Liu's Brother [mailto:liusbro@ymail.com]  
**Sent:** 15 July, 2019 9:41 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Subject:** Re: Request for 3rd party claims survey GBE7748E Claims against YP9107L

We did like to chose as follow

- LKK Auto Consultants Pte Ltd

Kindly arrange

Thank

Best Regard

Susan Low

M/s Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit

Singapore 417883 ☎: 6741 1730 📠: 6744 5746

On 15 Jul 2019, at 17:23, Motor Claim - III <motorclaim@iii.com.sg> wrote:



## LKK Auto Consultants Pte Ltd

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

### DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	16 Jul 2019 17:44	Cim Dtl Modified	Claimant's Name: -> GOLDBELL LEASING PTE LTD. Claimant's ID: -> 199001196N.	[A] HOW MEI KWAN
2	16 Jul 2019 17:44	Cim Veh Model Changed	(204531) TOYOTA HIACE 3.0 D TURBO 5 DR (M).	[A] HOW MEI KWAN
3	16 Jul 2019 17:44	Cim Created	Reg No: GBE7748E. Acct Date: 2019/07/11. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: M5 First Capital Insurance Ltd (HQ). Workshop: Liu's Brother Auto Engineering Workshop (HQ)	[A] HOW MEI KWAN
4	16 Jul 2019 17:44	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	16 Jul 2019 17:44	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/25	[A] HOW MEI KWAN
6	16 Jul 2019 17:44	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] HOW MEI KWAN
7	16 Jul 2019 17:44	Label Added	(30653):Direct Settlement.	[A] HOW MEI KWAN
8	16 Jul 2019 17:44	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] HOW MEI KWAN
9	25 Jul 2019 14:19	Cim Dtl Modified	Insured Name: -> AROMA CHEMICAL PRIVATE LIMITED.	[A] HOW MEI KWAN
10	07 Aug 2019 11:47	Adj Mandate Request	Cur,Req:0.00:PODS Liability: 100% Remarks: Insured driver rear-ended third party	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type

None

Go

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2214869	17/07/2019 08:41	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	GBE7748E	YP9107L	11.77

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	16 Jul 2019 17:44	Cim Dtl Modified	Claimant's Name: -> GOLDBELL LEASING PTE LTD, Claimant's ID: -> 199001196N,	[A] HOW MEI KWAN
2	16 Jul 2019 17:44	Cim Veh Model Changed	(204531) TOYOTA HIACE 3.0 D TURBO 5 DR (M).	[A] HOW MEI KWAN
3	16 Jul 2019 17:44	Cim Created	Reg No: GBE7748E. Acct Date: 2019/07/11. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: MS First Capital Insurance Ltd (HQ). Workshop: Liu's Brother Auto Engineering Workshop (HQ)	[A] HOW MEI KWAN
4	16 Jul 2019 17:44	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ);	[A] HOW MEI KWAN
5	16 Jul 2019 17:44	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/25	[A] HOW MEI KWAN
6	16 Jul 2019 17:44	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
7	16 Jul 2019 17:44	Label Added	(30653):Direct Settlement.	[A] HOW MEI KWAN
8	16 Jul 2019 17:44	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] HOW MEI KWAN
9	25 Jul 2019 14:19	Cim Dtl Modified	Insured Name: -> AROMA CHEMICAL PRIVATE LIMITED.	[A] HOW MEI KWAN
10	07 Aug 2019 11:47	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remarks: Insured driver rear-ended third party	[A] CHEW HSIAO TONG
11	07 Aug 2019 14:31	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/25	[I] Lalitha Krishnan
12	07 Aug 2019 14:31	Adj Mandate Set	Approved:0.00.	[I] Lalitha Krishnan

Date From

Date To

Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2214869	17/07/2019 08:41	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	GBE7748E	YP9107L	11.77

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	16 Jul 2019 17:44	Cim Dtl Modified	Claimant's Name: -> GOLDBELL LEASING PTE LTD. Claimant's ID: -> 199001196N.	[A] HOW MEI KWAN
2	16 Jul 2019 17:44	Cim Veh Model Changed	(204531) TOYOTA HIACE 3.0 D TURBO 5 DR (M).	[A] HOW MEI KWAN
3	16 Jul 2019 17:44	Cim Created	Reg No: GBE7748E. Acct Date: 2019/07/11. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: MS First Capital Insurance Ltd (HQ). Workshop: Liu's Brother Auto Engineering Workshop (HQ)	[A] HOW MEI KWAN
4	16 Jul 2019 17:44	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	16 Jul 2019 17:44	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/25	[A] HOW MEI KWAN
6	16 Jul 2019 17:44	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
7	16 Jul 2019 17:44	Label Added	(30653):Direct Settlement.	[A] HOW MEI KWAN
8	16 Jul 2019 17:44	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] HOW MEI KWAN
9	25 Jul 2019 14:19	Cim Dtl Modified	Insured Name: -> AROMA CHEMICAL PRIVATE LIMITED.	[A] HOW MEI KWAN
10	07 Aug 2019 11:47	Adj Mandate Request	Cur.Reg:0.00:PODS Liability: 100% Remarks: Insured driver rear-ended third party	[A] CHEW HSIAO TONG
11	07 Aug 2019 14:31	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/25	[I] Lalitha Krishnan
12	07 Aug 2019 14:31	Adj Mandate Set	Approved:0.00.	[I] Lalitha Krishnan
13	21 Aug 2019 10:09	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
14	21 Aug 2019 10:09	Cim Dtl Modified	Insured ID: -> -.	[A] JOANNE LEE KHANG MIN
15	21 Aug 2019 10:09	Cim Dtl Modified	JPJ Reg. Date: -> 2016/03/21.	[A] JOANNE LEE KHANG MIN
16	21 Aug 2019 10:09	Cim Details Notified		[A] JOANNE LEE KHANG MIN
17	22 Aug 2019 13:44	Adj Mandate Request	Cur.Reg:8907.45:PODS Liability: 100% Quantum: a)COR : \$8,100.00 + b)LOU: \$800.00 (10 days x\$80.00) +c) LTA: \$7.45 = Total \$8,907.45 Vehicle Model: Toyota HIACE 3.0 TURBO (2982cc) For your approval	[A] Chong Poh Kin

Date From



Date To



Audit Type

None

Go

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
-------------	-----------	----------	----------	------------------	-------	-------	--------

## Print Received Message

This mail is associated with :

**\*GBE7748E (MFL2019D0000779)**  
**[YP9107L]**

TP

GOLDBELL LEASING PTE LTD

Jul 11 2019 2:00PM

[AROMA CHEMICAL PRIVATE LIMITED]

Liu's Brother Auto Engineering Workshop

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 22/08/2019 14:27 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$8907.45) - GBE7748E - Claim Handler: Lalitha Krishnan

Approved:8907.45.

## Poh Kin (LKKAuto)

---

**From:** Poh Kin (LKKAuto)  
**Sent:** Tuesday, 27 August 2019 11:08 AM  
**To:** liusbro@ymail.com; Hsiao Tong (LKKAuto)  
**Cc:** Admin A  
**Subject:** ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. YP 9107L AND GBE 7748E ON 11.07.2019  
**Attachments:** DV GBE 7748E.pdf  
**Importance:** High

### WITHOUT PREJUDICE SAVE AS TO COSTS

Our Ref: CC4/III19012562/Upa3  
Your Ref: GBE7748E190711

Dear Susan,

### ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. YP 9107L AND GBE 7748E ON 11.07.2019

We refer to the above matter and your letter of demand dated 28.07.2019.

We hereby confirmed settlement as below:

1. Cost of Repair	S\$ 8,100.00
2. Loss of Use (\$80.00 x 10 days)	S\$ 800.00
3. LTA search	<u>S\$ 7.45</u>
	<u><b>S\$ 8,907.45</b></u>

Please duly sign the DV attached and return with **Authorization to ACT** to us (LKK) for payment processing.

We need **original copy DV**.

Your prompt action will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Our Ref: GBE7748E190711

Date: 28/07/2019

Your Ref:

India International Insurance Pte Ltd  
64 Cecil Street #04 / #05  
IOB Building  
Singapore 049711  
Attn: Motor Claims Department

Dear Sir / Madam

TRAFFIC ACCIDENT ALONG Tuas South Avenue 7  
INVOLVING GBE7748E AND YP9107L ON 11/07/2019

We/I, **Messers Goldbell Leasing Pte Ltd** (Nric / ROC No: **199001196N**), the registered owners of m/vehicle - GBE7748E at all material times of the above accident. Our/my vehicle was surveyed by "India Int'l" authorized appraiser and we/I based our/my claims on his recommendation for S\$ 8,100-00 being the repair for 08 Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle YP9107L when the same was involved in the aforesaid accident with our/my m/vehicle - GBE7748E.

We/I whereby you are the insurers of m/vehicle YP9107L and the driver / owner was caused solely by the negligence of your insured and as a result thereof our / my m/vehicle - GBE7748E has suffered loss and damage as follows:

(a) Cost of repairs	S\$	<u>8,100-00</u>
(b) LOU for pre-repair notice <u>02</u> days @ S\$ 80-00 [2982 cc]		<u>160-00</u>
(c) LOU Fee for <u>08</u> days @ S\$ 80-00 [2982 cc]		<u>640-00</u>
(d) GIA / LTA search fee		<u>7-45</u>
(e)		
<b>Total Amount</b>	<b>S\$</b>	<b><u>8,907-45</u></b>

We/I enclose herewith copies of the supporting documents for vehicle no. GBE7748E as follows:-

- (i) Motor Accident Report;
- (ii) Repair Invoices and documents;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu's Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,



The owner of m/vehicle GBE7748E  
Messers Goldbell Leasing Pte Ltd  
cc. Liu's Bro Auto Engrg Ws

## Authorization To Act

**Attn: Motor Claims Department**

India International Insurance Pte Ltd  
64 Cecil Street #04 / #05  
IOB Building  
Singapore 049711

I / We, Messers Goldbell Leasing Pte Ltd ("the third party claimant") of No. 18 Tuas Avenue 10 Singapore 639142 (address), owner of GBE7748E (vehicle no.) hereby authorize Liu's Brother Auto Engineering Workshop ("the workshop") to act for me / us with respect to my / our claim for repair costs and / or rental and / or loss of use ("claim") for my / our vehicle no. GBE7748E that was damaged pursuant to the accident which occurred on 11/07/2019 (date) along Tuas South Avenue 7 (location) involving YP9107L ("the accident").

I / We further authorize the workshop to settle my / our above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my / our claim with payment cheque / s being made in favour of the workshop.

I / We further acknowledge that any settlement the workshop may reach on my / our behalf is on a without prejudice and without admission of liability basis insofar as the driver / owner / insurers of the other vehicle / s is concerned.

Dated this 4th day of September (month) 20 19 (year)

3<sup>rd</sup> Party Claimant:

Workshop:

Signature: 

Signature: 

Name: Goldbell Leasing Pte Ltd

Name: Liu's Brother Auto Engrg Workshop

Address: No. 18 Tuas Avenue 10

Address: 1 Kaki Bukit Avenue 6 #01-01

Singapore 639142

AutoBay @ Kaki Bukit

Singapore 417883

Nric/ROC No: 199001196N

ROB No: 53291793J



## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: TP / MFL2019D0000779  
Claimant Ref: GBE7748E190711

We/I, Liu's Brother Auto Engineering Workshop ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 8,100.00 (repair cost), S\$ 800.00 (loss of use/rental), S\$ 7.45 (search fee), vehicle no. GBE 7748E that was damaged pursuant to the accident which occurred on 11/07/2019 (date) at TUAS SOUTH AVENUE 7 (location) involving vehicle no. YP 8107L (insured vehicle). This is pursuant to the inspection conducted on 16/07/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Goldbell Leasing Pte Ltd ("the third party claimant") of vehicle no. GBE 7748E to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to GBE 7748E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 8,907.45 to Liu's Brother Auto Engineering Workshop.

Dated this 4th day of September 20 19.

#### CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

Liu's Brother Auto Engineering Workshop

NRIC:

ROB No. 53291793J

Address:

No. 1 Kaki Bukit Avenue 6 #01-01  
AutoBay @ Kaki Bukit Singapore 417883

Nationality:

Occupation:

#### WITNESS:

Signature:

Signed by appointed Surveyor

Name:

LKK Auto Consultants Pte Ltd

NRIC:

1996071982

Address:

51 Ubi Ave 1 #4-25  
Paya Ubi Industrial Park  
(S140893)

Nationality:

Occupation:



cks.

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbrog@gmail.com

Invoice/Ref No: GBE7748E190711

**Final Bill**

Customer	Page 01 - 02
Name: India International Insurance Pte Ltd	Date: 28-07-10
Address: Motor Claims Department	Vehicle No: GBE7748E
64 Cecil Street #04-00 & #05-00	Model/Make: Toyota Hiace
IOB Building Singapore 049711	Van Turbo 5 DR Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate	\$ 2,051.60	\$ -
2	Tailgate Lock	\$ 394.90	\$ -
3	Tailgate Rubber	\$ 426.70	\$ -
4	Tailgate Inner Trim Board	\$ 165.30	\$ -
5	Tailgate Inner Trim Board Clips 1 set	\$ 50.00	SN \$ -
6	Tailgate Inner Lock	\$ 359.00	\$ -
7	Tailgate Suspension 02 pcs (@ \$335.20)	\$ 670.40	\$ -
8	Tailgate "Toyota" Motif	\$ 70.50	\$ -
8	Tailgate "8 PAX" Sticker	\$ 15.00	SN \$ -
9	Tailgate "70 KM/H" Sticker	\$ 15.00	SN \$ -
10	Tailgate Windscreen Glass	\$ 1,311.30	\$ -
11	Tailgate Windscreen Glass Moulding	\$ 219.00	\$ -
12	Tailgate Windscreen Glass Sealant	\$ 50.00	SN \$ -
13	Tailgate Wiper Motor	\$ 604.40	\$ -
14	Tailgate Wiper Arm	\$ 98.00	\$ -
15	Tailgate Wiper Blade	\$ 60.20	\$ -
13	Number Plate Lamp 02 pcs (@ \$578.60)	\$ 157.20	\$ -
14	Number Plate Outer Garnish	\$ 397.00	\$ -
15	Number Plate "Metal"	\$ 35.00	SN \$ -
16	Bumper	\$ 465.00	\$ -
17	Bumper Bracket 02 pcs (@ \$569.10)	\$ 138.20	\$ -
18	Bumper Clips 1 set	\$ 48.00	SN \$ -
19	Bumper Reverse Sensor	\$ 220.00	SN \$ -
20	Bumper Reverse Camera	\$ 690.00	SN \$ -
21	Air Garnish	\$ 170.00	\$ -
22	Tail Lamp 02 pcs (@ \$365.10)	\$ 730.20	\$ -
23	Tail Lamp Lower Garnish 02 pcs (@ \$65.10)	\$ 130.20	\$ -
24	3rd Brake Lamp	\$ 234.20	\$ -
25	Floor Panel	\$ 3,020.00	\$ -
26	Floor Panel Beam	\$ 260.00	\$ -
27	Floor Panel Top Wooden Board	\$ 650.00	SN \$ -
28	End Panel Outer	\$ 566.10	\$ -
29	End Panel Inner	\$ 936.20	\$ -
30	End Panel Top Plate	\$ 299.50	\$ -
31	End Panel Sealant	\$ 50.00	SN \$ -
32	Spare Tyre Carrier	\$ 289.00	\$ -
C/F Balance -->		\$ 16,047.10	\$ -



M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 - Tel: 6741-1730 / 731 - Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBE7748E190711

**Final Bill**

Customer		Page 02 - 02
Name:	India International Insurance Pte Ltd	Date: 28-07-19
Address:	Motor Claims Department	Vehicle No: GBE7748E
	64 Cecil Street #04-00 & #05-00	Model/Make: Toyota Hiace
	IOB Building Singapore 049711	Van Turbo 5 DR Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance —>	\$ 16,047.10	\$ -
32	Rear Rh Fender (Body Panel)	\$ 1,308.10	\$ -
33	Fender Inner Panel	\$ 1,069.10	\$ -
34	Tail Lamp Panel	\$ 936.20	\$ -
35	Corner Panel Garnish	\$ 376.50	\$ -
36	Corner Panel Bracket	\$ 166.50	\$ -
	"Corporate" Advertisement & Artwork	\$ 300.00	SN \$ -
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	\$ -
	To check all wiring & electrical component for proper function	\$ 80.00	\$ -
	Remove and refix rear bumper reverse sensor	\$ 80.00	\$ -
	Remove and refix rear bumper Reverse Camera	\$ 120.00	\$ -
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 120.00	\$ -
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 300.00	\$ -
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 2,500.00	\$ -
	To putty & spray painting & including touch up paint on accident affected	\$ 1,800.00	\$ -
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	\$ -

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 25,363.50

Total amount in Lump Sum Basis for repaired vehicle

\$ 8,100.00

SDLS: Eight Thousand One Hundred Only



M/s Liu's Brother Auto Engrg Wks

> Back to OneMotoring



Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701  
GST Registration No. : M4-0006529-2

Print Date/Time : 15 Jul 2019 / 10:51:47  
Receipt Date/Time : 15 Jul 2019 / 10:51:47

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190715-000650  
Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - YP9107L As at 11 Jul 2019/14:45:00 Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - YP9107L Enquiry Fee 20190715105013408976	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	0000000000004559 Credit Card Visa/MasterCard			7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement












































## CLAIM SUBFOLDER TRACKING























































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jul 2019 <a href="#">Edit Reg</a>		16 Jul 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$58,100.00</b> <a href="#">Edit Estimates</a>	<b>\$58,100.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>AROMA CHEMICAL PRIVATE LIMITED</b> , Co. Reg. No.: -								
Main Claimant:	<b>GOLDBELL LEASING PTE LTD</b> , Co. Reg. No.: 199001196N								
Vehicle Reg. No.:	<b>GBE7748E</b>	Date of Loss:	11/07/2019 14:00 - :59 [39 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MFL2019D0000779</b>	Policy/Cover Note No.:	D19MFL0001083						
Vehicle Reg. No. (Insured):	<b>YP9107L</b>	Policy No. (Claimant):	D-18090757MFCV						
		Excess:							
Repairer:	<b>Liu's Brother Auto Engineering Workshop (HQ)</b> BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Lalitha Krishnan</b> - 6347 6139]								
Claimant's Insurer:	<b>MS First Capital Insurance Ltd (HQ)</b> - Tel: 62222311								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 25/07/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>III_SG (22/08/2019): Alert - Adj Mandate Approved (\$58907.45) - GBE7748E - Claim Handler: Lalitha Kri...</li> <li>III_SG (07/08/2019): Alert - Adj Mandate Approved (\$50.00) - GBE7748E - Claim Handler: Lalitha Krishn...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBE7748E (MFL2019D0000779)  
[YP9107L]  
TP  
GOLDBELL LEASING PTE LTD  
Jul 11 2019 2:00PM  
[AROMA CHEMICAL PRIVATE LIMITED]  
Liu's Brother Auto Engineering Workshop

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/08/19 11:46	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
3	07/08/19 11:46	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
4	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
5	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
6	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
7	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
8	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
9	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
10	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
11	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
12	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
13	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
14	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
15	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
16	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
17	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
18	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
19	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
20	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
21	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
22	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
23	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
24	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
25	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
26	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
27	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
28	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
29	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
30	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
31	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
32	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
33	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
34	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
35	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
36	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
37	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
38	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
39	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
40	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
41	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
43	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
44	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
45	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
46	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
47	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
48	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
49	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
50	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
51	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
52	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
53	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
54	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
55	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
56	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
57	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
58	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
59	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
60	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
61	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
62	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
63	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
64	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
65	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
66	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
67	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
68	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
69	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
70	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
71	07/08/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>	
72	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
73	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
74	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
75	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
76	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
77	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
78	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
79	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
80	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
81	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
82	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
83	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
84	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
85	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
86	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
87	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
88	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
89	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
90	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
91	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
92	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
93	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
94	07/08/19 11:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	16/07/19 17:45	EMAIL FROM III DD 16.07.2019	 Load PDF		
2	16/07/19 17:45	LTA Search	 Load PDF		
3	16/07/19 17:45	TP GIA REPORT	 Load PDF		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
4	26/07/19 17:06	TP ESTIMATE-MARKED		Load PDF	
5	21/08/19 10:23	WORKSHOP INVOICE		Load PDF	
6	21/08/19 10:23	LTA SEARCH		Load PDF	
7	21/08/19 10:23	LOD		Load PDF	
8	19/09/19 11:43	AUTHORISATION TO ACT FORM		Load PDF	
9	19/09/19 11:43	DISCHARGE VOUCHER		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	17/07/19 08:41	Singapore Accident Statement		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19012562/UPA3Q2

Date: 19/09/2019

## REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0001083
Claimant Vehicle No :	GBE7748E	Insured Vehicle No :	YP9107L
Date of Loss:	11/07/2019	Nature of Claim:	TP
		Claim No:	MFL2019D0000779

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	GBE7748E		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No:	1KD2596281
Reg. Date:	21/03/2016 (Man. Year: 2016)	Chassis No:	JTFHT02PX00191566
Colour:	White	Odometer:	92083 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,203.50	7,405.92	12,797.58	63.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,160.00	2,740.00	2,420.00	46.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>25,363.50</b>	<b>10,145.92</b>	<b>15,217.58</b>	<b>60.00</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>25,363.50</b>	<b>8,100.00</b>	<b>17,263.50</b>	<b>68.06</b>
<b>+ Loss of Use (10.0 x S\$80.00/day) (S\$)</b>		800.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>8,907.45</b>		

## INSPECTION

Date of Assignment:	16/07/2019
Date Inspected:	16/07/2019 Inspected At:

Liu's Brother Auto Engineering  
Workshop (HQ)  
BLK 1 KAKI BUKIT AVE 6, #01-01  
AUTO BAY @ KAKI BUKIT  
Singapore 417883

Estimated Period of Repair: 8.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Aug 2019)
<b>Parts:</b>	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBE7748E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	2,051.60 F	*1,925.10 FL
2	1		*REAR TAILGATE LOCK	Dented / Jammed	394.90 F	*394.90 FL
3	1		*REAR TAILGATE RUBBER	Twisted	426.70 F	*395.10 FL
4	1		*REAR TAILGATE INNER TRIM BOARD	Torn	165.30 F	*165.30 FL
5	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
6	1		*REAR TAILGATE INNER LOCK	Shorted	359.00 F	*359.00 FL
7	2		*REAR TAILGATE SUSPENSION	Not Necessary	670.40 F	*- FL
8	1		*REAR TAILGATE TOYOTA MOTIF	Necessary	70.50 F	*70.50 FL
9	1		*REAR TAILGATE 8PAX STICKER	Necessary	15.00 FS	*10.00 FS
10	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
11	1		*REAR TAILGATE WINDSCREEN GLASS	Shattered	1,311.30 F	*1,205.10 FL
12	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	No such part	219.00 F	*- FL
13	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
14	1		*REAR TAILGATE WIPER MOTOR	Not Necessary	604.40 F	*- FL
15	1		*REAR TAILGATE WIPER ARM	Not Necessary	98.00 F	*- FL
16	1		*REAR TAILGATE WIPER BLADE	Not Necessary	60.20 F	*- FL
17	2		*REAR NUMBER PLATE LAMP	Not Necessary	157.20 F	*- FL
18	1		*REAR NUMBER PLATE OUTER GARNISH	Bent / Scratched	397.00 F	*397.00 FL
19	1		*REAR NUMBER PLATE METAL	Bent	35.00 FS	*15.00 FS
20	1		*REAR BUMPER	Distorted	465.00 F	*465.00 FL
21	4		*REAR BUMPER BRACKET	Bent	138.20 F	*138.20 FL
22	1		*SET REAR BUMPER CLIPS	Necessary	48.00 F	*48.00 FL
23	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
24	1		*SET REAR BUMPER REVERSE CAMERA	Shorted	690.00 FS	*300.00 FS
25	1		*REAR AIR GARNISH	Not Necessary	170.00 F	*- FL
26	2		*REAR TAIL LAMP	N/S Cracked / O/S Broken	730.20 F	*730.20 FL
27	1		*REAR TAIL LAMP LOWER GARNISH	O/S Dented	130.20 F	*65.10 FL
28	1		*REAR 3RD BRAKE LAMP	Not Necessary	234.20 F	*- FL
29	1		*REAR FLOOR PANEL	Repair	3,020.00 F	*- FL
30	1		*REAR FLOOR PANEL BEAM	Bent	260.00 F	*260.00 FL
31	1		*REAR FLOOR PANEL TOP WOODEN BOARD	Not fitted	650.00 FS	*- FS
32	1		*REAR END PANEL OUTER	Badly Dented	566.10 F	*566.10 FL
33	1		*REAR END PANEL INNER	Badly Dented	936.20 F	*936.20 FL
34	1		*REAR END PANEL TOP PLATE	Repeated	299.50 F	*- FL
35	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
36	1		*REAR SPARE TYRE CARRIER	Bent	289.00 F	*289.00 FL
37	1		*REAR RH FENDER (BODY PANEL)	Repair	1,308.10 F	*- FL
38	1		*REAR RH FENDER INNER PANEL	Repair	1,069.10 F	*- FL
39	1		*REAR RH TAIL LAMP PANEL	Badly Dented	936.20 F	*408.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR RH CORNER PANEL GARNISH	Not Necessary	376.50 F	*- FL
41	1		*REAR RH CORNER PANEL BRACKET	Not Necessary	166.50 F	*- FL
42	1		*CORPORATE ADVERTISEMENT & ARTWORK	Necessary	300.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>20,203.50</b>	<b>9,622.90</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$)</b>	<b>0.00</b>	<b>2,216.98</b>

<b>Total Parts (\$)</b>	<b>20,203.50</b>	<b>7,405.92</b>
-------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE AND REFIX TAILGATE COMPONENTS & WIPER MECHANISM	New	80.00	80.00
2	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	30.00
3	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	80.00	50.00
4	REMOVE AND REFIX REAR BUMPER REVERSE CAMERA	New	120.00	0.00
5	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS	New	120.00	120.00
6	TO REMOVE & REFIX AIR CON ,RE-FILL AIR CON GAS & TEST FOR LEAKAGES	New	300.00	0.00
7	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	2,500.00	1,400.00
8	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	1,800.00	1,000.00
9	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	80.00
Gross Labour Cost (\$\$)			<b>5,160.00</b>	<b>2,740.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >