

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/07/2019 15:36
Date Of Accident	15/07/2019 08:50
Exact Location Of Accident	29/31 TOH HEIGHTS CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS29M
Insured/Policyholder	
Name Of Registered Owner	LEONG JIAQUAN, BENJAMIN
NRIC No	S8509274Z
Email Address	BENJAMINLEONG85@ROCKETMAIL.COM
Mobile Phone No	(LOCAL) +65-90120029
Alternative Phone No	OFFICE-90120029

Vehicle Particulars

Manufacturer	AUDI
Model	RS6 AVANT 4.0 TFSI QUATTRO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D-18091577MVPC/1
Cover Note Number	

Driver

Name of Driver	LEONG JIAQUAN, BENJAMIN
NRIC No	S8509274Z
Date Of Birth	21/03/1985
Occupation	INDOOR
Date Of Driving Pass	01/04/2004
Driving Experience	15 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90120029
Fax Number	
Contact Number	OFFICE-90120029
E-Mail Address	BENJAMINLEONG85@ROCKETMAIL.COM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/07/2019 15:36
Date Of Accident	15/07/2019 08:50
Exact Location Of Accident	29/31 TOH HEIGHTS CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS29M
-----------------------------	--------

Insured/Policyholder

Name Of Registered Owner	LEONG JIAQUAN, BENJAMIN
NRIC No	S8509274Z
Email Address	BENJAMINLEONG85@ROCKETMAIL.COM
Mobile Phone No	(LOCAL) +65-90120029
Alternative Phone No	OFFICE-90120029

Vehicle Particulars

Manufacturer	AUDI
Model	RS6 AVANT 4.0 TFSI QUATTRO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	YES
--	-----

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D-18091577MVPC/1
Cover Note Number	

Driver

Name of Driver	LEONG JIAQUAN, BENJAMIN
NRIC No	S8509274Z
Date Of Birth	21/03/1985
Occupation	INDOOR
Date Of Driving Pass	01/04/2004
Driving Experience	15 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90120029
Fax Number	
Contact Number	OFFICE-90120029
EMail Address	BENJAMINLEONG85@ROCKETMAIL.COM

Address	31 TOH HEIGHTS
Postcode	507838
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN ATTACHED: NOTE: VEHICLE NOT PRESENT WHEN ACCIDENT REPORT LODGE. PHOTO BY OWNER HANDPHONE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJA29U
Vehicle Make/Model/Colour	BENTLEY / NEW FLYING SPUR W12
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SFG29K
-----------------------------	--------

Vehicle Make/Model/Colour TOYOTA / ALPHARD MOONROOF CVT
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number
Vehicle Make/Model/Colour
Details Of Properties ELECTRIC BOX
Vehicle Category NA/UNKNOWN
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 15/07/19

3.55pm



Driver's Signature

(If driver is not the policyholder)

Date & Time:

15 JUL 2019

IDAC KAKI BUKIT (VAC)

Reporting Centre: 23 Kaki Bukit Ave 4


Name: Singapore 415933

NRIC/TEL: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

CAR F, BENTLEY FLYING SPUR W12, SKS 29 M WAS REVERSING INTO THE GARAGE. WHEN ENGAGED ON REVERSE GEAR, SUDDENLY THE DOOR SWUNG OPEN ON DRIVER SIDE AND STARTED REVERSING VERY QUICKLY. IT WAS NOT ABLE TO STOP EVEN WITH DESPERATE ATTEMPTS TO USE THE BRAKES. CAR F RAMP RAMMED INTO CAR C, AUDI A5G, SKS 29 M AND THEN CAR B, TOYOTA ALPHARD, SKS 29 K WHILE BOTH CARS ARE STATIONARY.

THE MY DRIVER MR RAY SIM WAS THE DRIVER AT THAT POINT IN TIME. HE TRIED TO SHIFT CAR F FORWARD TO CHECK ON THE DAMAGES BUT WHEN SHIFT GEAR TO 'D', THE CAR IMMEDIATELY ACCELERATED AND MR RAY SIM LOST CONTROL OF THE CAR.

CAR F BANGED OUR GATE, SP FOUN BOX TWO STAIRS BOX JUST OUTSIDE OUR HOUSE.

THERE WERE NO INJURIES TO ANYONE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

15 JUL 2019

Policyholder's Signature

Date & Time: 15/07/19

3:55pm

Driver's Signature

(if driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Reporting Centre, Singapore 415933

Name: Tel: 67416697 Fax: 67492305

Email: vacbk@singnet.com.sg

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 4 Raffles Quay #18-00 Singapore 048500
 Tel (65) 6224 0030 Fax (65) 6224 0030
 Operating Hours: Monday to Friday, 09:00 - 17:00
 UEN: S60500306 / GST Reg. No.: S400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : _____ Vehicle Registration No: SKS 29 M
 Name (as shown in NRIC) : LEONG JIAQIAN, BENJAMIN NRIC/FIN/Passport No : S85092742
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate.
 Address : 31 TOH HEIGHTS Singapore (S) 07838
 Contact (Tel) : 6542 2929 Mobile No. : 9012 0029
 Email Address : benjaminleong15@rocketmail.com
 Date of Accident : 15/07/19 Time of Accident : 8:48 AM
 Place of Accident : 31 TOH HEIGHTS, S507838 BASEMENT CARPARK.
 Insurance Company: FIRST CAPITAL.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

UPDATE TO OWN DAMAGE CLAIM.

[Handwritten signature]

[Signature]
 Policyholder / Driver's Signature
 Date: 18/07/19

IDAC KAKI BUKIT (VAC)
 Reporting Centre: 28 Kaki Bukit Ave 4
 Name: Singapore 415933
 NRIC/TEL: 67416697 Fax: 67492305
 Date: Email: vackb@singnet.com.sg

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183
Email: claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0867/2019/GW
Date : 17-Jul-19

Vehicle in workshop. Kindly arrange for survey.

Your insured vehicle no : SKS 29 M

First Capital Insurance Ltd

36 Robinson Road
16-01 City House
Singapore 068877

Attn: Motor Claims Dept
Tel: 6854 3909 Fax: 6507 3849

Owner's Name : Mr. Leong JiaQuan, Benjamin
Address : 31 Toh Heights
Singapore 507838
Telephone : (HP) 90120029
Type of Claim : Own Damage claims
Policy No. : D-18091577MVPC/1
Vehicle No : **SKS 29 M**
Model Code : RS 6 AVENT 4.0 TFSI QUATTRO
Model / Year : Aug-14
Engine No : CRD 0052722
Chassis No : WAUZZZ4GSEN903833
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Jul-19
Place of Accident : 29/31 Toh Heights Car Park

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "best effort" basis
- No illegal modifications is allowed
- Supplementary items must be submitted
is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKS 29 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident.	S/N \$ 280.00 ✓	✓
2	To carry out first measurement test on car o-liner.	S/N \$ 800.00 ? photo. x	
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	✓
4	To remove and renew aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,600.00 ✓	✓
5	To remove and reinstall engine assy with gearbox assy to facilitate car-o-liner repairs.	S/N \$ 2,800.00 ? photo. x	
6	To remove and reinstall front suspension assy with subframe to facilitate car-o-liner repairs. Inspect for damages and renew if necessary.	S/N \$ 2,800.00 ? photo x	
SUB TOTAL LABOUR CHARGES		: <u>\$ 8,760.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKS 29 M

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
7	To renew front windscreen.	S/N S	480.00	✓ ✓
8	To place vehicle on car o - liner.	S/N S	2,400.00	? photo. x
9	To dismantle and renew front bumper, bonnet, both front fenders and both headlights. To renew lhs front chassis bracket. Renew front lock carrier and align to position. re-organise front crash management components. Reinstall all parts removed.	8000. S	8,800.00	6400. ✓
10	To respray front bumper, both front fenders, bonnet, bonnet hinges and engine compartment.	8000. S	5,500.00	3600. ✓
11	To carry out wheel alignment.	S/N S	240.00	? x
12	To carry out diagnostic checks.	S/N S	384.00	✓ ✓
TOTAL LABOUR CHARGES		:	<u>\$ 26,564.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 7,006.00	de ✓ ✓
2	FRONT BUMPER SECURING STRIP	\$ 13.00	de ✓ 6.50 13.20
3	FRONT BUMPER CLOSING ELEMENT -UPPER CENTRE	\$ 351.00	ana ✓ 350.50
4	FRONT BUMPER CLOSING ELEMENT-LH/RH	2 \$ 546.00	LH-de ✓, RH- 7 273
5	FRONT BUMPER END CAP-LH/RH	2 \$ 206.00	LH-dis ✓, RH X 103 205
6	FRONT BUMPER PULL STRAP	\$ 90.00	? plus for 89.90
7	FRONT BUMPER SPOILER	\$ 1,111.00	cu ✓ 1111
8	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 390.00	? 390 de ✓
9	FRONT BUMPER SPOILER-LOWER CENTRE	\$ 227.00	? 226.50 de ✓
10	FRONT BUMPER GRILLE-LH/RH	2 \$ 338.00	LH-de ✓ RH-X 169 337
11	FRONT BUMPER GRILLE COVER-LH/RH	2 \$ 684.00	LH-de ✓ RH-X 342 273.60
12	FRONT BUMPER AIR GUIDE GRILLE-LH/RH	2 \$ 796.00	LH-mis ✓, RH X 398 795
13	FRONT BUMPER AIR GUIDE COVER-LH/RH	2 \$ 154.00	LH-mis ✓, RH-X 77 1524
14	RADIATOR GRILLE- ALUMINIUM MATT	\$ 4,336.00	ana ✓ 4336
15	RADIATOR GRILLE LOGO COVER	\$ 122.00	cu ✓ 121.50
16	INSCRIPTION ' RS6 '	\$ 113.00	m's ✓ 112.50
17	RADIATOR GRILLE SECURING ELEMENT	\$ 11.00	de ✓ 10.30
18	FRONT REINFORCEMENT BEAM COVER	\$ 265.00	cu ✓ 265
19	FRONT SENSOR SUPPORT-LH/RH INNER	2 \$ 122.00	de ✓ 121.20
20	FRONT LICENCE PLATE HOLDER	\$ 497.00	m's ✓ 497
SUB TOTAL SPARE PARTS CHARGES		: \$ 17,378.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
* Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark.
21	FRONT REINFORCEMENT BEAM	\$ 754.00	bt ✓ 753.50
22	FRONT BUMPER FOAM	\$ 246.00	as ✓ 246
23	FRONT BUMPER UPPER COVER	\$ 318.00	as ✓ 318
24	FRONT BUMPER GUIDE PIECE-LH	\$ 99.00	dis ✓ 98.60
25	FRONT BUMPER BRACE-LH	\$ 27.00	? X nn
26	FRONT REINFORCEMENT BEAM HOLDER-LH	\$ 237.00	bt ✓ 236.50
27	SIGN ' CAUTION '	\$ 13.00	as ✓ 12.30
28	AIR CONDITIONER STICKER	\$ 16.00	as ✓ 15.90
29	FRONT PARKING AID SENSOR -INNER	2 \$ 419.00	? X nn
30	FRONT PARKING AID SENSOR -OUTER	2 \$ 462.00	? X nn
31	FRONT SENSOR SEAL RING	4 \$ 5.00	as ✓ 4.80
32	FRONT BUMPER WIRING SET	\$ 532.00	? X nn
33	FRONT SIGNAL HORN-LOW TONE -LH	\$ 182.00	? X nn
34	FRONT SIGNAL HORN-HIGH TONE -RH	\$ 180.00	X X nn
35	HORN BRACKET-LH	\$ 43.00	? X nn
36	HORN BRACKET-RH	\$ 40.00	X X nn
37	FRONT FENDER-LH/RH	2 \$ 6,832.00	bt ✓ 6832
38	FRONT FENDER BRACE-LH/RH	2 \$ 150.00	LH-bt ✓, RH X 75 74.60
39	FRONT FENDER CLOSING ELEMENT-LH/RH	2 \$ 96.00	? X nn
40	FRONT FENDER SEAL-LH	2 \$ 36.00	? X nn
SUB TOTAL SPARE PARTS CHARGES		\$ 10,687.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	FRONT WHEEL HOUSING LINER-LH	\$ 626.00	de / 625
42	FRONT WHEEL SPOILER-LH	\$ 62.00	de / 6160
43	BONNET	\$ 4,965.00	bt / 4965
44	BONNET LID HINGE-LH/RH	2 \$ 292.00	bt / 392
45	BONNET DAMPER	2 \$ 217.00	? X nn
46	BONNET CATCH HOOK	\$ 127.00	bt / 127
47	BONNET LOCK BAR	2 \$ 90.00	bt / 90
48	BONNET HINGE COVER-LH/RH	2 \$ 10.00	? X nn
49	BONNET CATCH HOOK	\$ 16.00	? 15.40 dis
50	BONNET CATCH HOOK COVER	\$ 4.00	? 3.20 dis
51	BONNET LID LOCK WITH MICRO SWITCH	2 \$ 391.00	LH-bt, RH-? 391
52	BONNET MICRO SWITCH	2 \$ 133.00	make ? X nn
53	BONNET LOCK CONNECTOR HOUSING BRACKET	2 \$ 18.00	? 17.30 dis
54	BONNET BOWDEN CABLE-CENTER	\$ 53.00	? 53.10 dis
55	BONNET BOWDEN CABLE COVER	\$ 9.00	? 8.90 dis
56	BONNET LOCK CABLE	\$ 67.00	? X nn
57	HEADLIGHT MOUNTING-LH/RH	2 \$ 214.00	LH-ann, RH-? 107
58	COOLANT REGULATOR SUPPORT-LH/RH	2 \$ 68.00	? 66.80
59	RADIATOR CORE SUPPORT-LH	\$ 268.00	? X nn
60	LED HEADLIGHT-LH/RH	2 \$ 22,420.00	can / 22420
SUB TOTAL SPARE PARTS CHARGES		\$ 30,050.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
61	LED HEADLIGHT FAN	S 363.00	? 363 shorted ✓
62	DRIVING LIGHT POWER MODULE	S 520.00	? 514.50 shorted ✓
63	CORNERING LIGHT POWER MODULE	S 508.00	? 507.50 shorted ✓
64	MAIN LIGHT POWER MODULE	S 1,070.00	? 1070 shorted ✓
65	LED HEADLIGHT HOSE	S 15.00	? X nn.
66	LED HEADLIGHT LIFT CYLINDER-LH/RH	2 S 432.00	LH - cr - RH X 216 215.50
67	LIFT CYLINDER HOSE	S 36.00	ut - 179
68	DISTRIBUTOR FOR LIFT CYLINDER	S 27.00	ut - 26.50
69	ELBOW FITTING FOR LIFT CYLINDER	S 19.00	ut - 19
70	ELBOW FITTING FOR LIFT CYLINDER	2 S 47.00	ut - 46.50
71	HEADLIGHT PUMP FOR WASHER SYSTEM	S 147.00	X
72	WASH WATER RESERVOIR	S 174.00	X
73	FRONT WINDSCREEN WASHER SYSTEM	S 118.00	X
74	WIPER COWL COVER	S 183.00	? X
75	WATER DEFLECTOR	S 69.00	? 68.50 de
76	LOCK CARRIER MOUNTING FOR RADIATOR	S 1,140.00	as - 1140
77	A/C CONDENSER	S 689.00	bt - 689
78	HIGH PRESSURE SWITCH FOR A/C VALVE	S 48.00	? X nn
79	PRESSURE SENSOR FOR A/C	S 175.00	? X nn
80	A/C PIPE - COMPRESSOR > CONDENSER	S 234.00	? 233.50 bt ✓
SUB TOTAL SPARE PARTS CHARGES		S 6,014.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

6157

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
81	RADIATOR	S 2,040.00	bt ✓ 2040
82	REFRIGERANT HOSE FOR A/C CONDENSER	S 234.00	? X nn
83	A/C CONDENSER PROTECTIVE GRILLE	S 127.00	? 127 ann ✓
84	RADIATOR RUBBER BUSH-UPPER	2 S 12.00	ner ✓ 11.80
85	RADIATOR RUBBER BUSH-CENTER	2 S 18.00	ner ✓ 17.60
86	RADIATOR RUBBER BUSH-LOWER	2 S 58.00	ner ✓ 57.60
87	COOLANT	S 84.00	ner ✓ 84
88	ADDITIONAL RADIATOR FOR FRONT CENTER	S 3,083.00	bt ✓ 3083
89	ADDITIONAL RADIATOR FOR FRONT-LH FRONT	S 1,840.00	? X
90	ADDITIONAL RADIATOR FOR FRONT-LH REAR	S 1,530.00	? X
91	ADDITIONAL RADIATOR BRACKET-LH	S 472.00	? X
92	ADDITIONAL RADIATOR UPPER BRACKET-LH	S 30.00	? X
93	ADDITIONAL RADIATOR COOLANT PUMP-LH OUTER	S 292.00	? X
94	COOLANT PUMP-LH INNER	S 1,219.00	? X
95	COOLANT PUMP STOP BUFFER-LH INNER	S 15.00	? X
96	ADDITIONAL COOLANT PUMP BRACKET-LH INNER	S 30.00	? X
97	ADDITIONAL COOLANT PUMP ATTACHMENT PARTS	S 66.00	? X
98	FRONT RADIATOR AIR GUIDE-LH	S 27.00	? X
99	TWIN FAN RING	S 400.00	nn ✓ 399.50
100	RADIATOR FAN-LH/RH	2 S 6,712.00	? 6712 nn ✓
SUB TOTAL SPARE PARTS CHARGES		: \$18,289.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
101	RADIATOR CENTER AIR GUIDE-LH/RH	2 S	92.00	LH-de- / RH-de- 46 90.80
102	RADIATOR CENTER AIR GUIDE-LH/RH REAR	2 S	100.00	LH-de- / RH-de- 50 49.60
103	RADIATOR CENTER LOWER COVER	S	154.00	? X nn
101	RADIATOR CENTER UPPER COVER	S	34.00	Cur 33.50
102	RADIATOR AIR GUIDE-LH/RH	2 S	158.00	? X
103	AIR INTAKE FILTER	S	467.00	? X
104	AIR INTAKE AIR GUIDE	S	46.00	? X
105	AIR INTAKE DUCT	S	87.00	? X
106	AIR INTAKE DUCT BELLOWS	2 S	105.00	? X
107	FRONT WINDSCREEN	S	2,671.00	ang 2671
108	FRONT WINDSCREEN RAIN SENSOR	S	749.00	? 128 net✓
109	PRIMER FOR FRONT WINDSCREEN	2 S	38.00	net 18.60
110	WATER DEFLECTOR STRIP - LH/RH	2 S	122.00	? X nn
111	FRONT W/S SEALANT	S/N S	200.00	ne 200
112	FRONT NO. PLATE	S/N S	40.00	mis 40
113	SUNDRIES	S	800.00	? 123.50 net✓
TOTAL SPARE PARTS CHARGES		: S	88,281.00	
TOTAL LABOUR CHARGES		: S	26,564.00	
GRAND TOTAL		: S	114,845.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

130085-40

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :


Tanglin 97495749
Not Authorised, Renewal.

Exp: to be advise. 18/7/19 @ 4/5 pm.

Repair before part

suve@khant.com

12 days

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
- For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1163

Supplementary Estimate 1

GST Reg No. 19-9902271-W

First Capital Insurance Ltd
36 Robinson Road
16-01 City House
Singapore 068877

Attn: Motor Claims Dept
Tel: 6854 3909 Fax: 6507 3849

Estimate No. PA/OD/0667/2019/GW
Date 27-Aug-19
Service Advisor Glory Tan
Pages 1 of 1
Regn No SKS 29 M
Model No RS 6 AVENT 4.0 TFSI QUATTRO

Quantity	Description	Unit Price	Amount
Parts			
1	Support for lock carrier	\$ 12.00 <i>MAI</i>	11.20
2	Guide piece RHS	\$ 99.00 <i>CR</i>	98.60
3	Audi emblem for radiator grille	\$ 113.00 <i>CR</i>	112.80
4	Emblem adapter	\$ 198.00 <i>CR</i>	197.50
5	Cover cap for lift cylinder LHS	\$ 102.00 <i>CR</i>	101.50
6	Compensating piece for headlight	\$ 153.00 <i>MAI</i>	152.60
7	Adjustment element for headlight	\$ 83.00 <i>MAI</i>	82.40
8	Breather line for additional radiator	\$ 45.00 <i>CR</i>	45
9	Spray nozzle, heated	\$ 42.00 <i>CR</i>	41.30
10	Air guide for charge air cooler	\$ 2,698.00 <i>CR</i>	2698
11	Seal for air guide for charge air cooler LHS	\$ 79.00 <i>CR</i>	78.10
12	Seal for air guide for charge air cooler RHS	\$ 79.00 <i>CR</i>	78.10
13	Cable guide for oil temperature sender	\$ 23.00 <i>CR</i>	22.40
14	Flat contact housing with contact	\$ 37.00 <i>CR</i>	36.50
15	locking mechanism <i>MAI</i>	\$ 15.00 <i>MAI</i>	14.50
16	Headlight hose RHS	\$ 347.00 <i>CR</i>	347
17	Thermo-pneumatic valve		
		\$ 4,125.00	

LABORS

1	To remove and renew charge air cooler and other damaged engine components.	S/N	\$ 980.00 ? ✓
---	--	-----	---------------

TOTAL \$ 5,105.00

For Premium Automobiles Pte Ltd

Authorised Signature

6002.40

Reine
28/08/19

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	S 7,006.00	de ✓
2	FRONT BUMPER SECURING STRIP LH	1 X S 13.00	de ✓
3	FRONT BUMPER CLOSING ELEMENT -UPPER CENTRE	S 351.00	ca ✓
4	FRONT BUMPER CLOSING ELEMENT-LH/RH	2 S 546.00	LH-de, RH-?
5	FRONT BUMPER END CAP-LH/RH	2 S 206.00	LH-de, RH-X
★ 6	FRONT BUMPER PULL STRAP	S 90.00	? photo cut ✓
7	FRONT BUMPER SPOILER	S 1,111.00	ca ✓
★ 8	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	S 390.00	? ca ✓
★ 9	FRONT BUMPER SPOILER-LOWER CENTRE	S 227.00	? ca ✓
★ 10	FRONT BUMPER GRILLE-LH/RH	2 S 338.00	LH-? RH-X ca ✓
11	FRONT BUMPER GRILLE COVER-LH/RH	2 S 684.00	LH-? RH-X ca ✓
★ 12	FRONT BUMPER AIR GUIDE GRILLE-LH/RH	2 S 796.00	LH-mis, RH-X ca ✓
★ 13	FRONT BUMPER AIR GUIDE COVER-LH/RH	2 S 154.00	LH-mis, RH-X ca ✓
14	RADIATOR GRILLE- ALUMINIUM MATT	S 4,336.00	ca ✓
15	RADIATOR GRILLE LOGO COVER	S 122.00	ca ✓
16	INSCRIPTION 'RS6'	S 113.00	mis ✓
17	RADIATOR GRILLE SECURING ELEMENT	S 11.00	de ✓
18	FRONT REINFORCEMENT BEAM COVER	S 265.00	ca ✓
19	FRONT SENSOR SUPPORT-LH/RH INNER	2 S 122.00	de ✓
20	FRONT LICENCE PLATE HOLDER	S 497.00	mis ✓
SUB TOTAL SPARE PARTS CHARGES		S 17,378.00	

All charges are not inclusive of GST

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

P. Hume
28/08/19

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT REINFORCEMENT BEAM	S 754.00	bt ✓
22	FRONT BUMPER FOAM	S 246.00	one ✓
23	FRONT BUMPER UPPER COVER	S 318.00	mis ✓
24	FRONT BUMPER GUIDE PIECE-LH	S 99.00	dis ✓
25	FRONT BUMPER BRACE-LH	S 27.00	?
26	FRONT REINFORCEMENT BEAM HOLDER-LH	S 237.00	bt ✓
27	SIGN "CAUTION"	S 13.00	new ✓
28	AIR CONDITIONER STICKER	S 16.00	new ✓
29	FRONT PARKING AID SENSOR -INNER	2 S 419.00	?
30	FRONT PARKING AID SENSOR -OUTER	2 S 462.00	?
31	FRONT SENSOR SEAL RING	4 S 5.00	new ✓
32	FRONT BUMPER WIRING SET	S 532.00	?
33	FRONT SIGNAL HORN-LOW TONE -LH	S 182.00	?
34	FRONT SIGNAL HORN-HIGH TONE -RH	S 180.00	X
35	HORN BRACKET-LH	S 43.00	?
36	HORN BRACKET-RH	S 40.00	X
37	FRONT FENDER-LH/RH	2 S 6,832.00	bt ✓
38	FRONT FENDER BRACE-LH/RH	2 S 150.00	LH-bt, RH-X
39	FRONT FENDER CLOSING ELEMENT-LH/RH	2 S 96.00	?
40	FRONT FENDER SEAL-LH	2 S 36.00	?
SUB TOTAL SPARE PARTS CHARGES		S 10,687.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	FRONT WHEEL HOUSING LINER-LH	\$ 626.00	de ✓
42	FRONT WHEEL SPOILER-LH	\$ 62.00	de ✓
43	BONNET	\$ 4,965.00	bt ✓
44	BONNET LID HINGE LH/RH	2 \$ 292.00	bt ✓
45	BONNET DAMPER	2 \$ 217.00	? ✓
46	BONNET CATCH HOOK	\$ 127.00	bt ✓
47	BONNET LOCK BAR	2 \$ 90.00	bt ✓
48	BONNET HINGE COVER-LH/RH	2 \$ 10.00	? ✓
49	BONNET CATCH HOOK	\$ 16.00	? ✓
50	BONNET CATCH HOOK COVER - missing	\$ 4.00	? ✓
51	BONNET LID LOCK WITH MICRO SWITCH	2 \$ 391.00	LH-bt ✓ RH-?
52	BONNET MICRO SWITCH	2 \$ 133.00	? ✓
53	BONNET LOCK CONNECTOR HOUSING BRACKET	2 \$ 18.00	? ✓
54	BONNET BOWDEN CABLE-CENTER	\$ 53.00	? at ✓
55	BONNET BOWDEN CABLE COVER - missing	\$ 9.00	? mis ✓
56	BONNET LOCK CABLE	\$ 67.00	? ✓
57	HEADLIGHT MOUNTING LH/RH	2 \$ 214.00	LH-ax ✓ RH-?
58	COOLANT REGULATOR SUPPORT-LH/RH	2 \$ 68.00	? ✓
59	RADIATOR CORE SUPPORT-LH	\$ 268.00	? ✓
60	LED HEADLIGHT LH/RH	2 \$ 22,420.00	can ✓
SUB TOTAL SPARE PARTS CHARGES		\$ 30,050.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

Damaged Parts & Prices

S/N	Parts Description	S/Nett	Remark
61	LED HEADLIGHT FAN	S 363.00	?
62	DRIVING LIGHT POWER MODULE	S 520.00	?
63	CORNERING LIGHT POWER MODULE	S 508.00	?
64	MAIN LIGHT POWER MODULE	S 1,070.00	?
65	LED HEADLIGHT HOSE	S 15.00	?
66	LED HEADLIGHT LIFT CYLINDER-LH/RH	2 S 432.00	LH-OK RH X
67	LIFT CYLINDER HOSE	S 36.00	OK ✓
68	DISTRIBUTOR FOR LIFT CYLINDER	S 27.00	OK ✓
69	ELBOW FITTING FOR LIFT CYLINDER	S 19.00	OK ✓
70	ELBOW FITTING FOR LIFT CYLINDER	2 S 47.00	OK ✓
71	HEADLIGHT PUMP FOR WASHER SYSTEM	S 147.00	X
72	WASH WATER RESERVOIR	S 174.00	X
73	FRONT WINDSCREEN WASHER SYSTEM	S 118.00	X
74	WIPER COWL COVER	S 183.00	?
75	WATER DEFLECTOR	S 69.00	OK ✓
76	LOCK CARRIER MOUNTING FOR RADIATOR	S 1,140.00	OK ✓
77	A/C CONDENSER	S 689.00	OK ✓
78	HIGH PRESSURE SWITCH FOR A/C VALVE	S 48.00	?
79	PRESSURE SENSOR FOR A/C	S 175.00	?
80	A/C PIPE - COMPRESSOR > CONDENSER	S 234.00	?
SUB TOTAL SPARE PARTS CHARGES		S 6,014.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
81	RADIATOR	\$ 2,040.00	bt ✓
82	REFRIGERANT HOSE FOR A/C CONDENSER	\$ 234.00	?
X 83	A/C CONDENSER PROTECTIVE GRILLE	\$ 127.00	?
84	RADIATOR RUBBER BUSH-UPPER	2 \$ 12.00	new ✓
85	RADIATOR RUBBER BUSH-CENTER	2 \$ 18.00	new ✓
86	RADIATOR RUBBER BUSH-LOWER	2 \$ 58.00	new ✓
87	COOLANT	\$ 84.00	new ✓
88	ADDITIONAL RADIATOR FOR FRONT CENTER	\$ 3,083.00	bt ✓
89	ADDITIONAL RADIATOR FOR FRONT-LH FRONT	\$ 1,840.00	?
90	ADDITIONAL RADIATOR FOR FRONT-LH REAR	\$ 1,530.00	?
91	ADDITIONAL RADIATOR BRACKET-LH	\$ 472.00	?
92	ADDITIONAL RADIATOR UPPER BRACKET-LH	\$ 30.00	?
93	ADDITIONAL RADIATOR COOLANT PUMP-LH OUTER	\$ 292.00	?
94	COOLANT PUMP-LH INNER	\$ 1,219.00	?
95	COOLANT PUMP STOP BUFFER-LH INNER	\$ 15.00	?
96	ADDITIONAL COOLANT PUMP BRACKET-LH INNER	\$ 30.00	?
97	ADDITIONAL COOLANT PUMP ATTACHMENT PARTS	\$ 66.00	?
98	FRONT RADIATOR AIR GUIDE-LH	\$ 27.00	?
99	TWIN FAN RING	\$ 400.00	new ✓
100	RADIATOR FAN-LH/RH	2 \$ 6,712.00	? ✓
SUB TOTAL SPARE PARTS CHARGES		\$18,289.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
101	RADIATOR CENTER AIR GUIDE-LH/RH	2 S	92.00	LH-de-1, RH-X ✓
102	RADIATOR CENTER AIR GUIDE-LH/RH REAR	2 S	100.00	LH-de-1, RH-X ✓
103	RADIATOR CENTER LOWER COVER	S	154.00	?
101	RADIATOR CENTER UPPER COVER	S	34.00	Cur ✓
102	RADIATOR AIR GUIDE-LH/RH	2 S	158.00	?
103	AIR INTAKE FILTER	S	467.00	?
104	AIR INTAKE AIR GUIDE	S	46.00	?
105	AIR INTAKE DUCT	S	87.00	?
106	AIR INTAKE DUCT BELLOWS	2 S	105.00	?
107	FRONT WINDSCREEN	S	2,671.00	an ✓
108	FRONT WINDSCREEN RAIN SENSOR	S	749.00	?
109	PRIMER FOR FRONT WINDSCREEN	2 S	38.00	net ✓
110	WATER DEFLECTOR STRIP - LH/RH	2 S	122.00	?
111	FRONT W/S SEALANT	S/N S	200.00	ne ✓
112	FRONT NO. PLATE	S/N S	40.00	mis ✓
113	SUNDRIES	S	800.00	?
TOTAL SPARE PARTS CHARGES		: S	88,281.00	
TOTAL LABOUR CHARGES		: S	26,564.00	
GRAND TOTAL		: S	114,845.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Veron Chen (LKKAUTO)

From: Neo Jie Si <Neojiesi@msfirstcapital.com.sg>
Sent: Monday, 19 August 2019 9:37 AM
To: Veron Chen (LKKAUTO); SUR
Subject: RE: LKK AUTO CONSULTANTS - TPD Survey Request / Our Ref: D19/4634M/PTE/JS
(Our veh: SJA29U) -OD VEHICLE SKS 29M

Dear Veron,

We have advised insured that the recommended number of repair days is 12 days.

Insured / Broker would like to check if we have informed the workshop on the number of repair days recommended as the repair has exceeded 12 days (according to insured/ broker, their car will only be ready next month).

Therefore, please advise if you have supporting documents to show that the workshop is aware about recommended the number of days for repair.

Thank you.

Best regards,
(Ms)Neo Jie Si
Motor Claims Dept.

12 days
We have checked with the workshop and the vehicle is still being repaired. We will follow-up with the workshop for any additional repair done on the vehicle and advise accordingly.

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 Singapore 068877 | DID : 6507 3858 | Fax No. : 6507 3849 | Company Regn. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP



Change of email address
neojiesi@msfirstcapital.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Thursday, August 15, 2019 4:21 PM
To: Neo Jie Si <Neojiesi@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: LKK AUTO CONSULTANTS - TPD Survey Request / Our Ref: D19/4634M/PTE/JS (Our veh: SJA29U) -OD VEHICLE SKS 29M

Dear Jie Si,

Please refer to our email below on 19/7/19.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Neo Jie Si <Neojiesi@msfirstcapital.com.sg>

Sent: Thursday, 15 August 2019 4:03 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: LKK AUTO CONSULTANTS - TPD Survey Request / Our Ref: D19/4634M/PTE/JS (Our veh: SJA29U) -OD VEHICLE SKS 29M

Dear Veron,

Noted.

Kindly advise the number of days recommended for the repair as insured is claiming loss of use benefit under own policy.

Thank you.

Best regards,

(Ms)Neo Jie Si

Motor Claims Dept.

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 Singapore 068877 | DID : 6507 3858 | Fax No. : 6507 3849 | Company Regn. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP



Change of email address

neojiesi@msfirstcapital.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Sent: Thursday, August 15, 2019 3:03 PM

To: Neo Jie Si <Neojiesi@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: LKK AUTO CONSULTANTS - TPD Survey Request / Our Ref: D19/4634M/PTE/JS (Our veh: SJA29U) -OD VEHICLE SKS 29M

Dear Jie Si,

According to repairer, the vehicle is still under repairing.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

From: Neo Jie Si <Neojiesi@msfirstcapital.com.sg>
Sent: Thursday, 15 August 2019 2:52 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: LKK AUTO CONSULTANTS - TPD Survey Request / Our Ref: D19/4634M/PTE/JS (Our veh: SJA29U) -OD VEHICLE SKS 29M

Dear Veron,

Please submit your final survey report if ready.

Thank you.

Best regards,
(Ms)Neo Jie Si
Motor Claims Dept.

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 Singapore 068877 | DID : 6507 3858 | Fax No. : 6507 3849 | Company Regn. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP



Change of email address
neojiesi@msfirstcapital.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.
Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Neo Jie Si
Sent: Monday, July 29, 2019 11:01 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: LKK AUTO CONSULTANTS - TPD Survey Request / Our Ref: D19/4634M/PTE/JS (Our veh: SJA29U) -OD VEHICLE SKS 29M

Dear Veron,

We refer to your preliminary advice dated 19 July 2019.

Please proceed to authorize repair up to \$108,403.50/- as advised.

Thank you.

Best regards,
(Ms)Neo Jie Si
Motor Claims Dept.

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 Singapore 068877 | DID : 6507 3858 | Fax No. : 6507 3849 | Company Regn. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP



Change of email address
neojiesi@msfirstcapital.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.
Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Sent: Friday, July 19, 2019 4:37 PM

To: Neo Jie Si <Neojiesi@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>; CWS Motor Claims
<cwsmotorclaims@msfirstcapital.com.sg>

Subject: RE: LKK AUTO CONSULTANTS - TPD Survey Request / Our Ref: D19/4634M/PTE/JS (Our veh: SJA29U) -OD
VEHICLE SKS 29M

Dear Jie Si,

Enclosed preliminary revised of vehicle SKS 29M

Date of survey: 18/7/2019

Number of days : 12 days

We have Not authorise repair.

Kindly let us have your approval please.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Neo Jie Si <Neojiesi@msfirstcapital.com.sg>

Sent: Friday, 19 July 2019 3:33 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: RE: LKK AUTO CONSULTANTS - TPD Survey Request / Our Ref: D19/4634M/PTE/JS (Our veh: SJA29U)

Dear Veron,

Attached our new motor survey assignment sheet (OD) for your record purposes only.

Thank you.

Best regards,

(Ms)Neo Jie Si

Motor Claims Dept.

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 Singapore 068877 | DID : 6507 3858 | Fax No. : 6507
3849 | Company Regn. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP



Change of email address
neojiesi@msfirstcapital.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Celine Fong (LKKAuto) <celinefong@lkkauto.com>

Sent: Friday, July 19, 2019 2:52 PM

To: Neo Jie Si <Neojiesi@msfirstcapital.com.sg>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: RE: LKK AUTO CONSULTANTS - TPD Survey Request / Our Ref: D19/4634M/PTE/JS (Our veh: SJA29U)

Dear Ms Neo,

Thank you for the email.

Dear Veron,

Please assist. Your Ref: CS/FCI19012579/T1vf3

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Neo Jie Si <Neojiesi@msfirstcapital.com.sg>

Sent: Friday, 19 July 2019 2:48 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Subject: RE: LKK AUTO CONSULTANTS - TPD Survey Request / Our Ref: D19/4634M/PTE/JS (Our veh: SJA29U)

Dear Celine,

Please refer to attached email from workshop.

SKS29M (insured with us) has reverted to claim OD instead.

There is no OD excess.

Please let us have your prelim advice on quantum before authorizing repair.

Thank you.

Best regards,
(Ms)Neo Jie Si
Motor Claims Dept.

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 Singapore 068877 | DID : 6507 3858 | Fax No. : 6507 3849 | Company Regn. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP



Change of email address
neojiesi@msfirstcapital.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Sent: Tuesday, July 16, 2019 5:20 PM

To: Neo Jie Si <Neojiesi@msfirstcapital.com.sg>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: RE: LKK AUTO CONSULTANTS - TPD Survey Request / Our Ref: D19/4634M/PTE/JS (Our veh: SJA29U)

Dear Jie Si

Please call me for this case.

Best Regards,

Bryan Ang

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: bryanang@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Neo Jie Si <Neojiesi@msfirstcapital.com.sg>

Sent: Tuesday, 16 July 2019 4:40 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: RE: LKK AUTO CONSULTANTS - TPD Survey Request / Our Ref: D19/4634M/PTE/JS (Our veh: SJA29U)

Dear Celine,

We would like to request Bryan to attend to this matter personally.

Thank you.

Best regards,

(Ms)Neo Jie Si

Motor Claims Dept.

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 Singapore 068877 | DID : 6507 3858 | Fax No. : 6507 3849 | Company Regn. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP



Change of email address
neojiesi@msfirstcapital.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Tuesday, July 16, 2019 4:03 PM

To: Rosliza Bte AB Rahman <Rosliza@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: Neo Jie Si <Neojiesi@msfirstcapital.com.sg>

Subject: RE: LKK AUTO CONSULTANTS - TPD Survey Request / Our Ref: D19/4634M/PTE/JS (Our veh: SJA29U)

Dear Sir/Madam,

Thank you for the assignment.

Best Regards

Celine Fong

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rosliza Bte AB Rahman [<mailto:Rosliza@msfirstcapital.com.sg>]

Sent: Tuesday, 16 July 2019 3:38 PM

To: assignments <assignments@lkkauto.com>

Cc: Claims Dept <claims@premiumauto.com.sg>; Neo Jie Si <Neojiesi@msfirstcapital.com.sg>

Subject: LKK AUTO CONSULTANTS - TPD Survey Request / Our Ref: D19/4634M/PTE/JS (Our veh: SJA29U)

Dear SIRS

TPD SURVEY REQUEST (FOR SKS29M)

Our Ref: D19/4634M/PTE/JS

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly forward us your report by email only to Surveyor@msfirstcapital.com.sg within the next 14 days.

Thank You

Regards
Rosliza AR
Support Staff

MS First Capital Insurance Ltd | 36 Robinson Road, City House #16-01 Singapore 068877 | TEL 6507 3848 | Fax No. : 6507 3849 | Company Regn. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP


Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0867/2019/GW
Date : 17-Jul-19

Vehicle in workshop. Kindly arrange for survey.

Your insured vehicle no : **SKS 29 M**

First Capital Insurance Ltd
36 Robinson Road
16-01 City House
Singapore 068877

*Hi Rasul,
18 days of repairs - ok - Jb
21-Nov-19*

Attn: Motor Claims Dept
Tel:6854 3909 Fax: 6507 3849

Owner's Name : Mr. Leong JiaQuan, Benjamin
Address : 31 Toh Heights
Singapore 507838
Telephone : (HP) 90120029
Type of Claim : Own Damage claims
Policy No. : D-18091577MVPC/1
Vehicle No : **SKS 29 M**
Model Code : RS 6 AVENT 4.0 TFSI QUATTRO
Model / Year : Aug-14
Engine No : CRD 0052722
Chassis No : WAUZZZ4G5EN903833
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Jul-19
Place of Accident : 29/31 Toh Heights Car Park

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKS 29 M

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident.	S/N	\$ 280.00	\$ 280.00
2	To carry out first measurement test on car o-liner.	S/N	\$ 800.00	na
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00	\$ 480.00
4	To remove and renew aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$ 1,600.00	\$ 1,600.00
5	To remove and reinstall engine assy with gearbox assy to facilitate car-o-liner repairs.	S/N	\$ 2,800.00	
6	To remove and reinstall front suspension assy with subframe to facilitate car -o-liner repairs. Inspect for damages and renew if necessary.	S/N	\$ 2,800.00	
SUB TOTAL LABOUR CHARGES		:	<u>\$ 8,760.00</u>	\$ 2,360.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKS 29 M

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
				\$ 2,360.00
7	To renew front windscreen.	S/N \$	480.00	\$ 480.00
8	To place vehicle on car o - liner.	S/N \$	2,400.00	
9	To dismantle and renew front bumper, bonnet, both front fenders and both headlights. To renew lhs front chassis bracket. Renew front lock carrier and align to position.re-organise front crash management components. Reinstall all parts removed.	\$	8,800.00	\$ 6,400.00
10	To respray front bumper, both front fenders, bonnet, bonnet hinges and engine compartment.	\$	5,500.00	\$ 3,600.00
11	To carry out wheel alignment.	S/N \$	240.00	
11a	Added labour charge - see attached	S/N \$	980.00	\$ 980.00
12	To carry out diagnostic checks.	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 27,544.00	\$ 14,204.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 7,006.00	\$ 7,006.00
2	FRONT BUMPER SECURING STRIP	2 \$ 13.00	\$ 12.20
3	FRONT BUMPER CLOSING ELEMENT -UPPER CENTRE	\$ 351.00	\$ 350.50
4	FRONT BUMPER CLOSING ELEMENT-LH/RH	2 \$ 546.00	\$ 273.00
5	FRONT BUMPER END CAP-LH/RH	2 \$ 206.00	\$ 205.00
6	FRONT BUMPER PULL STRAP	\$ 90.00	\$ 89.90
7	FRONT BUMPER SPOILER	\$ 1,111.00	\$ 1,111.00
8	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 390.00	\$ 390.00
9	FRONT BUMPER SPOILER-LOWER CENTRE	\$ 227.00	\$ 226.50
10	FRONT BUMPER GRILLE-LH/RH	2 \$ 338.00	\$ 337.00
11	FRONT BUMPER GRILLE COVER-LH/RH	2 \$ 684.00	\$ 273.60
12	FRONT BUMPER AIR GUIDE GRILLE-LH/RH	2 \$ 796.00	\$ 795.00
13	FRONT BUMPER AIR GUIDE COVER-LH/RH	2 \$ 154.00	\$ 152.40
14	RADIATOR GRILLE- ALUMINIUM MATT	\$ 4,336.00	\$ 4,336.00
15	RADIATOR GRILLE LOGO COVER	\$ 122.00	\$ 121.50
16	INSCRIPTION ' RS6 '	\$ 113.00	\$ 112.50
17	RADIATOR GRILLE SECURING ELEMENT	\$ 11.00	\$ 10.30
18	FRONT REINFORCEMENT BEAM COVER	\$ 265.00	\$ 265.00
19	FRONT SENSOR SUPPORT-LH/RH INNER	2 \$ 122.00	\$ 121.20
20	FRONT LICENCE PLATE HOLDER	\$ 497.00	\$ 497.00
SUB TOTAL SPARE PARTS CHARGES		\$ 17,378.00	\$ 16,685.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

S/N	Parts Description		<u>Damaged Parts & Prices</u>	
			<u>S/Nett</u>	<u>Remark</u>
		<i>c/f</i>		\$ 16,685.60
21	FRONT REINFORCEMENT BEAM		\$ 754.00	\$ 753.50
22	FRONT BUMPER FOAM		\$ 246.00	\$ 246.00
23	FRONT BUMPER UPPER COVER		\$ 318.00	\$ 318.00
24	FRONT BUMPER GUIDE PIECE-LH		\$ 99.00	\$ 98.60
25	FRONT BUMPER BRACE-LH		\$ 27.00	
26	FRONT REINFORCEMENT BEAM HOLDER-LH		\$ 237.00	\$ 236.50
27	SIGN ' CAUTION '		\$ 13.00	\$ 12.20
28	AIR CONDITIONER STICKER		\$ 16.00	\$ 15.90
29	FRONT PARKING AID SENSOR -INNER	2	\$ 419.00	
30	FRONT PARKING AID SENSOR -OUTER	2	\$ 462.00	
31	FRONT SENSOR SEAL RING	4	\$ 5.00	\$ 4.80
32	FRONT BUMPER WIRING SET		\$ 532.00	
33	FRONT SIGNAL HORN-LOW TONE -LH		\$ 182.00	
34	FRONT SIGNAL HORN-HIGH TONE -RH		\$ 180.00	
35	HORN BRACKET-LH		\$ 43.00	
36	HORN BRACKER-RH		\$ 40.00	
37	FRONT FENDER-LH/RH	2	\$ 6,832.00	\$ 6,832.00
38	FRONT FENDER BRACE-LH/RH	2	\$ 150.00	\$ 74.60
39	FRONT FENDER CLOSING ELEMENT-LH/RH	2	\$ 96.00	
40	FRONT FENDER SEAL-LH	2	\$ 36.00	
SUB TOTAL SPARE PARTS CHARGES			\$ 10,687.00	\$ 25,277.70

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
		<i>c/f</i>		\$ 25,277.70
41	FRONT WHEEL HOUSING LINER-LH		\$ 626.00	\$ 625.00
42	FRONT WHEEL SPOILER-LH		\$ 62.00	\$ 61.60
43	BONNET		\$ 4,965.00	\$ 4,965.00
44	BONNET LID HINGE-LH/RH	2	\$ 292.00	\$ 292.00
45	BONNET DAMPER	2	\$ 217.00	
46	BONNET CATCH HOOK		\$ 127.00	\$ 127.00
47	BONNET LOCK BAR	2	\$ 90.00	\$ 90.00
48	BONNET HINGE COVER-LH/RH	2	\$ 10.00	
49	BONNET CATCH HOOK		\$ 16.00	\$ 15.40
50	BONNET CATCH HOOK COVER		\$ 4.00	\$ 3.20
51	BONNET LID LOCK WITH MICRO SWITCH	2	\$ 391.00	\$ 391.00
52	BONNET MICRO SWITCH	2	\$ 133.00	
53	BONNET LOCK CONNECTOR HOUSING BRACKET	2	\$ 18.00	\$ 17.20
54	BONNET BOWDEN CABLE-CENTER		\$ 53.00	\$ 52.10
55	BONNET BOWDEN CABLE COVER		\$ 9.00	\$ 8.90
56	BONNET LOCK CABLE		\$ 67.00	
57	HEADLIGHT MOUNTING-LH/RH	2	\$ 214.00	\$ 107.00
58	COOLANT REGULATOR SUPPORT-LH/RH	2	\$ 68.00	\$ 66.80
59	RADIATOR CORE SUPPORT-LH		\$ 268.00	
60	LED HEADLIGHT-LH/RH	2	\$ 22,420.00	\$ 22,420.00
SUB TOTAL SPARE PARTS CHARGES			\$ 30,050.00	\$ 54,519.90

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
			\$ 54,519.90
61	LED HEADLIGHT FAN	\$ 363.00	\$ 363.00
62	DRIVING LIGHT POWER MODULE	\$ 520.00	\$ 519.50
63	CORNERING LIGHT POWER MODULE	\$ 508.00	\$ 507.50
64	MAIN LIGHT POWER MODULE	\$ 1,070.00	\$ 1,070.00
65	LED HEADLIGHT HOSE	\$ 15.00	
66	LED HEADLIGHT LIFT CYLINDER-LH/RH	2 \$ 432.00	\$ 215.50
67	LIFT CYLINDER HOSE	\$ 36.00	\$ 179.00
68	DISTRIBUTOR FOR LIFT CYLINDER	\$ 27.00	\$ 26.80
69	ELBOW FITTING FOR LIFT CYLINDER	\$ 19.00	\$ 19.00
70	ELBOW FITTING FOR LIFT CYLINDER	2 \$ 47.00	\$ 46.20
71	HEADLIGHT PUMP FOR WASHER SYSTEM	\$ 147.00	
72	WASH WATER RESERVOIR	\$ 174.00	
73	FRONT WINDSCREEN WASHER SYSTEM	\$ 118.00	
74	WIPER COWL COVER	\$ 183.00	
75	WATER DEFLECTOR	\$ 69.00	\$ 68.60
76	LOCK CARRIER MOUNTING FOR RADIATOR	\$ 1,140.00	\$ 1,140.00
77	A/C CONDENSER	\$ 689.00	\$ 689.00
78	HIGH PRESSURE SWITCH FOR A/C VALVE	\$ 48.00	
79	PRESSURE SENSOR FOR A/C	\$ 175.00	
80	A/C PIPE - COMPRESSOR > CONDENSER	\$ 234.00	\$ 233.50
SUB TOTAL SPARE PARTS CHARGES		\$ 6,014.00	\$ 59,597.50

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

S/N	Parts Description	Damaged Parts & Prices		
		S/Nett	Remark	
			\$	59,597.50
81	RADIATOR	\$ 2,040.00	\$	2,040.00
82	REFRIGERANT HOSE FOR A/C CONDENSER	\$ 234.00		
83	A/C CONDENSER PROTECTIVE GRILLE	\$ 127.00	\$	127.00
84	RADIATOR RUBBER BUSH-UPPER	2 \$ 12.00	\$	11.80
85	RADIATOR RUBBER BUSH-CENTER	2 \$ 18.00	\$	17.60
86	RADIATOR RUBBER BUSH-LOWER	2 \$ 58.00	\$	57.60
87	COOLANT	\$ 84.00	\$	84.00
88	ADDITIONAL RADIATOR FOR FRONT CENTER	\$ 3,083.00	\$	3,083.00
89	ADDITIONAL RADIATOR FOR FRONT-LH FRONT	\$ 1,840.00		
90	ADDITIONAL RADIATOR FOR FRONT-LH REAR	\$ 1,530.00		
91	ADDITIONAL RADIATOR BRACKET-LH	\$ 472.00		
92	ADDITIONAL RADIATOR UPPER BRACKET-LH	\$ 30.00		
93	ADDITIONAL RADIATOR COOLANT PUMP-LH OUTER	\$ 292.00		
94	COOLANT PUMP-LH INNER	\$ 1,219.00		
95	COOLANT PUMP STOP BUFFER-LH INNER	\$ 15.00		
96	ADDITIONAL COOLANT PUMP BRACKET-LH INNER	\$ 30.00		
97	ADDITIONAL COOLANT PUMP ATTACHMENT PARTS	\$ 66.00		
98	FRONT RADIATOR AIR GUIDE-LH	\$ 27.00		
99	TWIN FAN RING	\$ 400.00	\$	399.50
100	RADIATOR FAN-LH/RH	2 \$ 6,712.00	\$	6,712.00
	SUB TOTAL SPARE PARTS CHARGES	\$18,289.00		\$72,130.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 29 M

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
	<i>c/t</i>			\$ 72,130.00
101	RADIATOR CENTER AIR GUIDE-LH/RH	2 \$	92.00	\$ 90.80
102	RADIATOR CENTER AIR GUIDE-LH/RH REAR	2 \$	100.00	\$ 49.60
103	RADIATOR CENTER LOWER COVER	\$	154.00	
101	RADIATOR CENTER UPPER COVER	\$	34.00	\$ 33.50
102	RADIATOR AIR GUIDE-LH/RH	2 \$	158.00	
103	AIR INTAKE FILTER	\$	467.00	
104	AIR INTAKE AIR GUIDE	\$	46.00	
105	AIR INTAKE DUCT	\$	87.00	
106	AIR INTAKE DUCT BELLOWS	2 \$	105.00	
107	FRONT WINDSCREEN	\$	2,671.00	\$ 2,671.00
108	FRONT WINDSCREEN RAIN SENSOR	\$	749.00	\$ 128.00
109	PRIMER FOR FRONT WINDSCREEN	2 \$	38.00	\$ 18.60
110	WATER DEFLECTOR STRIP - LH/RH	2 \$	122.00	
111	FRONT W/S SEALANT	S/N \$	200.00	\$ 200.00
112	FRONT NO. PLATE	S/N \$	40.00	\$ 40.00
114	<i>Added parts - see attached</i>	\$	4,125.00	\$ 4,117.40
115	SUNDRIES	\$	800.00	\$ 123.50
	TOTAL SPARE PARTS CHARGES	: \$	92,406.00	\$ 79,602.40
	TOTAL LABOUR CHARGES	: \$	27,544.00	\$ 14,204.00
	GRAND TOTAL	: \$	119,950.00	\$ 93,806.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

First Capital Insurance Ltd 36 Robinson Road # 16-01 City House Singapore 068877 Attn: Motor Claims Dept Tel: 6854 3909 Fax: 6507 3849		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0867/2019/GW 27-Aug-19 Glory Tan 1 of 1 SKS 29 M RS 6 AVENT 4.0 TFSI QUATTRO
Quantity	Description	Unit Price	Amount
Parts			
1	Support for lock carrier	\$ 12.00	\$ 11.20
2	Guide piece RHS	\$ 99.00	\$ 98.60
3	Audi emblem for radiator grille	\$ 113.00	\$ 112.50
4	Emblem adapter	\$ 198.00	\$ 197.50
5	Cover cap for lift cylinder LHS	\$ 102.00	\$ 101.50
6	Compensating piece for headlight	\$ 153.00	\$ 152.80
7	Adjustment element for headlight	\$ 83.00	\$ 82.40
8	Breather line for additional radiator	\$ 45.00	\$ 45.00
9	Spray nozzle, heated	\$ 42.00	\$ 41.30
10	Air guide for charge air cooler	\$ 2,698.00	\$ 2,698.00
11	Seal for air guide for charge air cooler LHS	\$ 79.00	\$ 78.10
12	Seal for air guide for charge air cooler RHS	\$ 79.00	\$ 78.10
13	Cable guide for oil temperature sender	\$ 23.00	\$ 22.40
14	Flat contact housing with contact	\$ 37.00	\$ 36.50
15	locking mechanism		
16	Headlight hose RHS	\$ 15.00	\$ 14.50
17	Thermo-pneumatic valve	\$ 347.00	\$ 347.00
		\$ 4,125.00	\$ 4,117.40
LABORS			
1	To remove and renew charge air cooler and other damaged engine components.	S/N \$ 980.00	\$ 980.00
	TOTAL	\$ 5,105.00	\$ 5,097.40

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 29 November 2019 4:06 PM
To: Carrine Leong
Cc: 'Boo seng yak'; 'Chang Chee Sing'; jiayee.yap@premiumauto.com.sg; SUR
Subject: RE: FINAL REVISION - SKS29M - OD FIRSTCAP - SURVEYED RASUL - 18 JUL 19

Dear Carrine,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Thursday, 28 November 2019 5:30 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Chang Chee Sing' <claims@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; SUR <sur@lkkauto.com>
Subject: RE: FINAL REVISION - SKS29M - OD FIRSTCAP - SURVEYED RASUL - 18 JUL 19

Hi Veron,

Ok.

Thanks & Best Regard

Carrine Leong

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

* Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]

Sent: Monday, 25 November, 2019 3:34 PM

To: Boo seng yak <boojohnny@gmail.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; Jiayee.yap@premiumauto.com.sg; SUR <sur@lkkauto.com>

Subject: RE: FINAL REVISION - SKS29M - OD FIRSTCAP - SURVEYED RASUL - 18 JUL 19

Dear Carrine,

Confirm repair cost of \$93,806.40 @ 15 days instead of 18 days of repairs.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Thursday, 21 November 2019 6:58 PM

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; Jiayee.yap@premiumauto.com.sg

Subject: FINAL REVISION - SKS29M - OD FIRSTCAP - SURVEYED RASUL - 18 JUL 19

Hi Adrian, Rasul and all,

Revised estimate is attached. Photographs is obtainable from our Ubi office.

Please confirm repair cost of \$93,806.40 @ 18 days of repairs.

Your early closure is well appreciated.

Best regards - jb



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19012579/T1v3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-12-2019	
		Code : FCI2	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SKS 29M
Policy No.	D-18091577MVPC/1	Coverage (\$)	0.00
Claim No.	D19004660MVPC	Excess (\$)	0.00
Assign From	ROSLIZA	Assign Date	16/07/2019
2. Vehicle Particulars & Condition			
Make & Model	AUDI RS6 AVANT	c.c	3993
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WUJZZZ4G5EN903833	Colour	GREY
Odometer	80807	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/35 R20	MICHELIN	6 mm
L/H Front Tyre	275/35 R20	MICHELIN	6 mm
R/H Rear Tyre	275/35 R20	MICHELIN	6 mm
L/H Rear Tyre	275/35 R20	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/07/2019	Inspection Date	18/07/2019
Survey held at	24 BENOI SECTOR		
Repairer	PREMIUM AUTOMOBILES PTE LTD		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 29M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (SN)	DEFORMED	7,006.00	7,006.00
2	FRONT BUMPER SECURING STRIP (SN)	DEFORMED	13.00	12.20
1	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE (SN)	CRACKED	351.00	350.50
2	FRONT BUMPER CLOSING ELEMENT - LH / RH (SN)	N/S DEFORMED / O/S NOT NECESSARY	546.00	273.00
2	FRONT BUMPER END CAP - LH / RH (SN)	N/S DISTORTED / O/S DEFORMED	206.00	205.00
1	FRONT BUMPER PULL STRAP (SN)	DISTORTED	90.00	89.90
1	FRONT BUMPER SPOILER (SN)	CRACKED	1,111.00	1,111.00
1	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE (SN)	DEFORMED	390.00	390.00
1	FRONT BUMPER SPOILER - LOWER CENTRE (SN)	DEFORMED	227.00	226.50
2	FRONT BUMPER GRILLE - LH / RH (SN)	DEFORMED	338.00	337.00
2	FRONT BUMPER GRILLE COVER - LH / RH (SN)	N/S DEFORMED / O/S NOT NECESSARY	684.00	273.60
2	FRONT BUMPER AIR GUIDE GRILLE - LH / RH (SN)	N/S MISSING / O/S CRACKED	796.00	795.00
2	FRONT BUMPER AIR GUIDE COVER - LH / RH (SN)	N/S MISSING / O/S CRACKED	154.00	152.40
1	RADIATOR GRILLE - ALUMINIUM MATT (SN)	CRACKED	4,336.00	4,336.00
1	RADIATOR GRILLE LOGO CIVER (SN)	CRACKED	122.00	121.50
1	INSCRIPTION 'RS6' (SN)	MISSING	113.00	112.50
1	RADIATOR GRILLE SECURING ELEMENT (SN)	NECESSARY	11.00	10.30
1	FRONT REINFORCEMENT BEAM COVER (SN)	CRACKED	265.00	265.00
2	FRONT SENSOR SUPPORT - LH / RH INNER (SN)	NECESSARY	122.00	121.20
1	FRONT LICENCE PLATE HOLDER (SN)	MISSING	497.00	497.00
1	FRONT REINFORCEMENT BEAM (SN)	BENT	754.00	753.50
1	FRONT BUMPER FOAM (SN)	CRACKED	246.00	246.00
1	FRONT BUMPER UPPER COVER (SN)	MISSING	318.00	318.00
1	FRONT BUMPER GUIDE PIECE - LH (SN)	DISTORTED	99.00	98.60
1	FRONT BUMPER BRACE - LH (SN)	NOT NECESSARY	27.00	-

Report Ref No. CS/FCI19012579/T1vf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT REINFORCEMENT BEAM HOLDER - LH (SN)	BENT	237.00	236.50
1	SIGN 'CAUTION' (SN)	NECESSARY	13.00	12.20
1	AIR CONDITIONER STICKER (SN)	NECESSARY	16.00	15.90
2	FRONT PARKING AID SENSOR - INNER (SN)	NOT NECESSARY	419.00	-
2	FRONT PARKING AID SENSOR - OUTER (SN)	NOT NECESSARY	462.00	-
4	FRONT SENSOR SEAL RING (SN)	NECESSARY	5.00	4.80
1	SET FRONT BUMPER WIRING (SN)	NOT NECESSARY	532.00	-
1	FRONT SIGNAL HORN - LOW TONE - LH (SN)	NOT NECESSARY	182.00	-
1	FRONT SIGNAL HORH - HIGH TONE - RH (SN)	NOT NECESSARY	180.00	-
1	HORN BRACKET - LH (SN)	NOT NECESSARY	43.00	-
1	HORN BRACKET - RH (SN)	NOT NECESSARY	40.00	-
2	FRONT FENDER - LH / RH (SN)	BENT	6,832.00	6,832.00
2	FRONT FENDER BRACE - LH / RH (SN)	N/S BENT / O/S NOT NECESSARY	150.00	74.60
2	FRONT FENDER CLOSING ELEMENT - LH / RH (SN)	NOT NECESSARY	96.00	-
2	FRONT FENDER SEAL - LH (SN)	NOT NECESSARY	36.00	-
1	FRONT WHEEL HOUSING LINER - LH (SN)	DEFORMED	626.00	625.00
1	FRONT WHEEL SPOILER - LH (SN)	DEFORMED	62.00	61.60
1	BONNET (SN)	BENT	4,965.00	4,965.00
2	BONNET LID HINGE - LH / RH (SN)	BENT	292.00	292.00
2	BONNET DAMPER (SN)	NOT NECESSARY	217.00	-
1	BONNET CATCH HOOK (SN)	BENT	127.00	127.00
2	BONNET LOCK BAR (SN)	BENT	90.00	90.00
2	BONNET HINGE COVER - LH / RH (SN)	NOT NECESSARY	10.00	-
1	BONNET CATCH HOOK (SN)	DISTORTED	16.00	15.40
1	BONNET CATCH HOOK COVER (SN)	DISTORTED	4.00	3.20
2	BONNET LID LOCK WITH MICRO SWITCH (SN)	BENT	391.00	391.00
2	BONNET MICRO SWITCH (SN)	NOT NECESSARY	133.00	-
2	BONNET LOCK CONNECTOR HOUSING BRACKET (SN)	DISTORTED	18.00	17.20
1	BONNET BOWDEN CABLE - CENTER (SN)	DISTORTED	53.00	52.10
1	BONNET BOWDEN CABLE COVER (SN)	DISTORTED	9.00	8.90
1	BONNET LOCK CABLE (SN)	NOT NECESSARY	67.00	-
2	HEADLIGHT MOUNTING - LH / RH (SN)	N/S CRACKED / O/S NOT NECESSARY	214.00	107.00

Report Ref No. CS/FCI19012579/T1vf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	COOALNT REGULATOR SUPPORT - LH / RH (SN)	NECESSARY	68.00	66.80
1	RADIATOR CORE SUPPORT - LH (SN)	NOT NECESSARY	268.00	-
2	LED HEADLIGHT - LH / RH (SN)	CRACKED	22,420.00	22,420.00
1	LED HEADLIGHT FAN (SN)	SHORTED	363.00	363.00
1	DRIVING LIGHT POWER MODULE (SN)	SHORTED	520.00	519.50
1	CORNERING LIGHT POWER MODULE (SN)	SHORTED	508.00	507.50
1	MAIN LIGHT POWER MODULE (SN)	SHORTED	1,070.00	1,070.00
1	LED HEADLIGHT HOSE (SN)	NOT NECESSARY	15.00	-
2	LED HEADLIGHT LIFT CYLINDER - LH / RH (SN)	N/S CRACKED / O/S NOT NECESSARY	432.00	215.50
1	LIFT CYLINDER HOSE (SN)	CUT	179.00	179.00
1	DISTRIBUTOR FOR LIFT CYLINDER (SN)	NECESSARY	27.00	26.80
1	ELBOW FITTING FOR LIFT CYLINDER (SN)	NECESSARY	19.00	19.00
2	ELBOW FITTING FOR LIFT CYLINDER (SN)	NECESSARY	47.00	46.20
1	HEADLIGHT PUMP FOR WASHER SYSTEM (SN)	NOT NECESSARY	147.00	-
1	WASH WATER RESERVOIR (SN)	NOT NECESSARY	174.00	-
1	FRONT WINDSCREEN WASHER SYSTEM (SN)	NOT NECESSARY	118.00	-
1	WIPER COWL COVER (SN)	NOT NECESSARY	183.00	-
1	WATER DEFLECTOR (SN)	DEFORMED	69.00	68.60
1	LOCK CARRIER MOUNTING FOR RADIATOR (SN)	CRACKED	1,140.00	1,140.00
1	A/C CONDENSER (SN)	BENT	689.00	689.00
1	HIGH PRESSURE SWITCH FOR A/C VALVE (SN)	NOT NECESSARY	48.00	-
1	PRESSURE SENSOR FOR A/C (SN)	NOT NECESSARY	175.00	-
1	A/C PIPE - COMPRESSOR > CONDENSER (SN)	BENT	234.00	233.50
1	RADIATOR (SN)	BENT	2,040.00	2,040.00
1	REFRIGERANT HOSE FOR A/C CONDENSER (SN)	NOT NECESSARY	234.00	-
1	A/C CONDENSER PROTECTIVE GRILLE (SN)	CRACKED	127.00	127.00
2	RADIATOR RUBBER BUSH - UPPER (SN)	NECESSARY	12.00	11.80
2	RADIATOR RUBBER BUSH - CENTER (SN)	NECESSARY	18.00	17.60
2	RADIATOR RUBBER BUSH - LOWER (SN)	NECESSARY	58.00	57.60
1	COOLANT (SN)	NECESSARY	84.00	84.00
1	ADDITIONAL RADIATOR FOR FRONT CENTER (SN)	BENT	3,083.00	3,083.00
1	ADDITIONAL RADIATOR FOR FRONT - LH FRONT (SN)	NOT NECESSARY	1,840.00	-

Report Ref No. CS/FC119012579/T1vf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ADDITIONAL RADIATOR FOR FRONT - LH REAR (SN)	NOT NECESSARY	1,530.00	-
1	ADDITIONAL RADIATOR BRACKET - LH (SN)	NOT NECESSARY	472.00	-
1	ADDITIONAL RADIATOR UPPER BRACKET - LH (SN)	NOT NECESSARY	30.00	-
1	ADDITIONAL RADIATOR COOLANT PUMP - LH OUTER (SN)	NOT NECESSARY	292.00	-
1	COOLANT PUMP - LH INNER (SN)	NOT NECESSARY	1,219.00	-
1	COOLANT PUMP STOP BUFFER - LH INNER (SN)	NOT NECESSARY	15.00	-
1	ADDITIONAL COOLANT PUMP BRACKET - LH INNER (SN)	NOT NECESSARY	30.00	-
1	ADDITIONAL COOLANT PUMP ATTACHMENT PARTS (SN)	NOT NECESSARY	66.00	-
1	FRONT RADIATOR AIR GUIDE - LH (SN)	NOT NECESSARY	27.00	-
1	TWIN FOR RING (SN)	CRACKED	400.00	399.50
2	RADIATOR FAN - LH / RH (SN)	CRACKED	6,712.00	6,712.00
2	RADIATOR CENTER AIR GUIDE - LH / RH (SN)	DEFORMED	92.00	90.80
2	RADIATOR CENTER AIR GUIDE - LH / RH REAR (SN)	N/S DEFORMED / O/S NOT NECESSARY	100.00	49.60
1	RADIATOR CENTER LOWER COVER (SN)	NOT NECESSARY	154.00	-
1	RADIATOR CENTER UPPER COVER (SN)	CRACKED	34.00	33.50
2	RADIATOR AIR GUIDE - LH / RH (SN)	NOT NECESSARY	158.00	-
1	AIR INTAKE FILTER (SN)	NOT NECESSARY	467.00	-
1	AIR INTAKE AIR GUIDE (SN)	NOT NECESSARY	46.00	-
1	AIR INTAKE DUCT (SN)	NOT NECESSARY	87.00	-
2	AIR INTAKE DUCT BELLOWS (SN)	NOT NECESSARY	105.00	-
1	FRONT WINDSCREEN (SN)	CRACKED	2,671.00	2,671.00
1	FRONT WINDSCREEN RAIN SENSOR (SN)	NECESSARY	749.00	128.00
2	PRIMER FOR FRONT WINDSCREEN (SN)	NECESSARY	38.00	18.60
2	WATER DEFLECTOR STRIP - LH / RH (SN)	NOT NECESSARY	122.00	-
1	FRONT W/S SEALANT (SN)	NECESSARY	200.00	200.00
1	FRONT NO. PLATE (SN)	MISSING	40.00	40.00
1	SUNDRIES (SN)	NECESSARY	800.00	123.50
1	SUPPORT FOR LOCK CARRIER (SN) (ADDITIONAL)	MISSING	11.20	11.20
1	GUIDE PIECE RHS (SN) (ADDITIONAL)	CRACKED	98.60	98.60
1	AUDI EMBLEM FOR RADIATOR GRILLE (SN) (ADDITIONAL)	CRACKED	112.50	112.50

Report Ref No. CS/FCI19012579/T1vf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EMBLEM ADAPTER (SN) (ADDITIONAL)	CRACKED	197.50	197.50
1	COVER CAP FOR LIFT CYLINDER LHS (SN) (ADDITIONAL)	DEFORMED	101.50	101.50
1	COMPENSATING PIECE FOR HEADLIGHT (SN) (ADDITIONAL)	MISSING	152.80	152.80
1	ADJUSTMENT ELEMENT FOR HEADLIGHT (SN) (ADDITIONAL)	MISSING	82.40	82.40
1	BREATHER LINE FOR ADDITIONAL RADIATOR (SN) (ADDITIONAL)	CUT	45.00	45.00
1	SPRAY NOZZLE, HEATED (SN) (ADDITIONAL)	CRACKED	41.30	41.30
1	AIR GUIDE FOR CHARGE AIR COOLER (SN) (ADDITIONAL)	CRACKED	2,698.00	2,698.00
1	SEAL FOR AIR GUIDE FOR CHARGE AIR COOLER LHS (SN) (ADDITIONAL)	NECESSARY	78.10	78.10
1	SEAL FOR AIR GUIDE FOR CHARGE AIR COOLER RHS (SN) (ADDITIONAL)	NECESSARY	78.10	78.10
1	CABLE GUIDE FOR OIL TEMPERATURE SENDER (SN) (ADDITIONAL)	NECESSARY	22.40	22.40
1	FLAT CONTACT HOUSING WITH CONTACT (SN) (ADDITIONAL)	CRACKED	36.50	36.50
1	LOCKING MECHANISM (SN) (ADDITIONAL) (NPA)	NOT NECESSARY	-	-
1	HEADLIGHT HOSE RHS (SN) (ADDITIONAL)	MISSING	14.50	14.50
1	THEMO-PNEUMATIC VALVE (SN) (ADDITIONAL)	CRACKED	347.00	347.00
			92,541.40	79,602.40
	LABOUR			
	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.		280.00	280.00
	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	NOT NECESSARY	800.00	-
	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.		480.00	480.00
	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.		1,600.00	1,600.00
	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR-O-LINER REPAIRS.	NOT NECESSARY	2,800.00	-

Report Ref No. CS/FCI19012579/T1vf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR-O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	NOT NECESSARY	2,800.00	-
	TO RENEW FRONT WINDSCREEN.		480.00	480.00
	TO PLACE VEHICLE ON CAR-O-LINER.	NOT NECESSARY	2,400.00	-
	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW LHS FRONT CHASSIS BRACKET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		8,800.00	6,400.00
	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, BONNET HINGES AND ENGINE COMPARTMENT.		5,500.00	3,600.00
	TO CARRY OUT WHEEL ALIGNMENT.	NOT NECESSARY	240.00	-
	TO CARRY OUT DIAGNOSTIC CHECKS.		384.00	384.00
	TO REMOVE AND RENEW CHARGE AIR COOLER AND OTHER DAMAGED ENGINE COMPONENTS. (ADDITIONAL)		980.00	980.00
			27,544.00	14,204.00
GRAND TOTAL			120,085.40	93,806.40
RECOMMENDED COST OF REPAIRS				93,806.40

Report Ref No. CS/FCI19012579/T1vf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.