

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

WDC156942J607675

CHUNG HIU WAI

31 LORONG 39 GEYLANG

#07-01

S 387878

TPA16.

Asher.

Date

:03.08.2019

Vehicle No

:SML 2284 S

Make/Model

:MERCEDES GLA180

Accident date

:05.07.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear RH door <i>Dented</i>	1	\$ 1925 ✓
2	Rear RH door glass outer moulding <i>also new</i>	1	\$ 198 ✗
3	Rear RH door outer handle <i>it</i>	1	\$ 148.5 ✓
4	Rear RH door lower sticker <i>also</i>	1	\$ 31.9 ✓
5	Rear RH door inner lock <i>also</i>	1	\$ 319 ✗
6	Rear RH door top inner rubber <i>new</i>	1	\$ 154 ✗
7	Rear RH door inner weather strip <i>new</i>	1	\$ 313.5 ✓
8	Rear RH door inner board <i>also new</i>	1	\$ 1138.5
9	Rear RH door power window motor <i>also new</i>	1	\$ 566.5 ✗
10	Rear RH door power window regulator <i>also new</i>	1	\$ 649 ✗
11	Rear RH fender lower garnish <i>cut</i>	1	\$ 60.5 ✓
12	Front RH door <i>Regis</i>	1	\$ 1639 ✗
13	Front RH door glass outer moulding <i>also new</i>	1	\$ 176 ✗
14	RH rocker panel garnish <i>cut</i>	1	\$ 396 ✓
15	Rear RH sport rim <i>cut</i>	1	\$ 858 ✓
16	Rear RH tyre <i>also new</i>	1	\$ 330 ✗
			\$ 8903.4
Less 10% Disc			\$ 890.3
Total			\$ 8013.1

Labour Cost

- 1 Remove & reinstall door glass *fitting*
- 2 Remove, replace & repair consistent to the accident
- 3 Respray painting
- 4 Tuff kote

	\$ 300 <i>80.</i>
	\$ 1300 <i>500.</i>
	\$ 1400 <i>600.</i>
	\$ 150 ✗
Total	\$ 3150

Grand Total \$ 11163.1

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 4540.06

h/s: 3-61c

04 Days

3-61c