

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06012

Vehicle Insured : SMA2318L
 Accident Date : 11-Jul-2019

Date : 15-Jul-2019

Our Ref : 219110 (AIG) / CHAN

PAGE : 1

EMILY CHAN CHIN YEOK
 BLK 546 SERANGOON NORTH AVENUE 3
 #04-214
 Singapore 550546

*Not Withheld
 Putaway By paint
 2 days*

ESTIMATED COST OF REPAIR FOR HYUNDAI ELANTRA 1.6A SLS7314G

- 1 pc Rear bumper fascia
- 1 pc Rear bumper lower garnish
- 1 pc Rear o/s bumper reflector
- 1 pc Rear o/s bumper side retainer
- 1 pc Rear bumper reinforcement
- 1 pc O/s bumper reinforcement brakt
- 1 pc O/s reinforcment lower bracket
- 1 pc Rear end panel

CM	459.40	✓
Bu	250.10	✓
Pr	40.80	✓
R	44.30	x
R	294.30	7x
R	78.60	7x
R	25.60	7x
R	454.60	x

Less 20% : 1,647.70
 329.54

*750.30
 150.06
 600.24
 1,318.16
 300.00 sn x*

1 pc Rear bumper reverse sensor

To putty and spray replaced parts

2201 500.00

To remove, cut-out damaged parts,
 panel beating, welding, align,
 refix and to renew above parts

*2001
 400.00*

Total : S\$ 2,518.16

Singapore Dollars Two Thousand Five Hundred and Eighteen and Cents Sixteen Only

*P 600.24
 L 420.00

 → 1020.24 ✓ ok*

REMOVED Pcs Cost 7k 5.