


Vehicle Ston

REF:

NTUC NS/INC 19012587 / EAF 357

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OO / TP / WS / TP RES / OO RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop n/vs: _____
at: _____
Insured: SLB 29985
Policy No: 5078659181-03 (12/04/17-11/04/2024)
Claims No: WT/1105 3235-002
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____
(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lump Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT
Date / Time : _____ Action / Instruction



Veh No: SHC 4247T Yt Regn: 22/11/13
Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) / Prime Mover /
Truck / Trailer or
Make: Toyota Prius c.c: 1798
Colour: Maroon A/C Insured / Std / NI
Sp. Reading: 401994 T/Rndlnr Insured / Std / NI
Eng/No: _____
C/No: JTD KN 364 305705975
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/65R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Michelin Westlake
Front: _____ Rear: _____
R/Bal. 5 mm R/Bal. 5
L/Bal. 5 mm L/Bal. 5
D.O.A. 11/7/19 D.O.I. 12/7/19
Survey held at SMRT
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
front LH
The UIC / Chassis frame / Body Structure affected due to co

SHC 4247T- CS/TT 090 2294 8/1/19/1 ROA-10/10/2009 07/19/2048
SLB 29985-X SKB29985
29/7/19 Finalize Confir \$2750, 4 days (Red: 7213:14:720%)

RECEIVED 01 AUG 2019

Date/Time, File Pass to: _____
1/3 Typist
Date/Time, File Return to: _____
☐ : Prel. Report
☒ : Final Report

Days Of Repair: 4
Resurvey No. of Trip: 1

Report Format: TP
Lump Sum / I.B: 27501

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee:
Transportation
S.R. 2
Photos
Index
Total

Denise Tay (LKKAuto)

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Tuesday, 30 July 2019 8:35 AM
To: Steve Chen (LKK Auto)
Cc: SUR; CS A Team
Subject: RE: SHC4247T

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: Monday, 29 July 2019 7:41 PM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Subject: SHC4247T

Dear Poh Suan,

We confirm the finalize \$2750 (L/S, before GST). 4 repair days.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Monday, July 29, 2019 4:09 PM
To: Steve Chen (LKK Auto)
Cc: SUR; CS A Team
Subject: SHC4247T

Hi Steve,

Attached herewith the repair estimate of SHC 4247T having Case No: TAX/07/19/2048.

There is no change to the approved amount of \$2,750 @ 4 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Denise Tay (LKKAUTO)

From: MTCL@income.com.sg
Sent: Thursday, 1 August 2019 12:26 PM
To: Denise Tay (LKKAUTO)
Subject: FW: REQUEST CLAIM NUMBER

Hi,

All claims created.

With Regards

Samsia
Senior Admin Assistant,
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Thursday, 1 August 2019 11:43 AM
To: MTCL@income.com.sg; mtreg <mtreg@income.com.sg>
Subject: REQUEST CLAIM NUMBER

Dear Sir/Madam,

Request claim number

Date : 1/8/2019

S/No		Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1035311-002	SMRT	SHB 774U	SJL 3750S	8/3/2019	23:45	8,684.80	2100
2	MT/1053235-002	SMRT	SHC 4247T	SKB 2998S	11/7/2019	18:10	9,963.14	2750
3	MT/1052883-002	SMRT	SHC 4391J	AY 4532L	10/7/2019	20:05	11,892.10	1900

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No. (For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5078659181-03		LEE PENG ANN	S1201844D	GPC	drive PREMIUM	SKB2998S	SKB2998S	12/04/2019	11/04/2020

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/07/2019 10:39
Date Of Accident	11/07/2019 18:10
Exact Location Of Accident	ROCHOR CANAL ROAD TOWARDS BUKIT TIMAH ROAD
Country/State Of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4247T
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	
Driver	
Name of Driver	YAP TECK GIM
NRIC No	S7320819Z
Date Of Birth	07/06/1973
Occupation	OUTDOOR
Date Of Driving Pass	10/03/2003
Driving Experience	16 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 11
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - RELIEF
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1
 NAME: : UNKNOWN
 GENDER: : FEMALE
 Passenger 2
 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name SEMBANWANG NPC
 Police Station Address ROAD: 4 SEMBAWANG CRESCENT , POSTCODE: 757633 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20190711/2157 2 FEMALE PAX (FOREIGNER)

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TOO BIG
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKB2998S
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR

Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	YAP TECK GIM
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHC4247T
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Rochor canal Rd towards Bukit Timah Rd

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190711/2157

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

1 of 3

Report No. T/20190711/2157

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/07/2019 23:50		Vide Report No.:		Station Diary No.: 163
Informant's Particulars				
Name of Informant: YAP TECK GIM		Address: APT BLK 571C WOODLANDS AVENUE 1 #08-940 SINGAPORE 733571		
ID Type / ID No.: NRIC NO / S7320819Z		Contact No.: Home/Office: Mobile: 88168939		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 46	Date of Birth: 07/06/1973	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 11/07/2019 18:10	Type of Location: Straight Road
Location: Along Road 1 ROCHOR CANAL ROAD Rochor Canal Road towards Bukit Timah Road				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHC4247T	Car	TOYOTA	PRIUS TAXI (SMRT)	Maroon	Seriously Damaged	2
SKB2998S	Car	BMW		Black	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190711/2157

2 of 3

Report No. T/20190711/2157

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

CONTINUATION OF REPORT

Driver			
Name	YAP TECK GIM	ID No.	S7320819Z
Related Vehicle	NIL	Contact No.	88168939
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 11/07/2019 at about 6.10pm, I was driving along Rochor Canal Road towards Bukit Timah Road. There were 5 lanes, and I was driving on the 2nd right lane. While moving forward, a BMW vehicle on the 3rd lane swerve onto my lane without signaling which causes both our vehicles to collide. My vehicle sustained damages on the left front side of the vehicle.

We managed to exchange particulars however I have lost the particulars of the other driver and only has his handphone number, 98336662.

Due to the accident, I have sustained injuries on my neck and back. I went to seek medical treatment at Mount Alvernia Hospital and was given 5-days MC.



**SINGAPORE
POLICE FORCE**



T/20190711/2157

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

3 of 3

Report No. T/20190711/2157

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: L / Sgt 2 NUR ATIQA BINTE ABDULLAH @ ABDULL RAHIM	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 11/07/2019 23:50
Officer In Charge Of Case: TP / AEIT / Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED MOHD SAID Contact No.: 65476172	Classification Of Case: SN 035
Authentication Stamp NP168	Signature: Singapore Police Force

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 5369K

Vehicle Details

Vehicle No.: SHC4247T
Vehicle to be Exported: No
Intended Deregistration Date: 16 Jul 2019
Vehicle Make: TOYOTA
Vehicle Model: PRIUS TAXI (SMRT)
Primary Colour: Maroon
Manufacturing Year: 2013
Engine No.: 2ZR5906053
Chassis No.: JTDKN36U305705075
Maximum Power Output: 100.0 kW (134 bhp)
Open Market Value: \$33,120.00
Original Registration Date: 22 Nov 2013
First Registration Date: 22 Nov 2013
Transfer Count: 0
Actual ARF Paid: \$8,368.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 21 Nov 2021
PARF Rebate Amount: \$5,857.00

Intended COE Rebate Details

COE Expiry Date: 21 Nov 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 8
PQP Paid: \$63,297.00
COE Rebate Amount: \$18,571.00
Total Rebate Amount: \$24,428.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 16 Jul 2019

OK

Case Details

Case Reference Number : TAX/07/19/2048

Type of Repair : Accident Repair

Vehicle Registration Number : SHC4247T

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-7664-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income

Insurance Co-operative Ltd

Accident Date and Time : 11/07/2019 10:10 AM

Vehicle Age(In Months) : 68

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation					Repair/ Replace	Surveyor Quantity	Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Surveyor Final Price(\$)			Repair/Replace			
One Time Key In	Main			BUMPER CLIPS	10	1.61 16.10	16.10	25.00	12.08	Replace	10	12.08	Replace	✓	MC	
One Time Key In	Main		6505516	BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace	✓	BR	
One Time Key In	Main		6505541	BUMPER GRILLE SUB-ASSY,LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	Check	✓	X NAI	
One Time Key In	Main		6505438	FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	0	0	Check	✓	X NAI	
One Time Key In	Main			LENS & BODY, FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Givr	✓	X NAI	
One Time Key In	Main			BRACKET, FR TURN UPPER LH	1	24.40	24.40	25.00	18.30	Replace	0	0	Check	✓	X NAI	
One Time Key In	Main			BRACKET, FR TURN CENTER LH	1	58.20	58.20	25.00	43.65	Replace	0	0	Check	✓	X NAI	
One Time Key In	Main			BRACKET, FR TURN LOWER LH	1	26.00	26.00	25.00	19.50	Replace	0	0	Check	✓	X NAI	
One Time Key In	Main		6505616	BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Givr	✓	X NAI	
One Time Key In	Main		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Not Givr	✓	X NAI	
One Time Key In	Main		6505436	HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace	✓	BR	
One Time Key In	Main		6505558	FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	✓	PD	
One Time Key In	Main		6505640	NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.93	Replace	1	38.93	Replace	✓	MC	
One Time Key In	Main			SEAL, FRONT FENDER TO COWL SIDE LH	1	114.50	114.50	25.00	85.88	Replace	0	0	Not Givr	✓	X NAI	
One Time Key In	Main		6505554	FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.78	Replace	1	128.78	Replace	✓	MIS	

Total Spare Part Cost 6,007.37

Surveyor Total 1,991.80

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dia(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FENDER LINER PAD, FR WHEEL LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	X N/A
One Time Key In	Main			FENDER APRON FRT/LH	1	140.80	140.80	25.00	105.60	Replace	0	0	Not Give	X N/A
One Time Key In	Main		6505658	WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair	X R
One Time Key In	Main		6503707	TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	X N/A
One Time Key In	Main			WHEEL HUB FRT	1	549.70	549.70	25.00	412.28	Replace	0	0	Not Give	X N/A
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give	X N/A
One Time Key In	Main			DOOR FRT/LH	1	894.40	894.40	25.00	670.80	Replace	0	0	Not Give	X N/A
One Time Key In	Main			QUARTER GLASS FRT/LH	1	234.90	234.90	25.00	176.18	Replace	0	0	Check	X N/A
Standard	Main		6505517	BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	DO

Total Spare Part Cost 6,007.37

Surveyor Total 1,991.80

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 4,805.90

Final Sur Total 1,593.44

(Supp) 252.09

36.98

P = 2750.89

L = 1183

L/S = 2768.71

= 2750

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	845.00	450	
Total:			845.00	450.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT WHEEL HOUSE LH	180.00	0	
3	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
4	Main	TO RESPRAY RIM	180.00	50	
5	Main	TO RESPRAY FRONT DOOR LH	378.00	0	
6	Main	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0	
Total:			1,674.00	450.00	

+ 80 (Supp)

530

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	--------------	-----------	-------------------------	-------------------------	---------

			Recommendation(\$)	Adjustment(\$)
1	Main	TOWING CHARGE	84.00	0
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20 / <i>npc</i>
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60 / <i>npc</i>
4	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0 <i>na</i> <i>SAJ</i>
5	Main	TO TRANSFER DOOR MECHANISM	120.00	0
6	Main	TO WASH AND VACUUM	60.00	0
7	Main	TO REPLACE SUNDRY PARTS	100.00	20 / <i>npc</i>
Total:			689.00	100.00

10808.14

11573.57

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	4,805.90	1,593.44
Total Labour Cost	845.00	450.00
Total Spray Painting	1,674.00	450.00
Other	689.00	100.00
Overall Total	8,013.90	2,593.44
Lump Sum Repair Option		
Lump Sum Total	8,000.00	2,600.00
Surveyor Approved Amount		2,600.00
No of Repair Days*	6	4
Remarks		L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com.
Surveyor Name		STEVE CHEN
Signature		

Survey Date

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Save

Clear

REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX 07/19/2048	Date of Collection :	1 / 1
Vehicle No	SHC 4247 T	Date of Request	13/07/2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	20

S/N	Part Number	Part Description	Quantity	Unit Price
		FOG LAMP LH 336-12	1pc	1 DR 252.09 /
		FRONT BUMPER LIP	1pc	MISSING X NM
		FRONT FENDER LINER PAD LH 44-31	1pc	MISSING / MIS 36
	Labour	TO REPAIR FRONT FENDER APRON PANEL		\$ 200 100 /
	Labour	TO SPRAY FRONT FENDER APRON PANEL		\$ 180 80 /

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / FO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
62 Woodlands Industrial Park E4, Singapore 757705
FAX Number 63855592
Estimator Telephone Number 68692623
Accident Reporting Number 50602672



Date Generated : 29/07/2019

User ID : PohSuan

Section A - Accident Details

Registration Number	SHC4247T
Case Reference Number	TAX/07/19/2048
Registration Date	22/11/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	YAP TECK GIM(YE DEJIN)
Type of Accident	Side Swipe
Accident Date and Time	11/7/2019 6:10 PM
Accident Reported Date and Time	12/7/2019 10:47 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	11/7/2019 6:35 PM
Replacement Vehicle Issued?	No
Job Card Number	24102387
Special Instruction to ARC, if any	TOWED \$60/ TP NTUC - LKK
Prepared Date and Time	12/7/2019 2:38 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,045.00	\$550.00
Total Spray Cost	\$1,864.00	\$530.00
Total Spare Part Cost	\$6,296.43	\$2,280.89
Total Other Cost	\$689.00	(\$610.89)
TOTAL COST	\$9,894.43	\$2,750.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN (LKK) / NTUC
ARC / Surveyor Sign Off Date	16/07/2019 5:04 PM	16/07/2019 4:46 PM
Signature		
Remarks		L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1907-0451	Invoice Number	
Quotation Date	26.07.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$845.00	\$450.00
TO REPAIR APRON PANEL LH	\$200.00	\$100.00
Total Labour	\$1,045.00	\$550.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT WHEEL HOUSE LH	\$180.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$0.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$180.00	\$0.00
TO RESPRAY APRON PANEL LH	\$180.00	\$80.00
Total Spray Painting & Panel Beating	\$1,854.00	\$530.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$84.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$710.89)
Total Other Costs	\$669.00	(\$610.89)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
6505516		52116-47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace
6505541		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Check
6505438		81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Check
		81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given
		81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Check

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park S4, Singapore 757705
FAX Number: 63685582
Estimate Telephone Number: 68662623
Accident Reporting Number: 08652672

Date Generated : 23/07/2015

User ID : PehSuan

	81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check	X
	81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check	X
6505616	76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X
6505540	52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given	X
6505436	81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	
6505558	53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	
6505640	75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	
	53828-47030	SEAL, FRONT FENDER TO COWL SIDE LH	0.00	\$114.50	0.00	\$0.00	Replace	Not Given	X
6505554	53876-47030	FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$128.76	Replace	Replace	
	53852-47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X
	53720-12030	FENDER APRON FRT/LH	0.00	\$140.80	0.00	\$0.00	Replace	Not Given	X
6505658	42611-47140	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	
6503707		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
	43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Not Given	X
		STICKER DECAL SMRT (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X
	67002-47070	DOOR FRT/LH	0.00	\$894.40	0.00	\$0.00	Replace	Not Given	X
	62120-47021	QUARTER GLASS FRT/LH	0.00	\$234.90	0.00	\$0.00	Replace	Check	X
	52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace	
Total				\$7,585.65		\$1,991.82			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		81220-12230	FOG LAMP LH	1.00	\$280.10	10.00	\$252.09	Replace	Replace
		53852-47020	FENDER LINER PAD, FR WHEEL LH	1.00	\$49.30	25.00	\$36.98	Replace	Replace
Total					329.40		289.07		

2280.89
+ 550.00
+ 630.00

3460.89
- 20%

2768.71
L/S \$2750/-



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19012587/Etf3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 02-08-2019



189556

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKB 2998S	Veh. Inspected	SHC 4247T
Policy No.	5078659181-03	Coverage (\$)	0.00
Claim No.	MT/1053235-002	Excess (\$)	0.00
Assign From		Assign Date	12/07/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTDKN36U305705075	Colour	MAROON
Odometer	401994	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	WEST LAKE	5 mm
L/H Front Tyre	195/65R15	WEST LAKE	5 mm
R/H Rear Tyre	195/65R15	WEST LAKE	5 mm
L/H Rear Tyre	195/65R15	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/07/2019	Inspection Date	12/07/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4247T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
10	BUMPER CLIPS @ \$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER SUPPORT F/LH (DISC 25%)	BROKEN	76.40	57.30
1	FENDER FRT/LH (DISC 25%)	DENTED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	FENDER LINER FRT/LH (DISC 25%)	MISSING	171.70	128.78
1	BUMPER FRT (DISC 25%)	DENTED	482.00	361.50
1	HEAD LAMP LH (DISC 10%)	BROKEN	945.20	850.68
1	BUMPER GRILLE SUB-ASSY, LOWER	NOT NECESSARY	311.10	-
1	FOG LAMP LH	NOT NECESSARY	280.10	-
1	LENS & BODY, FR TURN LH	NOT NECESSARY	511.80	-
1	BRACKET, FR TURN UPPER LH	NOT NECESSARY	24.40	-
1	BRACKET, FR TURN CENTER LH	NOT NECESSARY	58.20	-
1	BRACKET, FR TURN LOWER LH	NOT NECESSARY	26.00	-
1	BUMPER LIP FRT	NOT NECESSARY	139.60	-
1	BUMPER FRT ABSORBER LOWER	NOT NECESSARY	127.70	-
1	SEAL, FRONT FENDER TO COWL SIDE	NOT NECESSARY	114.50	-
1	FENDER LINER PAD, FR WHEEL. LH	NOT NECESSARY	49.30	-
1	FENDER APRON FRT/LH	NOT NECESSARY	140.80	-
1	TYRE	NOT NECESSARY	126.74	-
1	WHEEL HUB FRT	NOT NECESSARY	549.70	-
1	STICKER DECAL SMRT (DOOR)	NOT NECESSARY	60.00	-
1	DOOR FRT/LH	NOT NECESSARY	894.40	-
1	QUARTER GLASS FRT/LH	NOT NECESSARY	234.90	-
1	WHEEL DISC. FRONT	TO REPAIR SEE LABOUR	1,484.20	-
1	SOLAR FILM (SN)	NOT NECESSARY	125.00	-
1	FOG LAMP LH (DISC 25%)	BROKEN	336.12	252.09
1	FRONT FENDER LINER PAD LH (DISC 25%)	MISSING	49.31	36.98
1	FRONT BUMPER LIP (NPA)	NOT NECESSARY	-	-
			8,110.57	2,280.89

Report Ref No. NS/INC19012587/Etf3s2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF WHEEL DISC. FRONT.		1,045.00	550.00
	SPRAY PAINT.		1,854.00	530.00
	TOWING CHARGE.		84.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	60.00
	TO TRANSFER DOOR MECHANISM.	NOT NECESSARY	120.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.		100.00	20.00
			3,463.00	1,180.00
	GRAND TOTAL		11,573.57	3,460.89
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,750.00

Report Ref No. NS/INC19012587/Etf3s2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.