

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 16/07/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 08 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0861/2019/GW
Date : 16-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian,
8 days exclude 2 Sunday and 2 PH -
ok - Jy - 02 Sep 2019

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tan Seck Sam
Address : 10G Bradell Hill
#19-27
Singapore 579726
Telephone : HP +65 96685009
Type of Claim : Own Damage Claims
Policy No. : 2100420253-04
Vehicle No : **SKU 1712 G**
Model Code : TT Coupe 2.0 TFSI Qu
Model / Year : Jun-15
Engine No : CHH 073489
Chassis No : TRUZZZFV9F1008725
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Jul-19
Place of Accident : Along College Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKU 1712 G

S/N	Nature of Jobs	Estimated Charges	
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy and parking aid.	S/N \$ 480.00	\$ 480.00
2	To remove and transfer air condenser, radiator, charged air cooler, electrical fans control unit. To carry out vacuum/ regas and to pressurise cooling system.	S/N \$ 1,200.00	\$ 1,200.00
3	To dismantle front bumper and lhs front fender. Renew front lock carrier and align to position. Renew front bumper, lhs front fender and headlight lh. Re-organise front crash management components. Reinstall all parts removed. (Headlamp replaced)	\$ 5,200.00	\$ 2,500.00
4	To respray front bumper, lhs front fender, bonnet and lhs door.	\$ 3,500.00	\$ 2,200.00
5	To dismantle lhs front door panel trims, remove and install lhs wing mirror assy.	\$ 400.00	\$ 250.00
	Supplementary		\$ 200.00
6	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
	TOTAL LABOUR CHARGES	: \$ 10,972.00	\$ 7,022.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKU 1712 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,158.00	\$ 1,726.40
2	FRONT BUMPER FIXING PARTS	\$ 440.00	
3	FRONT BUMPER CLOSING ELEMENT -LH/RH	2 \$ 202.00	
4	FRONT BUMPER SECURING STRIP-LH	\$ 39.00	
5	FRONT BUMPER GRILLE-CENTER	\$ 146.00	
6	FRONT BUMPER AIR GUIDE GRILLE-LH	\$ 103.00	
7	RADIATOR GRILLE	\$ 1,243.00	\$ 994.40
8	TRIM FOR ULTRASOUND SENSOR-LH/RH	2 \$ 62.00	
9	RADIATOR GRILLE CENTER COVER	\$ 97.00	
10	FRONT BUMPER CENTER COVER	\$ 59.00	
11	ULTRA SENSOR BRACKET-LH/RH	2 \$ 86.00	\$ 68.16
12	FRONT BUMPER COVER-LH/RH	2 \$ 102.00	
13	FRONT BUMPER SUPPORT ELEMENT	\$ 31.00	
14	FRONT FOAM FILLER PIECE	\$ 118.00	
15	FRONT REINFORCEMENT BAR	\$ 903.00	\$ 722.40
16	FRONT BUMPER TOP COVER	\$ 116.00	
17	SIGN ' CAUTION '	\$ 13.00	\$ 9.76
18	AIR CONDITIONER STICKER	\$ 7.00	\$ 5.12
19	FRONT FENDER -LH	\$ 1,084.00	
20	FRONT FENDER ATTACHMENT PART-LH	\$ 36.00	
SUB-TOTAL SPARE PARTS		\$ 7,045.00	\$ 3,526.24

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKU 1712 G

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f	\$	3,526.24
21	FRONT FENDER BRACE-LH		\$ 107.00	
21	LED HEADLIGHT WITH MATRIX BEAM		\$ 10,127.00	
22	FRONT AIR GUIDE-LH		\$ 31.00	
23	FRONT AIR DUCT-LH		\$ 46.00	
24	FRONT LOCK CARRIER WITH MOUNTING		\$ 899.00	\$ 718.00
25	FRONT RADIATOR SUPPORT BRACKET-LH/RH	2	\$ 34.00	
26	A/C CONDENDER WITH FLUID RESERVOIR		\$ 503.00	
27	CHARGE AIR COOLER		\$ 802.00	
28	FRONT INTAKE AIR-INLET		\$ 53.00	\$ 41.84
29	FRONT INTAKE AIR -INLET COVER		\$ 27.00	
30	READY MIX COOLANT	4	\$ 84.00	\$ 67.20
31	FRONT AUDI EMBLEM		\$ 113.00	\$ 90.00
32	FRONT NO. PLATE	S/N	\$ 25.00	\$ 25.00
	Supplementary			\$ 8,101.60
36	SUNDRIES		\$ 300.00	
	TOTAL SPARE PARTS	:	\$ 20,196.00	\$ 12,569.88
	TOTAL LABOUR CHARGES	:	\$ 10,972.00	\$ 7,022.00
	GRAND TOTAL	:	\$ 31,168.00	\$ 19,591.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0861/2019/GW 7-Aug-19 Glory Tan 1 of 1 SKU 1712 G TT Coupe 2.0 TFSI Qu	
Quantity	Description	Unit Price	Amount	
<u>Parts</u> 1	LED headlight RHS <i>Chipped</i>	\$ 10,127.00	\$ 8,101.60 <i>Ch</i>	
		\$10,127.00	\$ 8,101.60	
<u>LABORS</u> 1	To repair bonnet.	\$ 700.00	\$ 200.00 <i>Ch</i>	
	TOTAL	\$10,827.00	\$8,301.60	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKU 1712 G

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0859/2019/NH

30TH JAN 2020

from
Telephone +65-
Telefax +65-
Email
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SKU 1712 G, Audi TT Coupe 2.0 TFSI qu.

With reference to the above-mentioned vehicle, no. **SKU 1712 G**, claimant, **Mr. Tan Seck Sam**, please find the related document per attached.

1. A copy of the Original invoice no. 85014778 – S\$ 19,251.31.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SKU 1712 G

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9628 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:58

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85014778	Account: A0006 (T 0)		
		Date : 29/01/2020	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120		
		Order : SKU1712G			
		Term : 30			

Regn No: SKU1712G (V 25635)		Regn Date: 30/06/2015	Mileage: 31430	WIP No.: 60013	
Model: TT COUPE 2.0 TFSI qu FV307L		Chassis: TRUZZZVFV9F1008725	Engine: CHH 073489	Dept: U	
You have been assisted by :- UB-Tony Foong (33)					

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-1600.00	1.00	-1,600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR,CHARGED AIR COOLER,ELECTRICAL FANS AND CONTROL UNIT.TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	1200.00	1.00	1,200.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER AND LHS FRONT FENDER.RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RENEW FRONT BUMPER AND LHS HEADLIGHT.EORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	2500.00	1.00	2,500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,LHS FRONT FENDER, BONNET AND LHS DOOR.	2200.00	1.00	2,200.00
S	BODYWORK	M: TO DISMANTLE LHS FRONT DOOR PANEL TRIMS, REMOVE AND INSTALL LHS WING MIRROR ASSY	250.00	1.00	250.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK	M: TO REPAIR BONNET COVER	200.00	1.00	200.00
X	A8S0807065B GRU	Less 020%	1.00	2158.00	1,726.40
X	A8S0853651 3FZ	Less 020%	1.00	1243.00	994.40
X	A8S0853231	(A) (SK)BRACKET 29/7/ Less 020%	1.00	42.60	34.08

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6386 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 15:58

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014778 Date: 29/01/2020 Order: SKU1712G Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SKU1712G (V 25635) Regn Date: 30/06/2015 Mileage: 31430 WIP No.: 60013

Model: TT COUPE 2.0 TFSI qu FV307L Chassis: TRU222FV9F1008725 Engine: CHH 073489 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
X	A8S0853232	(A) (SK) BRACKET 29/7/	Less 020%	1.00	42.60
X	A8S0807109B	BEAM(LAST)	Less 020%	1.00	903.00
X	A8K0010520A	PLATE	Less 020%	1.00	12.20
X	A8V0010515A	STICKER	Less 020%	1.00	6.40
X	A8S7805594C	(A) (SK) CARRIER 29/7/	Less 020%	1.00	897.50
X	A5Q0129254B	AIR DUCT(LAST)	Less 020%	1.00	52.30
X	AG A13040M2	PREMIX-COOLANT	Less 020%	4.00	21.00
X	A8V0853742 2ZZ	AUDI SIGN(LAST)	Less 020%	1.00	112.50
X	A8S0941784C	HEADLIGHT(LAST)	Less 020%	1.00	10127.00

Parts 12,544.88
Labour 0.00
Sublet 7,047.00
Menus 0.00
Lubricant 0.00

Sub-Total 17,991.88

7% GST 1,259.43

Grand Total 19,251.31



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKU1712G

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0859/2019/TF
15 Aug 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

1

total pages

Make & Model : Audi TT COUPE 2.0 TFSI qu
Vehicle Chassis No. : TRUZZZFV9F1008725
Vehicle Regn No. : SKU1712G
Vehicle Mileage : 29824KM
Vehicle Owner : Mr. Tan Seck Sam
Certificate No : 2100420253-04
Own Damage Excess : \$1712.00 (Including 7% GST)
Accident Date : 08/07/2019
Place : Along College Road
Repair Cost : \$ 19,257.31
WIP No. : 60013
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

2018 _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jul 2019		17 Jul 2019 10:32 Edit Adj Rpt	S\$19,591.88 Edit Estimates	S\$19,591.88 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: TAN SECK SAM , ID: S0042791H	
Vehicle Reg. No.: SKU1712G	Date of Loss: 08/07/2019 16:00 - :59 [48 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type: OD / 9699433598SG	Policy/Cover Note No.: 2100420253-04 (Comprehensive)
	Excess: S\$1,600.00
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911	
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mithoo Singh, Aashweenjeet Kaur] Aashweenjeetkaur.Mithoosingh@aig.com	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/07/2019]	
Driver/Custodian: TAI HWEI YEE (60 / Female) , NRIC: S1298589D, Tel: +6596685009 Email: NOEMAIL	

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (13/08/2019): Alert - Adj Mandate Approved (S\$22018.00) - SKU1712G - Claim Handler: Mithoo Sin...
- AIG_SG (18/07/2019): Alert - Adj Mandate Approved (S\$11191.00) - SKU1712G - Claim Handler: Mithoo Sin...
- AIG_SG (18/07/2019): SKU1712G / OD / 08/07/2019 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKU1712G (9699433598SG)**
OD
Jul 8 2019 4:00PM
[TAN SECK SAM]
Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)
[View](#)
[View in Browser ▼](#)

Assessment Reports

1 per page ▼



No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/07/19 13:58	Adjuster Immediate Advice	Load HTM	
2	13/08/19 10:54	Adjuster Immediate Advice	Load HTM	

Photos/Images

3 per page ▼



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/07/19 13:53	General View	Load JPG	
2	17/07/19 13:53	Chassis Number	Load JPG	
3	17/07/19 13:53	General View	Load JPG	
4	17/07/19 13:53	General View	Load JPG	
5	17/07/19 13:53	General View	Load JPG	
6	17/07/19 13:53	General View	Load JPG	
7	17/07/19 13:53	General View	Load JPG	
8	17/07/19 13:53	General View	Load JPG	
9	17/07/19 13:53	General View	Load JPG	
10	17/07/19 13:53	General View	Load JPG	
11	17/07/19 13:53	General View	Load JPG	
12	17/07/19 13:53	General View	Load JPG	
13	17/07/19 13:53	General View	Load JPG	
14	17/07/19 13:53	General View	Load JPG	
15	17/07/19 13:53	General View	Load JPG	
16	17/07/19 13:53	General View	Load JPG	
17	17/07/19 13:53	General View	Load JPG	
18	17/07/19 13:53	General View	Load JPG	
19	17/07/19 13:53	General View	Load JPG	
20	17/07/19 13:53	General View	Load JPG	
21	17/07/19 13:53	General View	Load JPG	
22	17/07/19 13:53	General View	Load JPG	
23	17/07/19 13:53	General View	Load JPG	
24	17/07/19 13:53	General View	Load JPG	
25	17/07/19 13:53	General View	Load JPG	
26	17/07/19 13:53	General View	Load JPG	
27	17/07/19 13:53	General View	Load JPG	
28	17/07/19 13:53	General View	Load JPG	
29	17/07/19 13:53	General View	Load JPG	
30	17/07/19 13:53	General View	Load JPG	
31	17/07/19 13:53	General View	Load JPG	
32	17/07/19 13:53	General View	Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	17/07/19 13:53	General View	 Load JPG	☒
34	17/07/19 13:53	General View	 Load JPG	☒
35	17/07/19 13:53	General View	 Load JPG	☒
36	17/07/19 13:53	General View	 Load JPG	☒
37	17/07/19 13:53	General View	 Load JPG	☒
38	17/07/19 13:53	General View	 Load JPG	☒
39	13/08/19 10:50	Reinspection Photo	 Load JPG	☒
40	13/08/19 10:50	Reinspection Photo	 Load JPG	☒
41	13/08/19 10:50	Reinspection Photo	 Load JPG	☒
42	13/08/19 10:50	Reinspection Photo	 Load JPG	☒
43	13/08/19 10:50	Reinspection Photo	 Load JPG	☒
44	13/08/19 10:50	Reinspection Photo	 Load JPG	☒
45	13/08/19 10:50	Reinspection Photo	 Load JPG	☒
46	13/08/19 10:50	Reinspection Photo	 Load JPG	☒
47	13/08/19 10:50	Reinspection Photo	 Load JPG	☒
48	13/08/19 10:50	Reinspection Photo	 Load JPG	☒
49	13/08/19 10:50	Reinspection Photo	 Load JPG	☒
50	13/08/19 10:50	Reinspection Photo	 Load JPG	☒
51	13/08/19 10:50	Reinspection Photo	 Load JPG	☒
52	13/08/19 10:50	Reinspection Photo	 Load JPG	☒
53	13/08/19 10:50	Reinspection Photo	 Load JPG	☒
54	13/08/19 10:50	Reinspection Photo	 Load JPG	☒
55	13/08/19 10:50	Reinspection Photo	 Load JPG	☒
56	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
57	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
58	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
59	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
60	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
61	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
62	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
63	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
64	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
65	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
66	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
67	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
68	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
69	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
70	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
71	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
72	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
73	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
74	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
75	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
76	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
77	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
78	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
79	23/12/19 09:52	Reinspection Photo	 Load JPG	☒
80	23/12/19 09:52	Reinspection Photo	Load JPG	☒

Linked Accident Report Documents

Documents Checklist

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&objid=842879&extid=310593&corole=4&... 3/4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19012590/AQF3S2

Date: 05/02/2020

REFERENCE

Insured/Claimant:	TAN SECK SAM	Policy No:	2100420253-04	
Date of Loss:	08/07/2019	Nature of Claim:	OD	Claim No: 9699433598SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU1712G		
Make & Model:	AUDI TT, 2.0 COUPE (A)	Engine No:	CHH073489
Reg. Date:	30/06/2015 (Man. Year: 2015)	Chassis No:	TRUZZZFV9F1008725
Colour:	Red	Odometer:	29329 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$125,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,071.60	12,569.88	15,501.72	55.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,172.00	7,022.00	4,150.00	37.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,243.60	19,591.88	19,651.72	50.08
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	37,643.60	17,991.88	19,651.72	52.20
+ GST 7.00/7.00% (S\$)	2,635.05	1,259.43	1,375.62	52.20
Nett Amount (S\$)	40,278.65	19,251.31	21,027.34	52.20

INSPECTION

Date of Assignment:	17/07/2019	
Date Inspected:	16/07/2019	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	8.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,158.00 FS	*1,726.40 FS
2	1		*FRONT BUMPER FIXINGS PARTS	Not Necessary	440.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LH/RH	Not Necessary	101.00 FS	*- FS
4	1		*FRONT BUMPER SECURING STRIP - LH	Not Necessary	39.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	146.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	103.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,234.00 FS	*994.40 FS
8	2		*TRIM FOR ULTRASONIC SENSOR - LH/RH	Not Necessary	62.00 FS	*- FS
9	1		*RADIATOR GRILLE CENTER COVER	Not Necessary	97.00 FS	*- FS
10	1		*FRONT BUMPER CENTER COVER	Not Necessary	59.00 FS	*- FS
11	2		*ULTRA SONIC BRACKET - LH/RH	Necessary	86.00 FS	*68.16 FS
12	2		*FRONT BUMPER COVER - LH/RH	Not Necessary	102.00 FS	*- FS
13	1		*FRONT BUMPER SUPPORT ELEMENT	Not Necessary	31.00 FS	*- FS
14	1		*FRONT FOAM FILLER PIECE	Not Necessary	118.00 FS	*- FS
15	1		*FRONT REINFORCEMENT BAR	Bent	903.00 FS	*722.40 FS
16	1		*SIGN CAUTION	Necessary	13.00 FS	*9.76 FS
17	1		*AIR CONDITIONER STICKER	Necessary	7.00 FS	*5.12 FS
18	1		*FRONT FENDER - LH	Repair	1,084.00 FS	*- FS
19	1		*FRONT FENDER ATTACHMENT PART - LH	Not Necessary	36.00 FS	*- FS
20	1		*FRONT FENDER BRACE - LH	Not Necessary	107.00 FS	*- FS
21	1		*LED HEADLIGHT	Not Necessary	10,127.00 FS	*- FS
22	1		*FRONT AIR GUIDE - LH	Not Necessary	31.00 FS	*- FS
23	1		*FRONT AIR DUCT - LH	Not Necessary	46.00 FS	*- FS
24	1		*FRONT LOCK CARRIER WITH MOUNTING	Cracked	899.00 FS	*718.00 FS
25	2		*FRONT RADIATOR SUPPORT BRACKET - LH/RH	Not Necessary	34.00 FS	*- FS
26	1		*A/C CONDENSER WITH FLUID RESERVOIR	Not Necessary	503.00 FS	*- FS
27	1		*CHARGE AIR COOLER	Not Necessary	802.00 FS	*- FS
28	1		*FRONT INTAKE AIR - INLET	Cracked	53.00 FS	*41.84 FS
29	1		*FRONT INTAKE AIR - INLET COVER	Not Necessary	27.00 FS	*- FS
30	4		*READY MIX COOLANT	Necessary	84.00 FS	*67.20 FS
31	1		*FRONT AUDI EMBLEM	Necessary	113.00 FS	*90.00 FS
32	1		*FRONT NO. PLATE	Bent	25.00 FS	*25.00 FS
33	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
34	1		*LED HEADLIGHT RHS	Chipped	8,101.60 FS	*8,101.60 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **28,071.60** **12,569.88**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE, SENSOR AND HEADLIGHT WASHER ASSY AND PARKING AID.	New	480.00	480.00
2	TO REMOVE AND TRANSFER AIR CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM.	New	1,200.00	1,200.00
3	TO DISMANTLE FRONT BUMPER AND LHS FRONT FENDER. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, LHS FRONT FENDER AND HEADLIGHT LH. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	5,200.00	2,500.00
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS DOOR.	New	3,500.00	2,200.00
5	TO DISMANTLE LHS FRONT DOOR PANEL TRIMS, REMOVE AND INSTALL LHS WING MIRROR ASSY.	New	400.00	250.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
7	TO REPAIR BONNET.	New	200.00	200.00
Gross Labour Cost (S\$)			11,172.00	7,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >