

ASS. REC. BY:

REF:

CS11 CS19012593/Asf302

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Desmond Lee

of

ECICS

Date/Time: 12.7.19 10.18a.m

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMA 4115S

Insured: GBE 2258K

at Workshop m/s Kah Motor

Tel: 81006306

of 15 ubi road 4

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 10.7.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 17.7.19 11.08a.m

Person Contacted:

Amy

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMA 4115S - X
	GBE 2258K - X

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMA41155 Yr Regn: 2018 / JuneType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda HRV c.c. 1496Colour: Black A/C: Insured / Std / NI / NASp. Reading 24845 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JAMRU1810G X204135Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 16/07/19Survey held at Kah MotorDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ECICS

30/08/19 Confirmed ~~the~~ P/P \$ 8,440.39 @ 6 days with Adrian
(\$ 9,438.43 Red - 53%)

MV:

PV:

Nett:

RECEIVED 10 SEP 2019

Resurvey no. of TP - 2

Date/Time, File Pass to?

Date/Time, File Return to?

1) 30/08/19

2)

3) Typist

4)

5)

6)

Prel. Report:

Final Report: P/P \$ 8,440.39

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

<u>1590</u>
<u>11</u>
<u>461</u>

Re: SECOND REMINDER: Finalize TPDS-ECICS: SMA4115S & GBE2258K DOA:
10/07/2019@18.20PM

Shirley Hiew (LKK Auto)

Fri 30/8/2019 2:34 PM

To: Ary Chua <arychua@honda.com.sg>

Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>; assignments <assignments@lkkauto.com>;
SUR <sur@lkkauto.com>; Adrian Ling (LKKAuto) <adrianling@lkkauto.com>

Dear Ary,

Finalize amount confirmed.

Final invoice and all supporting documents sent over to ECICS Limited.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ary Chua <arychua@honda.com.sg>

Sent: Monday, 19 August 2019 5:21 PM

To: assignments <assignments@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>

Subject: SECOND REMINDER: Finalize TPDS-ECICS: SMA4115S & GBE2258K DOA: 10/07/2019@18.20PM

Dear Adrian Ling,

Finalize TPDS-ECICS: SMA4115S & GBE2258K DOA: 10/07/2019@18.20PM

Final Repair Costs (include GST)	\$8,440.39 + (\$590.81) = \$9,031.20
Repair Period* (Working Day)	06

Please examine the above information carefully. If no discrepancy is reported within 7 days (*Exclude Sunday and Public Holiday) from the date of this email,

the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Kah Motor Co. SDN BHD 15 Ubi Road 4 Singapore 408610

Phone: 6846 5673 Fax: 6748 0770 H/P: 81006306

Email Address : arychua@honda.com.sg

From: Ary Chua

Sent: Wednesday, 31 July 2019 10:51 AM

To: assignments@lkkauto.com; Admin A <admin-a@lkkauto.com>; Adrian Ling (LKKAuto) <adrianling@lkkauto.com>

Shirley Hiew (LKK Auto)

From: Ary Chua <arychua@honda.com.sg>
Sent: Monday, 19 August 2019 5:22 PM
To: assignments@lkkauto.com; Admin A; Adrian Ling (LKKAuto); 'sur@lkkauto.com'
Cc: Liew Thye Wui; Faeaz
Subject: SECOND REMINDER: Finalize TPDS-ECICS: SMA4115S & GBE2258K DOA: 10/07/2019@18.20PM
Attachments: 3909_001.pdf

Dear Adrian Ling,

Finalize TPDS-ECICS: SMA4115S & GBE2258K DOA: 10/07/2019@18.20PM

Final Repair Costs (include GST)	\$8,440.39 + (\$590.81) = \$9,031.20
Repair Period* (Working Day)	06

Please examine the above information carefully. If no discrepancy is reported within 7 days (*Exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Kah Motor Co. SDN BHD 15 Ubi Road 4 Singapore 408610

Phone: 6846 5673 Fax: 6748 0770 H/P: 81006306

Email Address : arychua@honda.com.sg

From: Ary Chua

Sent: Wednesday, 31 July 2019 10:51 AM

To: assignments@lkkauto.com; Admin A <admin-a@lkkauto.com>; Adrian Ling (LKKAuto) <adrianling@lkkauto.com>

Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>

Subject: Finalize TPDS-ECICS: SMA4115S & GBE2258K DOA: 10/07/2019@18.20PM

Dear Adrian Ling,

Finalize TPDS-ECICS: SMA4115S & GBE2258K DOA: 10/07/2019@18.20PM

Final Repair Costs (include GST)	\$8,440.39 + (\$590.81) = \$9,031.20
Repair Period* (Working Day)	06

Please examine the above information carefully. If no discrepancy is reported within 7 days (*Exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Kah Motor Co. SDN BHD 15 Ubi Road 4 Singapore 408610

Phone: 6846 5673 Fax: 6748 0770 H/P: 81006306

Email Address : arychua@honda.com.sg



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Nivitha (LKK Auto)

From: Desmond Lee Ker Wen (ECICS, Claims) <Desmond_Lee@ecics.com.sg>
Sent: Friday, 12 July 2019 10:18 AM
To: Ary Chua; Liew Thye Wui; Faeaz
Cc: assignments@lkkauto.com
Subject: FW: TPDS:(TM) & GBE2258K (ECICS) DOA: 10-07-2019@18.20PM
Attachments: 3338_001.pdf; 6.JPG; 7.JPG; 8.JPG; 9.JPG; 10.JPG; 11.JPG; 12.JPG; SMA4115S-F.mp4; 1.jpg; 2.jpg; 3.jpg; 4.jpg; 5.jpg; SMA4115S-F.MP4

Importance: High

Dear Ary

The video do not show our insured hitting your client's rear.

Dear LKK

Please assist with PRI of the vehicle.

Best regards

Desmond Lee

Senior Associate | Claims



DID (65) 6303 0167

Tel (65) 6337 4779

Email Desmond_Lee@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: ECICS Claims

Sent: Thursday, 11 July 2019 5:58 PM

To: Ary Chua

Cc: Liew Thye Wui; faeaz@honda.com.sg

Subject: FW: TPDS:(TM) & GBE2258K (ECICS) DOA: 10-07-2019@18.20PM

Importance: High

Dear Ary

Please forward video footage to us.

Thank you.

Best regards

Desmond Lee

Senior Associate | Claims



DID (65) 6303 0167

Tel (65) 6337 4779

Email Desmond_Lee@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunus Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Ary Chua [mailto:arychua@honda.com.sg]

Sent: Thursday, 11 July 2019 2:47 PM

To: ECICS Claims

Cc: Liew Thye Wui; Faeaz

Subject: TPDS: SMA4115S (TM) & GBE2258K (ECICS) DOA: 10-07-2019@18.20PM

Dear OIC-ECICS,

Kindly Establish this case Liability Issue Before Arrange for Car Survey. Car Not In Ubi Bodyshop.
Our Client got Front Video Footage.


Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor Kah Motor Co.Sdn.Bhd. Address:15 Ubi Road 4 S408610

E-mail: arychua@honda.com.sg H/P:81006306 DID:68465673 Fax: 67480770



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/07/2019 12:52
Date Of Accident	10/07/2019 18:20
Exact Location Of Accident	SERANGOON RD (L/P 115) NEAR BUS STOP B15
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA4115S
Insured/Policyholder	
Name Of Registered Owner	TIAN TOW HOE
NRIC No	S1416805B
Email Address	JUDY@OM-HOME.COM
Mobile Phone No	(LOCAL) +65-96478303
Alternative Phone No	OFFICE-90112130

Vehicle Particulars

Manufacturer	HONDA
Model	HR-V-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	P/USED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	19-MT103065-R01
Cover Note Number	

Driver

Name of Driver	TAN SIEW BENG
NRIC No	S1491355F
Date Of Birth	13/07/1961
Occupation	INDOOR
Date Of Driving Pass	15/02/1994
Driving Experience	25 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90112130
Fax Number	
Contact Number	OFFICE-90112130
Email Address	JUDY@OM-HOME.COM

Address	BLK 613B PUNGGOL DRIVE #15-837
Postcode	S822613
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TIAN CHELSA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

NOBODY INQUIRY DURING THE ACCIDENT & REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	GBE2258K
Vehicle Make/Model/Colour	TOYOTA/LORRY/SILVER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAN CHEONG POH
NRIC/Passport Number	S6826456A
Contact Number	92395312
Address	
Postcode	
Insurance Company Name	ECICS LIMITED
Nature Of Damage	
No. Of Passenger (Including Driver)	


Vehicle Number: SMA4115S


SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: **ARY CHUA**
 NRIC/FIN No.:

Sketch Plan Pg. 2

Vehicle Number: 5MA4135

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 10/7 abt 6:30pm, I was driving along Serangoon Road toward Macpherson Road. And the traffic was heavy and slow

As driving near St Michael Road, suddenly vehicle SG4457B swung out into my lane without warning. I immediately stop my car (CSMA 41158) to avoid collision.

The lorry (GBE 225BK) hit my back of the car.

I stop my car and go down to take a look. The driver of lorry (Mr Tan Cheong Poh) admit his mistake.

The contact of Mr Tan Cheng Poh: 92375312
Insurance: Ecies

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

11:11am
11 JUL 2016
Reporting Centre Personnel's Signature
Name: **ARY CHUA**
NRIC/FIN No.:

20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046

(65) 6221 6111 (65) 6221 4355 / (65) 6224 0895 tmts@tokiomarine.com.sg www.tokiomarine.com

TOKIO MARINE
INSURANCE GROUP
FORM MY1

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: 19-MT103065-R01 (Private Motor Car)

1. **Index Mark and Registration Number of Vehicle** SMA4115S **Chassis No.:** JHMRU1810GX204135
2. **Name of Policyholder** TIAN TOW HOE
3. **Effective date of the Commencement of Insurance for the purposes of the Act** 06/06/2019
4. **Date of Expiry of Insurance** 05/06/2020
5. **Persons or Class of Persons entitled to drive***
 - (a) The Policyholder.
 - (b) Any other person who is driving on the Policyholder's order or with his permission.

* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. **Limitations as to use***

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatsoever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

ADDITIONAL INFORMATION**Account:** E2316DDA

Insurance Plan:	Comprehensive Approved Workshop Plan	
Limit for total loss or theft:	Prevailing Market Value	
Policy Excess:	Own Damage Claims	SGD 600
	Windscreen Excess	SGD 100
Financial Interest:	OCBC BANK LIMITED	

Tokio Marine Insurance Singapore Ltd.

Authorised Signature

To: Whom It May Concern

I, Tian Tow Hoe authorize Tan Siew Beng
of NRIC S1491355F to sign documents related to my vehicle no
SMA 4115S accident date 10 Jul 2019 on my behalf.

Raymond
14

Signature of owner

NRIC: S1416805B

Insurance Company Tokio Marine Insurance Ltd.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Next Tuesday Survey
16/07/2019 by Gek Auto**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: ECICS LIMITED	Document No.	: SQT19003052	Page	1
	7 TEMASEK BOULEVARD	Date	: 11. Jul 2019		
	#10-01 SUNTEC TOWER FIVE	Customer No.	: WZE001		
	SINGAPORE 038987	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SMA4115S	Engine No	: L15B4534134		
Chassis No	: JHMRU1810GX204135	Date Time	: 11. Jul 2019 12:54:05 PM		
Model	: HRV DX-SIN CVT YM 2016	Surveyor Name	: DID : +65 6846 5673		
Owner's Name	: TIAN TOW HOE	Survey Date	: HP : +65 8100 6306		
Ins Policy No.	: 19-MT103065-R01	Authorisation Date	: Email : anychua@honda.com.sg		
Date of Accident	: 10/7/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: TIAN TOW HOE						
	OWNER INSURER: TOKIO MARINE INSURANCE LTD						
	ACC DATE: 10-07-2019@18.20PM						
	ACC: SERANGGO RD (L/P 115) NEAR BUS STOP B15						
	SURVEYED BY: Harold Chua @ Kk Adrian Ling (Kk) 16/07/2019 @ 10:48am						
	REF NO:						
	TP INSURER: ECICS LIMITED						
	TP VEH: GBE2258K - TOYOTA/LORRY SILVER						
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>nee</i>	1	60.00		60.00	4.20	✓ 64.20
33502-T7A-J01	LAMP UNITR. <i>cracked</i>	1	441.50		331.17 441.50	30.91	✓ 472.41
33552-T7A-J01	LAMP UNITL. <i>nee</i>	1	441.50		441.50	30.91	✓ 472.41
34150-T7A-J01	LIGHT ASSY,R.LID <i>nee cracked</i>	1	269.90		202.47 269.90	18.89	✓ 288.79
34155-T7A-J01	LIGHT ASSY,L.LID <i>cracked</i>	1	269.90		269.90	18.89	✓ 288.79
74890-T7A-J12ZC	GARNISH ASSY,R.R.LICENSE <i>cracked</i>	1	193.60		145.20 193.60	13.55	✓ 207.15
75701-T5A-000	EMBLEMH <i>nee</i>	1	10.70		9.02 10.70	0.75	✓ 11.45
90301-ST0-003	NUTPUSH 3MM <i>nee</i>	2	2.10		3.15 4.20	0.29	✓ 4.49
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER <i>nee</i>	1	19.30		14.47 19.30	1.35	✓ 20.65
73226-SZW-000	DAMPERSTD 5X5 <i>nee</i>	1	8.50		1.57 8.50	0.60	✓ 9.10
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER <i>nee</i>	1	19.30		14.47 19.30	1.35	✓ 20.65
76711-T6A-003	CAPPIVOT <i>nee</i>	1	4.80		3.60 4.80	0.34	✓ 5.14
91501-S70-003	FASTENER BW/SHIELD	4	5.30		15.90 21.20	1.48	✓ 22.68
91502-S70-003	FASTENER B	2	5.30		7.95 10.60	0.74	✓ 11.34
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80		5.70 7.60	0.53	✓ 8.13
74940-TZ5-A01	BUZZER ASSYSMART	1	60.40		X 60.40	4.23	? 64.63
38387-TZ5-A01	ANTENNA ASSYL.F.	1	59.30		X 59.30	4.15	? 63.45
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR	1	189.80		X 189.80	13.29	? 203.09
84550-T7A-J00	BOX ASSY,CARGO FLOOR	1	129.50		X 129.50	9.07	? 138.57

Printed on 11/7/2019 2:34:16 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : ECICS LIMITED
7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER FIVE
SINGAPORE 038987

Registration No : SMA4115S

Chassis No : JHMRU1810GX204135

Model : HRV DX-SIN CVT YM 2016

Owner's Name : TIAN TOW HOE

Ins Policy No. : 19-MT103065-R01

Date of Accident : 10/7/2019

Document No. : SQT19003052 Page 2

Date : 11. Jul 2019

Customer No. : WZE001

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L15B4534134

Date | Time : 11. Jul 2019 12:54:05 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
84431-T7A-J01ZA	LINING ASSYTAILGATE <i>Rehanded.</i>	1	136.00	102 ✓	136.00	9.52	145.52
84640-T7A-J01ZA	LINING ASSYRR.PANEL <i>Rehanded</i>	1	43.90	32.92 ✓	43.90	3.07	46.97
75722-T7W-A01	EMBLEMRR. <i>Reh</i>	1	13.30	9.97 ✓	13.30	0.93	14.23
75725-T8N-T00	EMBLEM,RR. I-VTEC <i>Reh</i>	1	14.50	10.27 ✓	14.50	1.02	15.52
71501-T7B-000	FACE RR.BUMPER <i>Rehanded</i>	1	777.90	343.77 ✓	777.90	54.45	832.35
91505-TM8-003	CLIP,BUMPER <i>Reh</i>	8	2.30	13.80 ✓	18.40	1.29	19.69
04717-T7A-000ZZ	FACER,RR.BUMPER CORNER <i>Repair</i>	1	94.10		94.10	6.59	100.69
04718-T7A-000ZZ	FACEL,RR.BUMPER CORNER <i>Repair</i>	1	94.10		94.10	6.59	100.69
71593-T7A-J00	SPACER,R,RR.BUMPER SIDE <i>Reh</i>	1	17.20	12.90 ✓	17.20	1.20	18.40
71598-T7A-J00	SPACER,L,RR.BPR S <i>Reh</i>	1	17.20	12.90 ✓	17.20	1.20	18.40
33505-T7A-J01	REFLECTOR ASSYR,RR. <i>Reh</i>	1	156.30		156.30	10.94	167.24
33555-T7A-J01	REFLECTOR ASSYL,RR. <i>Reh</i>	1	156.30		156.30	10.94	167.24
04655-T7A-310ZZ	PANEL SETRR.FLOOR <i>Repair</i>	1	675.50		675.50	47.29	722.79
65750-T5B-300ZZ	CROSSMEMBER COMPRR.FLOOR <i>Repair</i>	1	83.70		83.70	5.86	89.56
65513-T7A-300ZZ	STIFFENERRR.JACK UP <i>Reh</i>	1	61.40		61.40	4.30	65.70
65540-T7A-310ZZ	STIFFENER COMPR,RR.FRAME UP <i>Repair</i>	1	105.30		105.30	7.37	112.67
65590-T7A-310ZZ	STIFFENER COMPL,RR.FRAME UP <i>Repair</i>	1	105.30		105.30	7.37	112.67
66100-T7A-300ZZ	PANEL COMPRR. <i>Rehanded.</i>	1	373.10	279.92 ✓	373.10	26.12	399.22
74440-T7A-003	WEATHERSTRIPTAILGATE <i>Reh</i>	1	98.70	74.02 ✓	98.70	6.91	105.61
74800-T7Y-K01	LOCK ASSY,TAILGATE ASSY <i>Rehanded</i>	1	163.20	59.17 ✓	163.20	11.42	174.62
68100-T7A-J20ZZ	TAIL GATE COMP <i>Rehanded.</i>	1	855.70	641.77 ✓	855.70	59.90	915.60
Sum Item					6282.70	439.80	6,722.50
BOSUN	SUNDRIES	1	40.00	20 ✓	40.00	2.80	42.80
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	✓	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00	✓	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	140.00	120 ✓	140.00	9.80	149.80
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	160.00	140 ✓	160.00	11.20	171.20
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	✓	250.00	17.50	267.50

Printed on 11/7/2019 2:34:16 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : ECICS LIMITED
7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER FIVE
SINGAPORE 038987

Registration No : SMA4115S

Chassis No : JHMRU1810GX204135

Model : HRV DX-SIN CVT YM 2016

Owner's Name : TIAN TOW HOE

Ins Policy No. : 19-MT103065-R01

Date of Accident : 10/7/2019

Document No. : SQT19003052 Page 3

Date : 11. Jul 2019

Customer No. : WZE001

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L15B4534134

Date | Time : 11. Jul 2019 12:54:05 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	350.00	30	350.00	24.50	374.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	350.00	30	350.00	24.50	374.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	350.00	30	350.00	24.50	374.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	350.00	X	350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00	280	450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	550.00	450	550.00	38.50	588.50
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2800.00	1350	2800.00	196.00	2996.00
BKRP22M	CUT & RENEW RR PANEL, GUTTER AND RR FENDER.	1	4800.00	1960	4800.00	336.00	5136.00
Sum Labor					10790.00	755.30	11,545.30

Survey By

Date & Time

Excess

Status

Signature

Adrian Lj
16/07/19.
Not Authorised.
SP.

06 Days.

Total Amount 17,072.70 1,195.10 18,267.80

Total (Inclusive of GST) 18,267.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 11/7/2019 2:34:16 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

12676.81



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZE001 / ECICS LIMITED
Chassis No: JHMRU1810GX204135
License No: SMA4115S
Mileage: 25266
Engine No: L15B4534134

Document No: SVO19046898
Printed By: ARYCHUA
Order Date: 22. July 2019
Order Time: 12:13:31 PM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Includ GST
	TP DIRECT SETTLEMENT (J/NO: 73099) OWNER: TIAN TOW HOE OWNER INSURER: TOKIO MARINE INSURANCE LTD ACC DATE: 10-07-2019@18.20PM ACC: SERANGGO RD (L/P 115) NEAR BUS STOP B15 SURVEYED BY: ADRIAN LING@LKK 16/07/2019@10:48AM REF NO: DMCV1900040H/DL TP INSURER: ECICS LIMITED TP VEH: GBE2258K - TOYOTA/LORRY SILVER						
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
33502-T7A-J01	LAMP UNITR.	1	441.50	25	331.12	23.18	354.30
34150-T7A-J01	LIGHT ASSY,R.LID	1	269.90	25	202.42	14.17	216.59
74890-T7A-J12ZC	GARNISH ASSYRR.LICENSE	1	193.60	25	145.20	10.16	155.36
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
75722-T7W-A01	EMBLEMRR.	1	13.30	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.50	25	10.87	0.76	11.63
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
91505-TM8-003	CLIP,BUMPER	8	2.30	25	13.80	0.97	14.77
71593-T7A-000	SPACER,R.RR.BUMPER SIDE	1	17.20	25	12.90	0.90	13.80
71598-T7A-000	SPACER,L.RR.BUMPER SIDE	1	17.20	25	12.90	0.90	13.80
74800-T7A-J02	LOCK ASSYTAILGATE	1	78.90	25	59.17	4.14	63.31
68100-T7A-J20ZZ	TAIL GATE COMP	1	855.70	25	641.77	44.92	686.69
04717-T7A-000ZZ	FACER,RR.BUMPER CORNER	1	94.10	25	70.57	4.94	75.51
84431-T7A-J01ZA	LINING ASSYTAILGATE	1	136.00	25	102.00	7.14	109.14
33552-T7A-J01	LAMP UNITL.	1	441.50	25	331.12	23.18	354.30
34155-T7A-J01	LIGHT ASSYL.LID	1	269.90	25	202.42	14.17	216.59
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	43.90	25	32.92	2.30	35.22
66100-T7A-300ZZ	PANEL COMPRR.	1	373.10	25	279.82	19.59	299.41
74440-T7A-003	WEATHERSTRIPTAILGATE	1	98.70	25	74.02	5.18	79.20
	SUM PARTS:				3,020.39	211.41	3,231.80
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BOBC	EXT-YBH	1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						
BOJSE	EXT-YJ	1	100.00		100.00	7.00	107.00
	BODY JOINT SEALANT.						
BML02I	EXT-YJ	1	120.00		120.00	8.40	128.40
	INSPECT RR LIGHTING MECHANISMS.						
	PERFORM WATER						
	TEST.(N)						

WD = 6

Red

Green



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZE001 / ECICS LIMITED
Chassis No: JHMRU1810GX204135
License No: SMA4115S
Mileage: 25266
Engine No: L15B4534134

Document No: SVO19046898
Printed By: ARYCHUA
Order Date: 22. July 2019
Order Time: 12:13:31 PM
Service Advisor: ARY CHUA WAI NGEE

BA02R	EXT-YJ REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	140.00	140.00	9.80	149.80
BMI03D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	280.00	280.00	19.60	299.60
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	300.00	300.00	21.00	321.00
BC011R	0760 REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	300.00	300.00	21.00	321.00
BC012R	0760 RESET VEHICLE SMART ENTRY	1	300.00	300.00	21.00	321.00
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	450.00	450.00	31.50	481.50
BP03R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1	1,350.00	1,350.00	94.50	1,444.50
BKRP22M	EXT-YJ CUT & RENEW RR PANEL, GUTTER AND RR FENDER. ALIGN CHASSIS INCLUDING FITTING ON ATTACHMENT ITEM	1	1,960.00	1,960.00	137.20	2,097.20
			SUM LABOUR:	5,420.00	379.40	5,799.40
			TOTAL SGD	8,440.39	590.81	9,031.20

Total Payable (SGD)

9,031.20

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Midnight Accident

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Oct 2019 16:41 Edit Reg		12 Jul 2019 00:00 Edit Adj Rpt	S\$8,440.39 Edit Estimates	S\$8,440.39 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	-, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM		
Main Claimant:	-		
Vehicle Reg. No.:	SMA4115S	Date of Loss:	10/07/2019 00:00 - :59 [13 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / DMCV1900040H	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	GBE2258K	Policy No. (Claimant):	
		Excess:	
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Desmond Lee - 6303 0167]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 23/07/2019]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks Create New Task Complete
Due Date	Priority	Type	Task Group Subject Handler Assigned By Completed On Created On Done?
No results.			

Claim Documents

***SMA4115S (DMCV1900040H)
[GBE2258K]**












































TP


















-

Jul 10 2019 12:00AM

[-]

Kah Motor Co Sdn Bhd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser <input type="button" value="v"/>	
Photos/Images				3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
2	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
3	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
4	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
5	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
6	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
7	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
8	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
9	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
10	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
11	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
12	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
13	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
14	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
15	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
16	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
17	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
18	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
19	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
20	30/08/19 10:11	General View		Load JPG	<input checked="" type="checkbox"/>
21	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
22	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
23	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
24	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
25	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
26	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
27	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
28	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
29	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
30	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
31	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
32	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
33	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
34	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
35	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
36	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
37	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
38	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
39	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
40	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
41	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
42	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
43	30/08/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	30/08/19 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	30/08/19 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	30/08/19 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	30/08/19 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	30/08/19 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	30/08/19 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	30/08/19 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	30/08/19 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	30/08/19 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	30/08/19 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	30/08/19 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	30/08/19 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	30/08/19 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	30/08/19 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	30/08/19 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/10/19 16:57	Supplementary	 Load PDF	
No	Finalized On	ECICS Limited (HQ)	Thumbnail	Print
1	22/07/19 10:32	OI SAS - GBE2258K	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS19012593/ASF3E2

Date: 01/10/2019

REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant

Vehicle No : SMA4115S

Insured Vehicle No : GBE2258K

Date of Loss: 10/07/2019

Nature of Claim:

TP

Claim No: DMCV1900040H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SMA4115S

Make & Model:

HONDA HR-V, 1.5 DX CVT (A)

Engine No:

L15B4534134

Reg. Date:

06/06/2018 (Man. Year: 2018)

Chassis No:

JHMRU1810GX204135

Colour:

Black

Odometer:

24845 km

Engine Capacity:

1496 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side:

Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side:

Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,926.81	3,040.39	3,886.42	56.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,750.00	5,400.00	5,350.00	49.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,676.81	8,440.39	9,236.42	52.25
+ GST 7.00/7.00% (S\$)	1,237.38	590.83	646.55	52.25
Nett Amount (S\$)	18,914.19	9,031.22	9,882.97	52.25

INSPECTION

Date of Assignment:

12/07/2019

Date Inspected:

16/07/2019

Inspected At:

Kah Motor Co Sdn Bhd (Ubi)

15 Ubi Road 4

Singapore 408610

Estimated Period of Repair:

6.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 01 Oct 2019)	
Parts:	N/A	HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA4115S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
2	1		*LAMP UNITR	Cracked	441.50 FS	*331.12 FS
3	1		*LAMP UNITL	Not Necessary	441.50 FS	*- FS
4	1		*LIGHT ASSY,R.LID	Cracked	269.90 FS	*202.42 FS
5	1		*LIGHT ASSYL.LID	Not Necessary	269.90 FS	*- FS
6	1		*GARNISH ASSYRR.LICENSE	Cracked	193.60 FS	*145.20 FS
7	1		*EMBLEMH	Necessary	10.70 FS	*8.02 FS
8	1		*NUTPUSH 3MM (2PCS)	Necessary	4.20 FS	*3.15 FS
9	1		*RUBBER CR.WINDSHIELD DAMPER	Necessary	19.30 FS	*14.47 FS
10	1		*DAMPERSTD 5X5	Necessary	8.50 FS	*6.37 FS
11	1		*RUBBER CL.WINDSHIELD DAMPER	Necessary	19.30 FS	*14.47 FS
12	1		*CAPPIVOT	Necessary	4.80 FS	*3.60 FS
13	1		*FASTENER BW/SHIELD (4PCS)	Necessary	21.20 FS	*15.90 FS
14	1		*FASTENER B (2PCS)	Necessary	10.60 FS	*7.95 FS
15	2		*FASTENER AW/SHIELD	Necessary	7.60 FS	*5.70 FS
16	1		*BUZZER ASSYSMART	Not Necessary	60.40 FS	*- FS
17	1		*ANTENNA ASSYL.F	Not Necessary	59.30 FS	*- FS
18	1		*BOARD ASSYTRUNK FLOOR	Not Necessary	189.80 FS	*- FS
19	1		*BOX ASSY, CARGO FLOOR	Not Necessary	129.50 FS	*- FS
20	1		*LINING ASSYTAILGATE	Deformed	136.00 FS	*102.00 FS
21	1		*LINING ASSYRR.PANEL	Deformed	43.90 FS	*32.92 FS
22	1		*EMBLEMRR.	Necessary	13.30 FS	*9.97 FS
23	1		*EMBLEM,RR.I-VTEC	Necessary	14.50 FS	*10.87 FS
24	1		*FACE RR.BUMPER	Deformed	777.90 FS	*347.77 FS
25	1		*CLIP,BUMPER (8PCS)	Necessary	18.40 FS	*13.80 FS
26	1		*FACER.RR.BUMPER CORNER	Repair	94.10 FS	*- FS
27	1		*FACEL.RR.BUMPER CORNER	Repair	94.10 FS	*- FS
28	1		*SPACER,R.RR.BUMPER SIDE	Necessary	17.20 FS	*12.90 FS
29	1		*SPACER,L.RR.BPR S	Necessary	17.20 FS	*12.90 FS
30	1		*REFLECTOR ASSYR.RR.	Not Necessary	156.30 FS	*- FS
31	1		*REFLECTOR ASSYL.RR.	Not Necessary	156.30 FS	*- FS
32	1		*PANEL SETRR.FLOOR	Repair	675.50 FS	*- FS
33	1		*CROSSMEMBER COMPRR.FLOOR	Repair	83.70 FS	*- FS
34	1		*STIFFENERRR.JACK UP	Not Necessary	61.40 FS	*- FS
35	1		*STIFFENER COMPR.RR.FRAME UPP	Not Necessary	105.30 FS	*- FS
36	1		*STIFFENER COMPL.RR.FRAME UPP	Not Necessary	105.30 FS	*- FS
37	1		*PANEL COMPRR.	Dented	373.10 FS	*279.82 FS
38	1		*WEATHERSTRIPTAILGATE	Cut	98.70 FS	*74.02 FS
39	1		*LOCK ASSY, TAILGATE ASSY	Damaged	163.20 FS	*59.17 FS
40	1		*TAIL GATE COMP	Distorted	855.70 FS	*641.77 FS
41	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*FACER.RR.BUMPER CORNER	Deformed	70.57 FS	*70.57 FS
43	1		*LAMP UNITL	Cracked	331.12 FS	*331.12 FS
44	1		*LIGHT ASSYL.LID	Cracked	202.42 FS	*202.42 FS
F=Franchise part. S=SpcNett.				Total Parts (S\$)	6,926.81	3,040.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODY UNDERSIDE COATING	New	100.00	100.00
2	BODY JOINT SEALANT	New	100.00	100.00
3	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	140.00	120.00
4	REMOVE & RENEW REVERSE SENSORS - 4 PCS	New	160.00	140.00
5	APPLY BODY UNDERSIDE COATING	New	250.00	0.00
6	REMOVE & INSTALL RR WINDSCREEN	New	350.00	300.00
7	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	350.00	300.00
8	RESET VEHICLE SMART ENTRY SYSTEM	New	350.00	300.00
9	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	350.00	0.00
10	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	450.00	280.00
11	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	New	550.00	450.00
12	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	New	2,800.00	1,350.00
13	CUT & RENEW RR PANEL, GUTTER AND RR FENDER	New	4,800.00	1,960.00
Gross Labour Cost (\$\$)			10,750.00	5,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >