

ASS. REC. BY:

REF:

CS/F
CS/CI19012597/T1+8302

Special Instruction:

Surveyor: Tanketh

ASSIGNMENT (Office)

From (Person): Sithara

of

FC1

Date/Time: 16.7.19 4.49p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 3127B

Insured:

SHA 82013

at Workshop m/s

Borneo motor

Tel:

98476171 166311860 Thomas

96996192

of 1 Inch cape Body care Centre level 4

Policy No:

Claim No:

D19004584MFS4

Sum Insured:

Excess:

D.O.A. 11.7.2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

mp

H.O.D. Endorsement:

Date/Time: 16.7.19 5.02pm

Person Contacted:

Ashlyn

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLA 3127B X
	SHA 82013 CS/FC113018752/1m3K3
24/7@ 5.30pm -	Revised preli. advice via email.

(08/11/13)

ASS. REC. BY: TanphrREF PC1

ASSIGNMENT

From:

Date: 23.7.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLA 3127Bat Workshop n/s Borneo Motorof 2 Pandan Crescent

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh: 10.00 a.m - 12.00 p.m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Thomas

Veh No:

SLA 3127B Yr Regn: 2016, Feb.Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Wsh.

c.c

1718

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading:

77306

T/Radio: Insured / Std / NI / NA

Eng/No:

3T096 20W30J003690

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

YOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

23/7/19

Survey held at

Borneo MotorDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop orRear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/8/19Final Thomas \$12,855.10, 10 days (Red: 6801.40, 34%)

RECEIVED 08 AUG 2019

Date/Time, File Pass to?

5/8 Typist

Date/Time, File Return to?

2)

Report Format:

TPLump Sum / I.B.I: (\$ 12855.10)

Days Of Repair:

10

Resurvey No. of Trip:

1

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

3 + RS, SI

Photos OSPOthers 7/8/19

TOTAL

9x15 = 135

170 + 135505042447



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004584MFSH

Date: 24/7/2019

Our Ref: CS/FCI19012597/T1tf3


The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLA 3127B
Please be informed that we had conducted the inspection of the abovementioned vehicle
23/7/2019 at the premises of M/s Borneo Motor have the following to report: -

Workshop Estimate Amount	: S\$ 19,656.50
Revised Estimate Amount	: S\$ 12,672.90
"Check" Items Amount	: S\$ 3,368.10
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:
The vehicle sustained damages at the rear o/s portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	12-07-2019	Our Ref No. D19004584MFSH
Accident Date	11-07-2019	Claim Type. Third Party
Insured Vehicle	SHA8201J	Third Party Vehicle. SLA3127B
Survey Location	INCHCAPE BODYCARE CENTRE LEVEL 4 INCHCAPE CENTRE2 PANDAN CRESCENT	
Contact Person.	ASHLYN CHNG	
Contact No.	66311874/ 0	Fax No. 68727260
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BORNEO MOTORS (SINGAPORE) PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 24 July 2019 5:30 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004584MFSH/1
Attachments: PRELI ADVISED SLA 3127B.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLA 3127B**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 17 July 2019 10:32 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004584MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that the vehicle is not in workshop and repairer will arrange.

Best Regards

Celine Fong

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 16 July 2019 4:49 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004584MFSH/1

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1	Ms Lim Bee Yan Lilian 2B Hong San Walk #13-11 Palm Gardens Singapore 689048 Mobile: 98341311
	Document No 0	
	Document Date 11/07/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	ZGE20R	26/02/2016	SLA3127B	0	46706 72/DS/SLA3127B
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDGG20W30J003690	22R1721217	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: FIRST CAPITAL			net	50 100.00
		TP VEH: SHA8201J				
		DATE OF ACC: 11.07.2019				
2	Z	BP-SLANT -SUPPLY SEALANT (NETT)			net	100.00
3	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR (N				180.00
		ETT)				
4	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST (NET				122.40
		T)				
5	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				720.00
		(NETT)				
6	B	BP-LAB2 REPLACE RH REAR QUARTER GLASS (NETT)				282.00
7	L	BP-LPO SUPPLY 3M SOLAR FILM				230.00
8	B	BP-ECU2 TO RESET ECU AND REPROGRAMME (NETT)				180.00
9	B	BP-MECH2 REPLACE REAR EXHAUST PIPE SYSTEM (NETT)				720.00
10	B	BP-LAB2 REPLACE ACC DAMAGED PARTS				5760.00
		AND STRAIGHTEN/REALIGN				
		ACC AFFECTED AREAS				
11	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				4720.00
12	1	SP2061-12010 16 070 SENSOR	1.00	151.60		151.60
13	2	T52159-68907 REAR BUMPER COVER,	1.00	591.80		591.80

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle:	Parts Labour Materials Lubrication/Fluid Others	Amount Due

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

 DATE **11/07/2019**

 TIME **15:06**

 VEHICLE NO **SLA3127B**

 SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD


Inchcape

Borneo Motors
3939046
3939046

Total **Tan Guan 97495749 WP**
23/7/19 @ 11.50.
 Resurvey before paint.
 surelkhanta.com.
 10- days



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1	Ms Lim Bee Yan Lilian 2B Hong San Walk #13-11 Palm Gardens Singapore 689048 Mobile: 98341311
	Document No	
	Document Date	
	0	
	11/07/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	ZGE20R	26/02/2016	SLA3127B	0	46706 72/DS/SLA3127B
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDGG20W30J003690	2ZR1721217	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	3	S52161-OK040	PIECE, RR BUMPER	10.00	4.10	41.00
15	4	T52155-68030	R/RR BUMPER SUPPORT,	1.00	97.40	97.40
16	5	T52575-68020	R/R SIDE BPR RETAINER,	1.00	46.00	46.00
17	6	T52156-68030	L/RR BUMPER SUPPORT,	1.00	97.40	97.40
18	7	T52576-68020	L/R SIDE BPR RETAINER,	1.00	46.00	46.00
19	8	T52152-68030	R/R BUMPER EXTENSION,	1.00	67.00	67.00
20	9	T90189-06065	GROMMET,	10.00	2.10	21.00
21	0	T58307-68031	REAR LOWER FLR PANEL,	1.00	536.70	536.70
22	1	T52181-68010	REAR BUMPER ARM,	1.00	53.80	53.80
23	2	T52181-68010	REAR BUMPER ARM,	1.00	53.80	53.80
24	3	T58313-68010	R/R S/FLR EXTENSION,	1.00	108.10	108.10
25	4	T61601-68040	R/REAR QUARTER PANEL, (N/HOLE)	1.00	1052.00	1052.00
26	5	T62940-12170	DUCT ASSY, QUARTER	1.00	136.20	136.20
27	6	T08826-08115	PANEL BONDING AD	1.00	267.20	267.20
28	7	T62710-68070	R/REAR QUARTER GLASS,	1.00	410.30	410.30
29	8	T21000-20	SIKA 182010 SIKA TACK GO! (BLA	1.00	108.00	108.00
30	9	T21000-22	SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00	200.00
31	0	T67935-68020 B0	PLATE BACK DOOR	1.00	298.00	298.00
32	1	T64730-68040 B0	R/REAR SIDE DECK TRIM COVER	1.00	746.50	746.50
33	2	T90975-02086	TOYOTA SYMBOL EMBLEM,	1.00	72.20	72.20
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3939047

3939047

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 11/07/2019
TIME 15:06

VEHICLE NO SLA3127B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 /ICFIC1	Ms Lim Bee Yan Lilian 2B Hong San Walk #13-11 Palm Gardens Singapore 689048 Mobile: 98341311
	Document No 0	
	Document Date 11/07/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	ZGE20R	26/02/2016	SLA3127B	0	46706 72/DS/SLA3127B
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDGG20W30J003690	22R1721217	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
34	3	T75444-68010 LUGGAGE "VALVE MATIC "	1.00	41.10		41.10
35	4	T75443-ELGAN ELEGANCE EMBLEM	1.00	40.00		40.00
36	5	T81910-13022 R/R BUMPER REFLECTOR,	1.00	59.80		59.80
37	6	T89997-30070 ELECTRICAL ANTENNA,	1.00	166.10		166.10
38	7	T17430-37340 REAR EXHAUST PIPE,	1.00	1033.10		1033.10
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 6,542.10 Labour 12,884.40 Materials 230.00 Lubrication/Fluid 0.00 Others 0.00	19,656.50 GST 7.00% 1,375.96 Less 0.00 Amount Due 21,032.46

PLEASE TEAR ALONG PERFORATED LINE

3939048

3939048

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 11/07/2019
TIME 15:06

VEHICLE NO SLA3127B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD


Inchcape

Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail		Account No S1000005 / ICFIC1		Customer Detail	
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept		Document No 0		Ms Lim Bee Yan Lilian 2B Hong San Walk #13-11 Palm Gardens Singapore 689048 Mobile: 98341311	
		Document Date 31/07/2019			
Year	Make	Model	Reg Date	Veh Reg No	Kilometers
16	HPXNP S6	ZGE20R	26/02/2016	SLA3127B	0
			WIP No	Order No/Remarks	
			46706	72/DS/SLA3127B	
Chassis No		Engine No	Terms	Service Engineer	Vehicle In
JTDGG20W30J003690		2ZR1721217	60	Thomas Pang W T	23/07/2019 8.00 31/07/2019 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %
1	Z	BP-SUNDRY TP INS: FIRST CAPITAL TP VEH: SHA8201J DATE OF ACC: 11.07.2019 BY:LKK-TAUFIKH @ 23.07.2019 10 WORKING DAYS			
					50.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)			100.00
3	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR (N	*		180.00
		ETT)			122.40
4	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST (NET	*		720.00
		T)			282.00
5	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR	*		230.00
		(NETT)			180.00
6	B	BP-LAB2 REPLACE RH REAR QUARTER GLASS (NETT)	*		4320.00
7	L	BP-LPO SUPPLY 3M SOLAR FILM PO:23208	M30		
8	B	BP-ECU2 TO RESET ECU AND REPROGRAMME (NETT)	18		
9	B	BP-LAB2 REPLACE ACC DAMAGED PARTS	*		
		AND STRAIGHTEN/REALIGN			2950.00
		ACC AFFECTED AREAS	*		591.80
10	B	BP-RES2 RESPRAY ACC AFFECTED AREAS	1.00	591.80	
11	1	T52159-68907 COVER RR BUMPER			
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.					
For & on behalf of Borneo Motors		Customer's Signature	Change Summary		Total
		Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others		Less
					Amount Due

4040904

PLEASE TEAR ALONG PERFORATED LINE

4040904

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 31/07/2019
TIME 15:30

VEHICLE NO SLA3127B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail				Account No		Customer Detail			
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept				S1000005 / ICFIC1		Ms Lim Bee Yan Lilian 2B Hong San Walk #13-11 Palm Gardens Singapore 689048 Mobile: 98341311			
				Document No					
				0					
				Document Date					
				31/07/2019					
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks		
16	HPXNP S6	ZGE20R	26/02/2016	SLA3127B	0	46706	72/DS/SLA3127B		
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On				
JTDGG20W30J003690	2ZR1721217	60	Thomas Pang W T	23/07/2019	8.00	31/07/2019 18.00			
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
12	2	S52161-0K040	PIECE, RR BUMPER			10.00	4.10		41.00
13	3	T52155-68030	SUPPORT RR BUMPER RH			1.00	97.40		97.40
14	4	T52575-68020	RETAINER RR BUMPER			1.00	46.00		46.00
15	5	T90189-06065	GROMMET, SCREW			10.00	2.10		21.00
16	6	T61601-68040	PANEL QUARTER RH			1.00	1052.00		1052.00
17	7	T62940-12170	DUCT ASSY, QUARTER			1.00	136.20		136.20
18	8	T08826-08115	PANEL BONDING AD			1.00	267.20		267.20
19	9	T62710-68070	WINDOW ASSY RH			1.00	410.30		410.30
20	0	T21000-20	SIKA 210002-0 TACK GO! (BLACK) SG			1.00	108.00		108.00
21	1	T21000-22	SIKA 210002-2 G+P 207 ADHESIVE PRIN			1.00	200.00		200.00
22	2	T90975-02086	EMBLEM, SYMBOL			1.00	72.20		72.20
23	3	T75444-68010	PLATE, LUGGAGE COMPT			1.00	41.10		41.10
24	4	T75443-ELGAN	ELEGANCE EMBLEM			1.00	40.00		40.00
25	5	T81910-13022	REFLECTOR ASSY, RH			1.00	59.80		59.80
26	6	T58307-68031	PANEL LAMP LOWER			1.00	536.70		536.70
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.									
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total			
		Please acknowledge receipt of vehicle		Parts		12,855.10			
				Labour		GST 7.00%			
				Materials		899.86			
				Lubrication/Fluid		Less			
				Others		0.00			
						Amount Due			
						13,754.96			

4040905

PLEASE TEAR ALONG PERFORATED LINE

4040905

TO SECURITY GUARD

DATE 31/07/2019
TIME 15:30

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLA3127B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19012597/T1tf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-08-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8201J	Veh. Inspected	SLA 3127B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004584MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	16/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDGG20W30J003690	Colour	WHITE	
Odometer	77306	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/07/2019	Inspection Date	23/07/2019	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 3127B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER COVER (SN)	CRACKED	591.80	591.80
1	070 SENSOR (SN)	NOT NECESSARY	151.60	-
10	PIECE,RR BUMPER (SN)	NECESSARY	41.00	41.00
1	R/RR BUMPER SUPPORT (SN)	NECESSARY	97.40	97.40
1	R/R SIDE BPR RETAINER (SN)	NECESSARY	46.00	46.00
1	L/RR BUMPER SUPPORT (SN)	NOT NECESSARY	97.40	-
1	L/R SIDE BPR RETAINER (SN)	NOT NECESSARY	46.00	-
1	R/R BUMPER EXTENSION (SN)	NOT NECESSARY	67.00	-
10	GROMMET (SN)	NECESSARY	21.00	21.00
1	REAR LOWER FLR PANEL (SN)	BENT	536.70	536.70
1	REAR BUMPER ARM (SN)	NOT NECESSARY	53.80	-
1	REAR BUMPER ARM (SN)	NOT NECESSARY	53.80	-
1	R/R S/FLR EXTENSION (SN)	NOT NECESSARY	108.10	-
1	R/REAR QUARTER PANEL,(N/HOLE)(SN)	BENT	1,052.00	1,052.00
1	DUCT ASSY,QUARTER (SN)	DEFORMED	136.20	136.20
1	PANEL BONDING AD (SN)	NECESSARY	267.20	267.20
1	R/REAR QUARTER GLASS (SN)	NECESSARY	410.30	410.30
1	SIKA 182010 SIKA TACK GO (BLA)(SN)	NECESSARY	108.00	108.00
1	SIKA 207.G+P ADHESIVE PRIMER (SN)	NECESSARY	200.00	200.00
1	PLATE BACK DOOR (SN)	NOT NECESSARY	298.00	-
1	R/REAR SIDE DECK TRIM COVER (SN)	NOT NECESSARY	746.50	-
1	TOYOTA SYMBOL EMBLEM (SN)	NECESSARY	72.20	72.20
1	LUGGAGE "VALVE MATIC" (SN)	NECESSARY	41.10	41.10
1	ELEGANCE EMBLEM (SN)	NECESSARY	40.00	40.00
1	R/R BUMPER REFLECTOR (SN)	CRACKED	59.80	59.80
1	ELECTRICAL ANTENNA (SN)	NOT NECESSARY	166.10	-
1	REAR EXHAUST PIPE (SN)	NOT NECESSARY	1,033.10	-
1	SUNDRY (SN)	NECESSARY	100.00	50.00
1	SEALANT (SN)	NECESSARY	100.00	100.00
			6,742.10	3,870.70

Report Ref No. CS/FCI19012597/T1tf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	DRILL HOLE AND INSTALL REVERSE SENSOR.		180.00	180.00
	CHECK WIRING AND CONDUCT WATER TEST.		122.40	122.40
	REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR.		720.00	720.00
	REPLACE RH REAR QUARTER GLASS.		282.00	282.00
	SUPPLY 3M SOLAR FILM.		230.00	230.00
	TO RESET ECU AND REPROGRAMME.		180.00	180.00
	REPLACE REAR EXHAUST PIPE SYSTEM.	NOT NECESSARY	720.00	-
	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS.		5,760.00	4,320.00
	RESPRAY ACC AFFECTED AREAS.		4,720.00	2,950.00
			12,914.40	8,984.40
	GRAND TOTAL		19,656.50	12,855.10
RECOMMENDED COST OF REPAIRS				12,855.10

Report Ref No. CS/FC119012597/T1tf3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.