

ASS. REC. BY:

REF:

CS/CTI19012599/R114302

Special Instruction:

Survivor:

Rasul

ASSIGNMENT (Office)

From (Person): Tan Kah Leong

of C71

Date/Time: 17.7.19 11.19a.m

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMA 3761 H

Insured:

SGV 61247

at Workshop m/s Teamwork

Tel:

68442475

of 53 ubi Ave 1 #01-24

Policy No: DMPCSN30279219000

Claim No:

SNM 191520330402

Sum Insured:

Excess:

Make of Veh.

D.O.A. 13.7.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 17.7.19 11.20a.m

Person Contacted:

Darren

Vehicle IN/OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

SMA 3761 H NA/CTI19012429/24

SGV 61247 X

1518-

Confirm L/S \$2450, 3days with Letitia.

(Red: 10800.34, 81%)

*Ramu*

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SMA 3761H**  
at Workshop n/s **TEAMWORK**  
of **53, KAA USI ave 1. #01-24**  
Insured: **CR**

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Yes: Yes or No

Lum Sum: \_\_\_\_\_ % Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: **SMA 3761H** Yr Regn: **2018 / Jun**

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Subaru Forester 2.0i.c 1998**

Colour: **WHITE** A/C: Insured / Std / NI / NA

Sp. Reading: **023522** T/Audio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: **JF18J5KC5JG109798**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **225/60R17**

R: \_\_\_\_\_

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. **6** mm

L/Bal. **6** mm

D.O.A. **13/07/19**

Survey held at **TEAMWORK**

Rear

R/Bal. **6** mm

L/Bal. **6** mm

D.O.A. **24/07/19**

Des. of Damages: Frt ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 19 AUG 2019

Date/Time, File Pass to/

1) **19/8 Typist**

Date/Time, File Return to/

2)

Report Format :

Lump Sum / I.B.F. (\$) **TP 24501**

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Add Fee:

☐ Site Insp. (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

☐ 3 + RS. 31

☐ Photos

☐ Other:

TOTAL

220

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jul 2019		17 Jul 2019 10:42 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:									
Main Claimant:		ONG CHEE SIONG, ID: S7931286Z							
Vehicle Reg. No.:		SMA3761H	Date of Loss:	13/07/2019 17:00 - :59					
Claim Type:		TP / SNM19D203304C02	Policy/Cover Note No.:	DMPCSN30279219000					
Vehicle Reg. No. (Insured):		SGU6124T	Policy No. (Claimant):	1800066332					
			Excess:	S\$0.00					
Repairer:		Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]							
Claimant's Insurer:		AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/07/2019]							
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Sent:** Wednesday, 17 July 2019 10:35 AM  
**To:** Darren; assignments  
**Subject:** RE: OUR REF : SNM,19D203304/TANKL - OUR REF : 1907-43 // YOUR REF: SGU6124T ACCIDENT INVOLVING SGU6124T AND SMA3761H

WITHOUT PREJUDICE

Dear Darren,

We refer to your email of 17.07.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

**Tan Kah Leong**  
Assistant Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Darren [mailto:claims@teamworkgarage.com]  
**Sent:** Wednesday, 17 July, 2019 10:27 AM  
**To:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Subject:** RE: OUR REF : SNM,19D203304/TANKL - OUR REF : 1907-43 // YOUR REF: SGU6124T ACCIDENT INVOLVING SGU6124T AND SMA3761H

Hi Kah Leong,

Please appoint LKK

Darren  
Teamwork Garage Pte Ltd  
53 Ubi Avenue 1  
#01-24 Paya Ubi Industrial Park  
Singapore 408934  
Tel: 68442475  
Fax: 68442474

**From:** Tan Kah Leong

**Sent:** Wednesday, 17 July 2019 10:15 AM

**To:** TEAMWORK

**Subject:** RE: OUR REF : SNM,19D203304/TANKL - OUR REF : 1907-43 // YOUR REF: SGU6124T ACCIDENT INVOLVING SGU6124T AND SMA3761H

Re-send reminder.

Regards

**Tan Kah Leong**

Assistant Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Tan Kah Leong

**Sent:** Tuesday, 16 July, 2019 5:39 PM

**To:** TEAMWORK <[claims@teamworkgarage.com](mailto:claims@teamworkgarage.com)>

**Subject:** RE: OUR REF : SNM,19D203304/TANKL - OUR REF : 1907-43 // YOUR REF : SGU6124T ACCIDENT INVOLVING SGU6124T AND SMA3761H

Without Prejudice

Dear Shu Shan,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
LOW SAR HUEI
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
HONG FOOK CHOY
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards

**Tan Kah Leong**  
Assistant Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI  
**Sent:** Tuesday, 16 July, 2019 4:31 PM  
**To:** Tan Kah Leong <[KahLeong.Tan@sg.cntaiping.com](mailto:KahLeong.Tan@sg.cntaiping.com)>; Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; TEAMWORK <[claims@teamworkgarage.com](mailto:claims@teamworkgarage.com)>  
**Subject:** OUR REF : SNM,19D203304/TANKL - OUR REF : 1907-43 // YOUR REF : SGU6124T ACCIDENT INVOLVING SGU6124T AND SMA3761H

Dear Kah Leong,

Please conduct PRS for SMA3761H.

Dear Shu Shan,

Please note that the officer in charge is Kah Leong, 63896193.

Thank you

**Lim Shu Min**  
Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 63896156 | F: (65) 62247175

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** TEAMWORK [<mailto:claims@teamworkgarage.com>]  
**Sent:** Tuesday, 16 July, 2019 12:41 PM  
**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>  
**Cc:** TEAMWORK <[claims@teamworkgarage.com](mailto:claims@teamworkgarage.com)>  
**Subject:** OUR REF : 1907-43 // YOUR REF : SGU6124T ACCIDENT INVOLVING SGU6124T AND SMA3761H

WITHOUT PREJUDICE

OUR REF : 1907-43  
YOUR REF : SGU6124T

Dear Sir / Madam,  
PRE-REPAIR INSPECTION FOR SMA3761H  
ACCIDENT INVOLVING SGU6124T AND SMA3761H ON 13.07.2019.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.

Thank you and have a nice day.

Regards,

*Shu Shan*

Teamwork Garage Pte Ltd  
Blk 53 Ubi Avenue 1  
#01-24  
Paya Ubi Industrial Park  
Singapore 408934  
Tel: 6844 2475  
Fax: 6844 2474

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## Denise Tay (LKKAUTO)

---

**From:** claims@teamworkgarage.com  
**Sent:** Thursday, 15 August 2019 3:07 PM  
**To:** Rasul (LKKAUTO)  
**Cc:** 'TEAMWORK GARAGE CLAIMS'  
**Subject:** RE: SMA3761H SUBARU FORESTER

Hi Rasue,

We confirm cor @ \$ 2450 and DOR @ 3 days

*Thank you and have a nice day! ☺*

**Letitia**

*Teamwork Garage Pte Ltd*  
Blk 53 Ubi Avenue 1 #01-24 Paya Ubi Industrial Park  
Singapore (408934)  
Tel: 6844 2475 | Fax: 6844 2474

---

**From:** Rasul (LKKAUTO) [mailto:Rasul@lkkauto.com]  
**Sent:** Tuesday, August 6, 2019 8:52 AM  
**To:** Darren <claims@teamworkgarage.com>  
**Subject:** RE: SMA3761H SUBARU FORESTER

Hi Darren,

Refer to attachment

As I told you that day, the rear bumper lower garnish comes together with the bumper  
Finalised amount is \$ 2450 / 3 days lump sum


Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK  
Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** Darren [mailto:claims@teamworkgarage.com]  
**Sent:** Monday, 5 August, 2019 7:03 PM  
**To:** Rasul (LKKAUTO)  
**Subject:** RE: SMA3761H SUBARU FORESTER

Hi Sir,

Please see attached



MSME18082567 / SME Motor Pte Ltd - Kaki Bukit  
 ENTRY DATE & TIME: 15/07/2019 17:30  
 SUBMITTED BY: Chia Pei Ying

## SINGAPORE ACCIDENT STATEMENT

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report 15/07/2019 17:30  
 Date Of Accident 13/07/2019 17:15  
 Exact Location Of Accident BEFORE EXIT KALLANG BAHRU  
 Country/State of Loss SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number SMA3761H  
**Insured/Policyholder**  
 Name Of Registered Owner ONG CHEE SIONG  
 NRIC No S7931286Z  
 Email Address NOEMAIL  
 Mobile Phone No (LOCAL) +65-98788011  
 Alternative Phone No OFFICE-98788011

**Vehicle Particulars**

Manufacturer SUBARU  
 Model FORESTER

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

**Insurance Company**

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number 1800066332  
 Cover Note Number

**Driver**

Name of Driver ONG CHEE SIONG  
 NRIC No S7931286Z  
 Date Of Birth 07/10/1979  
 Occupation INDOOR  
 Date Of Driving Pass 13/08/2009  
 Driving Experience 9 YEARS AND 11 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-98788011  
 Fax Number  
 Contact Number OFFICE-98788011  
 Email Address NOEMAIL

Address BLK 268A PUNGGOL FIELD #06-133  
 Postcode 821268  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 5

Passenger 1 NAME: : NG HUI MIN  
 GENDER: : FEMALE

Passenger 2 NAME: : ONG CHEE SIONG  
 GENDER: : MALE

Passenger 3 NAME: : TOH AH HWA  
 GENDER: : FEMALE

Passenger 4 NAME: : CAYDEN ONG  
 GENDER: : MALE

### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

### Circumstances of Accident

I WAS TRAVELLING ALONG PIE TOWARDS KALLANG BAHRU EXIT. AS I WAS SLOWING DOWN MY VEHICLE SAFELY, I FELT AN IMPACT HIT ME FROM BEHIND MY CAR. I GOT A VIDEO FOOTAGE FOR MY STATEMENT.

### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: WITH TP WORKSHOP  
 Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGU6124T  
 Vehicle Make/Model/Colour

Details Of Properties

VEHICLE B

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

## SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature  
Date & Time:

15/7/19


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

TRAWOFF  
BMAER

## Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along PIE toward Kallang Bahru Exit. As I was slowing down my vehicle safely I felt an impact hit me from behind my car. I got a video footage for my statement.

## DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NR/C/TIN No.:



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

REPAIR PERFORMA INVOICE

China Taiping Insurance (Singapore) Pte Ltd  
105 Cecil Street #19-00  
The Octagon  
Singapore 069534

Vehicle number	SMA3761H
Make / Model	SUBBUA/FORESTER
Chassis number	JF1SJKC51JG109795
Accident date	13 July 2019
Reference	1903-74

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	END PANEL <i>repair Take photo bt</i>	398.40 ✓
1	END PAENL TOP GANRISH <i>X } su</i>	194.40
1	SPARE TYRE TOP BOARD <i>X } su</i>	403.20
1	REAR BUMPER <i>de</i>	720.00 ✓
1	REAR BUMPER TOP BEAM <i>2 bt</i>	345.60 ✓
2	REAR BUMPER SIDE BEAM <i>i X su</i>	108.00
1	REAR BUMPER REFLECTOR <i>2 Lt-X/RH-Ca</i>	108.00 <i>54</i>
1	REAR BUMPER LOWER GARNISH <i>de X (check Together or Separate)</i>	1800.00
1	REAR BUMPER LOWER SKIDE PLATE <i>bt</i>	375.00 ✓
2	REAR TAILLAMP <i>X</i>	1036.80
1	TAILGATE <i>X</i>	1287.36
1	TAILGATE LOCK <i>X</i>	264.00
1	TAILGATE LOCK STRIKER <i>X</i>	39.00
1	TAILGATE WEATHERSTRIP <i>X</i>	163.20
1	TAILGATE EMBLEM - LOGO <i>X</i>	118.80
1	TAILGATE EMBLEM - FORESTER <i>X</i>	102.00
1	TAILGATE INNER TRIM <i>X</i>	360.00
2	TAILGATE INNER LAMP <i>X</i>	582.30
1	TAILGATE OUTER GARNISH <i>X</i>	306.00
1	TAILGATE GLASS MOULDING <i>X</i>	36.00
1	KEYLESS SENSOR <i>X</i>	177.00
2	REAR FENDER INNER TRIM <i>X</i>	518.40
1	REAR EXHAUST SILENCER <i>X</i>	722.16
2	REAR EXHAUST MOUNTING <i>X</i>	48.00
1	REAR EXHAUST HEAT SHIELD <i>X</i>	96.00
2	REAR PDC SENSOR <i>? w price?</i>	1084.80 <i>542.40</i>
2	SENSOR HOLDER <i>nu</i>	156.00 <i>78</i>
Subtotal		11550.42
Less 20%		2310.08
Balance C/F		9240.34

4963.80

20%

3971.04

2513.40

20%

2010.72

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	9240.34
1 SET	REAR BUMPER CLIP <del>mu</del> ✓	40.00
1	JOINT SEALANT <del>X</del> } <sup>x</sup> <del>nn</del>	150.00
1	WINDSCREEN SEALANT <del>X</del> }	150.00
	Subtotal	340.00
	Balance C/F	9580.34
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	9580.34
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	70.00 <del>Xnn</del>
2	REMOVE, REFIT REAR LINING, TRIM AND GANRISH	200.00 <del>60</del>
3	REMOVE AND RENEW REAR EXHAUST	150.00 <del>X</del>
4	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 <del>60</del>
5	REMOVE AND REFIT REAR WINDSCREEN	150.00 <del>Xnn</del>
6	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 <del>Xnn</del>
7	PANEL BEATING ON AFFECTED AFFECTED AREAS	1400.00 <del>300</del> 400
8	SPRAY PAINTING ON AFFECTED AREAS	1200.00 <del>200</del> 400
9	APPLY ANTI RUST ON AFFECTED AREAS	150.00 <del>Xnn</del> 500
	Subtotal	3670.00
	Grand total	13250.34

2010.72

40.00

1020.00

3070.72

20%

2456.57

45-2,450

3 days

3791.04  
40.00  
+ 1020.00  
4851.04  
20%  
3880.83

45- \$ 3800  
DOR - 3 days

RASUL

HP 90010068

3 days

P/P

24/07/19 @ 1630

Resey to be part



Pte Ltd

**TeamWork Garage Pte Ltd**

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : [claims@teamworkgarage.com](mailto:claims@teamworkgarage.com)

Register number : 201015366H

**REPAIR PERFORMA INVOICE**

**China Taiping Insurance (Singapore) Pte Ltd**

105 Cecil Street #19-00

The Octagon

Singapore 069534

Vehicle number	SMA3761H
Make / Model	SUBBUA/FORESTER
Chassis number	JF1SJKC51JG109795
Accident date	13 July 2019
Reference	1903-74

**Qty Particulars**

**Unit Price - SGD \$**

<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	END PANEL <i>repair bt</i>	398.40
1	END PAENL TOP GANRISH <i>x</i>	194.40
1	SPARE TYRE TOP BOARD <i>x</i>	403.20
1	REAR BUMPER <i>de</i>	720.00
1	REAR BUMPER TOP BEAM <i>?</i>	345.60
2	REAR BUMPER SIDE BEAM <i>?</i>	108.00
2	REAR BUMPER REFLECTOR <i>x</i>	108.00
1	REAR BUMPER LOWER GARNISH <i>bt x</i>	1800.00
1	REAR BUMPER LOWER SKIDE PLATE <i>bt</i>	375.00
2	REAR TAILLAMP <i>x</i>	1036.80
1	TAILGATE <i>x</i>	1287.36
1	TAILGATE LOCK <i>x</i>	264.00
1	TAILGATE LOCK STRIKER <i>x</i>	39.00
1	TAILGATE WEATHERSTRIP <i>x</i>	163.20
1	TAILGATE EMBLEM - LOGO <i>x</i>	118.80
1	TAILGATE EMBLEM - FORESTER <i>x</i>	102.00
1	TAILGATE INNER TRIM <i>x</i>	360.00
2	TAILGATE INNER LAMP <i>x</i>	582.30
1	TAILGATE OUTER GARNISH <i>x</i>	306.00
1	TAILGATE GLASS MOULDING <i>x</i>	36.00
1	KEYLESS SENSOR <i>x</i>	177.00
2	REAR FENDER INNER TRIM <i>x</i>	518.40
1	REAR EXHAUST SILENCER <i>x</i>	722.16
2	REAR EXHAUST MOUNTING <i>x</i>	48.00
1	REAR EXHAUST HEAT SHIELD <i>x</i>	96.00
2	REAR PDC SENSOR <i>?</i>	1084.80
2	SENSOR HOLDER <i>new</i>	156.00
Subtotal		11550.42
Less 20%		2310.08
Balance C/F		9240.34

2 pcs A  
245 A



<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	9240.34
1 SET	REAR BUMPER CLIP <i>all ✓</i>	40.00
1	JOINT SEALANT <i>X</i>	150.00
1	WINDSCREEN SEALANT <i>X</i>	150.00
	Subtotal	340.00
	Balance C/F	9580.34
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	9580.34
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	70.00 <i>X</i>
2	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	<del>200.00</del> <i>60</i>
3	REMOVE AND RENEW REAR EXHAUST	150.00 <i>X</i>
4	REMOVE AND RENEW REAR REVERSE SENSOR	<del>150.00</del> <i>60</i>
5	REMOVE AND REFIT REAR WINDSCREEN	150.00 <i>X</i>
6	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 <i>X</i>
7	PANEL BEATING ON AFFECTED AFFECTED AREAS	<del>1400.00</del> <i>300</i> <i>400</i>
8	SPRAY PAINTING ON AFFECTED AREAS	<del>1200.00</del> <i>200</i> <i>400</i> <i>500</i>
9	APPLY ANTI RUST ON AFFECTED AREAS	150.00 <i>X</i>
	Subtotal	3670.00
	Grand total	13250.34

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*25/7/19* *RASUL*  
*HP 90010068*  
*3 days*  
*P/P*  
*24/07/19 01630*  
*Resey 30 for part*

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19012599/R1TF3N2

Date: 20/08/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30279219000	
Claimant Vehicle No :	SMA3761H	Insured Vehicle No :	SGU6124T	
Date of Loss:	13/07/2019	Nature of Claim:	TP	Claim No: SNM19D203304C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SMA3761H		
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Engine No:	FB20YD81858
Reg. Date:	05/06/2018 (Man. Year: 2018)	Chassis No:	JF1SJ5KC5JG109795
Colour:	White	Odometer:	23522 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	225/60R17	Rear Tyre Size:	225/60R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,580.34	2,050.72	7,529.62	78.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,670.00	1,020.00	2,650.00	72.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,250.34</b>	<b>3,070.72</b>	<b>10,179.62</b>	<b>76.83</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,450.00</b>		
<b>(S\$)</b>	13,250.34	2,450.00	10,800.34	81.51
<b>+ GST 7.00/7.00% (S\$)</b>	927.52	171.50	756.02	81.51
<b>Nett Amount (S\$)</b>	<b>14,177.86</b>	<b>2,621.50</b>	<b>11,556.36</b>	<b>81.51</b>

## INSPECTION

Date of Assignment:	17/07/2019	
Date Inspected:	24/07/2019	Inspected At: Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Aug 2019)

Parts: M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMA3761H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*END PANEL	Bent	398.40 FL	*398.40 FL
2	1		*END PANEL TOP GARNISH	Serviceable	194.40 FL	*- FL
3	1		*SPARE TYRE TOP BOARD	Serviceable	403.20 FL	*- FL
4	1		*REAR BUMPER	Deformed	720.00 FL	*720.00 FL
5	1		*REAR BUMPER TOP BEAM	Bent	345.60 FL	*345.60 FL
6	2		*REAR BUMPER SIDE BEAM	Serviceable	108.00 FL	*- FL
7	1		*REAR BUMPER REFLECTOR	O/s Cracked/N/s Not Necessary	108.00 FL	*54.00 FL
8	1		*REAR BUMPER LOWER GARNISH	Not Necessary	1,800.00 FL	*- FL
9	1		*REAR BUMPER LOWER SKIDE PLATE	Bent	375.00 FL	*375.00 FL
10	2		*REAR TAILLAMP	Not Necessary	1,036.80 FL	*- FL
11	1		*TAILGATE	Not Necessary	1,287.36 FL	*- FL
12	1		*TAILGATE LOCK	Not Necessary	264.00 FL	*- FL
13	1		*TAILGATE LOCK STRIKER	Not Necessary	39.00 FL	*- FL
14	1		*TAILGATE WEATHERSTRIP	Not Necessary	163.20 FL	*- FL
15	1		*TAILGATE EMBLEM-LOGO	Not Necessary	118.80 FL	*- FL
16	1		*TAILGATE EMBLEM-FORESTOR	Not Necessary	102.00 FL	*- FL
17	1		*TAILGATE INNER TRIM	Not Necessary	360.00 FL	*- FL
18	2		*TAILGATE INNER LAMP	Not Necessary	582.30 FL	*- FL
19	1		*TAILGATE OUTER GARNISH	Not Necessary	306.00 FL	*- FL
20	1		*TAILGATE GLASS MOULDING	Not Necessary	36.00 FL	*- FL
21	1		*KEYLESS SENSOR	Not Necessary	177.00 FL	*- FL
22	2		*REAR FENDER INNER TRIM	Not Necessary	518.40 FL	*- FL
23	1		*REAR EXHAUST SILENCER	Not Necessary	722.16 FL	*- FL
24	2		*REAR EXHAUST MOUNTING	Not Necessary	48.00 FL	*- FL
25	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	96.00 FL	*- FL
26	1		*REAR PDC SENSOR (4 Pcs)	Not Working (2 Pcs only)	1,084.80 FL	*542.40 FL
27	1		*SENSOR HOLDER (4 Pcs)	Necessary (2 Pcs only)	156.00 FL	*78.00 FL
28	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
29	1		*JOINT SEALANT	Not Necessary	150.00 FS	*- FS
30	1		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,890.42	2,553.40
- List Item Discount on L Items 20.00/20.00% (S\$)	2,310.08	502.68
Total Parts (S\$)	9,580.34	2,050.72

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	70.00	0.00
2	REMOVE,REFIT REAR LINING,TRIM AND GARNISH	New	200.00	60.00
3	REMOVE AND RENEW REAR EXHAUST	New	150.00	0.00
4	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	60.00
5	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	0.00
6	TRANSFER PARTS,ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	0.00
7	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	400.00
8	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	500.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (\$\$)			<b>3,670.00</b>	<b>1,020.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >