

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0865/2019/TG
Date : 17-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Michael Chong
Address : 778 Bedok Reservoir Road
#15-24
Singapore 479254
Telephone : (HP)+65 97762981 (Owner)
(HP)+65 81836015 (Driver)
Type of Claim : Own Damage Claims
Policy No. : 1700059602-01
Vehicle No : **SLR 9942 K**
Model Code : Audi A5 SB 2.0 TFSI Quattro (A)
Model / Year : 2/9/2017
Engine No : CVK 043404
Chassis No : WAUZZZF51JA022067
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Jul-19
Place of Accident : Bedok Reservoir Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLR 9942 K

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00	500
3	To respray front bumper and lhs front fender.	\$ 2,300.00	550
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 5,772.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLR 9942 K**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>shd</i>	\$ 2,073.00	✓
2	FRONT BUMPER FIXING PARTS <i>nen</i>	\$ 368.00	+
3	FRONT BUMPER SECURING STRIP <i>?</i>	\$ 32.00	?
4	FRONT BUMPER GRILLE - CENTER <i>nen</i>	\$ 178.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>nen</i>	\$ 207.00	+
6	FRONT BUMPER SPOILER <i>nen</i>	\$ 489.00	+
7	FRONT BUMPER GRILLE-LOWER CENTRE <i>nen</i>	\$ 187.00	+
8	FRONT BUMPER AIR GUIDE - LH <i>nen</i>	\$ 56.00	+
9	RADIATOR GRILLE <i>nen</i>	\$ 2,131.00	+
10	ULTRA SOUND SENSOR SUPPORT - LH / RH <i>2</i>	\$ 95.00	+
11	RADIATOR GRILLE COVER - UPPER	\$ 174.00	+
12	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 431.00	+
13	FRONT BUMPER FOAM FILLER PIECE	\$ 113.00	+
14	FRONT BUMPER CARRIER	\$ 733.00	+
15	FRONT BUMPER GUIDE SECTION - LH <i>nen</i>	\$ 33.00	+
16	FRONT BUMPER TOP COVER <i>2</i>	\$ 116.00	+
17	CAUTION STICKER <i>nen</i>	S/N \$ 13.00	+
18	AC STICKER	S/N \$ 7.00	+
19	FRONT BUMPER BRACKET FOR LOCK CARRIER <i>2</i>	\$ 125.00	+
20	FRONT BUMPER SUPPORT BRACKET - LH / RH <i>2</i>	\$ 51.00	+
SUB-TOTAL SPARE PARTS		\$ 7,612.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLR 9942 K**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT PARKING AID SENSOR	\$	231.00 +
22	FRONT PARKING AID SENSOR SEAL RING	4 \$	12.00 +.
23	FRONT FENDER - LH	\$	968.00 +
24	FRONT FENDER ATTACHMENT PARTS	\$	48.00 +
25	FRONT FENDER CLOSING ELEMENT - LH	\$	68.00 +
26	FRONT FENDER BRACKET - LH	\$	32.00 +
27	FRONT FENDER BRACE - LH	\$	107.00 +
28	FRONT FENDER DEFORMATION ELEMENT - LH	\$	45.00 +.
29	POP RIVET	5 \$	15.00 X
30	FRONT WHEEL HOUSING LINER - LH	\$	256.00 +
31	FRONT WHEEL SPOILER	TBC	+
32	FRONT WHEEL SPOILER TRIM - LH	\$	32.00 +
33	STONE CHIP GUARD - LH	\$	46.00 +
34	FRONT FENDER TOP LEDGE COVER - LONG	S/N \$	32.00 *
35	FRONT FENDER TOP LEDGE COVER - SHORT	S/N \$	14.00 +
36	FRONT FENDER EMBLEM	S/N \$	145.00 +
37	FRONT HEADLIGHT - LH	\$	7,204.00 +
38	FRONT HEADLIGHT LIFT CYLINDER - LH	\$	181.00 +
39	FRONT HEADLIGHT BRACKET FOR LIFT CYLINDER - LH	\$	13.00 +
40	CORRUGATED PIPE	\$	78.00 +.
SUB TOTAL SPARE PARTS		\$	9,527.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 9942 K

<u>S/N</u>	<u>Parts Description</u>		<u>Damaged Par</u> <u>S/Nett</u>
41	RADIATOR AIR GUIDE - LH / RH <i>Not Nee</i>	2 \$	42.00 ✓
42	FRONT NO. PLATE <i>Not Nee</i>	S/N \$	40.00 ✓
43	SUNDRIES ?	\$	400.00 ?
TOTAL SPARE PARTS		:	\$ 17,621.00
TOTAL LABOUR CHARGES			\$ 5,772.00
GRAND TOTAL			\$ 23,393.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian King.
: 17/07/19.
:
:
:
:
: Not Authorised, 03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant