

FWD

† Reprint 2

MAH LIAN MOTOR VEHICLE REPAIRER

No. 38 Defu Lane 9 Singapore 539278
TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
GST: M90362564P RCB NO: 201327339E

not Authorized Mark

US \$ 15,000

20 July

M/S : FWD INSURANCE SINGAPORE PTE LTD
6 Temasek Boulevard
#18-01 Suntec Tower Four Singapore 038986

Estimate No: ES1700549
Date: 12 Jul 2019
Policy No: GA467549/1
Veh Reg No: YK3300K
Make/Model: ISUZU NPR71L
Chassis No: JAANPR71L37101654
Engine No: 4HG1972388
Reg. Date: 17/04/2003

TEL: venessa.chan@fwd.com FAX: 67275799
ATTN: Motor Claim Department
Your Ref No: HENRY GAS PTE LTD
Claim Type: Third Party
Accident Date: 11/07/2019

Estimate Repair Cost to Vehicle No : YK3300K

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 Front Bumper	825.00	1 PC D.S	825.00	✓
2 Front Bumper Reinforcement	485.00	1 PC 17	485.00	X
3 Front Bumper Bracket - LH/RH	108.00 ✓	2 PC n/s bet	216.00	1 pc 103
4 Headlamp Assy - LH/RH	254.00 ✓	2 PC n/s 320	508.00	1 pc
5 Headlamp Bracket - LH/RH	102.00 ✓	2 PC n/s 201	204.00	1 pc
6 Headlamp Top Garnish - LH/RH	85.00 ✓	2 PC n/s bet	170.00	1 pc
7 Horn	132.00	2 PC n 2	264.00	X
8 Signal Lamp - LH/RH	95.00 ✓	2 PC n/s 320	190.00	1 pc
9 Front Chassis Bracket - LH/RH	588.00	2 PC R	1,176.00	X
10 Front Grille	462.00	1 PC CR	462.00	✓
11 Front Panel	983.00	1 PC D.S	983.00	✓
12 Front wiper garnish	663.00	1 PC D.S	663.00	✓
13 Front Corner Panel - LH/RH	122.00 ✓	2 PC n/s D.S	244.00	1 pc
14 Wiper Blades	38.00 ✓	2 PC n/s bet	76.00	1 pc
15 Wiper Link		1 PC bet bet	236.00	✓
16 Wiper Panel Nozzle	58.00	2 PC 17	116.00	X
17 Front Windscreen	980.00	1 PC 320	980.00	✓
18 Windscreen Rubber Seal	238.00	1 PC R	238.00	✓
19 Door Assy - LH/RH	2,345.00 ✓ n/s	2 PC succ	4,690.00	1 pc
20 front door inner trim board n/s	1665	1 PC D.S	316.00	✓
21 Cabin Roof	2200	1 PC D.S	3,785.00	✓
22 Cabin Roof Lining	1,185.00	1 PC D.S	1,185.00	✓
23 Side Mirror Frame - LH/RH	318.00 ✓	2 PC n/s bet	636.00	1 pc
24 Side Mirror Bracket - LH/RH	68.00 ✓	2 PC n/s bet	136.00	1 pc
25 Side Mirror Garnish - LH/RH	95.00 ✓	2 PC n/s CR	190.00	1 pc
26 Side Mirror - LH/RH	128.00 ✓	2 PC n/s 320	256.00	1 pc
27 Dashboard Assy	1,983.00	1 PC D.S	1,983.00	✓
28 Dashboard Reinforcement	985.00	1 PC 17	985.00	X
29 Cabin Roof Top Compartment	608.00	1 PC 17	608.00	X
30 Front LH Side Compartment	582.00	1 PC 17	582.00	X
31 Meter Assy	850.00	1 PC 17	850.00	X
32 Rear View Mirror	68.00	1 PC 17	68.00	X
33 Rear View Mirror Bracket	34.00	1 PC 17	34.00	X
34 Rear Cabin Glass	226.00	1 PC CR	226.00	✓
35 Rear Cabin Glass Rubber Seal	108.00	1 PC R	108.00	✓
36 Door Hinges Upper - LH/RH	75.00 ✓	2 PC n/s 201	150.00	1 pc
37 Door Hinges Lower - LH/RH	85.00 ✓	2 PC n/s 201	170.00	1 pc
38 Aircon Compressor	1,380.00	1 PC n 2	1,380.00	X
39 Aircon Cooling Unit	680.00	1 PC CR	680.00	✓

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

LKK Auto Consultants hence notify the Repairer of the following:
 The Repairer is to be notified before after spray painting damaged part(s) during resurvey. The Repairer is on a "Without Prejudice" basis. The Repairer is allowed to inspect the vehicle. The Repairer is allowed to inspect the vehicle. The Repairer is allowed to inspect the vehicle.

M/S : FWD INSURANCE SINGAPORE PTE LTD
 6 Temasek Boulevard
 #18-01 Suntec Tower Four Singapore 038986

TEL: venessa.chan@fwd.com FAX: 67275799
 ATTN: Motor Claim Department
 Your Ref No: HENRY GAS PTE LTD
 Claim Type: Third Party
 Accident Date: 11/07/2019

Estimate No: **ES1700549**
 Date: 12 Jul 2019
 Policy No: GA467549/1
 Veh Reg No: **YK3300K**
 Make/Model: ISUZU NPR71L
 Chassis No: JAANPR71L37101654
 Engine No: 4HG1972388
 Reg. Date: 17/04/2003

Estimate Repair Cost to Vehicle No :YK3300K

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
40 Aircon Evaporator Unit	808.00	1 PC <i>CLQ</i>	808.00 ✓	
41 Aircon Discharge Hose	108.00	1 PC <i>11</i>	108.00 X	
42 Aircon Liquid Hose	88.00	1 PC <i>11</i>	88.00 X	
43 Aircon Suction Hose	38.00	1 PC <i>11</i>	38.00 X	
44 Aircon Drier	58.00	1 PC <i>11</i>	58.00 X	
45 Aircon Block Valve	28.00	1 PC <i>11</i>	28.00 X	
46 License Lamp	80.00	1 PC <i>11</i>	80.00 X	
47 Taillamp - LH/RH	108.00	2 PC <i>CLa</i>	216.00 ✓	
			28,478.00	
		Less 10%	2,847.80	25,630.20
Net Price				
48 Front Crossmember	1,480.00	1 PC <i>a</i>	1,480.00 X	
49 Radio	280.00	1 PC <i>11</i>	280.00 X	
50 Number Plate	50.00	2 PC <i>Rear Pls</i>	100.00 <i>141PC</i>	
51 Rear Bumper	1,580.00	1 PC <i>Dis</i>	1,580.00 <i>800</i>	
52 Rear Bumper Bracket - LH/RH	688.00	2 PC <i>Set</i>	1,376.00 <i>700</i>	
53 Company Advertisement Sticker	980.00	1 SET <i>rel</i>	980.00 <i>300</i>	
54 Front Wooden Deck Frame	1,850.00	1 SET <i>CLo</i>	1,850.00 <i>800</i>	
			7,646.00	7,646.00
Labour				
55 Towing Charge .	150.00	1 JOB	150.00 <i>60</i>	
56 Labour to remove & refit windscreen , seal .	150.00	1 JOB	150.00 <i>80</i>	
57 Labour to dismantle front wooden tipper frame & renew .	850.00	1 JOB	850.00 <i>300</i>	
58 Labour to jack & straighten chassis .	2,300.00	1 JOB <i>11</i>	2,300.00 X	
59 Labour to remove & refit aircon system & top up gas .	680.00	1 JOB	680.00 <i>100</i>	
60 Labour to remove & refit dashboard .	220.00	1 JOB	220.00 <i>200</i>	
61 Labour to remove & knock & jack & refit all dented parts .	4,800.00	1 JOB	4,800.00 <i>1500</i>	
62 To rust proofing .	850.00	1 JOB	850.00 <i>100</i>	
63 To spray & painting on dented affected area .	2,800.00	1 JOB	2,800.00 <i>1500</i>	
64 Labour to check & connect wiring & refocus all headlamp .	890.00	1 JOB	890.00 <i>80</i>	
			13,690.00	13,690.00

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : FWD INSURANCE SINGAPORE PTE LTD
 6 Temasek Bouleved
 #18-01 Suntec Tower Four Singapore 038986

TEL: venessa.chan@fwd.com FAX: 67275799

ATTN: Motor Claim Department

Your Ref No: HENRY GAS PTE LTD

Claim Type: Third Party

Accident Date: 11/07/2019

Estimate No: ES1700549

Date: 12 Jul 2019

Policy No: GA467549/1

Veh Reg No: **YK3300K**

Make/Model: ISUZU NPR71L

Chassis No: JAANPR71L37101654

Engine No: 4HG1972388

Reg. Date: 17/04/2003

Estimate Repair Cost to Vehicle No :YK3300K

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			Total	SS 46,966.20
			Add GST @ 7%	3,287.63
			Total Amount Payable	SS 50,253.83

TOTAL: SINGAPORE DOLLAR FIFTY THOUSAND TWO HUNDRED FIFTY THREE AND CENTS EIGHTY THREE ONLY

**For MAH LIAN MOTOR VEHICLE
 REPAIRER**

 AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Jul 2019 Edit Reg		17 Jul 2019 00:00 Edit Adj Rpt	S\$15,000.00 Edit Estimates	S\$15,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	MOK SHAO WEI , ID: S8240132F		
Main Claimant:	HENRY GAS PTE LTD , Co. Reg. No.: 200210783Z		
Vehicle Reg. No.:	YK3300K	Date of Loss:	11/07/2019 16:00 - :59 [194 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201900020199	Policy/Cover Note No.:	PNPV2019-00009479 (Comprehensive) Coverage: 02/07/2019 - 01/07/2020
Vehicle Reg. No. (Insured):	SJH371T	Policy No. (Claimant):	GA467549/1
		Excess:	S\$2,500.00
Repairer:	Mah Lian Motor Vehicle Repairer (HQ) NO. 38 DEFU LANE 9, 539278 Defu Lane - Tel:		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 26/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

