

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

15th July 2019

ZVWS08035565

10 AXA
Vivian

Accident date: 15th July 2019

Estimated repair cost for vehicle no: SMH9115Y TOYOTA PRIUS HYBRID 1.8A

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid		\$1,250.00	X
2	1	boot lid LH logo		\$45.00	✓
3	1	Rear boot lid emble logo		\$74.10	✓
4	1	Rear Boot Lid Inner Lock		\$283.10	X
5	1	Rear boot lid inner rubber		\$236.10	X
6	2	boot lid side reflector	\$285.00	\$570.00	X
7	1	Rear Boot Lid Number Plate		\$50.00	X
8	2	Rear Boot Lid Number Plate Lamp	\$135.10	\$270.20	X
9	1	Rear Boot Lid Inner Trim board		\$425.00	X
10	1	Rear tail lamp		\$1,458.00	✓
11	4	Rear tail lamp clips	\$8.50	\$34.00	X
12	1	Rear Bumper		\$1,077.00	586
13	2	Rear Bumper side reflector	\$115.00	\$230.00	X
14	1	Rear Bumper Reinforcement		\$521.00	281
15	2	Rear Bumper Side Bracket	\$55.60	\$111.20	✓
16	1	Rear Bumper reverse sensor		\$350.00	200(SN)
17	2	Rear Bumper Bracket	\$68.40	\$136.80	✓
18	8	Rear bumper clips	\$6.50	\$52.00	50
19	1	rear bumper lower cover		\$385.00	✓
20	1	Rear end panel		\$582.00	X
21	1	Rear End Panel Top Garnish		\$258.00	✓
22	1	Rear spare tire lock		\$536.10	X

Subtotal :- \$8,316.60

2328.30 SW:200
1746.22



labour charges

To Check Wiring System

~~\$60.00~~ 30

Tuff Kote

~~\$120.00~~ X

To Remove & refix cushion

~~\$120.00~~ 60

To Remove & refix rear windscreen

~~\$120.00~~ X

Gum

~~\$50.00~~ X

To Remove & refix reverse Sensor

~~\$100.00~~ 50

Panel beating

~~\$800.00~~ 600

Spray painting

~~\$800.00~~ 700

Subtotal :- \$2,170.00

Total:- \$10,486.60

1440

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 338622

4/5 2.7K

05 Days.

Date: _____
 Signature: _____
 Acknowledged by Repairer: _____

is subject to final approval from insurance company
 • Supplemental work must be reviewed and
 • No repair work is to be done without prior approval
 • Parts must be approved by insurance company
 • To comply with all safety and security
 • To remove before any repair work
 the Repairer of the following:

LKK Auto Consulting hence notify