

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopte ltd@yahoo.com.sg
GST:200712509E RCB NO:201004495R

Not Authorized
17/7/19
The height of the
4/5 \$7000
Sdy.

M/S : FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER FOUR
SINGAPORE 038986
TEL: 6727 5721
ATTN: Motor Claim Department
Your Ref No: SLZ2534J
Claim Type: Third Party
Accident Date: 15/07/2019
TP Veh Reg No: SMG4352S

Estimate No: EST0000959
Date: 17 Jul 2019
Policy No: 5100439320-01
Veh Reg No: SLZ2534J
Make/Model: TOYOTA WISH 1.8
Chassis No: JTDGG20W70J008701
Engine No: 2ZR0A50042
Reg. Date: 27/04/2018

Estimate Repair Cost for Vehicle No :SLZ2534J

PAGE:1/2

Description	U/Price	Quantity	Price S\$	Amount S\$
List Price				
1 Rear Boot <i>Body</i>	1,455.90	1 PC	1,455.90	✓
2 Rear Boot Lock <i>m</i>	491.60	1 PC	491.60	✓
3 Rear Boot Lock Catch <i>11</i>	35.20	1 PC	35.20	X
4 Rear Boot Rubber <i>bin</i>	381.60	1 PC	381.60	✓
5 Rear Boot Emblem <i>ner</i>	39.60	1 PC	39.60	✓
6 Rear Boot Centre Moulding <i>Body/CNA</i>	295.70	1 PC	295.70	✓
7 Rear Boot Centre Logo <i>ner</i>	65.60	1 PC	65.60	✓
8 Rear Boot Centre Moulding Clipse <i>11</i>	12.90	2 PCS	25.80	X
9 Rear Boot Reflector <i>CNA</i>	312.60	2 PCS	625.20	✓
10 Rear Boot Inner Board <i>bin</i> <i>485.60</i>	651.90	1 PC	651.90	✓
11 Rear Boot Inner Pull Garnish <i>11</i>	40.20	1 PC	40.20	X
12 Rear Boot Shock Absorber <i>11</i>	361.70	2 PCS	723.40	X
13 Rear Boot Top Hinge <i>11</i>	46.20	2 PCS	92.40	X
14 Rear Windscreen Seal <i>ner</i>	56.20	1 PC	56.20	✓
15 Rear Tail Lamp <i>CNA</i> <i>512.30 x 2 = 1024.60</i>	651.90	2 PCS	1,303.80	✓
16 Rear Tail Lamp Clipse <i>11</i>	5.50	2 PCS	11.00	X
17 Rear Fender Inner Side Garnish <i>De/1011645.10425</i>	816.90	1 PCS	1,633.80	✓
18 Rear Floor Panel <i>n</i>	659.60	1 PC	659.60	X
19 Rear Compartment Top Cover Board <i>no/mup</i>	581.60	1 PC	581.60	✓
20 Rear Compartment Top Cover Board Support <i>11</i>	281.60	1 PC	281.60	X
21 Rear End Panel <i>inner lower</i> <i>Body</i>	198.20	1 PC	198.20	✓
22 Rear End Panel Outer <i>Body</i>	555.90	1 PC	555.90	✓
23 Rear End Panel Top Garnish <i>11</i>	255.60	1 PC	255.60	✓

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
 TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg
 GST:200712509E RCB NO:201004495R

M/S : FWD SINGAPORE PTE LTD
 6 TEMASEK BOULEVARD
 #18-01 SUNTEC TOWER FOUR
 SINGAPORE 038986
 TEL: 6727 5721
 ATTN: Motor Claim Department
 Your Ref No: SLZ2534J
 Claim Type: Third Party
 Accident Date: 15/07/2019
 TP Veh Reg No: SMG4352S

Estimate No: EST0000959
 Date: 17 Jul 2019
 Policy No: 5100439320-01
 Veh Reg No: SLZ2534J
 Make/Model: TOYOTA WISH 1.8
 Chassis No: JTDGG20W70J008701
 Engine No: 2ZR0A50042
 Reg. Date: 27/04/2018

Estimate Repair Cost for Vehicle No :SLZ2534J

PAGE:2/2

Description	U/Price	Quantity	Price S\$	Amount S\$
24 Rear Bumper <i>Dis</i>	655.90	1 PC	655.90	
25 Rear Bumper Side Retainer <i>11</i>	85.90	2 PCS	171.80	
26 Rear Bumper Bracket <i>11</i>	95.60	2 PCS	191.20	
27 Rear Bumper Lower Clip <i>11</i>	5.50	4 PCS	22.00	
28 Rear Smart Sensor <i>11</i>	156.20	1 PC	156.20	
29 Rear Bumper Dust Cover <i>11</i>	98.20	2 PCS	196.40	
			11,854.90	
	Less 25%		2,963.73	8,891.20
Special Net				
30 Rear Number Plate <i>bent</i>	50.00	1 PC	50.00	
31 Rear Bumper Sensor <i>short</i>	300.00	1 PC	300.00	
			350.00	350.00
Labour				
32 Panel Beating	1,800.00	1	1,800.00	
33 Check Wiring	60.00	1	60.00	
34 Rust Proofing	60.00	1	60.00	
35 To Remove & Refit Rear Windscreen	160.00	1	160.00	
36 To Remove & Replace Bumper Sensor	80.00	1	80.00	
37 To Remove & Refit Rear Seat And Up-holstery	160.00	1	160.00	
38 Spray Painting	1,000.00	1	1,000.00	
			3,320.00	3,320.00
Total			S\$ 12,561.20	

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND FIVE HUNDRED SIXTY ONE AND CENTS TWENTY ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Focus Auto Pte Ltd
 No 1 Kaki Bukit Ave 6 #02-50
 Singapore 417883
 Tel: 66349695

AUTHORISED SIGNATURE

8757.52
 207
 7006