

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 2119T

DATE 16/7/2019 9:26

AAAT

MAKE :

LKK-kalvin.

Cheng

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 553.00
	Rear Bumper Reinforcement ?			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs ✓			\$ 22.00
	Rear Bumper Bracket ?		\$ 35.60	\$ 71.20
	Rear Bumper Sponge ?			\$ 103.50
	Rear Bumper Under Cover ✓			\$ 228.00
	Rear Bumper Reflector Lamp (LH) ✓			\$ 30.60
	SUB TOTAL			\$ 1,597.30
	LESS 20%			\$ 319.46
	DISCOUNTED TOTAL			\$ 1,277.84
	Rear Bumper Rubber Mat ✓			\$ 50.00 Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70 Nett
				\$ 185.70
	Labour Charge			
	Panel Beating			\$ 350.00 ²⁰⁰
	Spray Painting Charge			\$ 250.00 ²⁰⁰
	Wiring Charge			\$ 30.00 ¹⁰
	Remove/Refix Reverse Sensor			\$ 80.00 ³⁰
	<i>Towing Fee.</i>			\$ 60.00 ✓
	TOTAL LABOUR			\$ 710.00
	ESTIMATE TOTAL			\$ 2,173.54

Kalvin LKK
17/7/19 1010h
2 Pgs
PIP
Before Paint photo

LKK Air. Some of parts hence notify
 to a Reparer of the following:
 • To resurvey before/after spray painting
 • To display (damaged parts) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No lifted modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Reparer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.