

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 AIG BUILDING, SINGAPORE 079120
 TEL: 64193000 FAX: 68357416
 ATTN: Motor Claim Department

Estimate No: EST1900220
Date: 16 Jul 2019
Veh Reg No: SKS7446X
Make/Model: TOYOTA VIOS J GRADE MT
Chasis No: MHFBT9F3X06030386
Reg. Date: 04/05/2015
Your Ref No: SGZ6800Z

Claim Type: Third Party
Accident Date: 12/07/2019
TP Veh Reg No: SGZ6800Z

Khanchha

Estimate Repair Cost to Vehicle No :SKS7446X

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
List Price			
1	1 PC REAR BUMPER <i>behnd.</i>	482.70	—
2	1 PC REAR BUMPER REINFORCEMENT <i>Best</i>	316.70	—
3	2 PCS REAR BUMPER SIDE RETAINERS <i>neu</i>	226.80	—
4	2 PCS REAR BUMPER SMALL RETAINERS <i>neu</i>	43.60	X.
5	1 PC REAR BUMPER REFLECTOR RH <i>behnd</i>	179.80	—
6	1 PC REAR PANEL <i>Revis</i>	620.10	X
7	1 PC REAR PANEL TRIM <i>behnd</i>	232.00	—
8	1 PC TAIL LAMP - RH <i>behnd</i>	346.50	—
9	1 PC TAIL LAMP - LH <i>neu</i>	346.50	X.
10	1 PC BOOT LID LOCK <i>neu</i>	95.90	X
11	1 PC BOOT LID LOGO <i>neu</i>	58.80	—
12	1 PC BOOT LID "VIOS" EMBLEM <i>neu</i>	43.60	—
13	1 PC BOOT LID RUBBER <i>neu cut</i>	166.40	—
		3,159.40	
	Less 25%	789.85	2,369.58
Special Net			
14	2 PCS "L" PLATE BRACKET <i>neu</i>	70.00	50
15	1 PC REAR BUMPER STICKER <i>neu</i>	195.00	—
16	1 SET REAR BUMPER CLIPS <i>neu</i>	48.00	30
17	1 SET REAR PANEL TRIM CLIPS <i>neu</i>	40.00	10.
18	1 PC BOOT LID 537 STICKER <i>neu</i>	35.00	—
		388.00	388.00
Labour			
19	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00	400
20	1 TO SPRAY PAINTING	1,000.00	600
21	1 TO SPRAY UNDERSEAL	100.00	X
22	1 TO CHECK WIRING	50.00	30.

2053.30
1539.97

320

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1900220
Date: 16 Jul 2019
Veh Reg No: SKS7446X
Make/Model: TOYOTA VIOS J GRADE MT
Chasis No: MHFBT9F3X06030386
Reg. Date: 04/05/2015
Your Ref No: SGZ6800Z

Claim Type: Third Party
Accident Date: 12/07/2019
TP Veh Reg No: SGZ6800Z

Estimate Repair Cost to Vehicle No :SKS7446X

Quantity	Description	List Price	Amount
23	1 TO REPLACE STICKERS	80.00 1080	50.00
		2.230.00	2.230.00
		Total	S\$ 4,987.58
		Add GST @ 7%	349.13
		Total Amount Payable	<u>S\$ 5,336.71</u>

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND THREE HUNDRED THIRTY SIX AND CENTS SEVENTY ONE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

For Kang Car Repairers Pte Ltd


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


AUTHORISED SIGNATURE

Adrian Lj
L/S 16/07/19.
04 days.
total 2939.97.
L/S 2350