



TAN CHONG INDUSTRIAL MACHINERY PTE LTD
23 JALAN BUROH
SINGAPORE 619479
TEL:6703 8755 FAX:62665862

From ALFRED LEE

Date

To MSIG INSURANCE (SINGAPORE) PTE LTD

Our ref

Attn MOTOR CLAIM DEPT

Tel

Fax

VEH NO : XE1548U

Model :

Chassis : JNCM1F1AXGU005597

Eng No :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1. The above vehicle was inspected by TCIM and append here under is the estimated repair cost :

Claim type: OWN DAMAGE

Description	Qty	Unit Price	Amount
LH BUMPER ASSY	1	\$ 497.28	NETT \$ 497.28 <i>bt</i>
BUMPER REINFORCEMENT	1	\$ 834.72	NETT \$ 834.72 <i>bt</i>
LH STEP BUMPER	1	\$ 65.00	NETT \$ 65.00 <i>mis</i>
LH BUMPER SIDE	1	\$ 48.50	NETT \$ 48.50 <i>mis</i>
LH HEADLAMP ASSY	1	\$ 1,392.64	NETT \$ 1,392.64 <i>ane</i>
LH FOG LAMP ASSY	1	\$ 252.19	NETT \$ 252.19 <i>ane</i>
LH SIGNAL LAMP ASSY	1	\$ 44.40	NETT \$ 44.40 <i>ane</i>
BUMPER GRILLE (LH INNER)	1	\$ 88.80	25% \$ 66.60 <i>m.v</i>
BUMPER GRILER (LH OUTER)	1	\$ 82.80	25% \$ 62.10 <i>aa</i>
LH CORNER PANEL	1	\$ 185.00	NETT \$ 185.00 <i>aa</i>
FRONT PANEL ASSY	1	\$ 820.51	NETT \$ 820.51 <i>bt</i>
UD EMBLEM	1	\$ 128.00	NETT \$ 128.00 <i>ne</i>
PANEL LOCK ASSY	1	\$ 195.55	25% \$ 146.66 <i>bt</i>
LH PANEL HINGE	1	\$ 39.96	NETT \$ 39.96 <i>ane</i>
PANEL GRILLE	1	\$ 452.88	NETT \$ 452.88 <i>per Cons</i>
LOWER GRILLE	1	\$ 399.60	NETT \$ 399.60 <i>mi</i>
LH AIR BELLOW ASSY	1	\$ 408.48	NETT \$ 408.48 <i>elo</i>
AIR FITTING JOINT	1	\$ 25.66	NETT \$ 25.66 <i>dis</i>
LH CABIN ABSORBER	1	\$ 108.34	NETT \$ 108.34 <i>bt</i>
AIRCON UNI PIPE	1	\$ 245.00	25% \$ 183.75 <i>del</i>
AIRCON GAS AND OIL	1	\$ 60.00	NETT \$ 60.00 <i>res</i>
WINDSCREEN WASHER TANK	1	\$ 195.36	NETT \$ 195.36 <i>de</i>

Estimated parts cost \$ 6,417.63

Labour cost

To putty/primer application and spray painting including touch-up affected areas with polyurethane paint.

\$ 550.00 *400*

TO REPLACE RH DOOR ASSY.
TO PANEL BEAT AND PUTTY FOR RH SIDE PANEL.
TO REMOVE CABIN UPHOSTER TO FACILIATE PANEL BEATING OF REAR PANEL ASSY.


\$ 2,880.00 *2400*
(6 DAYS)

Estimated labour cost \$ 3,430.00

EST. LABOUR & PARTS COST \$ 9,847.63

1. All prices quoted are subjected to 7% GST. The above quotation is based on initial visual inspection only.

Thank you and regards



ALFRED LEE
Marketing Executive
Service Department
alfred_lee@tanchong.com

DID : 6703 8755
HP: 97879034

Tan Chong 97495749
18/7/19 2315pm Not Authorise, Revert
8750 Ex: to be advise 7 days
sure lkkanto.com
Part by Part
Resurvey before paint