



**ASSESSMENT FOR REPAIR : JFM 39**

**YAMAHA NMAX**

**COE EXPIRY :**

Lump Sum / Part by Part

| <u>Qty</u> | <u>Description</u>             | <u>Repairer's Estimate</u> |
|------------|--------------------------------|----------------------------|
| 1          | Front fender / <i>cut</i>      | 60.00                      |
| 1          | Mole side cover 1 / <i>cut</i> | 40.00                      |
| 1          | Board Footrest / <i>cut</i>    | 30.00                      |
| 1          | Side Cover / <i>cut</i>        | 40.00                      |
| 1          | Body Cowling = ?               | 60.00                      |
| 1          | Panel ?                        | 32.00                      |
| 1          | Mole side Cover 2 / <i>cut</i> | 40.00                      |
|            |                                | <u>302.00</u>              |

Special Nett Items

0.00

Total Parts 302.00

Labour Charges

|   |                                   |                          |
|---|-----------------------------------|--------------------------|
| 1 | Towing                            | 0.00                     |
| 2 |                                   | 0.00                     |
| 3 |                                   | 0.00                     |
| 4 | Workmanship to renew damage parts | 200.00                   |
|   |                                   | <u>200.00</u> <i>100</i> |

Total Parts & Labours Concluded 502.00

*1-2 Days.*

*Lumpsum repair.*

*After repair photos.*

*GnoRiang - 8288 0282*

*17/7/19*

SANFU MOTOR PTE LTD

Company Reg No.: 2006124876

1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883

Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010

Email: sanfumotor0243@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: