

27/05/2017

ASS. REC. BY

REF C83/SPF/8015023/Gvd3-1

Special Instruction

Surveyor

GQ

ASSIGNMENT (Office)

From (Person)

Hafizul Farhan

of

SPF

Date/Time

17/07/2019

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

GU 4394T

Insured

GZ 3371P

at Workshop in/s

N-51 Automotive

Tel

68420051

of

2 Kelki Bldg Ave 2 #01-17118

Policy No

Claim No

AEMD 1105 / 009 / 2018 / 098

Sum Insured

Excess

Make of Veh

D.C.A

14/08/2018

(Client's Record)

CA / REV / REP / REV 24 HRS

lup

H.O.D. Endorsement

Date/Time

3:31pm @ 17/08/18

Person Contacted

Melody

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

GU 4394T - NAI NC / 80 / 4500 / 13

D.C.A 14/08/18

GZ 3371P - NAI NC / 80 / 4500 / 13

D.C.A 14/08/18

Submit LIS \$1700 @ 3 days

1/8/19 Submit (LS) \$1150, 3 Days.

upper range \$1200 - \$1700


 31/7/2019

Do Not Finalise

RECEIVED 01 AUG 2019

PAS
Ked. RGR: SFE B 8100 J ✓
17 Nov 2001

From: Date: Estimated Cost: C
OD / TP / WS / TP RES / OD RES / EVA / INV / MY
To Inspect Vehicle No: N-51
at Workshop no: of
Insured: Policy No: Claims No: Sum Insured: Excess: (Client's Record): Make of Veh:

(Policy Condition): Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$21K
IDAC Accident Rpt.: Consistent? Yes or No
GIA / PR Seen: Consistent? Yes or No
Est. Repairs: 3 days Res: Yes or No
Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS
Date: Person Contacted: Vehicle: IN / OUT

Date / Time: Action / Instruction: \$2000 - \$3000 1700

644394T
Type: Motor / Motorcycle / Bus / Van / Light Truck / Prime Mover / Taxi / Other
Track / Trailer: Make: Nissan Cabstar 3153
Colour: Silver VIN: 287365
Tyre: Insured / Std / NI / NA
Engine: JN15F4F23B0843811
Gear: Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt / or
Brake: In order / Jammed / Leaked / Burnt / or
Misc: Air / SRim / STD Air / or

Tyre Size: F: 195 R15
R: 155 R12
BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO MAXXIS

Front: Rear: R/Bal: 5 mm L/Bal: 5 mm
D.O.A: 17-08-18 5:45pm
Survey held at: w/s

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop / or 24 w/s
The U/C / Chassis frame / Body Structure affected due to collision

Date/Time: File Pass to: ☐ : Prelim. Report
typist ☒ : Final Report
Date/Time: File Return to: Report Format: 7P
Lump Sum / BL: 1700

Days Of Repair: 3
Resurvey No. of Trip: 2
Survey Fee: 280
Transportable: Add Fee: Site Insp: \$ Ind: \$ Fuel: \$ Tools: \$

Nivitha (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Wednesday, 17 July 2019 10:24 AM
To: Admin-D (LKKAuto); assignments; Veron Chen (LKKAuto)
Cc: Frankie THAY (SPF)
Subject: Re-Survey for GU4394T
Attachments: LKK Survey 2018-98.pdf; GU4391T Surveyor 2018-98.pdf

Our ref: AEMD/105/009/2018/098

Kindly re-survey GU4394T.

The third party cost of repair is \$3,745.00 (pls refer to attached).

Thank you.

Best Regards,

Hafizul Farhan Bin Rahmat

AEMD / PLD

Singapore Police Force

DID: (65) 6478 4840 / FAX: (65) 6478 4850



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|------------------|
| Date Of Report | 15/08/2018 12:39 |
| Date Of Accident | 14/08/2018 14:00 |
| Exact Location Of Accident | GANGSA ROAD |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|------------------------|
| Vehicle Registration Number | GU4394T |
| Insured/Policyholder | |
| Name Of Registered Owner | BEST QUALITY FURNITURE |
| Co Reg No | 46858100J |
| Email Address | NOEMAIL |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-92768799 |

Vehicle Particulars

| | |
|------------------------------------------------------------------------------|--------------------|
| Manufacturer | NISSAN |
| Model | CABSTAR |
| Exact Purpose for which vehicle was being used at time of accident | PARKED VEH |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | COMMERCIAL VEHICLE |

Insurance Company

| | |
|---------------------------|----------------------------------------|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | THIRD PARTY |
| Fleet Policy | NO |
| Policy Number | 5098056275 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | LEE CHIN POH |
| NRIC No | S1395457G |
| Date Of Birth | 23/12/1959 |
| Occupation | INDOOR |
| Date Of Driving Pass | 07/11/1977 |
| Driving Experience | 40 YEARS AND 9 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-92768799 |
| Fax Number | |
| Contact Number | |
| EMAIL Address | NOEMAIL |

Address BLK 117 PENDING ROAD
#03-228
Postcode 670117

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLIDED INTO PARKED VEHICLE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name BUKIT PANJANG

Police Station Address ROAD: 1 SEGAR ROAD . POSTCODE: 677738 . COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-8929999 - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GZ3371P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

1. Please report correctly the details of the accident to us (2 up to 10 work days).
2. The form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any false or misleading information withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this form by insurance company is a private agreement between the policyholder and the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the UK Accident Management Association (UKAMA) to the relevant authorities. The UKAMA is a member of the Association of Singapore (AIA) for assisting and the copies of this report will form part of the evidence available for investigation by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the information contained in the report being made available to the relevant authorities.
8. Consent under the Personal Data Protection Act (PDPA)

- _____
Policyholder's Signature
Date & Time

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS PER POLICE REPORT

VEHICLE A
 1/2 X 1/2 = 1/2
 1/2 X 1/2 = 1/2

VEHICLE A - C.O. 12345 (1/2 X 1/2 = 1/2)

VEHICLE B - C.O. 12345 (1/2 X 1/2 = 1/2)

DECLARATION

STATE OF THE ACCIDENT



13/08/18

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

BEST QUALITY FURNITURE
25 KISMIS AVE
SINGAPORE 598202

Contact : 92768799

TAX INVOICE

Date : 13/06/2019
Date in : 15/08/2018
Vehicle Num. : GU4394T
Make/Model : NISSAN CABSTAR-2001
Chassis/Eng# : JN1SF4F23Z0843811/QD32147119
Accident Date : 14/08/2018
Claim No : CLM14712
Reference : AUG-43/2018
Policy No. : 5098056275 (16/03/2019)

LUMPSUM REPAIR BILL
AS PER SURVEYOR REPORT
REF : 0293-19-N51 DATED 03/06/2019
BY PAR AUTOMOTIVE CONSULTANCY

Amount S\$
3,500.00

| | | |
|-----------------------|-----------|----------|
| E. & O.E. | Sub S\$: | 3,500.00 |
| Add GST (7 %) S\$: | | 245.00 |
| Total Amount S\$: | | 3,745.00 |



for N-51 AUTOMOTIVE PTE LTD



bizSAFE₃

PAR Automotive Consultancy

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131

Regn No: 52986974L

Report No: 0293-19-N51

03 June 2019

ACCIDENT VEHICLE SURVEY REPORT

Best Quality Furniture
25 Kismis Avenue
Singapore 598202

VEHICLE INFORMATION:

| | | | |
|------------------|-------------------------------------------------------------------------------------------------|--------------------------------|------------|
| Vehicle Reg No.: | GU4394T | Odometer: | 287365km |
| Make & Model: | Nissan Cabstar | Colour: | Silver |
| Chassis number: | JN1SF4F23Z0843811 | Date of accident: | 14/08/2018 |
| Year of Regn.: | 17/03/2001 | Date inspected: | 18/08/2018 |
| Repairer at: | N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921 | Date inspected (After Repair): | 24/08/2018 |

STATIC CHECKS, where applicable:

| | |
|---------------------|-------------|
| Steering : | serviceable |
| Footbrake : | serviceable |
| Handbrake : | serviceable |
| Paintwork : | Good |
| General condition : | Good |

TIRE CONDITION:

| | | | |
|----------|------------------|------------------|-------------|
| | <u>LH / Make</u> | <u>RH / Make</u> | <u>Size</u> |
| Front: | 3mm/Condor | 3mm/Condor | 195R15 |
| Rear: x2 | 4mm/Maxmiller | 4mm/Maxmiller | 155R12 |

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the front LH portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

| Description of part | Qty | Condition | Repairer's estimate | Our adjustment |
|-----------------------------------|-----|-----------|---------------------|---------------------------|
| FRONT BUMPER | 1 | squashed | 675.50 | 675.50 ✓ |
| FRONT BUMPER INNER BRACKET | 1 | bent | 47.50 | 47.50 X <i>NA</i> |
| FRONT BUMPER LH FOGLAMP | 1 | reuse | 197.50 | 0.00 <i>NA</i> |
| FRONT CORNER PANEL LH | 1 | distorted | 412.40 | 412.40 X <i>NA</i> |
| FRONT GRILLE | 1 | fractured | 376.60 | 376.60 X <i>NA</i> |
| FRONT GRILLE 'LOGO' EMBLEM | 1 | necessary | 45.60 | 45.60 X <i>NA</i> |
| FRONT LH HEADLAMP | 1 | fractured | 482.00 | 482.00 X <i>NA</i> |
| FRONT LH STEP GARNISH | 1 | fractured | 139.40 | 139.40 ✓ |
| FRONT SIDE LAMP LH | 1 | fractured | 195.60 | 195.60 <i>156.8</i> |
| Subtotal before discount | | | S\$ 2,572.10 | S\$ 2,374.60 <i>971.7</i> |
| Percentage discount 10% and 10% | | | S\$ 257.21 | S\$ 237.46 <i>874.53</i> |
| Sub-total 1 | | | S\$ 2,314.89 | S\$ 2,137.14 |
| FRONT BUMPER CLIPS - SET | 1 | necessary | 100.00 | X 100.00 <i>NA</i> |
| FRONT CORNER PANEL LH CLIPS - SET | 1 | necessary | 40.00 | X 40.00 <i>NA</i> |
| FRONT GRILLE CLIPS - SET | 1 | necessary | 50.00 | X 50.00 <i>NA</i> |
| FRONT LH DOOR COMPANY STICKER | 1 | necessary | 25.00 | ✓ 25.00 |
| FRONT LH STEP GARNISH CLIPS - SET | 1 | necessary | 40.00 | X 40.00 <i>NA</i> |
| FRONT SIDE LAMP LH CLIPS - SET | 1 | necessary | 30.00 | X 30.00 <i>NA</i> |
| Subtotal before discount | | | S\$ 285.00 | S\$ 285.00 |
| Sub-total 2 | | | S\$ 285.00 | S\$ 285.00 |
| Parts-total | | | S\$ 2,599.89 | S\$ 2,422.14 |

LABOUR

| | | |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-------------------|
| To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR) | 120.00 | 50.00 <i>30</i> |
| To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident. | 1,000.00 | 880.00 <i>300</i> |
| To provide labour, workmanship to change the above damaged bodyparts, repair, reconstruct and re-align body structure, body alignments and damaged consistent to the accident. | 800.00 | 750.00 <i>200</i> |
| To apply anti-rust chemical on repaired and replaced panel. | 120.00 | X 60.00 <i>NA</i> |
| Labour Total | | S\$ 2,040.00 |
| Parts & Labour Total | | S\$ 4,639.89 |
| | | S\$ 1,740.00 |
| | | S\$ 4,162.14 |

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 3,500.00 and the recommended number of working days for the repairs is within 7 day(s).



B J Loi (I Eng., MIMI, AIRTE)
Automotive Appraiser

1429.53

20% 1150



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS3/SPF18015023/Gvd3s2-1

ACCIDENT CLAIM SECTION (SPORE POLICE
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMYSINGAPORE 298333

Date : 01-08-2019



ATTN: HAFIZUL FARHAN

Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|-----------------------|----------------|------------|
| Insured Veh. | GZ 3371P | Veh. Inspected | GU 4394T |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | AEMD/105/009/2018/098 | Excess (\$) | 0.00 |
| Assign From | HAFIZUL FARHAN | Assign Date | 17/07/2019 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|----------|
| Make & Model | NISSAN CABSTAR | c.c | 3153 |
| Engine No. | HIDDEN | Year of Reg. | 2001 |
| Chassis No. | JN1SF4F23Z0843811 | Colour | SILVER |
| Odometer | 287365 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|---------|--------|---------|
| R/H Front Tyre | 195 R15 | MAXXIS | 5 mm |
| L/H Front Tyre | 195 R15 | MAXXIS | 5 mm |
| R/H Rear Tyre | 155 R12 | MAXXIS | 5 mm |
| L/H Rear Tyre | 155 R12 | MAXXIS | 5 mm |

4. Description of Damages

| |
|---------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS. |
|---------------------------------------------------------------------------------|

5. General Information

| | | | |
|----------------|-------------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date | 14/08/2018 | Inspection Date | 17/08/2018 |
| Survey held at | N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921 | | |

5a. Remarks

| |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|----------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GU 4394T

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | FRONT BUMPER | SQUASHED | 675.50 | 675.50 |
| 1 | FRONT BUMPER INNER BRACKET | NOT NECESSARY | 47.50 | - |
| 1 | FRONT BUMPER LH FOGLAMP | NOT NECESSARY | 197.50 | - |
| 1 | FRONT CORNER PANEL LH | NOT NECESSARY | 412.40 | - |
| 1 | FRONT GRILLE | NOT NECESSARY | 376.60 | - |
| 1 | FRONT GRILLE 'LOGO' EMBLEM | NOT NECESSARY | 45.60 | - |
| 1 | FRONT LH HEADLAMP | NOT NECESSARY | 482.00 | - |
| 1 | FRONT LH STEP GARNISH | FRACTURED | 139.40 | 139.40 |
| 1 | FRONT SIDE LAMP LH | FRACTURED | 195.60 | 156.80 |
| | LESS 10% DISCOUNT | | -257.21 | -97.17 |
| | | | 2,314.89 | 874.53 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | SET FRONT BUMPER CLIPS (SN) | NOT NECESSARY | 100.00 | - |
| 1 | SET FRONT CORNER PANEL LH CLIPS (SN) | NOT NECESSARY | 40.00 | - |
| 1 | SET FRONT GRILLE CLIPS (SN) | NOT NECESSARY | 50.00 | - |
| 1 | FRONT LH DOOR COMPANY STICKER (SN) | NECESSARY | 25.00 | 25.00 |
| 1 | SET FRONT LH STEP GARNISH CLIPS (SN) | NOT NECESSARY | 40.00 | - |
| 1 | SET FRONT SIDE LAMP LH CLIPS (SN) | NOT NECESSARY | 30.00 | - |
| | | | 285.00 | 25.00 |
| <u>LABOUR</u> | | | | |
| | TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING. (TO FR) | | 120.00 | 30.00 |
| | TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT. | | 1,000.00 | 300.00 |
| | TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. | | 800.00 | 200.00 |
| | TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL. | NOT NECESSARY | 120.00 | - |
| | | | 2,040.00 | 530.00 |
| GRAND TOTAL | | | 4,639.89 | 1,429.53 |



| | | | |
|-------------------------------------------------------------------------|--|--|----------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 1,700.00 |
|-------------------------------------------------------------------------|--|--|----------|

Report Ref No. CS3/SPF18015023/Gvd3s2-1

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,200.00 - \$1,700.00

RECOMMENDED REPAIR DAYS : 3

WEEKENDS : 1

TOTAL DAYS : 4

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.