

INS. CASE OWNER:

CC 6, TP 190 12692, Kpa39

LKK:
IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

17/7/19

Date / Time:

17/7/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :S\$

D.O.A: 17/7/19

Place of Accident :

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

S6E 41562



INSRS:

WSP:

Tel :

Liability :

RMKS:

CHMK



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

S6E 41562 - C13 / 11/12/2019 / 11/12/2019 / 11/12/2019

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$

(days)

Reduction:

%

Email ☐Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with

Email ☐Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐LOU only ☐

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

357-00

Total: S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASS. REC. BY:

REF: TP 1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 817k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 09 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 3/8/11 Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGE 41568 Yr Regn: 03, 06
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or _____
Make: Toy Wish c.c. 1794

Colour: M. Dark Blue A/C: Insured / Std / NI / NA

Sp. Reading: 354732 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZNE 10. 0292689

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / R/Rim / STD A/Rim or

Tyre Size: F: _____

R: 205/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Finzer

Front

R/Bal: 7 mm

L/Bal: 7 mm

D.O.A. 12/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

11 PM 849502 Confirmed

(Recd \$ 1651.27/257.)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / L.B.I: (\$

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS \$

Fuel:

Others:

TOTAL

145.00
50 + 50
30.00
80.00
385.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/07/2019 09:45
Date Of Accident	12/07/2019 18:30
Exact Location Of Accident	SENGKANG EAST DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGE4156Z
Insured/Policyholder	
Name Of Registered Owner	STEVE YEE YEW KONG
NRIC No	S1790116H
Email Address	STEVEY2E@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90107387
Alternative Phone No	OTHERS-90107387

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC19B00014900
Cover Note Number	

Driver

Name of Driver	STEVE YEE YEW KONG
NRIC No	S1790116H
Date Of Birth	04/07/1967
Occupation	INDOOR
Date Of Driving Pass	25/01/1992
Driving Experience	27 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90107387
Fax Number	
Contact Number	OTHERS-90107387
Email Address	STEVEY2E@GMAIL.COM

Name NAH CHOON HWA
Approximate Age
Injuries Sustain
Injured person in which vehicle? FBD40P
Were seat belts worn?
Was this injured conveyed to hospital by
ambulance? NO
Address
Postcode

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: 

Date & Time:

13 JUL 2019

Driver's Signature:

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:


Jenny Lim
S8927273H



**SINGAPORE
POLICE FORCE**



T/20190712/2164

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

2 of 3

Report No. T/20190712/2164

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	Nah Choon Hwa	ID No.	S7338783C
Related Vehicle	FBD40P (Motorcycle)	Contact No.	90274474
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	STEVE YEE YEW KONG	ID No.	S1790116H
Related Vehicle	SGE4156Z (Car)	Contact No.	96107387
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 12/07/2019 at about 1830hrs, I drove my car vehicle registration number SGE4156Z before the junction of Sengkang East Drive and Sengkang East Way, near to the bus stop of B67511. One car (unknown plate number) which was driving in front of my car suddenly braked and I managed to brake to avoid collision. One rider riding his motorcycle FBD40P then hit onto my car rear boot.

He then informed that he believed he had sprained his wrist and suffered pain on his hand. No police or ambulance came to scene. I have no in-car camera footage and I have a witness who has in-car camera. He had provided his details to me namely Sandy, contact no: 96288380.

Both of us agreed for insurance claim. Hence, I am here to lodge this traffic accident report as the rider claimed he was injured.

Scanned by CamScanner

REPUBLIC OF SINGAPORE DRIVING LICENCE

Identification No. **S1790116H**

Name: **STEVE YEE YEW KONG**

Age from: **04 Jul 1967**

Valid from: **07 Apr 2008**

1000157698H




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S1790116H**

Name: **STEVE YEE YEW KONG**

余耀光

Race: **CHINESE**

Date of Birth: **04-07-1967**

Sex: **M**

Country of Birth: **SINGAPORE**




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3: **Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms**

PASS DATE: **25 Jan 1992**

Licence No. **S1790116H**

P 426A



200

200

NRIC No. **S1790116H**

Speed Group: **D+**

Date of issue: **05-10-1996**

APT BLK 237 COMPASSVALE WALK #16-536

SINGAPORE 540237

NRIC No: **S1 790116H**

Date: **02-09-1998**

No: **2655454**




来發 (明記) 摩哆有限公司, LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267

GST No: M2-0128609-3

UEN: 199407592C

ESTIMATE

EST No EST0022739
Steve Yee Yew Kong

Page 1 of 3
Your ref TP-FBD 40P DAI
Job No 70691
Our ref 19.07.25
Payment
Date 16/7/2019

Attn

Vehicle No SGE 4156Z
Vehicle Model Toyota Wish
Accident on 12/7/2019

Not Authorised
1 Day 8?
Recovery After Party 8 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts					
1.00	Pc	Rear tailgate	1,210.40	25.00	<i>Rt</i> 907.80
1.00	Pc	Rear tailgate lock	443.50	25.00	<i>Ln</i> 332.63
1.00	Pc	Rear tailgate chrome moulding	239.10	25.00	<i>cm</i> 179.33
1.00	Pc	Rear tailgate weatherstrip	<i>nd/dit</i> 304.00	25.00	<i>cm</i> 228.00
1.00	Pc	Rear bumper	580.80	25.00	<i>Ru</i> 435.60
1.00	Pc	Rear bumper side retainer RH	57.05	25.00	<i>cm</i> 42.79
1.00	Pc	Rear bumper screw grommet LH (round)	3.50	25.00	<i>mi</i> 2.63
1.00	Pc	Rear bumper screw grommet RH (round)	3.50	25.00	<i>mi</i> 2.63
4.00	Pcs	Rear bumper lower clips	<i>14</i> 3.50	25.00	<i>ru</i> 10.50
1.00	Pc	Rear logo emblem	50.20	25.00	<i>ru</i> 37.65
1.00	Pc	Rear end panel	441.20	25.00	<i>Rt</i> 330.90
1.00	Pc	Rear end inner panel	132.90	25.00	<i>Rt</i> 99.68
1.00	Pc	Rear end panel top cover	232.96	25.00	<i>ru</i> 174.72
1.00	Pc	Rear tail lamp LH	<i>headlight mi</i> 472.60	25.00	354.45
1.00	Pc	Rear tail lamp RH	472.60	25.00	354.45
1.00	Pc	Rear windscreen moulding	92.70	25.00	<i>ru</i> 69.53
1.00	Pc	Rear spare tyre holder	297.28	25.00	<i>dit</i> 222.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST No: EST0022739
Steve Yee Yew Kong

Page: 2 of 3
Your ref: TP-FBD 40P DAI
Job No: 70691
Our ref: 19.07.25
Payment:
Date: 16/7/2019

Attn:

Vehicle No: SGE 4156Z
Vehicle Model: Toyota Wish
Accident on: 12/7/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		Special nett item			
			35.00		<i>Net</i> 35.00 ✓
1.00	Pc	Rear number plate	200.00		<i>cm</i> 200.00 ✓
1.00	Set	Rear reversing sensor with installation			
		Labour & Misc:			<i>1200</i>
			140.00		140.00
1.00		To remove and refix rear windscreen			
			40.00		40.00 ✓
1.00		To supply sealant			
			120.00		120.00 <i>200</i>
1.00		To replace rear floor insulation			
			80.00		80.00 ✓
1.00		Tuff coat			
			50.00		50.00 ✓
1.00		To transfer rear tailgate top spoiler			
			150.00		150.00 <i>1200</i>
1.00		To dismantle + refix rear fender side trim, rear passenger seat, etc			

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAIC Deluxe oven heater for re-spraying all motor vehicles."

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0116H

Vehicle Details

Vehicle No.: SGE4156Z
Vehicle to be Exported: Yes
Intended Deregistration Date: 13 Jul 2019
Vehicle Make: TOYOTA
Vehicle Model: WISH 1.8 A
Primary Colour: Black
Manufacturing Year: 2006
Engine No.: 1ZZ2501148
Chassis No.: ZNE100292689
Maximum Power Output: 97.0 kW (130 bhp)
Open Market Value: \$20,640.00
Original Registration Date: 16 Mar 2006
First Registration Date: 16 Mar 2006
Transfer Count: 0
Actual ARF Paid: \$22,704.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 15 Mar 2021
COE Category: B - Car (1601cc & above)
COE Period(Years): 5
PQP Paid: \$25,466.00
COE Rebate Amount: \$8,516.00
Total Rebate Amount: \$8,516.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Jul 2019

OK



Thank you

Lai Mei Ling Deborah has successfully logged out.

Your last login date and time was 13 Jul 2019, 09:49:51.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type
1	Vehicle	FBD40P	-	18.32 Insurance Enquiry (GIRO Payr
• Log Date/Time 13 Jul 2019 / 09:50:18				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LAI HUAT (MENG KEE) MOTOR PL			Ref : CC6/TP19012692/Kpa3q2	
160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722 ON BEHALF OF STEVE YEE YEW KONG			Date : 09-09-2019	
			Code : TP081	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SGE 4156Z	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		17/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH (A)	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	ZNE100292689	Colour	METALLIC BLACK	
Odometer	354732	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R15	FIRENZA	7 mm	
L/H Front Tyre	205/65 R15	FIRENZA	7 mm	
R/H Rear Tyre	205/65 R15	FIRENZA	8 mm	
L/H Rear Tyre	205/65 R15	FIRENZA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/07/2019	Inspection Date	17/07/2019	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGE 4156Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	BENT	1,210.40	1,210.40
1	REAR TAILGATE LOCK	JAMMED	443.50	443.50
1	REAR TAILGATE CHROME MOULDING	CRACKED	239.10	239.10
1	REAR BUMPER	BUCKLED	580.80	580.80
1	REAR BUMPER SIDE RETAINER RH	CRACKED	57.05	57.05
1	REAR BUMPER SCREW GROMMET LH (ROUND)	MISSING	3.50	3.50
1	REAR BUMPER SCREW GROMMET RH (ROUND)	MISSING	3.50	3.50
4	REAR BUMPER LOWER CLIPS @\$3.50	NECESSARY	14.00	14.00
1	REAR LOGO EMBLEM	NECESSARY	50.20	50.20
1	REAR END PANEL	BENT	441.20	441.20
1	REAR END INNER PANEL	BENT	132.90	132.90
1	REAR END PANEL TOP COVER	DENTED	232.96	232.96
1	REAR TAIL LAMP LH	MISSING	472.60	472.60
1	REAR TAIL LAMP RH	MISSING	472.60	472.60
1	REAR WINDSCREEN MOULDING	NECESSARY	92.70	92.70
1	REAR SPARE TYRE HOLDER	DISTORTED	297.28	297.28
	LESS 25% DISCOUNT		-1,186.07	-1,186.07
			3,558.22	3,558.22
1	REAR TAILGATE WEATHERSTRIP (50%) (SN)	DENTED / DISTORTED	304.00	152.00
	LESS 25% DISCOUNT		-76.00	-
			228.00	152.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	DENTED	35.00	35.00
1	SET REAR REVERSING SENSOR WITH INSTALLATION (SN)	CRACKED	200.00	200.00
			235.00	235.00
<u>LABOUR</u>				
	TO REMOVE AND REFIX REAR WINDSCREEN.		140.00	120.00
	TO SUPPLY SEALANT.		40.00	40.00
	TO REPLACE REAR FLOOR INSULATION.		120.00	80.00
	TUFF COAT.		80.00	80.00

Report Ref No. CC6/TP19012692/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER REAR TAILGATE TOP SPOILER.		50.00	50.00
	TO DISMANTLE+REFIX REAR FENDER SIDE TRIM ,REAR PASSENGER SEAT ,ETC.		150.00	120.00
	TO STRAIGHTEN REAR BODY INCLUDING CUTTING AND WELDING ,TO KNOCK DENTS ON REAR FLOOR PANEL, REAR FLOOR UNDER FRAME AND RENEW OF PARTS.		1,100.00	1,000.00
	TO SPRAY PAINT.		900.00	800.00
			2,580.00	2,290.00
GRAND TOTAL			6,601.22	6,235.22
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,950.00

Report Ref No. CC6/TP19012692/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.