

INS. CA. COMP. NO.

CC: 3 / ASM 15012693 / Kpa352

TAY.
IDAS:

127632

Surveyor:

Kenneth

DOI:

17/7/19

Date / Time:

17/7/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SBY 2088D

Name of Insured:

cho Chew Kenk

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A: 16/7/19

Is driver the owner?

(- YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SHB 99085



INSRS:

WSP: Trans-cab

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SHB 99085: CC3/AXA13019901/KR63C3; D.O.A: 21/10/15
SBY 2088D: 06/AYA13005391/UR634; D.O.A: 23/3/13

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

(days) Reduction:

%

Confirm by:

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

Email ☐ Call ☐

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

Loss of Use (LOU):

S\$

Loss of Income (LOI):

S\$

LOR only ☐ LOU only ☐

S\$

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

S\$

Payee 2: (Strike if N.A.)

S\$

Payee 3: (Strike if N.A.)

S\$

Name 1:

Name 2:

Name 3:

Email ☐ Call ☐

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT
11/7/19

(e.g. Tow/ Independent)

Global Sum S\$:

Confirm with:

Name 1:

Name 2:

Name 3:

Name 3:

Name 3:

Name 3:

ASS. REC. BY:

REF:

ALA/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 9908S

Yr Regn:

08, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

548170

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VI-1A9615AUC 273467

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal.

9

mm

R/Bal.

6

mm

L/Bal.

9

mm

L/Bal.

6

mm

D.O.A.

16/7/19

D.O.I.

17/7/19

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S 151

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

US \$ 74W Credit \$ 52732.78 / 887.1

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 99085**AAD1907-157***Not Authorised*
1/1/2013

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

17 JUL 2013

Third Party Insurer :

Date of Registration:

SHB 99085

VF1ABL15AUC273467

RENAULT

LATITUDE

16.7.19

AXA

30/8/2013

PART**LIST**

1	DOOR PANEL REAR LH	\$	Bu	2,844.66	✓
1	DOOR GUIDE REAR LH	\$	Sn	176.82	
1	DOOR HINGE UPPER LH	\$	N	274.50	
1	DOOR HINGE LOWER LH	\$	N	300.55	
1	DOOR CHECK REAR LH/RH L70Y	\$	Sn	203.06	
1	DOOR LOCK REAR LH	\$	N	908.75	
1	DOOR FINISHER REAR LH	\$	Sn	423.10	
1	DOOR WHEATHESTRIIP REAR LH	\$	Sn	410.66	
1	DOOR SEAL REAR LH	\$	Sn	162.02	X
1	DOOR CASING REAR LH	\$	Sn	1,509.06	
1	DOOR HANDLE OUTER REAR LH	\$	Sn	126.49	
1	DOOR HANDLE CAP REAR LH	\$	Sn	35.52	
1	DOOR HANDLE SEAL REAR LH	\$	Sn	7.89	
1	DOOR HANDLE COVER REAR LH	\$	Sn	13.22	
1	DOOR HANDLE MODULE REAR LH	\$	Sn	133.60	
1	DOOR REGULATOR REAR LH	\$	N	1,135.10	
1	DOOR REGULATOR MOTOR REAR LH	\$	N	893.75	
1	DOOR PANEL FRT LH	\$	Bu	2,844.66	✓
1	DOOR HINGE UPPER LH	\$	Bu	261.28	✓
1	DOOR HINGE LOWER LH	\$	Bu	300.55	✓
1	DOOR CHECK FRT LH	\$	Bu	194.77	✓
1	DOOR LOCK FRT LH	\$	Tu	908.75	✓
1	DOOR CATCH FRT LH	\$	N	131.23	X
1	DOOR HANDLE OUTER FRT LH	\$	Sn	477.76	X
1	DOOR HANDLE COVER FRT LH	\$	Sn	13.22	X
1	DOOR HANDLE MODULE FRT LH	\$	Sn	133.60	X
1	DOOR REGULATOR FRT LH	\$	Bu	505.19	✓
1	DOOR REGULATOR MOTOR FRT LH	\$	Tu	796.46	✓
1	DOOR REGULATOR GUIDE FRT LH	\$	Sn	120.97	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9908S**AAD1907-157**

1	DOOR WHEATHESTRIP FRONT LH	\$	S 410.66
1	DOOR MOULDING FRONT LH	\$	S 176.82
1	DOOR FINISHER INNER FRONT LH	\$	S 323.44
1	DOOR FINISHER FRONT LH	\$	S 423.10
1	DOOR CASING FRONT LH	\$	S 1,509.06
1	DOOR BLIND FRONT LH	\$	S 741.80
1	DOOR WATER SHIELD FRONT LH	\$	S 30.39
1	DOOR CASING CLIP	\$	S 12.63
1	DOOR CASING LIGHT L70Y	\$	S 48.74
1	DOOR BLIND FRONT LH	\$	S 741.80
1	DOOR SEAL FRONT LH	\$	S 162.02
1	DOOR GLASS RUNNER SEAL FRONT LH	\$	S 229.31
1	DOOR WAIST SEAL OUTER FRONT LH	\$	S 334.69
1	DOOR WAIST SEAL INNER FRONT LH	\$	S 115.64
1	ROCKER PANEL INNER GARNISH LH	\$	S 466.51
1	ROCKER PANEL INNER LH	\$	R 1,024.79
1	ROCKER PANEL OUTER LH	\$	R 1,184.99
1	ROCKER PANEL CENTER LH	\$	R 990.25
1	DOOR MIRROR ASSY LH	\$	S 1,483.40
1	DOOR HARNESS WIRE LH	\$	S 2,670.00
1	FENDER PANEL FRT LH	\$	R 783.83
1	WHEELARCH FRT LH	\$	S 278.84
1	FENDER BRACKET LOWER LH	\$	S 15.79
1	FENDER INSULATOR LH	\$	S 130.84
1	FENDER PANEL REAR LH	\$	R 3,299.13
1	FENDER PANEL INNER TRIM REAR LH	\$	S 671.45
1	WHEELARCH REAR LH	\$	S 543.47
1	TAILLAMP LH	\$	S 552.55
1	TAILLAMP PANEL LH	\$	R 986.70
1	BUMPER COVER REAR	\$	S 1,108.46
1	BUMPER LOWER REAR	\$	S 768.84
1	BUMPER BRACKET CTR REAR	\$	S 113.47
1	BUMPER BRACKET SIDE LH REAR	\$	S 135.97
1	BUMPER RETAINER LH REAR	\$	S 44.99
1	BUMPER REFLECTOR LH	\$	S 43.61
1	BUMPER BEAM REAR	\$	R 777.52
1	BUMPER BEAM BRACKET LH REAR	\$	S 225.95
1	FUEL FLAP	\$	S 343.57

X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 99085**AAD1907-157**

1	LOWER ARM LH L70Y	\$	SH	685.76	}	X
1	KNUCKLE ARM LH L70Y	\$	SH	846.98		
1	ABSORBER FRT LH L70Y	\$	SH	360.54		
1	DRIVESHAFT LH	\$	N	1,747.45		
1	STABILIZER BAR FRT	\$	SH	604.65		
1	BOOT REFLECTOR LAMP LH	\$	SH	493.35		
TOTAL		\$		44,890.95		
10%		\$		4,489.09		
		\$		40,401.85		

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	N	300.00	605N	}	X
1	FRONT DOOR STICKER 'Trans-Cab'	\$	N	80.00	605N		
1	FRONT DOOR STICKER 'Classic'	\$	N	80.00	155N		
1	DOOR CHECK BOLT	\$	N	22.69			
1	DOOR GUIDE SCREW	\$	N	10.85			
1	DOOR HINGE BOLT	\$	N	10.85			
1	DOOR HINGE NUT LH	\$	N	14.60			
1	DOOR CHECK BOLT	\$	N	22.69			
1	DOOR CHECK NUT	\$	N	3.75			
1	DOOR LOCK SCREW L70Y	\$	N	6.12			
1	DOOR CATCH SCREW L70Y	\$	N	10.06			
1SET	WHEELARCH CLIP FRT LH	\$	N	30.50			
1	FRONT LEFT TYRE	\$	SH	300.00			
1	FRONT LEFT TYRE RIM	\$	SH	380.00			
1	FRONT WINDSCREEN SEALANT	\$	N	253.80			
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	N	100.00			
1	FRONT WINDSCREEN MOULDING	\$	N	120.00			
1SET	PARKING AID	\$	SH	700.00			
1SET	REAR BUMPER CLIP	\$	N	66.00			
1SET	BUMPER BRACKET CTR CLIP	\$	N	33.00			
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	N	10.00			
1SET	BUMPER RETAINER CLIP LH RR	\$	N	20.00			
1SET	BUMPER LOWER REAR RIVET	\$	N	22.00			
1SET	BUMPER LOWER REAR CLIP	\$	N	66.00			
1	TAILLAMP CLIP LH	\$	N	5.00			
1	FENDER INNER TRIM CLIP LH	\$	N	28.00			
1SET	FENDER WHEELARCH REAR LH CLIP	\$	N	35.00			

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9908S**AAD1907-157**

1	REAR LEFT TYRE	\$	<i>P2</i> 300.00 X
1	REAR LEFT TYRE RIM	\$	<i>P2</i> 380.00 X

TOTAL	\$	3,410.93
--------------	-----------	-----------------

TOTAL PARTS	\$	43,812.78
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	<i>5001</i> 6,000.00
Putty and spray painting of the affected portion.	\$	6,000.00 <i>6601</i>
To check steering geometry and computer wheel alignment	\$	<i>22</i> 220.00 X
To transfer of front windscreen fittings and conduct water seepage test.	\$	<i>22</i> 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>22</i> 170.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>22</i> 380.00 X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<i>22</i> 380.00 <i>601</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>22</i> 380.00 X
To transfer of Front door fittings, attachment and perform water seepage test.	\$	380.00 <i>601</i>
To rust-proofing of the affected areas.	\$	170.00 <i>601</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9908S**AAD1907-157**

To transfer of Front fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn 380.00 X
TOTAL	\$	16,320.00
Over All Total	\$	60,132.78

LUMP SUM (REPAIR DAY)**20 DAYS***9 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Owner ID:

Company

3878K

Vehicle Details

Vehicle No.:

SHB99085

Vehicle to be Exported:

Yes

Intended Deregistration Date:

16 Jul 2019

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour:

Red

Manufacturing Year:

2013

Engine No.:

M9R8839C000407

Chassis No.:

VF1ABL15AUC273467

Maximum Power Output:

127.0 kW (170 bhp)

Open Market Value:

\$19,998.00

Original Registration Date:

30 Aug 2013

First Registration Date:

30 Aug 2013

Transfer Count:

0

Actual ARF Paid:

\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

29 Aug 2021

PARF Rebate Amount:

\$8,748.00

Intended COE Rebate Details

COE Expiry Date:

29 Aug 2021

COE Category:

A - Car (1600cc & below)

COE Period(Years):

8

PQP Paid:

\$54,952.00

COE Rebate Amount:

\$14,550.00

Total Rebate Amount:**\$23,298.00****Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 16 Jul 2019

OK

TP Veh	SHB9908S
Date of Reg	30.08.2013
DOA	16.07.2019
COE Expiry Date	29.08.2021

(I) Estimated Book Value

Unit Cost	38,000.00
Import Duty	3,999.60
Registration Fee	140.00
PQP Paid	54,952.00
ARF Paid	12,498.00
Estimated Per Taxi Purchase Price	109,589.60
Estimated Per Taxi Purchase Price	109,589.60
Less 60% of ARF Paid	7,498.80
Estimated Full Lifespan Depreciation	102,090.80
Estimated Full Lifespan Depreciation	102,090.80
Times Balance Life (25/96 months)	26,586.15
Add 60% of ARF Paid	7,498.80
Estimated Book Value	34,084.95

(II) Adjusted LTA Rebate

PARF Rebate	
PQP Paid	
Times Balance Life (69/96 months)	
Adjusted COE Rebate	
PARF Rebate	
Add Adjusted COE Rebate	
Adjusted LTA Rebate	23,298.00

(Summary) Estimated Nett Value

Estimated Book Value	34,084.95
Less Adjusted LTA Rebate	23,298.00
Estimated Net Value	10,786.95

Hsiao Tong (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Monday, 22 July 2019 11:19 AM
To: Hsiao Tong (LKKAUTO)
Subject: FW: New message for service request 127632, vehicle number SHB9908S

19/7/19 4:21 PM *** PROCEED DS *** Message Please check TP's NBV & ERV - LOH Cynthia

-----Original Message-----

From: cynthia.loh@axa.com.sg [mailto:cynthia.loh@axa.com.sg]
Sent: Friday, 19 July, 2019 4:22 PM
To: admin-d@lkkauto.com
Subject: New message for service request 127632, vehicle number SHB9908S

AXA Insurance has sent you a message for claim number S9M01U7W.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



<TP - Mandate IA> - S9M01U7W [ACCIDENT INVOLVING SBY 2088D(OI) & SHB 9908S(TP) ON 16/07/2019]

Type

🔗 Question

Message

Liability: 100%. Insured driver turned out from minor road and collided with third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$8,505.61(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 17-Aug-19

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 17/8/2019

Survey Details:

Date of loss	16-Jul-19
Date of appointment	17-Jul-19
Date of survey	17-Jul-19
Location of survey	TRANS-CAB AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SHB 9908S
Make and Model	RENAULT LATITUDE 2.0L DCI - 1995cc
Date of registration	30-Aug-13
Parf Rebate	
Market Value	\$ 34,000.00
Parf Rebate	\$ 23,298.00
Nett Loss	\$ 10,702.00

Repair details:

Initial Estimate	60,132.78
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 7,925.69
Check items (estimate)	\$ -
Labour	\$ 1,360.00
Total	\$ 9,285.69
Lump Sum(if applicable)	\$ 7,400.00

Number of days for repair	4.0
---------------------------	-----



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

OID turned out from minor road & hit third party.

Mandate:

Liability(TP)		100%
Proposed repair cost (w/GST)	\$	7,918.00
Loss of use		NIL
Loss of rental	\$	380.16 (4days x \$95.04)
Loss of income	\$	200.00 (4days x \$50.00)
LTA search fees	\$	7.45
Others		NIL
Proposed Total	\$	8,505.61

Hsiao Tong (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Tuesday, 15 October 2019 4:45 PM
To: Hsiao Tong (LKKAUTO)
Subject: FW: New message for service request 127632, vehicle number SHB9908S

15/10/19 2:24 PM *** APPROVE- LOH Cynthia

-----Original Message-----

From: cynthia.loh@axa.com.sg <cynthia.loh@axa.com.sg>
Sent: Tuesday, 15 October, 2019 2:24 PM
To: admin-d@lkkauto.com
Subject: New message for service request 127632, vehicle number SHB9908S

AXA Insurance has sent you a message for claim number S9M01U7W.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Tuesday, 29 October 2019 10:16 AM
To: Hsiao Tong (LKKAUTO)
Cc: jasminetan@transcab.com.sg
Subject: RE: Your Ref: AAD1907-157 (SHB9908S) *Our Ref: CC3/ASM19012693/Kpa3 [ACCIDENT INVOLVING SBY 2088D(AXA) AND SHB 9908S ON 16/07/2019]

WITHOUT PREJUDICE

Dear Hsiao Tong

Please proceed to send us the DV.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

**** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg*

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Saturday, 26 October, 2019 11:54 AM
To: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; Ng Wai Yin <waiyin.ng@transcab.com.sg>; claims@transcab.com.sg
Subject: Your Ref: AAD1907-157 (SHB9908S) *Our Ref: CC3/ASM19012693/Kpa3 [ACCIDENT INVOLVING SBY 2088D(AXA) AND SHB 9908S ON 16/07/2019]

Your Ref: **AAD1907-157 (SHB9908S)**
Our Ref: CC3/ASM19012693/Kpa3

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING SBY 2088D(AXA) AND SHB 9908S ON 16/07/2019

We refer to the above matter.

We propose settlement at a global sum of \$8,500.00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com

HP

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1907-157

Your Ref : SDY2088D

Date : 25.July 2019

AXA INSURANCE S PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SHB9908S AND SDY2088D ON 16/07/19 04:10 PM ALONG TANNERY ROAD X GENTING ROAD

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	7,971.50
2.	Loss of Rental for <u>4</u> days @ \$ <u>95.04</u> per day	\$	380.16
3.	Loss of Income for <u>4</u> days @ \$ <u>50</u> per day	\$	200.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	\$	0.00
	Total	\$	8,559.15

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)

Trans-Cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666

Fax: 6287 7764

Co. Reg. No.: 201019626G

GST Reg. No.: 201019626G

Tax Invoice / Debit Note**TO:****AXA INSURANCE PTE LTD**

8 SHENTON WAY, #27-01

AXA TOWER

068811 SINGAPORE

ATTENTION:

INVOICE NO. : INV1907-209**DATE** : 25. July 2019**REFERENCE NO** : AAD1907-157**TERMS** :**DUE DATE** : 25. July 2019**PAGE** : 1

NO.	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1.	6050101	REPAIR-SHB9908S; DOA 16.07.19(LUMP SUM-19)	1	7,971.50	7,971.50

Total SGD Excl. GST : 7,450.00**7% GST :** 521.50**Total SGD Incl. GST :** 7,971.50****** SEVEN THOUSAND NINE HUNDRED SEVENTY ONE AND FIFTY SGD ONLY**********

- 1) All cheques should be crossed and made payable to "Trans-Cab Auto Services Pte Ltd"
- 2) Please quote our Invoice Number during payment.
- 3) We reserve the right to charge interest @ 1.5% per month on overdue invoice.
- 4) Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

E. & O. E.

THIS IS A COMPUTER GENERATED INVOICE WHICH REQUIRES NO SIGNATURE

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC3/ASM19012693/Kpa3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: CYNTHIA LOH

Date : 11-11-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBY 2088D	Veh. Inspected	SHB 9908S
Policy No.	VPA/P2204923	Coverage (\$)	0.00
Claim No.	S9M01U7W	Excess (\$)	0.00
Assign From		Assign Date	17/07/2019

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	VF1ABL15AUC273467	Colour	METALLIC WHITE / RED
Odometer	548170	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	9 mm
L/H Front Tyre	215/60 R16	GITI	9 mm
R/H Rear Tyre	215/60 R16	GITI	6 mm
L/H Rear Tyre	215/60 R16	GITI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/07/2019	Inspection Date	17/07/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9908S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR PANEL REAR LH (CONSISTENT)	BUCKLED	2,844.66	2,844.66
1	DOOR GUIDE REAR LH (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER LH (CONSISTENT)	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER LH (CONSISTENT)	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH/RH L70Y (CONSISTENT)	SERVICEABLE	203.06	-
1	DOOR LOCK REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	908.75	-
1	DOOR FINISHER REAR LH (CONSISTENT)	SERVICEABLE	423.10	-
1	DOOR WEATHERSTRIP REAR LH (CONSISTENT)	SERVICEABLE	410.66	-
1	DOOR SEAL REAR LH (CONSISTENT)	SERVICEABLE	162.02	-
1	DOOR CASING REAR LH (CONSISTENT)	SERVICEABLE	1,509.06	-
1	DOOR HANDLE OUTER REAR LH (CONSISTENT)	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR LH (CONSISTENT)	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR LH (CONSISTENT)	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR LH (CONSISTENT)	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR LH (CONSISTENT)	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,135.10	-
1	DOOR REGULATOR MOTOR REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	893.75	-
1	DOOR PANEL FRT LH (CONSISTENT)	BENT	2,844.66	2,844.66
1	DOOR HINGE UPPER LH (CONSISTENT)	BENT	261.28	261.28
1	DOOR HINGE LOWER LH (CONSISTENT)	BENT	300.55	300.55
1	DOOR CHECK FRT LH (CONSISTENT)	BENT	194.77	194.77
1	DOOR LOCK FRT LH (CONSISTENT)	JAMMED	908.75	908.75
1	DOOR CATCH FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	131.23	-
1	DOOR HANDLE OUTER FRT LH (CONSISTENT)	SERVICEABLE	477.76	-
1	DOOR HANDLE COVER FRT LH (CONSISTENT)	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT LH (CONSISTENT)	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT LH (CONSISTENT)	BENT	505.19	505.19

Report Ref No. CC3/ASM19012693/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR REGULATOR MOTOR FRT LH (CONSISTENT)	JAMMED	796.46	796.46
1	DOOR REGULATOR GUIDE FRT LH (CONSISTENT)	SERVICEABLE	120.97	-
1	DOOR WEATHERSTRIP FRONT LH (CONSISTENT)	SERVICEABLE	410.66	-
1	DOOR MOULDING FRONT LH (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR FINISHER INNER FRONT LH (CONSISTENT)	SERVICEABLE	323.44	-
1	DOOR FINISHER FRONT LH (CONSISTENT)	SERVICEABLE	423.10	-
1	DOOR CASING FRONT LH (CONSISTENT)	SERVICEABLE	1,509.06	-
1	DOOR BLIND FRONT LH (CONSISTENT)	SERVICEABLE	741.80	-
1	DOOR WATER SHIELD FRONT LH (CONSISTENT)	SERVICEABLE	30.39	-
1	DOOR CASING CLIP (CONSISTENT)	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y (CONSISTENT)	SERVICEABLE	48.74	-
1	DOOR BLIND FRONT LH (CONSISTENT)	SERVICEABLE	741.80	-
1	DOOR SEAL FRONT LH (CONSISTENT)	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL FRONT LH (CONSISTENT)	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER FRONT LH (CONSISTENT)	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER FRONT LH (CONSISTENT)	SERVICEABLE	115.64	-
1	ROCKER PANEL INNER GARNISH LH (CONSISTENT)	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL OUTER LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,184.99	-
1	ROCKER PANEL CENTER LH (CONSISTENT)	TO REPAIR SEE LABOUR	990.25	-
1	DOOR MIRROR ASSY LH (CONSISTENT)	SERVICEABLE	1,483.40	-
1	DOOR HARNESS WIRE LH (CONSISTENT)	SERVICEABLE	2,670.00	-
1	FENDER PANEL FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT LH (CONSISTENT)	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH (CONSISTENT)	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH (CONSISTENT)	SERVICEABLE	130.84	-
1	FENDER PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL INNER TRIM REAR LH (CONSISTENT)	SERVICEABLE	671.45	-
1	WHEELARCH REAR LH (CONSISTENT)	SERVICEABLE	543.47	-
1	TAILLAMP LH (CONSISTENT)	SERVICEABLE	552.55	-

Report Ref No. CC3/ASM19012693/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILLAMP PANEL LH (CONSISTENT)	TO REPAIR SEE LABOUR	986.70	-
1	BUMPER COVER REAR (CONSISTENT)	SERVICEABLE	1,108.46	-
1	BUMPER LOWER REAR (CONSISTENT)	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR (CONSISTENT)	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE LH REAR (CONSISTENT)	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH (CONSISTENT)	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR (CONSISTENT)	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR (CONSISTENT)	SERVICEABLE	225.95	-
1	FUEL FLAP (CONSISTENT)	SERVICEABLE	343.57	-
1	LOWER ARM LH L70Y (CONSISTENT)	SERVICEABLE	685.76	-
1	KNUCKLE ARM LH L70Y (CONSISTENT)	SERVICEABLE	846.98	-
1	ABSORBER FRT LH L70Y (CONSISTENT)	SERVICEABLE	360.54	-
1	DRIVESHAFT LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,747.45	-
1	STABILIZER BAR FRT (CONSISTENT)	SERVICEABLE	604.65	-
1	BOOT REFLECTOR LAMP LH (CONSISTENT)	SERVICEABLE	493.35	-
	LESS 10% DISCOUNT		-4,489.07	-865.63
			40,401.87	7,790.69
	SPECIAL NETT ITEMS			
1	REAR DOOR STICKER '6555-3333' (SN) (CONSISTENT)	NECESSARY	300.00	60.00
1	FRONT DOOR STICKER 'TRANS-CAB' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER 'CLASSIC' (SN) (CONSISTENT)	NECESSARY	80.00	15.00
1	DOOR CHECK BOLT (SN) (CONSISTENT)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN) (CONSISTENT)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN) (CONSISTENT)	NOT NECESSARY	10.85	-
1	DOOR HINGE NUT LH (SN) (CONSISTENT)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN) (CONSISTENT)	NOT NECESSARY	22.69	-
1	DOOR CHECK NUT (SN) (CONSISTENT)	NOT NECESSARY	3.75	-
1	DOOR LOCK SCREW L70Y (SN) (CONSISTENT)	NOT NECESSARY	6.12	-
1	DOOR CATCH SCREW L70Y (SN) (CONSISTENT)	NOT NECESSARY	10.06	-
1	SET WHEELARCH CLIP FRT LH (SN) (CONSISTENT)	NOT NECESSARY	30.50	-

Report Ref No. CC3/ASM19012693/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT LEFT TYRE (SN) (CONSISTENT)	SERVICEABLE	300.00	-
1	FRONT LEFT TYRE RIM (SN) (CONSISTENT)	SERVICEABLE	380.00	-
1	FRONT WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	253.80	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	FRONT WINDSCREEN MOULDING (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
1	SET PARKING AID (SN) (CONSISTENT)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
1	SET BUMPER BRACKET CTR CLIP (SN) (CONSISTENT)	NOT NECESSARY	33.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN) (CONSISTENT)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
1	TAILLAMP CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	5.00	-
1	FENDER INNER TRIM CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	28.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	REAR LEFT TYRE (SN) (CONSISTENT)	SERVICEABLE	300.00	-
1	REAR LEFT TYRE RIM (SN) (CONSISTENT)	SERVICEABLE	380.00	-
			3,410.91	135.00
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF DOOR HINGE UPPER LH, DOOR HINGE LOWER LH, DOOR LOCK REAR LH, DOOR REGULATOR REAR LH, DOOR REGULATOR MOTOR REAR LH, DOOR CATCH FRT LH, ROCKER PANEL INNER LH, ROCKER PANEL OUTER LH, ROCKER PANEL CENTER LH, FENDER PANEL FRT LH, FENDER PANEL REAR LH, TAILLAMP PANEL LH, BUMPER BEAM REAR AND DRIVESHAFT LH.		6,000.00	500.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	660.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-

Report Ref No. CC3/ASM19012693/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
			16,320.00	1,360.00
GRAND TOTAL			60,132.78	9,285.69

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,400.00
---	--	--	-----------------

Report Ref No. CC3/ASM19012693/Kpa3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.