

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9908S**AAD1907-157***Not Authorised*
1/1/19

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident : 17 JUL 2019

Third Party Insurer :

Date of Registration:

SHB 9908S

VF1ABL15AUC273467

RENAULT

LATITUDE

16.7.19

AXA

30/8/2013

PART		LIST	
1	DOOR PANEL REAR LH	\$	Bu 2,844.66 ✓
1	DOOR GUIDE REAR LH	\$	SL 176.82
1	DOOR HINGE UPPER LH	\$	N 274.50
1	DOOR HINGE LOWER LH	\$	N 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	SL 203.06
1	DOOR LOCK REAR LH	\$	N 908.75
1	DOOR FINISHER REAR LH	\$	SL 423.10
1	DOOR WHEATHESTRIIP REAR LH	\$	SL 410.66
1	DOOR SEAL REAR LH	\$	SL 162.02
1	DOOR CASING REAR LH	\$	SL 1,509.06
1	DOOR HANDLE OUTER REAR LH	\$	SL 126.49
1	DOOR HANDLE CAP REAR LH	\$	SL 35.52
1	DOOR HANDLE SEAL REAR LH	\$	SL 7.89
1	DOOR HANDLE COVER REAR LH	\$	SL 13.22
1	DOOR HANDLE MODULE REAR LH	\$	SL 133.60
1	DOOR REGULATOR REAR LH	\$	N 1,135.10
1	DOOR REGULATOR MOTOR REAR LH	\$	N 893.75
1	DOOR PANEL FRT LH	\$	Bu 2,844.66 ✓
1	DOOR HINGE UPPER LH	\$	Bu 261.28 ✓
1	DOOR HINGE LOWER LH	\$	Bu 300.55 ✓
1	DOOR CHECK FRT LH	\$	Bu 194.77 ✓
1	DOOR LOCK FRT LH	\$	Tu 908.75 ✓
1	DOOR CATCH FRT LH	\$	N 131.23 X
1	DOOR HANDLE OUTER FRT LH	\$	SL 477.76 X
1	DOOR HANDLE COVER FRT LH	\$	SL 13.22 X
1	DOOR HANDLE MODULE FRT LH	\$	SL 133.60 X
1	DOOR REGULATOR FRT LH	\$	Bu 505.19 ✓
1	DOOR REGULATOR MOTOR FRT LH	\$	Tu 796.46 ✓
1	DOOR REGULATOR GUIDE FRT LH	\$	SL 120.97 X

Trans-cab Auto Services Pte Ltd**AAD1907-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9908S

1	DOOR WHEATHESTRIP FRONT LH	\$	S _L	410.66
1	DOOR MOULDING FRONT LH	\$	S _L	176.82
1	DOOR FINISHER INNER FRONT LH	\$	S _L	323.44
1	DOOR FINISHER FRONT LH	\$	S _L	423.10
1	DOOR CASING FRONT LH	\$	S _L	1,509.06
1	DOOR BLIND FRONT LH	\$	S _L	741.80
1	DOOR WATER SHIELD FRONT LH	\$	S _L	30.39
1	DOOR CASING CLIP	\$	u _n	12.63
1	DOOR CASING LIGHT L70Y	\$	S _L	48.74
1	DOOR BLIND FRONT LH	\$	S _L	741.80
1	DOOR SEAL FRONT LH	\$	S _L	162.02
1	DOOR GLASS RUNNER SEAL FRONT LH	\$	S _L	229.31
1	DOOR WAIST SEAL OUTER FRONT LH	\$	S _L	334.69
1	DOOR WAIST SEAL INNER FRONT LH	\$	S _L	115.64
1	ROCKER PANEL INNER GARNISH LH	\$	S _L	466.51
1	ROCKER PANEL INNER LH	\$	R	1,024.79
1	ROCKER PANEL OUTER LH	\$	R	1,184.99
1	ROCKER PANEL CENTER LH	\$	R	990.25
1	DOOR MIRROR ASSY LH	\$	S _L	1,483.40
1	DOOR HARNESS WIRE LH	\$	S _L	2,670.00
1	FENDER PANEL FRT LH	\$	R	783.83
1	WHEELARCH FRT LH	\$	S _L	278.84
1	FENDER BRACKET LOWER LH	\$	S _L	15.79
1	FENDER INSULATOR LH	\$	S _L	130.84
1	FENDER PANEL REAR LH	\$	R	3,299.13
1	FENDER PANEL INNER TRIM REAR LH	\$	S _L	671.45
1	WHEELARCH REAR LH	\$	S _L	543.47
1	TAILLAMP LH	\$	S _L	552.55
1	TAILLAMP PANEL LH	\$	R	986.70
1	BUMPER COVER REAR	\$	S _L	1,108.46
1	BUMPER LOWER REAR	\$	S _L	768.84
1	BUMPER BRACKET CTR REAR	\$	S _L	113.47
1	BUMPER BRACKET SIDE LH REAR	\$	S _L	135.97
1	BUMPER RETAINER LH REAR	\$	S _L	44.99
1	BUMPER REFLECTOR LH	\$	S _L	43.61
1	BUMPER BEAM REAR	\$	R	777.52
1	BUMPER BEAM BRACKET LH REAR	\$	S _L	225.95
1	FUEL FLAP	\$	S _L	343.57

X

Trans-cab Auto Services Pte Ltd

AAD1907-157

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9908S

1	LOWER ARM LH L70Y	\$	SH 685.76	} X
1	KNUCKLE ARM LH L70Y	\$	SH 846.98	
1	ABSORBER FRT LH L70Y	\$	SH 360.54	
1	DRIVESHAFT LH	\$	N 1,747.45	
1	STABILIZER BAR FRT	\$	SH 604.65	
1	BOOT REFLECTOR LAMP LH	\$	SH 493.35	
TOTAL		\$	44,890.95	
10%		\$	4,489.09	
		\$	40,401.85	

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	N 300.00	6555	} X
1	FRONT DOOR STICKER 'Trans-Cab'	\$	N 80.00	6555	
1	FRONT DOOR STICKER 'Classic'	\$	N 80.00	1555	
1	DOOR CHECK BOLT	\$	N 22.69		
1	DOOR GUIDE SCREW	\$	N 10.85		
1	DOOR HINGE BOLT	\$	N 10.85		
1	DOOR HINGE NUT LH	\$	N 14.60		
1	DOOR CHECK BOLT	\$	N 22.69		
1	DOOR CHECK NUT	\$	N 3.75		
1	DOOR LOCK SCREW L70Y	\$	N 6.12		
1	DOOR CATCH SCREW L70Y	\$	N 10.06		
1SET	WHEELARCH CLIP FRT LH	\$	N 30.50		
1	FRONT LEFT TYRE	\$	SH 300.00		
1	FRONT LEFT TYRE RIM	\$	SH 380.00		
1	FRONT WINDSCREEN SEALANT	\$	N 253.80		
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	N 100.00		
1	FRONT WINDSCREEN MOULDING	\$	N 120.00		
1SET	PARKING AID	\$	SH 700.00		
1SET	REAR BUMPER CLIP	\$	N 66.00		
1SET	BUMPER BRACKET CTR CLIP	\$	N 33.00		
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	N 10.00		
1SET	BUMPER RETAINER CLIP LH RR	\$	N 20.00		
1SET	BUMPER LOWER REAR RIVET	\$	N 22.00		
1SET	BUMPER LOWER REAR CLIP	\$	N 66.00		
1	TAILLAMP CLIP LH	\$	N 5.00		
1	FENDER INNER TRIM CLIP LH	\$	N 28.00		
1SET	FENDER WHEELARCH REAR LH CLIP	\$	N 35.00		

Trans-cab Auto Services Pte Ltd**AAD1907-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9908S

1	REAR LEFT TYRE	\$	<i>PL</i> 300.00	X
1	REAR LEFT TYRE RIM	\$	<i>PL</i> 380.00	X

TOTAL	\$	3,410.93
--------------	-----------	-----------------

TOTAL PARTS	\$	43,812.78
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	<i>5001</i>
Putty and spray painting of the affected portion.	\$	6,000.00	<i>6601</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of front windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	<i>601</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
To transfer of Front door fittings, attachment and perform water seepage test.	\$	380.00	<i>601</i>
To rust-proofing of the affected areas.	\$	170.00	<i>601</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>

Trans-cab Auto Services Pte Ltd**AAD1907-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9908S

To transfer of Front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>nn</i> 380.00 <i>X</i>
TOTAL	\$	16,320.00
Over All Total	\$	60,132.78

LUMP SUM (REPAIR DAY)**20 DAYS***8 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: